

MONTHLY	Q -
MONTHLY	Small Arms PM Tips 36-38
	M2/M2A1 Machine Gun Bushing Gage Not Needed 39
ISSUE 774 MAY 2017	X26E Taser DPM Needed for Storage 39
	Secure Gun Sights to Prevent Loss or Damage 40-41
COMBAT VEHICLES 2	MISSILES 42
M119A3 Howitzer Fire Control Computer PQDR 3 M777A2 Howitzer LRU Turn-ins Needed 4-5	Avenger ECU/PPU W103 Cable Torque 42
M2/M3-Series Bradley M242 Gun Bags and Covers 5	OO coon
M113-Series FOV Glow-plug Engine Conversion Kit 6-7	CBRN 43
DSESTS Assistance 7	CBRN Room Checklist Available 43
Stryker Ramp Hydraulics PM 8 Stryker, No Water in Air Intake 9	
Survivor victor in make	TOOLS 44
TACTICAL VEHICLES 10	
	M7 FRS Operation and Maintenance Tips 44-45
M1165A1, M1152A1 HMMWV Mount Guidance 11	COMMUNICATIONS 46
HMMWV Transmission Filter NSN 12 M1235A4/A5 MaxxPro Dash ISS w/OGPK/CROWS	
Pitman Arm Output Shaft Boot 13	SINCGARS RT-1523G, HUB CCA Replacement 47
M1083A1P2 FMTV Axle Replacement Update 14-15	HMS Manpack Radio, RT-1967(C)U, Low Power Defect Workaround 48
M1117 ASV Side Door Foothold Safety 15	
CONSTRUCTION	AN/PSQ-20, -20B Batteries, Warranty Info 49
EQUIPMENT 16	SOLDIER SUPPORT 50
Construction Equipment Tire Leak Prevention 17	MRE Expiration Guidance 50-52
MK III VMMD Husky Cab Air Vent Filter 18-19	Containerized Kitchen PMCS 50-52
MK III VMMD Husky Ink Spray Hose Damage 19	MTRCS Engine Oil Drain Line Fix 53-54
621G Scraper Cab Air Filter Protection 20	IETMs No Longer Viewable Online 54
AVIATION 21	LOGISTICS MANAGEMENT 55
Advanced Cargo Parachute Release System Tips 22-23	How to Get Army Publications 56-57
IHADSS Helmet Size Mixup 23-24	MILES Mobile Apps 58-59
UH-60 Series Flutter Dampeners Turn-in 24 UH-60A/L, HH-60M Series, Seat Hits Dome Light 25	Verifying Active Publications 59
UTITOURIE, TITTOURI JETTES, JEAUTIUS DUTTIE LIQUI 23	

Dogfight Over Berlin

SMALL ARMS

TB 43-PS-774. The Preventive Maintenance Monthly, is an official publication of the Department of the Army, providing information for all Soldiers assigned to combat and combat support units and all Soldiers with unit maintenance and supply duties. All information published has been reviewed and approved by the agency responsible for the equipment, publication or policy discussed. Application of the information is optional with the user. Masculine pronouns may refer to both genders. The use of product or company names does not constitute endorsement of those products, services or companies by the U.S. Army. The use of non-DoD hyperlinks, along with their content, does not constitute endorsement by DoD or DA. Neither DoD nor DA exercises any editorial control over, and cannot vouch for, content on non-DoD websites.

PS, The Preventive Maintenance Monthly (ISSN 0475-2953) is published monthly by the Department of the Army, Redstone Arsenal, AL 35898. Periodical postage is paid at the Huntsville, AL post office and at additional mailing offices. Postmaster: Send address changes to PS. The Preventive Maintenance Monthly, USAMC LOGSA (AMXLS-GP), Bldg, 3303, Redstone Arsenal, AL 35898.

You are invited to send PS your ideas for improving maintenance procedures, questions on maintenance and supply problems and questions or comments on material published in PS.

Just write to:

MSG Half-Mast PS, the Preventive Maintenance Monthly USAMC LOGSA (AMXLS-GP) Bldg. 3303

Redstone Arsenal, AL 35898

UH-60M, Parts Turn-in Needed

Or email:

usarmy.redstone.logsa.mbx.psmag@mail.mil

Internet address:

https://www.logsa.army.mil/psmag/pshome.cfm

By order of the Secretary of the Army:

MARK A. MILLEY

General, United States Army Chief of Staff

Official:

26 Connie's Post Scripts

GFRALD B. O'KFFFF

Administrative Assistant to the Secretary of the Army


1704801

60-61

27-34



Good PM Takes More Than Just the TM



 ${f F}$ ollowing the PMCS tables in the -10 TMs is a **given**. But you also need to use your









TO UNCOVER PROBLEMS THAT COULD DEADLINE YOUR VEHICLE!

Catches, locks and hinges should operate smoothly. Look for metal fatigue, wear and other damage. Listen for squeals that indicate rust.

Check bolts, clamps, nuts and screws regularly for looseness. Chipped paint, bare metal or rust around the heads can indicate loose fasteners.

A failing weld point may show movement, gaps, corrosion or flaked or missing paint.

Look for broken, worn or cut electrical connections and cables.

Check out hose fittings, clamps and the hose itself for abrasions, seepage or leaks. Feel for leaks in areas you can't see. Some fluids have a distinct odor, so use your nose, too.





- Computer Problems?
 File a PQDR!
- LRU Turn-ins
 Needed Now!
- That Wasn't an M242 Cover!
- New Engine Conversion Kit!
- DSESTS Problems
 Got You Down?
- Hydraulic Woes Make Ramp Not Go
- Keep Water Away
 From Air Intake



PS774

2

MAY 17










INSTEAD, FILE A
PRODUCT QUALITY
DEFICIENCY REPORT
(PQDR) SO THE
ARMY IS AWARE OF
THE PROBLEM AND
CAN TAKE STEPS TO
CORRECT IT.

IT'LL ALSO HELP YOUR UNIT AVOID UNNECESSARY CHARGES. FILE PQDRS THROUGH THE PRODUCT DATA REPORTING AND EVALUATION PROGRAM (PDREP): https://www.pdrep.csd.disa.mil/

FOR HELP WITH PDREP OR FILING PQDRS, CONTACT CUSTOMER SUPPORT AT DSN 684-1690, (207) 438-1690, OR EMAIL: webptsmh@navy.mil

QUESTIONS? CONTACT YOUR TACOM LAR OR THE TACOM FIELD ARTILLERY AND INFANTRY SUPPORT CORE TEAM AT: usarmu.detroit.tacom.mbx.ilsc-fa-core-team@mail.mil

NOTE: PQDRS SHOULD NOT BE SUBMITTED FOR ISSUES OR DAMAGE BECAUSE OF IMPROPER USE, IMPROPER HANDLING OR NORMAL WEAR AND TEAR. SEE PARA 1 OF AR 702-7 FOR FURTHER GLIDANCE. FOR THESE TYPES OF ISSUES, TURN IN THE UNSERVICEABLE FCC AND ORDER A NEW ONE THROUGH NORMAL SUPPLY CHANNELS.



CREWMEN AND
MECHANICS, LINE
REPLACEABLE
UNITS (LRUS)
FOR THE
M777A2 TOWED
HOWITZER'S
DIGITAL FIRE
CONTROL SYSTEM
ARE URGENTLY
NEEDED!

TURNING IN
LRUS WILL HELP
IMPROVE COMBAT
READINESS AND
EARN YOUR UNIT
UNSERVICEABLE
CREDIT.



Line replaceable units (LRUs) like communication location assembly (CLA) are urgently needed

IF YOU HAVE ANY OF THESE LRUS
THAT ARE UNSERVICEABLE OR EXCESS THAT
ARE JUST LAYING AROUND, TURN
THEM IN ASAP

...GO CRITICAL
REPAIR PARTS CAN
GET BACK INTO THE
SUPPLY SYSTEM:

LRU	NSN
Chief of section's display (CSD)	6625-01-533-8823
Mission computer (MSC)	7021-01-578-7165 7021-01-533-8722
Communication location assembly (CLA)	5825-01-533-8812
Power conditioning and control module (PCCM)	1290-01-533-8761

DON'T
TURN IN
THE ASIP
SINCGARS,
RADIO
AMPLIFIER,
DAGR OR PIK
WITH THE CLA.


QUESTIONS?

CONTACT PETE MAGON AT DSN 786-3392, (586) 282-3392, OR EMAIL: peter.c.mason.civ@mail.mil

OR MYESHA SWINSON AT DSN 786-2460, (586) 282-2460, OR EMAIL: myesha.swinson.civ@mail.mil

M2/M3-Series Bradley...

THAT WASN'T AN M242 COVER!



Dear Editor,

Page 9 in PS 766 (Sep 16) said you could order a cover for your M242 gun with NSN 1005-01-171-8316.


Unfortunately, we discovered after ordering that NSN it's actually for the gun bag that goes inside the Bradley.

But that brings up an important point: If the Bradley is missing the gun bag, the Bradley is NMC. And gun bags often go missing because crews remove them when the bags get in the way. If the bag's mounting hardware disappears, the components have to be ordered individually, which is a hassle.


Commanders need to make sure crews leave the bags in place.

SGT Corey Hampton Ft Hood, TX NSN 1005-01-171-8316 brings gun BAG, not gun COVER

Editor's note: Sorry we got gun bags mixed up with gun covers. Tarps that protect the M242 are part of the Bradley's BII. Get a green tarp with NSN 2540-00-587-2532 and a tan one with NSN 2540-01-330-8062.




PS 774 5 MAY 17




NEW ENGINE CONVERSION KIT!

THE M113-SERIES FOV'S HEATER BOX-EQUIPPED ENGINE, NSN 2815-01-248-7644, IS BEING PHASED OUT THROUGH ATTRITION.

ITS REPLACEMENT IS THE GLOW PLUG-EQUIPPED ENGINE, NSN 2815-01-412-2715.





IF YOU HAVE AN MILT THAT'S DUE FOR AN ENGINE REPLACEMENT, ORDER THE NEW VERSION!

KEEP IN MIND THAT YOU'LL NEED THE GLOW-PLUG CONVERSION KIT, NSN 2815-01-653-9437.

THE KIT UPGRAPES THE ELECTRICAL SYSTEM SO IT CAN ACCEPT THE NEW ENGINE.

YOU'LL FIND THE
INSTRUCTIONS FOR
INSTALLING THE
CONVERSION KIT IN
TM 9-2350-277-13&P
IN IETM EM 0321
(OCT 14).



QUESTIONS? CONTACT:

CHRISTOPHER FAIOLA AT DSN 786-8291,(586) 282-8291, OR EMAIL:

christopher.j.faiola.civ@mail.mil

OR FLOYD PERRY AT DSN 786-8290, (586) 282-8290, OR EMAIL:

floud.n.perru.civ@mail.mil

OR RICHARD DARLING AT DSN 786-2517, (586) 282-2517, OR EMAIL:

richard.j.darling.civ@mail.mil

GCSS-ARMY HAS ITS OWN SET OF DOCUMENT NUMBERS. ONCE THE CUSTOMER IS ISSUED A GLOW PLUG-EQUIPPED ENGINE, NSN 2815-01-412-2715, A ZRL (RETURN DELIVERY TO 55Å) PURCHASE REQUEST DOCUMENT IS CREATED. THE ZRL DOCUMENT NUMBER IS ELIGIBLE FOR CREDIT FOR 180 DAYS.

THE CUSTOMER THEN TURNS IN THE HEATER BOX-EQUIPPED ENGINE, NSN 2815-01-248-7644, WITH A ZXS (EXCESS REQUISITION) DOCUMENT SINCE THE RETURN HAS NO CORRESPONDING ISSUE. THE ZXS DOCUMENT WILL BE ASSIGNED A RETURN ADVICE COPE (RAC) OF 1W.

THE \$6A WILL NEED TO MANUALLY MATCH THE -7644 RETURN RECEIPT AGAINST THE -2715 ISSUE DOCUMENT AND MANUALLY REMOVE THE RAC TO ALLOW THE SYSTEM TO GENERATE CREDIT. THE \$6A WILL ALSO NEED TO MANUALLY CLOSE THE **ZRL** DOCUMENT SO THAT IT DOESN'T MATCH TO ANOTHER TURN-IN RECEIPT.

NOTE: THE ISSUE AND RETURN MILSTRIP DOCUMENT NUMBERS



DSESTS Problems Got You Down?



Problems with
your direct
support electronic
systems test set
(DSESTS) got you

STUMPED?


YES! I PON'T
KNOW WHAT
TO PO!



DRS field service representatives (FSRs) can provide help over the phone or by e-mail. If a functional self test (FST) or troubleshooting a line replaceable unit (LRU) has you pulling out your hair, call John Moore at (256) 895-2472, (256) 361-8300 or email: john.moore@drs.com FSRs can also provide on-site support and help you troubleshoot NMC DSESTS, make repairs or provide informal training. To request an FSR visit, contact your local LAR or email the TACOM DSESTS team at: usarmy.detroit.tacom.mbx.ilsc-dsests@mail.mil

PS 774 7 MAY 17

Stryker... HYDRAULIC WOES MAKE RAMP NOT GO





Crewmen, has your Stryker's ramp lost its pep? A slow or balky ramp could mean your Stryker is having hydraulic problems.

But before you call your mechanic, a quick check of the hydraulic level will tell you for sure.

Open the rear service hatch and eyeball the vertical tube at the back. If the fluid is $^{1}/_{4}$ to $^{1}/_{2}$ full in the tube, the hydraulic level is OK.

If the hydraulic level is too high—above ¹/₂ full—hydraulic seals will blow. Too low—below ¹/₄ full—and you'll have trouble raising and lowering the ramp.

The annunciator panel should flash and sound if the hydraulic fluid drops below $6^{-1/2}$ gallons.





Stryker... REEP WATER AWAY FROM AR INTAKE



WHEN IT'S TIME TO GIVE YOUR STRYKER A GOOD WASHING, MAKE SURE YOU DON'T PROWN THE ENGINE WHILE YOU'RE AT IT!


WHILE AT THE
WASH RACK, YOU
DON'T NEED TO
SPRAY EVERY NOOK
AND CRANNY. THAT'S
ESPECIALLY TRUE
FOR THE
ENGINE AIR INTAKE.


EVEN LOW-PRESSURE WATER CAN GET INSIDE AN UNCOVERED AIR INTAKE.

THEN THE NEXT TIME YOUR STRYKER IS STARTED, ALL THAT WATER GETS SUCKED STRAIGHT INTO THE AIR FILTER CANISTER.

A WET FILTER
BLOCKS GOOD AIR
FLOW, CHOKING THE
ENGINE, THAT'S A
SOUND THAT'S SURE
TO MAKE YOU CRINGE!

BEFORE YOU WASH YOUR STRYKER, MAKE SUIRE THE AIR INTAKE IS PROPERLY COVERED WITH THE ENVIRONMENTAL COVER, NSN 5340-20-000-0183.





PS 774

MAY 17

9

PS TACTICAL VEHICLES







MASTER SERGEANT HALF-MAST, I HAVE A QUESTION. IS THERE A RING MOUNT WE CAN USE FOR OUR MITSZAI AND MITGSAI HMMWVS?

THE SHORT
ANSWER IS NO.
THE M1152A1 AND
M1165/M1165A1
WERE NEVER
INTENDED TO
BE ARMAMENT
CARRIERS.




IF YOU HAVE THE M998 CARGO CARRIER THOUGH, THE M7 PEDESTAL, NSN 1005-01-518-9037, WORKS GREAT!

THE M197 MOUNT FITS RIGHT ON THE M7.


THE M7 CAN BE MOUNTED IN THE FORWARD **OR** REAR (OVER THE WHEEL WELLS) POSITION ON THE M998. ITS COLUMN BASE
IS DESIGNED
TO ELIMINATE
CRACKED
SUPPORT BRACES
AND TRIPPING
HAZARDS.

AND IT HAS A
DEPRESSION
STOP TO
PREVENT
ACCIDENTAL
FIRING IN THE
CAB AREA.

THE M7 COMES WITH A LARGE MOUNTING PLATE TO STOP SPENT CASINGS FROM BUILDING UP ALONG THE EEGES OF THE VEHICLE BED AND TO PROVIDE ADDITIONAL BLAST PROTECTION FROM BELOW.



FILTER FOUND FOR FEWER FUNDS



Dear Editor.

I tried to order a transmission filter, PN 24210468, for one of our M1152A1 HMMWVs. But the PN doesn't cross to an NSN and is only available by ordering a transmission parts kit. The kits, NSNs 2520-01-624-2208 and 2520-01-600-3071, cost $$\pm 350$ and $$\pm 230$ respectively. Either one is a hefty price when only a filter is needed.

After some research, I found that there was a **new** part number available for that filter. PN 24210956 crosses to NSN 4330-01-496-5720, which costs a little under \$11.


Please pass the word so other maintainers can save money on this filter.

> SGT David Lindstrom Ft Stewart, GA



Get new transmission filter with NSN 4330-01-496-5720

Editor's note: Will do, Sergeant. Mechanics, note that this filter works on any HMMWV with a 4L80-E or 4L85-E transmission.




Some units are deadlining the M1235A4/A5 MaxxPro Dash ISS MRAP during checks and services. Why? Because they see cracks in the rubber boot cover on the steering gear output shaft that connects to the pitman arm.

Step 3 of Items 15 and 106 in the PMCS tables of TM 9-2355-441-10 says to check the pitman arms for cracks and bends. If the pitman arm is cracked or bent, the vehicle is deadlined.


But this is a case of mistaken identity! This particular check is referring to the pitman arm itself, not the output shaft's rubber boot.

Cracks or tears in the output shaft boot **do not** deadline your vehicle. Cracks there have no bearing on the form, fit or function of the pitman arm. The pitman arm has an internal seal to protect it.



For more info, check out TACOM Maintenance Information message 16-046: https://tulsa.tacom.army.mil/Maintenance/message.cfm?id=MI16-046.html

M1083A1P2 FMTV LTAS...



Dear Half-Mast,

While creating service packets for our mechanics, I noticed that the M1083A1P2's TM 9-2320-333-13&P says to replace the vehicle's carrier flange bolts during semi-annual services. The TM also says to replace the front axle once the bolts have been replaced three times.

Is this right? If we follow these guidelines, we'll have to replace axles every 18 months. We store and service equipment for 74 Army reserve units, so the cost of replacing all those axles is extremely high, especially when you consider these vehicles get minimum usage and show no signs of leaking.

Mr. T.T.

Dear Sir.

The front axle, NSN 2520-01-573-2772, that's used on the FMTV LTAS requires inspections at normal service intervals to detect accelerated wear caused by the additional weight of armor on the cab.

In the meantime, the instructions in the TM will be changed. The axle housing and assembly inspection is to be completed after 6,000 miles to include the following:

- Check the carrier flange bolt to make sure it's torqued to 74-96 lb-ft.
- Look for any carrier flange leaks.



If any carrier flange bolts show leaks:

- Replace all carrier flange bolts. Put some sealing compound, NSN 8030-01-014-5869, on the replacement bolt's threads and torque to 74-96 lb-ft.
- Metal stamp, electro-etch or engrave the date on the axle housing each time the carrier flange bolts are replaced.
- If the carrier flange bolts are replaced three times, then replace the axle.

Tests have confirmed that the LTAS' additional weight strains the front axle and can, over time, stretch the flange bolts and warp the holes on the axle housing. The replacement instructions were put in place to ensure your safety and the safety of your equipment.

Add sealing compound to bolt threads and torque to 74-96 lb-ft

M1117 Armored Security Vehicle...

DON'T FLUB THE FOOTHOLD!



THE FOOTHOLD ON THE SIDE DOORS OF THE M1117 ARMORED SECURITY VEHICLE (ASV) IS A HANDY PLACE TO STEP WHEN YOU EXIT THE VEHICLE.

THAT IS, LONG AS YOUR BOOT DOESN'T GET STUCK IN THE FOOTHOLD!

WHEN YOU'RE READY TO EXIT THE ASV, PLACE YOUR FOOT ON TOP OF THE FOOTHOLD.

DON'T STICK IT INSIDE THE FOOTHOLD'S


THAT'S A GOOD WAY TO GET STUCK, TWIST AN ANKLE OR LAND ON YOUR FACE!

IT ALSO PUTS
YOU IN THE WAY
OF OTHERS AS
THEY EXIT THE
VEHICLE.




PS 774 15 MAY 17

PS CONSTRUCTION



STOP THAT SNEAKY LEAK







OPERATORS,
WORKING IN ROCKY
SOIL CAN PLAY
HAVOC WITH THE
TIRES ON YOUR
CONSTRUCTION
EQUIPMENT.

WHEN SMALL
ROCKS GET STUCK
BETWEEN THE TIRE
AND WHEEL RIM,
TIRE PRESSURE
GOES RIGHT OUT
THE WINDOW!

SO WHENEVER YOU'VE GOT A FEW MINUTES, GET POWN ON YOUR HAND'S AND KNEES AND EYEBALL THE WHEEL ASSEMBLY. IF YOU SEE SMALL ROCKS WEDGED BETWEEN THE TIRE AND RIM, SING OUT TO YOUR MECHANIC.

Look for rocks wedged between tire and rim




HE'LL LET A LITTLE
AIR OUT OF THE
TIRE TO RELEASE
SOME PRESSURE.
THAT MAKES IT
EASIER TO PULL
THE ROCKS LOOSE
WITH SOMETHING
LIKE A PAIR OF
PLIERS.

JUST MAKE SURE HE REINFLATES IT AFTERWARDS!

YOU'LL FIND THE RIGHT TIRE PRESSURE LISTED IN THE VEHICLE'S -10 TM.

Keepin' It Cool in the Cab



Operators, with the flip of a lever you can let more air into the cab during operations. The lever is right next to your shoulder inside the Husky's cab.

This lever operates a cab air vent. It allows air to flow from outside, through an air filter and into the cab.

If the filter is clean, so is the air flowing into your cab. But you gotta do your part to keep the filter clean.

Use a 13mm open-end wrench to remove the four bolts that secure the housing in place. Pull out the filter element. If it's dirty, tap it lightly with your hand to loosen dust and sand. If it's very dirty, use low-pressure air (30 psi or less) to clean the filter.





You'll need to clean the filter more often when operating in dusty areas. But never wash the filter with soap and water! That ruins it. Replace a damaged filter with NSN 2945-01-572-7345.


When reinstalling the filter, remember that the foam side faces away from the cab. That keeps dust from slipping in past the filter.





MK III VMMD Husky...

RESTRAIN INK SPRAY HOSES!




OPERATORS, MAKE SURE THE HUSKY'S INK SPRAY HOSES ARE PROPERLY ROUTED, ATTACHED AND TUCKED AWAY WHENEVER THE VEHICLE'S MINE DETECTOR HEADS ARE IN THE ELEVATED POSITION.

HOSES THAT ARE LOOSE OR PANGLING WILL GET RIPPED OFF THE VEHICLE ON THE WAY TO THE WORK SITE, YOU WON'T BE MARKING MANY MINES THEN!

Dangling ink spray lines will get ripped off!

CHECK THE HOSES BEFORE AND AFTER THE DAY'S RUN. NOTIFY YOUR MECHANIC IF ANY OF THE INK LINES ARE LOOSE OR DAMAGED.

YOU'LL FIND MORE ON PROPER INK HOSE ROUTING IN WPS 0084 AND 0085 OF TM 9-2355-316-10.



PS 774 18 MAY 17



perators, make sure you keep a close eye on the 621G scraper's cab air filter, especially after a heavy rain.


The filter's access door has a series of louvers that allows open air flow. Problem is, the louvers also allow water from rain and cab run-off inside the door. That water fills the channel along the inside bottom of the door.


If there's too much water, it overflows the channel and the air filter soaks it up like a sponge. A soaked filter element gets moldy real quick!

You may also see buildup from water that seeps past the drain hoses attached to the A/C drip pan.


The hoses are installed with a grommet that fits into a hole in the plastic drip pan. But the grommet doesn't fit tight and leaks.


Replace a wet or moldy filter element with NSN 4310-01-602-0614. Then follow the instructions in TACOM GPA 17-008. It tells how to drill two drain holes in the door channel and add two O-rings, NSN 5331-01-333-6444, to the A/C drip pan grommet. See the message at:





https://tulsa.tacom.army.mil/Safety/message.cfm?id=GPA17-008.html





A LOT OF ARMY CARGO IS NOW BEING AIRDROPPED FROM FIXED WING AIRCRAFT USING THE NEW ADVANCED CARGO PARACHUTE RELEASE SYSTEM (ACPRS), NSN 1670-01-608-4698.

THE ACPRS REPLACES THE OLP M1, NSN 1670-01-095-8816, AND M2, NSN 1670-01-097-8817, CARGO PARACHUTE RELEASE SYSTEMS.

IT'S MORE RELIABLE,
OPERATES WELL IN ALL
WEATHER CONDITIONS,
AND AUTOMATICALLY
DISENGAGES THE RECOVERY
PARACHUTES FROM THE
LOAD AT IMPACT.

THAT PREVENTS DAMAGE FROM PRAGGING AND PROTECTS ANYONE ASSIGNED TO RECOVER THE LOAD.

TO MAKE SURE THAT
CARGO REACHES THE
GROUND SAFELY, THE
SOLDIER RESPONSIBLE FOR
THE ACPRS MUSI BE A

AFTER RECEIVING A NEW ACPRS AND BEFORE RIGGING, THE 92R MUST INSPECT THE UNIT FOR PAMAGE.

THAT MEANS FOLLOWING ALL THE INSPECTION AND MAINTENANCE PROCEDURES IN TM 10-1670-337-23&P, CARGO PARACHUTE RELEASE SYSTEM, TO BE PUBLISHED IN FY 17.


DURING THE INSPECTION, CHECK FOR DAMAGE TO THE PARACHUTE RELEASE, YOU'LL ALSO NEED TO OPERATE THE RELEASE TO MAKE SURE IT WORKS.

FOR TRACKING PURPOSES, ASSIGN A
TEST ITEM NUMBER TO THE ACPRS, THE
LOWER SUSPENSION LINKS AND THE
PARACHLITE CONNECTORS.

DOCUMENT ANY DAMAGE OR PROBLEMS IN A TECHNICAL INFORMATION REPORT (TIR).

A DD FORM 1473, REPORT DOCUMENTATION PAGE, CONTAINING AN ABSTRACT OF THE PUBLICATION IS FORWARDED TO THE DTIC WITHIN 10 WORK PAYS OF THE RELEASE OF THE ORIGINAL PUBLICATION.

ONCE THE ACPRS PASSES INSPECTION, THE RIGGING PROCESS AND AUTOMATED TESTING OF THE UNIT TAKES ABOUT 40 MINUTES WITH TWO QUALIFIED RIGGERS.



Helmet... ENDING APACHE D MODEL HELMET CONFUSION!




The TACOM headshed recently discovered that years back units had mistakenly identified their medium IHU helmets as NSN 1270-01-182-3719 and large IHU helmets as NSN 1270-01-181-3314. Take a quick look now because you may have a few of these incorrectly labeled helmets.

PS 774 23 MAY 17

All medium and large IHUs were field retrofitted between 1989-1990 by MWO 9-1270-200-20-1. The MWO added the then new adjustable mount for the helmet display unit (HDU).

The adjustable mount HDU, which all Apaches currently have, is not compatible with the older IHU configuration because of the style of the HDU receiver assembly. When the MWO was applied, not all maintainers updated the NSNs to reflect the new configuration: NSN 1270-01-295-6255 for the medium IHU and NSN 1270-01-298-3455 for the large IHU.



and installing PN 10114889-101 receiver assembly

Property book officers need to work with their aviation life support equipment (ALSE) folks to screen all unit IHUs. If you find any medium or large IHUs that are misidentified, contact TACOM's James Casto at DSN 786-1359, (586) 282-1359 or by email: james.e.casto.civ@mail.mil



UH-60 Series Flutter Dampeners Needed?


Mechanics, check your area now to see if you have flutter dampeners, NSN 1650-01-285-3024 (PN 70106-08100-046), lying around the hangar. If so, turn in the unserviceable ones for repair. The flutter dampeners are critically needed to support repair programs.



Go-pilots, your Black Hawk cockpit seat can be raised, lowered and tilted! However, when the seat is completely lowered, tilting it back isn't a good idea. Here's why:


Some have learned the hard way that when you tilt the seat back while it's in its lowest position, the connector for the dome light dimming switch hits the box housing the pilots collective stick. When that happens, it breaks the dome light connector.

The only way to prevent tearing up the connector is to raise the seat up just enough for the headrest to clear the circuit breaker panel above, which provides clearance below for the dimming switch connector, then push the seat back completely. Then when you tilt the seat back to the cabin floor, the connector will clear the box and it won't get damaged.



UH-60M...

RETURN PARTS AND ORDER THE RIGHT REPLACEMENTS



MECHANICS, THE CURRENT DEMAND FOR M-MODEL BLACK HAWK PARTS IN THE SUPPLY SYSTEM IS

HIGH!

PS 7774

THAT'S WHY IT'S IMPORTANT TO TURN IN ALL UNSERVICEABLE ASSETS TO SUPPORT THE MAINTENANCE AND OVERHAUL PROGRAM. GET THAT DONE ASAP SO THE REPAIRED ITEMS CAN BE PUT BACK INTO THE SUPPLY SYSTEM TO HELP OTHER SOLDIERS WHO NEED PARTS. NOT TURNING IN PARTS FOR REPAIR HURTS AVAILABILITY.

Remember

TURN IN
UNSERVICEABLE
ASSETS TO
POSSIBLY
RECEIVE
CREDITI

LOOK AROUND YOUR HANGAR FOR THESE CRITICAL PARTS AND TURN THEM IN NOW!

- Left-hand stabilator, NSN 1560-01-542-7904
- Center box stabilator, NSN 1560-01-294-7824
- Drive shaft assembly, NSN 1615-01-491-1924
- Right-hand stabilator, NSN 1560-01-542-8455
- Air data computer, NSN 6610-01-558-4786-


HIGHLIGHTED NSNS ARE KNOWN READINESS DRIVERS.

Ordering Parts

WHEN ORDERING PARTS, NOTE THE FOLLOWING CHANGES:

- Large resilient mount, NSN 5342-01-543-9891, is now a terminal item. Order the new replacement mount with NSN 5440-01-589-2083.
- Aircraft strut, NSN 1560-01-586-1959, is a terminal item and is replaced with NSN 1560-01-586-1963.

26 MAY 17




THE ME 262 WAS THE LUFTWAFFE'S LAST HOPE TO STAVE OFF THE RELENT-LESS AIR ASSAULT BEING CARRIED OUT BY ALLIED BOMBERS.



IF THE ME 2625 COULD GET PAST THE FIGHTER ESCORTS AND SHOOT DOWN ENOUGH B-17 FLYING FORTRESSES, GERMANY MIGHT DELAY ITS DEFEAT OR EVEN POSSIBLY FORCE THE ALLIES TO AGREE TO BETTER SURRENDER TERMS.





MARGI 23, 1945;

AT AN AIRFIELD SOMEWHERE IN ITALY, A GROUP OF PILOTS FROM THE 332NP FIGHTER GROUP-THE FAMED FAMED TAILS-ARE GATHEREP AROUND A P-510 MUSTANG FIGHTER PLANE.

THE 332NP IS MADE UP OF THE FAMED TUSKEGEE AIRMEN AMERICA'S FIRST AFRICAN-AMERICAN COMBAT PILOTS.












LATER AT THE AIRFIELD, PILOTS AND GROUND CREWS ARE BUSY GETTING THE P-515 READY FOR THE NEXT PAY'S MISSION.










PS 774 28 MAY 17
















PS 774 31 MAY 17






DESPITE THEIR SUPERIOR SPEED, THE GERMAN ME 2625 FAILED TO STOP THE B-175 FROM REACHING THEIR TARGETS THAT DAY. THE MEN OF THE 332ND HELD OFF THE ENEMY FIGHTER JETS SO THE BOMBERS COULD LAND ANOTHER BLOW AGAINST THE GERMAN WAR MACHINE. GERMANY SURRENDERED JUST WEEKS LATER.














Dear Editor.

Through our work keeping weapons firing at Ft Stewart, we offer these tips:

Remove batteries from night vision equipment and sights before storing them in the arms room. This is so basic, but every year we lose expensive equipment because no one bothered to remove batteries before storing sights and goggles. The batteries leak and the equipment is ruined. A \$12k sight becomes trash because no one could spare a minute to take out the batteries.


Keep a brush handy for applying CLP. Soldiers can buy CLP wipes on the Internet (they're called Break Free Wipes), but they cost \$7 for just 20. We find a small soft paint brush works great for applying CLP, especially if you're cleaning and lubing several weapons.






Never transport or store weapons with the bolt to the rear. If a round is in the chamber, a bump in the road could cause the weapon to fire. That would be extremely bad!


If you store a weapon with the bolt locked to the rear and the hammer cocked, the trigger and hammer springs lose their strength and have to be replaced. For storage, always leave the bolt or slide forward, the selector on SEMI for the MI6 rifle and M4 carbine or the selector off SAFE for the pistols and machine guns with the hammer uncocked.



Include the -10 TMs when weapons are checked out of the arms room. We find that the -10s never leave the arms room (if they have the TMs in the first place). That means Soldiers must do PMCS from memory, which is hard to do. Be sure to replace the TMs that disappear. Remember they're free to units.



PMCS weapons before you go to the field or range. If you find minor problems, your small arms repairman may be able to fix them right away. Few repairs are possible in the field.




PS 774 36 MAY 17

Check MK 19s for a loose barrel before firing. Just grab the barrel and feel if it's loose. There should be zero movement. We've had several instances of repairmen not completely tightening the barrel.

Twist barrel to see if it's loose

For the M2, M240 and M249 machine guns, take both barrels to the field and use them. If you go to the range and fire and fire through the same barrel, the barrel gets so hot it warps.




If you're going to fire blanks with the M2, remove the cartridge stop and store it in the arms room. If it goes to the field, count on never seeing it again.

Tony Gibson Robert Hesch Alden James Ft Stewart, GA







Dear Half-Mast,

In the M2 machine gun's special tools list in TM 9-1005-213-23&P, there is no mention of a bushing gage. The special tools list in the M2A1's TM 9-1005-347-23&P shows a bushing gage, but there's nothing in the TM about using it. What gives?

Mr. N.C.

ALL THE PROCEDURES FOR DOING A BARREL SUPPORT AND MACHINE THREAD BUSHING CHECK HAVE BEEN MOVED TO DEPOT MAINTENANCE.

TACOM IS WORKING ON A NEW TM THAT WILL COVER BOTH THE M2 AND M2AI. IT WILL REMOVE ALL REFERENCES TO THE BUSHING GAGE.


DON'T Remove Taser DPM

Dear Editor,


We've run into a big problem with units removing the digital power magazine (DPM) from the Launched Electrode Stun Device (LESD) Taser X26E ECD for storage.

As it states on Page 0006-1 of TM 9-1095-213-13&P, the X26E must be stored with the DPM/XDPM inserted at all times. Otherwise, the X26E software can be damaged, which means the taser could fail. Please help spread the word.

LTC John Benson Chief, Law Enforcement Branch



Editor's note: Consider it done, Sir!



UNLESS YOU'VE CAREFULLY SECURED SIGHTS ON YOUR RIFLE OR MACHINE GUN...



...THEY CAN
WORK LOOSE FROM THE
MOUNTING RAIL AND...



...DISAPPEAR WHEN YOU'RE IN THE FIELD!






SSG ANDREW NEAL GAVE PS AN EXCELLENT WAY ON PAGES 38-39 IN PS 726 (MAY 13) TO MAKE SURE SIGHTS RETURN FROM THE FIELD.

> IT WAS SO GOOD, WE'RE REPEATING IT!


HERE'S WHAT YOU NEED:

- Wire rope,
- NSN 4010-01-151-6230 • Hex bolt.
- NSN 5305-00-576-6107
 Ring crimp,

NSN 5940-01-143-4794



PS 774 41 MAY 17




If your Avenger is to get it right, you've got to make sure the W103 cable for the environmental control unit/primary power unit (ECU/PPU) is tight. The W103 has a shielded ground. If the cable is loose, it arcs and starts a fire. The gunner could be cooked in the turret!


During before-operations PMCS, check **all** the cables between the ECU and PPU for looseness, but pay special attention to the W103.

Firmly grasp the W103's connector and try to turn it clockwise. If you can move it at all, your repairman needs to tighten it to 95-105 in-lbs. Even if you can't budge the W103, but suspect it might have problems, get your repairman to check it. Don't take chances!

Repairmen, remember that you're supposed to check the W103's torque every 250 hours of operation or semiannually, whichever comes first. This is spelled out in Table 2-1 in TM 9-1440-433-24-1 in IETM EM 0017 (Sep 13).

The W103 torquing procedure is in Para 19-31 in TM 9-1440-433-24-2 of the IETM. To properly torque the W103 connector on the bottom of the ECU, you must first remove the antenna bracket and the W101 and W102 cables.





Is Your CBRN Room All It Can Be? Checklist Can Help!



ESPECIALLY FOR JUST-OUT-OF SCHOOL CBRN SPECIALISTS, SETTING UP AND MAINTAINING A CBRN ROOM CAN SEEM OVERWHELMING.

FORTUNATELY,
THE CBRN STAFF
OF FT CARSON'S
4TH INFANTRY
DIVISION HAS
COME UP WITH
A PETAILED
CHECKLIST THAT
WORKS GREAT AS
A GUIDPELINE!



HERE ARE SOME OF THE CHECKS ON THE CHECKLIST:

- Does the unit have a tracking system that contains the following information: protective mask admin number, names, mask size, canister and facepiece lot number, date fitted and optical inserts requirement?
- Does the unit have a tracking system for each Soldier's JSLIST item and are sizes entered into DTMS?
- Is the unit conducting mask fit validation tests?
- Has the unit recon/survey team been identified and is it on orders signed by the unit commander?


IN ADDITION, THE CHECKLIST INCLUDES **ALL**

- ARsDA PAMs
- FMs
- TBs

NEEDED IN A CBRN ROOM. IT ALSO COVERS THE CBRN ROOM'S PHYSICAL ORGANIZATION, CBRN SOPS, NECESSARY TRAINING AND ACCOUNTABILITY.




IF YOU WOULD LIKE A COPY OF THE CHECKLIST, EMAIL PS: usarmu.redstone.logsa.mbx.psmaq@mail.mil




Dear Editor,

Your FRS will be fresh for action if you remember these rules we came up with at Ft Stewart:

Faithfully do the PMCS for the generator and the air compressor. If you don't start them up monthly and check them out, they eventually stop working or, in the case of the compressor, have trouble building up pressure.





Remember to check the crane's hydraulic fluid, too. Just a glance at the indicator will tell you if it's low.

Careful with the bay doors. They weight over

200 pounds, so you definitely don't want to try raising one by yourself. If you lose your grip, you could lose your head. So get help! Also keep your hands away from the doors' pinch points. Imagine 200 pounds pinching your hands!



During PMCS, it's a good idea to check the piano hinge screws at the top of the bay doors. If the screws fall out, the door could collapse. Tighten loose screws and report missing ones.

If piano hinge screws work loose, door can come falling down

In the field, park the FRS as level as possible. If it's at an angle, the doors can twist when you open them and get out of alignment. Then the doors won't shut properly. HEY, THIS ISN'T
GONNA WORK!
I NEED TO BE
LEVEL OR MY
DOORS WILL BE
DAMAGED.

CW2 Michael Johns
SPC Joseph Wesseldyk
Ft Stewart, GA



PEFINITELY A
ONE OTHER CHECK THAT CAN KEEP
FRESH TAKE ON
YOUR FRESH IS TO INCLUDE THE
SOLAR VENT IN YOUR WEEKLY PMCS.

Make sure solar vent works and is turned on



MAKE SURE IT'S **WORKING** AND ITS SWITCH IS **ON.** THE SOLAR VENT DRAWS AIR THROUGH THE TWO VENTS ON THE REAR WALL AND OUT THROUGH THE SOLAR VENT, WHICH HELPS **REDUCE** MOISTURE IN THE FRS.

PS 774 44 MAY 17



How to Fix HUB Expiration Date



Dear Editor,

The RT-1523G has a hold up battery (HUB) circuit card assembly (CCA) that needs to be replaced, unlike an E or F model SINCGARS that has a built-in HUB.

One issue is that the RT-1523G's HUB CCA is only rated to last 5-10 years, depending on the use of the RT. But once it expires and is replaced, the HUB installation and expiration date stay the same on the radio display.

There's a way to change the HUB installation date so the next field maintenance person doesn't mistakenly think that they have to replace the HUB again. It was quite a hunt for me to find out how, so I wanted to share what I found.

WP 0848 in TM 11-5820-890-13&P-5 (Aug 14) tells how to change the HUB installation date, which automatically changes the expiration date. But this info is buried in the TM on a troubleshooting flow chart. There's no other reference that I could find. It's not in the WP that tells how to replace the HUB CCA, where it should logically be included.


Also, your readers should know that the RT-1523G uses a different CCA extender card for testing. Its NSN is 5998-01-594-2230, but it's not included in the newest series of TMs dated August 2014.

SFC James Rowe IAARNG

Editor's note: Roger that, Sergeant! A great example of why input from Soldiers like you keeps PS invaluable. Also, it's a good reminder to everyone to submit a DA Form 2028 when you find critical info missing from or buried in a TM or you have suggestions for improvement!



Check for LOW POWER DEFECT



A NUMBER OF RT-1967(C)/U
TWO-CHANNEL MANPACK RADIO
RECEIVER-TRANSMITTERS (RT)
ARE HAVING PROBLEMS WITH A
SINCGARS LOW-POWER DEFECT
ON ONE OR TWO CHANNELS.

THAT
COULD
LEAVE YOU
WITH POOR
RANGE IN
THE FIELD.

RT-1967(C)/U IS USED IN THE FOLLOWING RADIO SETS:

- AN/PRC-155(V)2
- AN/VRC-116(V)1
- AN/VRC-117(V)2

BUT THANKFULLY THERE'S AN EASY WAY TO CHECK IF YOUR RT-1967(C)/U HAS THIS PROBLEM!

BEFORE A
MISSION, OR
ANY TIME
THERE IS A
NOTICEABLE
DROP IN
RANGE, DO
THIS ON EACH
CHANNEL:

- Launch a single-channel SINCGARS plain text or cypher test preset. Do not use frequency hop.
- Initiate a push-to-talk (PTT) of at least 30 seconds.
- Monitor the human-machine interface (HMI) for a continuous built-in test (CBIT) alert.
- If you see an exclamation icon in the alert/status area of the HMI, select the alert/status area of the HMI, and press the enter button to read messages.

CBIT alert indicates SINCGARS low power defect

Messages

Message 1

14-Nov-2016 21:08:36 CH1 CBIT Set

RC_BITALCTests ForwardPo

PRESS ENTER TO ACKNOWLEDGE\DELETE OR ESC TO EXIT

[60**>** ■ 1

21:08:44

IF YOU GET THE CBIT ALERT, YOUR RT HAS THE LOW POWER DEFECT.

IF YOU'RE ON A MISSION, OPERATE SINCGARS ON THE GOOD CHANNEL. IF THE DEFECT AFFECTS BOTH CHANNELS, YOUR RT IS NMC. IN EITHER CASE, GET YOUR RT FIXED ASAP.

FOR SUPPORT, GO TO https://tr.army.mil/tr/menu.cfm
AND CLICK <u>CAC LOGIN</u> AT THE TOP RIGHT, THEN CLICK THE SUPPORT TAB,
WHICH WILL GIVE A DROP-DOWN MENU. CLICK <u>SUPPORT HOME</u>.

Don't Forget AN/PSQ-20B!

DON'T FORGET ME! I'M ONE OF THE AN/PSQ-20S!



Dear Editor,

Thanks for the info on Page 50 in PS 766 (Sep 16) on how to get AN/PSQ-20 night vision goggles repaired for free.

But you missed one version of the goggles: AN/PSQ-20B, NSN 5855-01-603-0486. It's covered by TM 11-5855-336-10 and -23&P.

One other point: Soldiers need to be reminded **never** to use the batteries for their MILES equipment in the AN/PSQ-20. The batteries look alike, but the MILES batteries are twice the voltage and will burn out the goggles. Use **only** the 1.5V lithium battery, NSN 6135-01-333-6101.

Scott Taylor Small Arms Repairman Ft Benning, GA





THE AN/P6Q-20, NSN 5855-01-534-6449, IS COVERED BY TM 11-5855-322-10 AND -23&P.

THE AN/PGQ-20A, NSN 5855-01-603-0489, IS COVERED BY TM 11-5855-335-10 AND -23&P.

UNITS NEED TO MAKE A NOTE OF THE FREE REPAIR INFO ON PAGE 50 OF PS 766.

IT CAN SAVE THEM THE COST OF \$18.000 GOGGLES!

FIND THE ARTICLE AT https://www.logsa.army.mil/psmag/ archives/PS2016/766/766-50.pdf

ONE IMPORTANT NOTE: THE AN/P6Q-20B IS NOT COVERED BY THE FREE REPAIR! BUT THE OTHER VERSIONS ARE, THE -20B CAN BE REPAIRED BY THE 94F MAINTAINER.

Do MREs *Ever* Expire?







Dear Cloe,

What's the shelf life for meals, ready-to-eat (MREs)? Our unit has about 50 boxes and I need to figure out if they're still good. The boxes have been in storage about three years and kept well-ventilated at room temperature.

SGT M.L.

Dear Sergeant,

Good question. The Defense Logistics Agency's (DLA) Troop Support oversees military rations. DLA Troop Support has a webpage with MRE info here:


https://www.dla.mil/TroopSupport/Subsistence/ Operationalrations/RationsPrograms.aspx

As stated on the website, "The shelf life of the MRE is three (3) years at 80°F. However, the shelf life can be extended through the use of cold storage facilities prior to distribution."

So MREs don't have expiration dates, but rather inspection test dates (ITDs). If an MRE is nearing its ITD, contact your local Public Health Command food inspectors to see if the shelf life can be extended another six months.

Containerized Kitchen...

PROPER LUBE A PROBLEM SOLVER!



Dear Editor.

I've noticed that a lot of units are rushing past some of the Before PMCS on their containerized kitchens (CKs). I guess their thoughts are focused more toward what's cookin' later than on what's working right now!

I've seen CKs with their doors literally falling off for lack of lube on the hinges. Without proper and timely lubing, the hinges rust together at the pins. When the door is opened, the hinges peel apart.

Also, when the CK's floorwings are lowered, the tension isn't being removed from the cables by fully placing the weight of the floor on the jacks. That leads to cable fraying and undue stress on the winch assemblies as both equipment and the operator's weight is moved onto the floor space.



PS 774 50 MAY 17 PS 774 51 MAY 17

To decode the manufacturing and ITDs on your MRE boxes or packages, you may also find this commercial site helpful:

http://www.mreinfo.com/us/mre/mre-date-codes.html

You'll find an MRE date checker calculator on the lower left-hand side of the website.







In WP 0016 of TM 10-7360-226-13&P, the $\it Before\ PMCS$ tables tell the operator/maintainer to:

- Inspect exterior of container for obvious weld cracks, damage to door hinges, handles, or seals. Check doors for freedom of movement. Lubricate door hinges as necessary (WP 0051 00, Table 1, Item 6).
- Inspect jacks for damage, missing parts, and freedom of movement.
 Lubricate corner jacks as necessary
 (WP 0051 00, Table 1, Item 4).
- Inspect winches for missing or damaged hardware, and freedom of movement. If necessary, apply a light coat of grease to the gears (WP 0051 00, Table 1, Item 4).

Doing that Before operation PMCS will stop a lot of the problems we're seeing. Now to fix a little TM confusion. If you go to the expendable and durable items list in WP 0051 to look for the lube specified by the three PMCS items, you'll run into a little trouble.

For the door hinge lube, you're directed to use Item 6, silicone lubricant, NSN 6850-01-265-3115. That's wrong. The correct lube is engine lubricating oil, OEA HDO 15/40, NSN 9150-01-152-4117.

For both the corner jacks and winch gears, you're directed to use Item 4, pipe joint compound. Not a good idea! The correct lube to use is automotive grease, NSN 9150-01-197-7690.

David Merchant TACOM LAR Kuwait NEEP HELP WITH YOUR CK? CONTACT JOSEPH GONZALES AT PSN 256-6092, (508) 233-6092, OR EMAIL Joseph.k.gonzales2.civ@mail.mil



MTRCS... SLAP A PATCH ON OIL DRAIN LINE










Dear Editor.


We recently received two new multi-temperature refrigerated container systems (MTRCS) here at RTS-M Devens. We received both the MTRCSO1, NSN 8145-01-534-3597, and the MTRCSO2, NSN 8145-01-592-9018, and found the same problem on each of the systems.

The engine oil drain line is connected to the diesel engine's sump on one end and an oil drain valve on the other. The problem comes where the oil drain line passes through the MTRCS frame between the sump and valve. The tolerance there is very tight, so vibration during movement, transportation and operation allows the drain line to rub against the frame.



The front part of the frame is rounded and causes no problem. But the inside of the frame is another story. That edge is sharp and jagged and the drain lines on both of the new MTRCSs showed signs of wear. If this hose is cut, all the contents of the oil sump will drain and the engine could burn out.

Oil drain line rubs against edge of frame and creates damage that could cause leaks



Wrap drain line with

radiator hose for

protection

As a temporary fix, we wrapped the drain line with a piece of reinforced radiator hose and held it in place with wire ties, NSN 5975-00-984-6582. Then we periodically check the drain line to make sure the radiator hose is still in good shape.



IETMs
No Longer
Viewed
Online

EFFECTIVE 1 NOV 16, INTERACTIVE ELECTRONIC TECHNICAL MANUALS (IETMS) CAN NO LONGER BE VIEWED ON THE LOGSA ETM WEBSITE.

> HOWEVER, IETMS ARE STILL AVAILABLE FOR **DOWNLOADING** AT: https://www.logsa.army.mil/etms


QUESTIONS? CONTACT THE LOGGA ETM HELP DESK AT DON 645-0809, (256) 955-0809, TOLL FREE (800) 270-1408, OR BY EMAIL: USATMY.redstone.logsa.mbx.logetm@mail.mil

PS 774 54 MAY 17

LOGISTICS



How to Get Army Publications





YOUR ON-THE-JOB LEARNING CURVE PROBABLY SEEMS MIGHTY STEEP.



EVEN EXPERIENCED CLERKS FIND THAT THE ARMY'S FREQUENT PUBS CHANGES KEEP 'EM



IT'S NOT THAT BAD!



BEFORE YOU CAN ORDER PUBLICATIONS FOR YOUR UNIT, YOU MUST FIRST ESTABLISH AN ACCOUNT, HOW YOU ESTABLISH THAT ACCOUNT DEPENDS ON WHETHER YOUR UNIT IS IN CONUS OR OCONUS.



DEPLOYED
UNITS OR
THOSE GETTING
READY TO
DEPLOY
SHOULD GO
BY OCONUS
INSTRUCTIONS.

PS 774 56 MAY 17

FOLLOW THESE INSTRUCTIONS TO REQUEST AN ARMY PUBLICATIONS ACCOUNT:



AUTHORIZED ARMY UNITS THAT DON'T HAVE A PUBLICATIONS ACCOUNT CAN REQUIEST ONE BY SUBMITTING A DA FORM 12. GET THE FORM AT: https://ptclick.hqda.pentagon.mil/DA%20Form%2012.pdf

EMAIL THE COMPLETED FORM TO THE ARMY PUBLISHING DIRECTORATE'S MEDIA DISTRIBUTION DIVISION (MDD) AT:

usarmy.stlouis-mo.106-sig-bde.mbx.apdcustsrv@

INSTRUCTIONS FOR COMPLETING AND SUBMITTING THE DA FORM 12 ARE FOUND ON THE POINT AND CLICK ORDERING SYSTEM UNDER THE LOGIN MENU: https://btclick.hqda.pentagon.mil/index.aspx

IF YOU HAVE PROBLEMS WITH THE POINT AND CLICK ORDERING WEBSITE, CONTACT MDD CLISTOMER SERVICE AT DSN 693-9606, (314) 592-0910, OR EMAIL THEM AT THE ADDRESS ABOVE.

TO CHANGE YOUR UNIT'S MAILING ADDRESS OR OTHER ACCOUNT INFO, SEND AN UPDATED DA FORM 12 TO MDD CUSTOMER SERVICE AT THE SAME EMAIL.



OGO!US

Army Units in Europe, Africa, Middle East or Southwest Asia

ARMY UNITS THAT DON'T HAVE A PUBLICATIONS ACCOUNT MUST REQUEST AN ACCOUNT BY SUBMITTING DA FORM 12.

GET THE FORM AT:

https://ptclick.hqda.pentagon.mil/ DA%20Form%2012.pdf

COMPLETE AND EMAIL IT TO THE PUBLICATIONS AND RECORDS CENTER OF EXCELLENCE (P&R COE)
CUSTOMER SERVICE AT:

usarmy.sembach.imcom-europe.mbx.aepubs@mail.mil

INSTRUCTIONS FOR COMPLETING THE DA FORM 12


ARE ON THE AEPUBS WEBSITE AT:

http://www.eur.army.mil/aepubs/OrderPubs.html



THE P&R COE CUSTOMER SERVICE TEAM WILL VALIDATE YOUR ADDRESS INFORMATION AND FORWARD TO MDD FOR PROCESSING.

Mobile Apps Go the Extra MILES!







FORCE-ON-FORCE TRAINING MEANS USING THE MULTIPLE INTEGRATED LASER ENGAGEMENT SYSTEM (MILES).

BUT IF YOU HAVEN'T USED MILES FOR SOME TIME, WILL YOU REMEMBER EVERYTHING YOU NEED TO KNOW?

NO WORRIES!

THE ARMY PROGRAM EXECUTIVE OFFICE FOR SIMULATION TRAINING & INSTRUMENTATION (PEO STRI) HAS RECENTLY COMPLETED DEVELOPING THEIR MILES MOBILE APPS TO HELP YOU RECALL THE KNOWLEDGE AND SKILLS NEEDED ANYTIME. ANYWHERE.

SO GET YOUR APP NOW!



THA GI

THE UNRESTRICTED APPS CAN BE FOUND AT THE GOOGLE PLAY AND APPLE APP STORES, JUST ENTER THE NAME OF THE MILES PRODUCT IN THE SEARCH FIELD AND INSTALL IT ON YOUR DEVICE.

THE RESTRICTED APPS ARE ON THE TRADOC APP GATEWAY (TAG) AT: https://public.tag.army.mil

Unrestricted

- M1A2SEPV2 MILES XXI
- M2A2/M3A2 Bradley MILES XXI
- Anti-tank Guided Missile (ATGM) Stryker
- Infantry Carrier Vehicle (ICV) Stryker
- Individual Weapons System (IWS)
- TESS Instrumentation
- Homestation Instrumentation Training
 System (HITS)

Restricted

- M136 Anti-Tank 4 (AT-4)
- Bunker Defeat Munitions (BDM)
- M1A2SEPV2 Abrams Combat Vehicle Tactical Engagement Simulation System (CVTESS)
- M2A3/M3A3 Bradley CVTESS
- Stryker In-Bore Device
- Stryker Mobile Gun System (MGS) TESS
- Man-Portable Aircraft Survivability Trainer (MAST)/Weapons Effects Signature Simulator (WESS)
- Main Gun Signature Simulator (MGSS)
- MK-19 Simulation Player Unit (SPU)
- RPG-7
- Tactical Vehicle System (TVS)
- Universal Controlled Device/Micro Controller Device (UCD/MCD)
- Wireless Independent Target System (WITS)

QUESTIONS?
HERE'S WHAT
YOU DO!

CONTACT PEO STRI OR PM TRADE-LTS BY EMAIL AT: usarmu.orlando.peo-stri.list.trng-feedback@mail.mil

Checking Army Forms, Pubs Revisited

On Page 61 of PS 769 (Dec 16), we explained how to access DA Pam 25-30, Consolidated Index of Army Publications and Blank Forms, to verify if a publication or form is still active. Although that publication is no longer available, you can check the status of a pub by searching for it on APD's website:

http://armypubs.army.mil
Click on Search and then Search Active Pub/Form Content.

PS 774 58 MAY 17


Connie's POST SCRIPTS

NEED HELP WITH AIRCRAFT ARMAMENT?

The TACOM headshed is ready to help with any questions you might have about the TACOM managed portion of aircraft armament. Email your queries to the TACOM team at:

usarmy.detroit.tacom.mbx.ilsc-aircraft-armament@mail.mil

Avenger GEN 1 and 2 FLIRs Being Replaced by GEN 3



THE AVENGER'S GEN 1 AND 2 FLIRS
ARE GRADUALLY BEING REPLACED BY THE
GEN 3 FLIR, NON 5855-01-518-8691, BY
ATTRITION. EVENTUALLY, UNITS WILL NOT
BE ABLE TO GET GEN 1 AND 2 FLIRS
REPAIRED BECAUSE OF LACK OF PARTS
AND MUST ORDER THE GEN 3.

QUESTIONS? EMAIL THE CRUISE MISSILE DEFENSE PROJECT OFFICE (CMDS) AT:

usarmy.redstone.peo-ms.mbx. cmds-sustainment@mail.mil

M1074, M1075 PLS DDEC II Engine Upgrade

The DDEC II engine used in the base PLS is no longer supported. If your unit has an issue with an engine that needs to be upgraded to a DDEC III/IV, contact TACOM's PLS Team for help at:

usarmy.detroit.tacom.mbx.ilsc-PLS2@mail.mil

CAT CONSTRUCTION EQUIPMENT SERVICE KITS

PS gets a lot of questions from the field about service kits for the newer CAT construction equipment like the 120M grader, 621G scraper and D7R dozer. At present, no service kits are available. But we'll keep you posted. When the NSNs for those kits become available, you'll see them in PS.

M915A5 Rear Wheel Seal

Get a new rear wheel seal for your M915A5 tractor truck with NSN 5330-01-568-5883 (PN CR47691, CAGE 338X5). It replaces PN CM10008717 (Item 9 in Fig 138) and NSN 5330-01-117-1014 (Item 9 in Fig 139) from TM 9-2320-426-13&P in IETM EM 0308 (Aug 14).

D7R II Seat Knob Bolt

Need a new seat adjustment knob bolt for your D7R II dozer? *Don't* use NSN 5305-01-517-2222, which is shown as Item 94 in Fig 118 of TM 5-3805-293-24P (Feb 16). Not only is that bolt too long, but it also isn't threaded properly and doesn't include a roll pin hole. Order the right bolt with NSN 5306-01-659-5535 and make a note until the TM is updated.

ATLAS II Tech Manuals Updated

Attention operators! The ATLAS II forklift's manuals were recently updated. The update includes:


- TM 10-3930-677-10
- LO 10-3930-677-13
- TM 10-3930-677-23&P on IETM EM 0359
 Note that EM 0359 replaces the old EM 0296.

 Order the manuals from the Army Publishing Directorate at:

https://ptclick.hqda.pentagon.mil/index.aspx
Or download them from LOGSA's ETM website:
https://www.logsa.army.mil/etms/

Reactive armor Manuals

Need a manual for your Bradley or M1-series tank with reactive armor? Order TM 9-1375-217-14&P (Apr 12) for Bradleys with reactive armor tiles (BRAT) and reactive armor skirts (BRASS). If you have an M1-series tank with the tank urban survivability kit (TUSK), order TB 9-2350-264-12&P-1 (Aug 07, w/Ch2, Sep 09) for the M1A1 and TB 9-2350-388-12&P-1 (Aug 08, w/Ch 2, Aug 09) for the M1A2 SEP.



A1/A1P2 FMTVs, HIMARS K16 Relay

Got an A1/A1P2 FMTV or HIMARS with a Caterpillar 3126 or C7 engine? Listen up! The original K16 exhaust brake relay made by Tyco and used on PDM #4 is obsolete. If you use the replacement relay called for in the TMs, the K16 exhaust brake relay will malfunction. A new relay, NSN 5945-01-645-9112 (PN B120-7038), manufactured by Cooper Bussmann, **must be used** so the vehicle's exhaust brake system can work properly.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for the TB 43-PS-Series.

Would You Stake Your Life on the Condition of Your Equipment?

PS 774 60 MAY 17

STOP, PRIVATE MIX-A-LOT!



Mixed Recyclables can't be Recycled and Must be disposed of as Regulated waste. That costs your unit BIG BUCK5!