

UNCLASSIFIED

MSG DTG 151300Z DEC 21

FROM COMMANDER, AMCOM, REDSTONE ARSENAL, AL //AMAM-SFA//

**SUBJECT - AVIATION MAINTENANCE ACTION MESSAGE (AMAM),
INFORMATIONAL, TITAN TORQUE WRENCH, AGSE-22-AMAM-02**

NOTE

This message is issued per AR 750-6 to all Army Commands (ACOM), Army National Guard (ARNG), Army Service Component Commands (ASCC), and Direct Reporting Units (DRU). Commanders must retransmit this message to all subordinate organizations.

NOTE

A listing of all messages and any required reports, supplements, or addendums can be downloaded at: "<https://asmprd.redstone.army.mil>".

1. END ITEM / MISSION DESIGN SERIES (MDS) AFFECTED - All U.S. Army Aircraft Systems utilizing Aviation Ground Support Equipment.

2. SUMMARY -

2.1. Background - General Services Administration (GSA) previously issued a contract to Wright Tool Company who delivered a Titan manufactured Torque Wrench to the field. The U.S. Army Test, Measurement, and Diagnostic Equipment Activity (USATA) field activities concluded that reasonable calibration of $\pm 4\%$ accuracy is not achievable with the Titan torque wrench.

2.2. Message Purpose - Direct all units to identify affected Titan Manufactured Torque Wrenches (NSN: 5120-01-400-0232, PN: 23146) and discontinue use immediately.

2.2.1. Direct all units to replace Titan manufactured Torque Wrench with compliant Torque Wrench through GSA.

3. INITIAL TAMMS-A (THE ARMY MAINTENANCE MANAGEMENT SYSTEM - AVIATION) ENTRY - N/A.

4. SPECIAL PROVISIONS TO MESSAGE REQUIREMENTS - N/A.

NOTE

The maintenance actions in this message are not Department of the Army Directed Event (DADE) maintenance actions for reporting requirements.

5. MAINTENANCE APPLICATION - N/A.

6. ASSEMBLIES/COMPONENTS/PARTS -
Assemblies/Components/Parts to be affected -

CAGEC	WUC	NOMENCLATURE	PN	NSN
7NU33	N/A	Wrench, Torque	23146	5120-01-400-0232

7. SPECIAL TOOLS AND FIXTURES REQUIRED - N/A.

8. TECHNICAL PROCEDURES/INSTRUCTIONS -

8.1. Immediately upon receipt, Unit Commanders or their designated representative will ensure all applicable personnel are briefed on the contents of this message and the following requirements are completed.

8.2. Identify affected Titan Manufactured Torque Wrenches

(NSN: 5120-01-400-0232, PN: 23146) and **DISCONTINUE USE IMMEDIATELY.**

8.3. Units will dispose of the Titan Manufactured Torque Wrenches per the guidance in paragraph 10.

8.4. Units may acquire compliant replacement Torque Wrenches per the guidance in paragraph 10.

9. PROCEDURES/INSTRUCTIONS FOR ASSEMBLIES/COMPONENTS/PARTS IN WORK OR IN STOCK (AT ALL LEVELS INCLUDING WAR RESERVES) - N/A.

10. SUPPLY/PARTS (REQUISITION/DISPOSITION) -

10.1. Parts Required –

NOMENCLATURE	PN	NSN	QTY	COST EA \$\$	TOTAL \$\$
Wrench, Torque	J6062 / J6062C	5120-01-400-0232	1	\$86.75	\$86.75

10.2. Bulk and Consumable Materials - N/A.

10.3. Replacement Instructions -

10.3.1. For a replacement, contact GSA at the following email: fssi.mro-req@gsa.gov

10.3.2. The subject line of your email should read, "5120-01-400-0232, Torque Wrench Replacement".

10.3.3. In the body of your email, please cite the requisition number(s) associated with your original order(s), as well as the required quantity for replacement (i.e., 2 EA).

10.3.4. If you do not have or are not sure of your requisition number(s), please provide your DODAAC(s).

10.3.5. The vendor Wright Tool will provide you with a new Proto J6062 or J6062C at no cost using the most efficient method(s) available based on the current situation of the customer.

10.3.6. Please be advised that due to supply chain issues, there are currently a limited number of the Proto J6062 or J6062C Wrenches available. For some customers, your replacement order may be on backorder for an undetermined period of time. GSA and/or the vendor will communicate backorder status to customers.

10.3.7. If additional alternate part numbers are found in the commercial marketplace that can be verified by both GSA and Army to be in compliance with NSN: 5120-01-400-0232, those options will be presented to customers as they become available.

10.3.8. GSA will only issue replacements to customers who ordered the Titan Wrench under NSN: 5120-01-400-0232.

10.4. Disposition of Discrepant Parts/Components – Tag discrepant Torque Wrench with DD Form 1577 Unserviceable (Condemned) Tag-Materiel and dispose through normal supply channels.

10.5. Disposition of Hazardous Material - N/A.

11. COMPLIANCE REPORTING REQUIREMENTS - N/A.

12. PUBLICATION REQUIREMENTS -

12.1. References -

12.1.1. AR 750-6.

12.1.2. AR 702-7-1

12.1.3 DA PAM 738-751

12.2. Publication Changes - N/A.

13. POINTS OF CONTACT -

13.1. Technical POCs -

13.1.1. Primary – Timothy Aultman, DSN 897-3617 or 256-313-3617.

Email: "timothy.a.aultman.civ@army.mil".

13.1.2. Alternate – Jacob Bussey, DSN 8978-3713 or 256-313-3713.

Email: "jacob.r.bussey@army.mil".

13.2. Project/Product Manager (PM) Office POCs -

13.2.1. Primary – Samuel Lamb, 256-955-0837.

Email: "samuel.e.lamb2.civ@army.mil".

13.3. AMCOM Safety POCs -

13.3.1. Safety (Primary) - Mr. Damon Beck, DSN 897-2871 or 256-313-2871.

Email: "damon.c.beck.civ@army.mil".

13.3.2. Alternate - Ms. Kacey Tyra, DSN 897-2095 or 256-313-2095.

Email: "kacey.m.tyra.civ@army.mil".