

 Clearly mark designated smoking areas and strictly enforce rules in nosmoking areas. Prominently display "NO SMOKING WITHIN 50 FEET" signs near flammable items or hazardous areas.

• Keep all lifting devices (jacks, jack stands, hoists, cranes) properly maintained and in usable condition. Do regular inspections by the TMs.




• Use lubrication pits for servicing military vehicles only. Keep pits well-ventilated and illuminated. Place steel fences around pits when vehicles are not being serviced.



• Only trained and authorized personnel wearing appropriate personal protective equipment (PPE) should handle Chemical Agent Resistant Coating (CARC) paint. Painting areas must be covered and protected from debris.



- Store and secure gas cylinders to walls or fixed surfaces to prevent them from tipping, falling or rolling.
- Stencil maximum load capacity on both sides of support assemblies for overhead cranes and hoist assemblies. Be sure they are readily visible.
- Close off the battery shop from the general maintenance area. Make sure the shop is clearly marked.



- Store battery packs away from other metal objects.
- Operate power tools away from explosives, flammable liquids, gases, or dust. Power tools create sparks that may ignite dust or fumes.





• Remember, only fully trained and qualified licensed personnel are authorized to weld. Use an exhaust system when welding.



 Ensure serviceable PPE is available and used by all personnel.



P.S ENC