
START
1. Press Tablet BRT+ button several times.
2. Cycle NVIS/Blackout button to ensure not in NVIS mode.
Is touchscreen illuminated?
Yes
EXIT
No
Shut down Tablet IAW WP 0011. NOTE: If unable to complete proper shutdown, press and hold Tablet Power button until Power LED is no longer illuminated.
Verify/connect Universal Power Adapter to W1M Cable P4 and external AC power source.
Verify/connect W1M P3 to Tablet J1.
Start up Tablet IAW WP 0007.
Is touchscreen illuminated?
Yes
EXIT
No
Contact Signal/ Comm Maintenance.