

PS Magazine Index No. 70, 2014

Subject	Issue/Pg	Subject	Issue/Pg
AIR CONDITIONERS		Anti-collision light damaged by blades	737 23
60K-BTU IECU--Cover, storage bag	737 45	M230--Barrel, remove for cleaning	738 26
60K-BTU IECU--Replaces FDECU	743 61	Microclimate cooling system (MCS) parts	740 24
60K-BTU IECU--Storage of components	738 48	Work platform access door inspection	741 25
AIRCRAFT ARMAMENT SUBSYSTEMS		AIRCRAFT, OH-58D, KIOWA	
M230--Cleaning, lubing, sideloader, hydraulics	737 25	Blade tie-down wand assembly fix	739 25
M230--Sideloader, cannon plug, lock wires...	742 24	Ground handling wheel pickup point	734 25
AIRCRAFT, GENERAL		Ground handling wheel safety	741 24
DA-authenticated TMs only	745 26	Ground wheel NSN	737 60
Electrical system circuit breaker lockout	743 23	M3P--Seating extractor	739 23
Fire extinguisher use, number needed	735 22	Mast-mounted sight servicing	739 24
FMs being converted to TMs	737 61	Weapon systems cable connections	739 26
Forms, TMs, FCC, signal data converters...	744 18	AIRCRAFT, UAV	
Hand signal posters for download	735 28	Shadow--TM & logbook, keep up-to-date	734 26
Hand Signals Make All the Difference	735 26	AIRCRAFT, UH-60, BLACK HAWK	
JTDI vs CAPS	745 23	Electrical control panel replaces legacy parts	743 60
Pitot tubes, use covers but without heater	744 11	ESSS wing hookup electrical lead	742 61
PQDRs now go through PDREP	744 12	Flight control computer turn-in	735 23
Sheet metal stripped screw removal	744 16	MEDEVAC portal, MilSuite access	735 21
Sling loading operations clarified (731-41)	737 22	Microclimate cooling system (MCS) parts	740 24
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		Shaft assy fan and drive needed for turn-in	737 24
AGPU--D/E model NSN update	740 23	Signal converters needed for turn-in	740 61
DAWS--Conversion to 3-scale DAWS	741 23	Static line anchoring device for parachuting	736 22
Nitrogen generation and servicing equipment	744 13	Transmission oil filter sleeve check	740 26
Non-standard item TMs	735 25	TS-3920C/ASM CTS calibration	742 60
PM AGSE help desk	741 61	Windshield wiper assembly	741 61
Primer for CARC paint now aerosol	734 22	AMMUNITION	
SATS--Unexpected movement permanent fix	736 24	AMMO Help website	743 60
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		Ammo placards for vehicles	745 42
ASEK--Knife placement	736 20	ANTENNA, AS-1729, AS-1730	
MCU--Turn-in help	743 26	Matching unit ground	742 48
One-man life raft air hose fitting	742 60	AOAP	
SKRAM--Contents, number needed	735 24	LIW app, supplies	743 56
AIRCRAFT TOOLS		ARMORED COMBAT EARTHMOVER, M9	
Sewing machine parts	736 61	Cutting edge, blade folding, hydraulics check	742 18
Sheet metal stripped screw removal	744 16	Ejector hydraulic cylinder rod, not a step	736 18
AIRCRAFT, AH-64, APACHE		Hydraulic line clamp	736 19
Collective servocylinder bellcrank assy bracket	744 23	Hydraulic line, fluid level check	743 19
M230--Worm gear installation	739 22	Rear step, starter master relay, exhaust hose	735 18
M261--Contact, tube cleaning	745 25	ARMORED SECURITY VEHICLE, M1117	
Main rotor blade wedges demand	736 61	Transmission pan filter, not a field-level fix	741 08
Unserviceable component list for turn-in	744 22	ARTILLERY EQUIPMENT	
Water pooling after washing	741 26	DA Form 2408-4, who is responsible?	744 38
AIRCRAFT, CH-47D/F, CHINOOK		AVLB, M60/M48	
Aft rotor pylon step (ARPS) plans	738 22	O-ring NSN change	735 04

Subject	Issue/Pg	Subject	Issue/Pg
AVLB, M104 WOLVERINE		CARRIER, AMMO, M992A2	
Battery retainer modification	741 06	Cooling fan screens for maintenance	744 36
Recuperator, reduction gear box leaks	740 02	CARRIER, COMMAND POST, M1068-SERIES	
AWARDS		M1068A3--Hour meter location for APU	744 25
2013 DOD Maintenance Awards	738 61	CARRIER, PERSONNEL, M113 FOV	
2014 AAME nomination packets due soon	743 59	Battery maintenance	744 26
2014 CLEA awards announced	744 53	Hull rust prevention	738 04
BACK COVER		Idler wheel lubing	743 06
CLP vs LSA and LAW	737 62	Stowage seat kit	741 09
Don't Let Ladders Be Your Downfall	744 62	CBRN EQUIPMENT	
First Line of Defense Against FOD Is You!	741 62	CBRN information resource center	737 44
Job Isn't Finished Until Clean Up Is Done	742 62	Collective Protection Equip--HORN OFF button	734 42
Make PM a Priority Now	736 62	JACKS for CBRN questions	743 44
Santa Not Only One with Heavy Load	745 62	JBPDS--Generator insulation, exhaust hose...	739 42
Save Your Sight...Use Combat Eyewear	739 62	JCAD--M42 alarm needed	738 44
Take Spare Barrels to the Field and Use Them	743 62	M41 PATS--Reagent grade alcohol only	740 41
Take Time to Check for Loose Nuts	740 62	M41 PATS--Shipping do's and don'ts	745 45
UTAP: One-Stop Shop for Training Material	738 62	CLOTHING	
Wake Up! Carbon Monoxide Dangers	734 62	Army combat shirt ordering info	745 52
BATTERY, HAWKER		Barbed wire handler's gloves	738 60
Tricking dead batteries back to life	742 12	Soutache braid stored in ACU pocket	739 60
BATTERY, LEAD-ACID		Winter clothing articles	734 58
Battery acid NSNs	741 61	COMMERCIAL CONSTRUCTION EQUIP (CCE)	
Battery acid NSN	743 49	Service kit NSNs	742 14
Battery box coating compound	745 61	Tire tread direction, follow arrow	741 18
Electrolyte NSNs	744 60	COMPACTOR, 815F	
Solar charger info, NSN	738 10	Engine accessory belt with A/C NSN	741 60
VRLA--Charging, test equipment	734 12	Engine oil hot and cold check	745 19
BODY ARMOR		COMPUTERS & SOFTWARE	
Improved outer tactical vest PM	743 27	EMS-2--Sunsets with Windows XP	744 59
BRIDGE BOAT, TWIN-JET		EMS NG--Newsletter available	741 59
MK2--CPS code in parts TM	735 20	EMS NG--Suspending troubleshooting	741 58
CABLES, COMMUNICATION		MSD software downloading	739 52
Fiber optic cable PM	743 50	MSD-V3--Software upgrade needed	740 60
CAN, FUEL		COMSEC EQUIPMENT	
Water can differences	744 50	CCI--Software upgrades online	738 45
CAN, WATER		Fill cable needed for connecting equipment	734 54
Fuel can differences	744 50	NET team training	742 51
CARBINE, M4-SERIES		CONTAINER HANDLER, RT (RTCH)	
Be your own inspector	737 38	Fuel/water separator draining	745 21
General PM tips	738 27	Starter, don't engage for more than 30 seconds	734 13
Improved cleaning kit components	740 36	CONTINUITY	
M4 converting to M4A1	741 60	Battle for PM	739 27
Rail bracket, grip NSN changes	738 44	Dr. Drill Show	736 27
Selector switch installed by 91F	744 41	Forgotten Mission of NoSurprise	737 27
		Hand Signals Make All the Difference	735 26

Subject	Issue/Pg	Subject	Issue/Pg
How the Vest Was Won, Part 1	741 27	FORWARD REPAIR SYSTEM, M7	
How the Vest Was Won, Part 2	742 27	Low coolant sensor, harness for Tier III engine	737 61
Knight to Castle 4	745 27	Retrofit free through 14 Jul 14	739 61
M1-series tank air induction system PM	744 27	GENERATORS, SMALL	
PM Is Start of Beautiful Friendship (M16/M4)	738 27	3-kW, 5-kW--Engine oil, fuel, and heat PMCS	739 46
PM Needs a Lot of Thought	740 27	10-kW AMMP5--Overspeed shutdown fault	743 48
Therapy for the Improved Outer Tactical Vest	743 27	GRADERS	
CRANES		130G--Exhaust pipe positioning for transport	741 18
Hand signal posters for download	735 28	130G--Hydraulic unloading valve use	742 20
Hand Signals Make All the Difference	735 26	130G--Turbocharger coupling leak fix	737 20
DECON		GRENADE LAUNCHER, M203	
M12--Corrosion, heater, communications	740 42	Turn-in instructions	745 40
EDITORIAL		GUN, MACHINE	
From GPS to PMCS	745 01	M2/A1--M205 lightweight tripod available	742 43
If TM Says Do It, Do It!	735 01	M2A1--Barrel cover fits w/o flash suppressor	741 42
Key Point to Remember	744 01	M2A1--Barrel, securing properly	742 42
Lose the Rabbit Habit	736 01	M2A1--Barrel support removal tool nonexistent	741 43
Maintenance Takes Time	743 01	M2A1--BFA installation different from M2	744 43
Moment for Mechanics	734 01	M2A1--LBS needed for boresighting	736 39
PS: Free but Priceless	737 01	M2A1--Sluggish firing cure	743 39
CSM Chance: Are You Ready for GCSS-A?	741 01	M3P--Seating extractor	739 23
Report the Problem Gauge!	742 01	M3P--Seating extractor correction (739-23)	744 61
Study Warnings Ahead of Time	738 01	M203 Tripod--Pinch hazard warning	735 38
What Can You Do in 15 Minutes?	740 01	M230--Barrel, remove for cleaning	738 26
Your Best Insurance	739 01	M230--Cleaning, lubing, sideloader, hydraulics	737 25
EXCAVATOR, HYEX		M230--Worm gear installation	739 22
230--Starters, two types to choose from	742 21	M240--DA 2028 submission for TM mistakes	738 43
230, 330--Fuel/water separator draining	745 20	M240C--Securing pin suggestion	738 05
Lubricity filter change interval	742 61	M240H--Bipod assembly parts changes	739 36
Warmup, cool down, engine oil and dipstick	738 20	M240H--Bipods available for free issue	743 60
FIRE SUPPORT VEHICLES		M240L--M26 BFA for short barrel	741 36
M1200--Transmission pan filter, not field-level	741 08	M240L--M26 BFA for short barrel after MWO	743 43
FORKLIFTS		M240L--Pistol grip, check for looseness	741 43
6K--Battery retaining strap NSN	742 61	M240L--Safety spring, replace when removed	739 36
6K--Fuel shutoff solenoid for 165-hp engine	743 21	M240-Series--Ejection port cover reassembly	744 42
6K, ATLAS--Axle lubrication	734 18	M240-Series--MWOs extended, renumbered	742 40
6K, ATLAS--Fork extensions not allowed	739 61	M240-Series--Op rod pin loose	739 44
6K, ATLAS--Fork extensions not allowed	743 20	M249--AR vs LMG differences	743 40
ATLAS II--Starter NSN	744 60	M242--Barrel, only one now available	738 05
Hand signal posters for download	735 28	M249--BFA differences	738 42
Hand Signals Make All the Difference	735 26	M249--Buttstock MWO	742 41
FORMS, GENERAL		M249--Extractor kits with bad springs	743 60
DA Form 2404--Pencil vs ink	737 54	M249--Extractor kits with bad springs	745 40
PDF fillable forms	738 60	M249--Pistol grip changed	735 38
FORMS, SUPPLY		M249--Welded op rod, check for cracks	736 41
DA Form 1300-4--Make multiple copies	741 56	MK 19--COE1 items missing from TM	737 41
		MK 19--M205 lightweight tripod available	742 43

Subject	Issue/Pg	Subject	Issue/Pg
MK 19--Model differences	739 40	XCK2000/E1--Crank handle NSN	737 60
MK 19--Runaway, lower both charging handles	737 42	LASER RANGEFINDER	
MK 19--Sear, feed slide SMR code changes	741 41	AN/PED-5--Input/output (I/O) cable damage	741 39
HARDWARE		LAUNDRY ADVANCED SYSTEM (LADS)	
DILNet for hardware searches	739 53	Doors closed to keep out dirt, dust	737 51
Sealant for moisture seepage	736 60	Drain water before cold weather hits	744 48
Zipper lube NSN	740 61	LOADER, BACKHOE (BHL)	
HAZARDOUS MATERIALS & WASTE (HAZMAT)		HMEE-1--BII/COEI charts updated	741 20
nPB limit in solvents changed	740 61	HMEE-1--Warm-up/cool-down, battery switch...	740 18
HEATER, PERSONNEL		Roof pad NSN correction (729-21)	739 60
A-20--Control panel tips	737 05	Secondary air filter NSN	742 60
HEATER, SPACE		UTAP maintenance video	742 60
Convective--Battery pack recharging	741 50	LOADER, SCOOP-TYPE	
HELMETS, AVIATION		966H--Battery disconnect, hood tilt, engine oil...	734 14
HGU-56/P--CEP disconnect, PM tips	743 25	966H--Bucket lubing	736 16
HGU-56/P--Helmet sizes, NSNs	741 22	H100C--Alternator NSNs	737 21
HELMETS, GROUND		MW24C--Rotary dimmer switch NSN	734 19
Night vision mount	744 47	LOADER, SKID-STEER, BOBCAT	
HOWITZER, GENERAL		M400T/W--Door assembly NSN	739 60
Cannon cleaning for borescope inspection	722 08	M400W--Solid tire NSN	734 19
TM 9-1000-202-14 sections for borescoping	736 40	M400W--Solid rubber tire NSNs	734 20
HOWITZER, SP, M109-SERIES		LOGISTICS ASSISTANCE	
Cooling fan searches for maintenance	744 36	SAMS-E help desk support	734 61
HOWITZER, SP, M109A6 PALADIN		TACOM LAR, how to find	734 48
Bore evacuator O-ring swelling	736 02	LOGISTICS MANAGEMENT	
Idler arm lubing	744 35	EPIC policy search tool	744 56
MCS exercise, water draining	741 05	GCSS-Army data cleanup	743 53
HOWITZER, TOWED, M119-SERIES		GCSS-Army EXORD 001-14 released	734 60
A3--APUBS vacuum release valve	737 06	GCSS-Army glossary	742 61
A3--FCC touch screen cracking	741 03	GCSS-Army SASMO training	734 60
Bore cleaning air tool kit	745 03	GCSS-Army training, milSuite forums	736 57
Wheel assembly upgraded with stem guard	742 08	GCSS-Army Wave 2 transition prep	744 58
HOWITZER, TOWED, M777A2		GCSS-Army website reminder	745 61
Belly pan quick-release pin lubing	740 07	GCSS-Army worldwide program update	737 60
Breech pivot pin/roller lubing	740 08	LIW training	738 54
DFCS CLE cable pinching	737 07	SAMS-E developer on milSuite	740 61
Website for manuals, training, software, etc.	736 03	SAMS-E info on AKO	736 61
INTERNET		WebFLIS	736 56
Army Enterprise Service Desk (AESD)	738 57	MAINTENANCE MANAGEMENT	
milSuite websites	739 54	10% variance on maintenance services	736 52
Portals, forums may not be official	738 58	COEI, BII, AAL turn-in requirements	739 56
KITCHEN EQUIPMENT		Deferred maintenance tracking	740 58
MBU--Dust prevention	736 48	Manufactured tool limits	742 56
MBU--Pack extra filters for deployment	734 61	Shop stock, when allowed	737 55
MBU--V3 upgrade for adjustable heat output	736 46	MAINTENANCE, GENERAL	
MTRCS--Hook arm pin damage	745 48	FMSWeb	740 22
		LOGSA maintenance/readiness mailboxes	738 61

Subject	Issue/Pg	Subject	Issue/Pg
Oshkosh equipment warranty claims	744 60	AN/PVS-7B, -7D, -14--Batteries, caps, data label	745 50
MASK, PROTECTIVE		AN/PVS-14--Helmet mount hardware change	738 50
M40, M42--Be Your Own Inspector	742 44	AN/PVS-14--Retaining ring loose	741 40
M40, M42--Fitting solutions	745 44	Helmet mount, order the latest	744 47
M40-Series--M40 can't covert to M40A1	741 35	PISTOLS	
M52--Nose cup flap sticking	740 44	M9--Holster NSNs	736 38
MINE CLEARING EQUIPMENT		M9--Holsters, new NSNs added	742 39
Husky--Cab ledge step, detection heads	736 15	POL	
Husky--Dust cap, air filter cleaning	738 18	PS MAGAZINE	
Husky--Fuel/water separator draining	736 14	Back issue requests	736 59
Husky--Shock absorber bracket loose	736 12	How to order	734 50
Husky III--CTIS control unit NSN	741 60	Issues too large to email	738 61
MISSILE, AVENGER		PS: Free but Pricelless	737 01
Contact, non-skid strips, no step, climbing...	736 42	Radionerds website for back issues	742 61
Primary power unit PM tips	737 35	Search engine instructions	741 53
W87 cable, canopy, azimuth brake, FLIR...	737 36	Unit-maintained equipment covered by PS	737 59
MISSILE, HIMARS		Winter clothing articles	734 58
Biannual/biennial definition (734-46)	742 46	PUBLICATIONS	
Cab spanner nuts, cab lock, wash rack, batteries	745 36	AR 750-1 released	734 49
Shock absorber mandatory replacement parts	734 46	AR 750-10 revised	736 55
MISSILE, PATRIOT		AR 750-43 revised	742 57
AMG--Feed horn plugs, pneumatic pump covers	734 43	AR 750-59 revised	741 61
Filters, GPS cable, DLTM doors, antenna puller...	734 44	Aviation FMs being converted to TMs	737 61
SSS--Keypad temp, straps for travel	739 35	Bring pubs back from deployment	738 51
MISSILES, GENERAL		DA Pam 25-30 for pubs availability	742 61
PQDRs now go through PDREP	744 12	DA Pam 385-1 revised	736 59
MLRS		DA Pam 385-11 released	736 59
Cab, launcher safety	742 06	DA Pam 385-63 revised	741 60
Dash lights, hoist carriage assy, prop shaft bolts...	742 36	DA Pam 738-751 revised	742 23
Desiccant panels, cable security, limit switches...	743 36	DA Pam 750-1 revision adds CMDP	738 57
Heater cleaning, fuse replacement	743 03	DA Pam 750-3 revised	738 57
Water cleaning precautions	737 02	DA Pam 750-43 revised	739 61
MORTARS		EMS NG viewer printing	742 53
DA Form 2408-4, who is responsible?	744 38	EOPDB for pubs list	734 47
M120, M121--Store legs before travel	734 42	FM 3-20.21 helps with Bradley gunnery	743 05
M120, M121--Store legs correction (734-42)	741 39	Official manuals only for maintenance	737 52
M224/A1--Handle, firing mechanism torque	741 38	Ordering Army publications	734 50
Paint only for alignment lines	737 40	Publications status tracker	744 61
Sight protection during baseplate settling	745 41	Winter publications	734 58
TM 9-1000-202-14 sections for borescoping	736 40	RADIO SET, SINCGARS	
MOUNT, WEAPONS		Radio frequency cable damage	737 46
M66--Parts info	738 41	REELING EQUIPMENT	
M153 CROWS II--Components remain	736 41	MARS reels lighter, stronger	738 46
M153 CROWS II--Travel locks	739 45	RIFLE, M16-SERIES	
NIGHT VISION EQUIPMENT		Be your own inspector	737 38
AN/PVS-6, -7, -14--Image intensifier tube	740 46	General PM tips	738 27
		Improved cleaning kit components	740 36

Subject	Issue/Pg	Subject	Issue/Pg
Rail bracket, grip NSN changes	738 44	Accounting for nonexpendible COEI	742 58
Selector switch installed by 91F	744 41	Component protection in storage	740 52
Sight post, square vs. round	739 41	Estimated ship date tools on LIW	739 58
RIFLE, SNIPER		FED LOG help for ordering parts	738 52
M107--XM107 conversion info	737 42	PBUSE AIT quick setup guides	743 54
M107--XM107 now converted	734 60	Shelf-life information	745 54
M110 SASS--Bolt repair part NSNs	745 38	Supply discrepancy reports	745 58
M110 SASS--Day sight dust covers	739 39	WebFLIS changes coming	738 60
M110 SASS--Trigger assembly POC	737 42	SURVEILLANCE SYSTEMS	
M110 SASS--Trigger assembly replaced?	734 60	BETSS-C--Generator PM	739 46
M2010--Components for turn-in with rifle	739 38	TANK, M1-SERIES	
ROBOTS, GROUND		Air induction system PM	744 27
310 SUGV Mini-EOD--Weight, track check	740 20	Battery retainer modification	741 06
EOD robot parts ordering system	744 60	Breech crank assembly bolts missing	745 07
XM1216 SUGV--Power button warning	734 21	Breech inspection, cleaning, servicing	734 04
ROCKET LAUNCHER		Bustle rack cargo net, extension	735 02
M260, M261--Cleaning, PMCS, loading tool...	734 40	Cleaning inside and outside of tank	738 08
SAFETY		DA Form 2408-4, who is responsible?	744 38
Fire prevention	737 56	DSESTS--M934 truck still prime mover	734 06
Hand signal posters for download	735 28	Gun card, keep updated	737 04
Hand Signals Make All the Difference	735 26	M1A1--M19 particulate filter replacement	734 05
Heat injury prevention, Part 1	740 50	M18A1 filter canister caution	742 07
Heat injury prevention, Part 2	741 46	Recuperator, reduction gear box leaks	740 02
MSDS at DLA's HMIRS website	737 61	Replenisher level, recoil system bleeding	745 08
SCRAPER, EARTHMOVER, 621B		Transmission oil filler neck needs funnel	743 07
Guide roller lubing	736 17	Turret lifting device bolts, mount assembly	739 08
Starter NSN	745 61	Turret screens not for hanging gear	739 07
SIGHTS & SCOPES		TENTS	
AN/PSQ-23/A--Heater, turn off	734 39	Zipper lube NSN	740 61
Batteries no longer included with new items	744 44	TEST EQUIPMENT	
M151--Night vision goggle addition	745 39	DSESTS--M934 truck still prime mover	734 06
SLEEPING BAG		MSD software downloading	739 52
Replacement parts, NSNs	737 48	STE-M1/FVS--Bradleys with ED	742 60
SMALL ARMS		TS-3920C/ASM CTS calibration	742 60
Armorer no longer weapons maintainer	738 43	TIRES	
Bubble wrap no good for long trips	740 35	CCE tire tread direction, follow arrow	741 18
CCMCK gage needs no calibration	743 42	DOT code determines shelf life	735 12
Clearing rod, how to make	734 38	General PM	740 14
CLP vs LSA and LAW	737 62	Retreads not allowed on some vehicles	738 14
COMET: TMs, tool protection, jack stands...	736 35	Safety tips	738 12
DA 2407-E, bolts, barrels, transport, CCMCK...	738 38	Tire chain use, NSNs	734 07
Lubes and weapons they're used on	741 44	TOOLS	
Packing for safe travel	734 36	Accountability checklist	740 38
PQDR submission website	734 35	Common #1, #2 replaced by SATS?	745 43
Safety wire, one loop or more?	739 39	SATS--Corrosion, generator door, travel prep...	738 35
SUPPLY, GENERAL		SATS--Door handle NSN change	739 60
		SATS--Tool drawer layout	742 46

Subject	Issue/Pg	Subject	Issue/Pg
Torque wrench, zero out to maintain accuracy	745 43	LED headlight NSN	741 61
TRACTOR, D7E/F/G/R		M1151--Tarp for gunner's turret	737 17
Rear winch cable fix	737 18	Self-locking nut NSN change	741 60
TRAILERS		Snow plow kit	744 03
Brake air coupling identification	739 21	Up-armored--Door NMC criteria updated	736 06
M1076--Interface kit components explained	745 12	Up-armored--Windshield deicer shorting	736 04
M1077--Stowage box repair, replacement	735 08	TRUCK, 5-TON, M939-SERIES	
M1101, M1102--Adjustable lunette	738 17	M939/A1/A2-Series--Starter assembly NSN	745 61
M1112--Hand brake repair parts NSNs	741 14	M939A2-Series--Alternator change for Hawkers	743 15
M1112--Hand brake repair correction (741-14)	743 61	TRUCK, FMTV	
TRAILERS, SEMI		Batteries, don't mix Hawkers with wet cell	744 06
Linseed oil to protect wood decks	740 19	Battery tray retainer missing corrosion coating	742 11
M129A3/A4--Data plate model identification	741 16	Bogie O-ring NSN	736 60
M870/A1--Wood decking replacment	735 09	Brake air tanks, drain after operation	735 06
M870/A1--Wood deck correction (735-9)	743 61	Brake spider NSN	739 60
M870A1--Wood decking kit	740 19	Cab support tool use, NSN	735 05
M872A4--Bumper pin NSN replacement	741 60	Cargo cover kits, components	739 10
M969A3--Radar fuel level sensor NSN	738 61	Cargo cover repair	741 12
M1000--Ramp chain restraint shap hook	743 17	GRS for soft shell cabs	744 09
TRAINING		Interconnecting box NSN change	737 60
Driver's check ride explanation	739 57	LTAS--CTIS switch bypass cable unplugged	745 11
LIW training	738 54	LTAS--M66 ring mount parts	740 10
NET team training	742 51	LTAS -A1P2--Auxiliary starter relay bracket	744 08
SASMO DCO training session	737 60	LTAS -A1P2--Cab door damper NSN	745
Transportation basic freight traffic course	736 58	M1081--Cargo bed D-rings, clean and lube	738 15
UTAP for recovery vehicle info	734 15	M1083--Tailgate bumper damage	744 07
UTAP newsletter covers legacy equipment	742 60	M1083/A1P2--M66 mounting instructions	744 09
UTAP: One-Stop Shop for Training Material	738 62	M1083A1P2--Passenger-side door window	737 60
TRANSPORTATION		M1089A1--Wrecker load test faults	735 07
Basic freight traffic course	736 58	Oil pressure gauge check	736 10
CDDP launched	738 56	Safety mirrors	735 08
TRUCK, M915-SERIES		TRUCK, HEMTT	
M915-Series--Tire size differences	743 16	A4 Models--Hydraulic enable switch to OFF	737 14
M916A3--Gladhand/plug holder NSN	738 60	A4 Models--Hydraulic filter O-rings	737 14
M917A1--Air dryer NSN	738 60	A4 Models--Steering gear replaced	738 16
TRUCK, M1070 HET		A4 Models--Temperature sensor O-rings	736 61
A0/A1--Wheel hub assembly seal	739 60	A4 Models--Universal service kit NSN	734 60
Heated LED headlight NSN	736 60	A4 Models--Wiring harnesses over manifold	737 15
Transfer case rotary pump NSN	744 60	Heated LED headlight NSN	736 60
TRUCK, 1 1/4-TON, HMMWV		LED headlight NSN	744 60
Cdr's seat, don't remove bolts to recline	744 05	M978A4--Hydraulic pump assembly warranty	737 16
Door latch lubing	738 12	M978A4--V1 emergency valve MC bracket	745 15
Frag armor, OGPk repair parts	745 14	M1120A2/A4--E-CHU/CHU removal	734 61
Fuel solenoid flyback diode	744 04	Multiple use adapter (MUA) usage	736 08
Gearhd hub fill plug washer	738 61	Spin-on oil filter conversion	736 61
Hardtop cover NSNs	741 10	TRUCK, PALLETIZED LOADING (PLS)	
LED headlight NSN	737 61	A1 Models--Hydraulic enable switch to OFF	737 14

Subject	Issue/Pg	Subject	Issue/Pg
Basic first aid kit, item expiration dates	739 61	M-ATV--Lube order update	743 61
Heated LED headlight NSN	736 60	MaxxPro--AFES battery backup kit	743 60
M1074, M1075--4500SP TCM NSN	741 60	MaxxPro Dash/DXM--Air filler valve NSN	743 60
M1074, M1075--Air intake hose NSN	734 61	MEL TB available	736 60
M1074, M1075--Mud flap hanger fix	743 14	VEHICLE, RECOVERY, M88-SERIES	
M1074, M1075--Speed sensor for 24V system	745 14	A1--Personnel access door lubing	738 07
M1074, M1075--Transmission fluid types	743 13	End connector, center guide torque	737 08
M1074A1, M1075A1--Hydraulic hose 2-piece	743 14	Spare roadwheel rust prevention	741 02
M1074A1, M1075A1--Shift cable boot	740 12	VEHICLE, STRYKER	
M1074A1, M1075A1--Warning light, MG mount	734 61	AFES PMCS checks	739 02
M1075/A1--E-CHU/CHU removal	734 61	DA Form 2408-4, who is responsible?	744 38
Mud flap hanger kit	737 61	Hub fill plug O-rings	735 03
TRUCKS, GENERAL		IETM contributions requested	740 04
Battery box coating compound	745 61	Left window extraction kit (LWEK)	740 05
Elastic cord for canvas covers	738 60	M1129A1, XM1252--Mortar tube stress cracks	743 09
GPK, OGPk maintenance TMs	734 37	M1135 NBCRV--ACADA water problem	736 44
GRS guidance, PMCS, NSNs, deadlining...	737 10	M1135 NBCRV--Moisture, fluids, axle oil	737 43
Hand signal posters for download	735 28	M1135 NBCRV--SSA troubleshooting	743 46
Hand Signals Make All the Difference	735 26	MGS--Battery box boots, cover needed	741 04
Operator's manual, keep with vehicle	740 09	Recovery rope improved	738 02
Parts bin helps with maintenance organization	743 11	Run-flat tire tips	739 04
Retreads not allowed on some vehicles	738 14	Storage of gear and equipment	739 06
Service kit NSNs	742 14	Winch pulley lubing	743 08
Solar charger info, NSN	738 10	VEHICLES, COMBAT	
Tire chain placement for tactical vehicles	734 10	Air filter ice, moisture damage	743 04
Tire chain use, NSNs	734 07	Battery box coating compound	745 61
Tire safety tips	738 12	Hand signal posters for download	735 28
Towing safety	735 10	Hand Signals Make All the Difference	735 26
Towing safety update (735-10)	741 17	Operator's manual, keep with vehicle	740 09
VEHICLE, FIGHTING, M2/M3 BRADLEY		Service kit NSNs	742 14
Battery charging, CIV tarp, gun card	734 02	Slat armor not for storage	739 05
DA Form 2408-4, who is responsible?	744 38	Towing safety	735 10
FM 3-20.21 pre-fire checklist	743 05	Track pad identification	737 09
FSS test set upgraded, renamed	738 06	VEHICLES, GENERAL	
Idler wheel nuts loosen	742 03	Hand signal posters for download	735 28
M240C--Securing pin suggestion	738 05	Hand Signals Make All the Difference	735 26
M242--Barrel, only one now available	738 05	Operator's manual, keep with vehicle	740 09
M242--Cleaning, lubing, assembly, PMCS...	745 04	WARRANTY	
M242, TOW--Firing PM	742 04	Oshkosh equipment warranty claims	744 60
Schematics for troubleshooting	743 05	WATER PURIFICATION	
STE-M1/FVS not needed with ED	742 60	TWPS--Filter NSNs	734 16
Track connecting with tanker's bar	744 37	WATER PURIFICATION UNITS (ROWPU)	
VEHICLE, MRAP		Filter NSNs	734 16
Driver's survey	743 12	WATER SUPPLY	
Driver training, publications	745 16	Dehydration dangers in winter	734 56
M-ATV--Brake chamber vent line replacement	740 13	FAWPSS--Cargo container NSN	744 60
M-ATV--Cushion set	736 60	Water publications	736 50