

PS Magazine Index No. 73, 2017

Subject	Issue/Pg	Subject	Issue/Pg
AIR CONDITIONERS		AIRCRAFT, HH-60M, BLACK HAWK	
A/C, refrigeration certification	777 46	Authorized MEDEVAC devices listed	772 22
AIRCRAFT ARMAMENT SUBSYSTEMS		Black Hawk Aircrew Trainer (BAT)	779 23
M144 Mounts--Ammo can pin, E-clip replaced	775 26	Co-pilot seat tilt breaks dome light	774 25
M230--GMD, loading, recoil adapter fluid...	775 19	Data analysis controller turn-in needed	771 26
TACOM help email address	774 60	Drive shaft assembly turn-in	776 52
AIRCRAFT, GENERAL		Dynamic rollout dangers	772 27
ACPRS inspection, safety	774 22	EMRH hoist adapter mounting bolts	780 20
AR 95-4 released	773 21	Engine parts needed for turn-in	779 22
Genex interface communications unit NSN	771 61	External rescue hoist TM updates	778 22
Navsolve cleaner approved for use	772 31	MEDEVAC direct email address	781 61
Solvent types, when and where to use	776 52	MEDEVAC news online	777 23
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		Pro-seal removal tool	775 25
AGPU--Cocoon cover NSN, instructions	778 24	Rescue basket safety issue	778 20
B-1 maintenance stand caster w/lock assembly	775 22	T700-GE-700 engine excess components	779 20
Equipment list with NSNs	780 24	T700-GE-701D engine igniter separation	775 23
SATS wheel installation guidance	777 22	Tinted overhead windows available	780 23
Sewing machine oil NSN	771 26	Utility helicopter safety help	781 23
Zephyr approved for rescue hoist	771 24	AIRCRAFT, UAV	
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		Shadow--Pre-flight, communication, logs...	781 24
ASE ordering, installation for deployment	777 24	AIRCRAFT, UH-60, BLACK HAWK	
AIRCRAFT, AH-64, APACHE		Co-pilot seat tilt breaks dome light	774 25
Armor transparent barrier	776 47	Distribution box turn-in	776 53
Connecting link turn-in	777 60	Dynamic rollout dangers	772 27
Engine oil requirements	771 23	EBAPS kits need part number change	775 23
Hardware storage board kits	781 19	Engine oil requirements	771 23
Hellfire rack, no spares allowed	777 26	Engine parts needed for turn-in	779 22
Helmet shell NSNs	771 22	External rescue hoist TM updates	778 22
IAFS combo pak turn-in	777 60	FLIR a 2-man lift	775 24
Main rotor blade phase adjustment tool	771 21	Flutter dampeners needed for turn-in	774 24
Main rotor blade unserviceables	775 21	Gyroscopes needed for turn-in	773 20
Parts turn-in list	781 22	Parts needed for turn-in	774 26
Quadrant part turn-in	777 60	Pro-seal removal tool	775 25
Servocylinder, ship in original containers	776 51	T700-GE-700 engine excess components	779 20
Support actuator turn-in	775 21	Tinted overhead windows available	780 23
Tools and test equipment turn-in	779 26	Tools and test equipment turn-in	779 26
Trailing arm turn-in	778 60	UHPO access on JTDI website	780 21
AIRCRAFT, CH-47D/F, CHINOOK		Utility helicopter safety help	781 23
Cockpit sun shade NSNs	778 26	AIRCRAFT, UH-72A, LAKOTA	
Headshed email help	777 23	Deck dampers installed backwards	772 25
Transmission corrosion treatment before shipping	773 18	UHPO access on JTDI website	780 21

Subject	Issue/Pg
ALARM, CHEMICAL	
M42--TM 3-6665-338-13&P available	773 40
AMMUNITION	
Dummy rounds updated	775 40
M855A1--Gaging different for M4/M4A1	779 39
ANTENNAS, GENERAL	
AB-1386 QEAM--Lubrication	779 45
AOAP	
AOAP explained, supply NSNs, forms	770 47
ARMORED COMBAT EARTHMOVER, M9	
Hydraulic parts kit	778 61
ARMORED SECURITY VEHICLE, M1117	
Alternator belt NSN	781 61
Drain plug use, location	780 12
Side door foothold tripping hazard	774 15
AVLB, M104 WOLVERINE	
DECU health check	778 60
AWARDS	
2017 LEA winners	781 55
CSA Deployment Excellence Award info	770 53
BACK COVER	
Be a Double-Dipper (oil dipstick accuracy)	770 62
Don't Destroy That DA Form 348!	777 62
Give Machine Gun Barrel a Rest!	780 62
Got a Question About Vehicle Batteries?	776 62
Loud Noise Harms Your Hearing!	772 62
Maintenance: what not to wear	773 62
No Matter How Old the Vehicle...PMCS	781 62
PS mobile app	771 62
Something Out of Reach? Use a Ladder!	778 62
Stop Private Mix-a-Lot	774 62
Wanted: Know-it-All Murphy	779 62
BATTERY, HAWKER	
Got a Question About Vehicle Batteries?	776 62
Battery box coating compound	779 61
Battery hookup guidance	777 12
BATTERY, LEAD-ACID	
Got a Question About Vehicle Batteries?	776 62
Battery box coating compound	779 61
Battery hookup guidance	777 12
BATTERY, LITHIUM	
Shipping rules for air transportation	772 46

Subject	Issue/Pg
BATTERY, RECHARGEABLE	
Battery types, chargers	773 50
BODY ARMOR	
Authorized sources only for purchase	780 60
CAN, FUEL	
Color-coding caps	777 57
CARBINE, M4-SERIES	
Cleaning, selector vs takedown/pivot springs	776 36
Conversion to M4A1	771 38
Enhanced performance magazine issued	771 36
Loose parts check after firing	779 36
M855A1--Bore erosion gage change	779 39
CARRIER, PERSONNEL, M113 FOV	
Battery charging	779 08
M113A3--Engine fire prevention	781 06
M113A3--Ramp system, armor vs unarmored	776 08
Ramp cable PM	772 04
Extinguisher bottle hydrostatic testing	771 61
Glow plug engine conversion	774 06
Hull water draining	772 03
Oil check, fuel cap, ramp reservoir, steering...	778 04
CBRN EQUIPMENT	
CBRN room checklist	774 43
JACKS website	772 41
M20 SCPE--PMCS keeps it working	778 42
M41 PATS--18-month calibration needed	773 38
M41 PATS--No smoking, perfumes, lotions...	773 39
M159 DR SKO--Air compressor check	773 41
M159, M164 DR SKO--Air setting wrong	779 42
CLOTHING	
Aviation boots	777 20
Cleaning procedures	779 49
OCP uniform patch NSNs	772 51
CLOTHING, PROTECTIVE	
JSLIST--Overboot sizing changes	781 42
JSLIST--Training suits	781 43
COMMAND AND CONTROL	
AN/TYQ-103 IPC-2--Backup batteries	771 48
COMMERCIAL CONSTRUCTION EQUIP (CCE)	
CAT ether start valve filter NSN	776 19
CAT service kits not available	774 60
CAT service kits now available	781 16
Maintenance Expenditure Limits (MEL)	772 17

Subject	Issue/Pg	Subject	Issue/Pg
Rocks wedge between tire and wheel	774 17	DETECTOR, CHEMICAL	
Tire wear limits	776 18	M4 JCAD--Confidence sample, sieve pack...	776 44
COMMUNICATIONS EQUIPMENT		M42--TM 3-6665-338-13&P available	773 40
Cable protectors	779 46	EDITORIAL	
Equipment codes decoded	775 49	Buyer Beware!	772 01
NSN primer from DLA	773 53	Decisions, Decisions	781 01
COMPUTERS & SOFTWARE		Excess Equipment: Going, Going, Gone!	770 01
CHESSE the source for hardware, software	780 57	Excess Equipment: Rest of the Story (770-01)	775 02
JBC-P keyboard NSN	772 47	Good PM Take More Than Just the TM	774 01
JV5 display replacement	779 44	Help Your Fellow Soldiers	779 01
MSD--EMS downloads	778 61	LARs: Familiar Faces in the Field	777 01
MSD--Software version listing	781 59	Positively Presidential	771 01
MSD--Software version matched to system	778 55	Readiness Starts with You	780 01
MSD-V2--OS upgrade to Windows 7	778 57	Stock Current TMs...and Use Them!	778 01
MSD-V2--Software glitch fix	778 60	Walk the Line	773 01
MSD-V3--Warranty support info	773 44	You Can Prevent Low Stock!	776 01
PCMCIA cards can be tossed	779 56	FED LOG	
COMSEC EQUIPMENT		LIW address system being updated	773 55
AN/PYQ-10--Software download support	773 49	FIRE SUPPORT VEHICLES	
KGV-72--Battery mixup	777 51	M1200--SMA clamp adjustment change	781 61
KGV-72--Locking block damage	771 46	FIRST AID KITS	
CONTAINERIZED KITCHEN		Combat application tourniquet updated	772 55
Hinge rust, cracks, jack damage, winches...	774 50	FORKLIFTS	
Water pump NSN	776 60	5K LCRTF--Tarp NSN	781 60
Water pump NSN	778 53	ATLAS, ATLAS II--Wheel differences	777 17
CONTINUITY		ATLAS II--Tire size correction (766-15)	781 60
As Times Change, So Does PS!	775 27	ATLAS II--TMs updated	774 61
Dogfight Over Berlin	774 27	FORMS, GENERAL	
Don't Let Good Idea Fairy Lead You Astray!	781 27	DA Form 348, don't destroy	777 62
Dungeons and Dragoons	778 27	DA Form 2028, Help Your Fellow Soldiers	779 01
Flight of the Tranquility	776 27	DA Form 2028 submission addresses	779 58
Game of Drones	777 27	DA Form 2404 still authorized	777 58
Mount Problems? Not Anymore!	773 27	DA Form 3161 to prevent property loss	770 03
PM Portal	771 27	SF 368 PQDR	770 19
Race for PM	779 27	Supply Discrepancy Report (SDR)	770 16
Readiness Problems? BLST Them Away!	780 27	FORWARD REPAIR SYSTEM, M7	
CORROSION		PMCS, crane hydraulic fluid, bay doors...	774 44
Monitoring, prevention, publications	770 35	GENERATORS, LARGE	
DECON		100-, 200-kW--AOAP enrollment	770 51
M12A1--Terrain decon spray bar (TDSB)	778 45	150-kW--250-, 1,000-hour service kits	772 44
M26--IUID MWO rescinded	775 61	840-kW TQG--AOAP enrollment	772 48
M26--PMCS keeps it working	778 42	Shut down powered equipment first	778 48
M26--PPE, oil level, fuel can, start button...	771 41		

Subject	Issue/Pg	Subject	Issue/Pg
GENERATORS, SMALL		A3--W16 cable with grips NSN	776 07
2-kW--Shutdown cable control assembly	771 60	A3--W16 cable with grips NSN	776 61
10-kW--MEP-803A in-line fuel filter NSN	778 61	Breechblock pin necessary	775 08
GRADERS		HOWITZER, TOWED, M777A2	
120M--Cab step damage, circle drive hose	775 16	Breech block pin, alignment	771 04
120M--Centershift lock assembly O-ring	777 60	Hub assembly wheel bearing preloading	771 06
120M--Hub draining tool	781 16	LRUs needed for turn-in	774 04
120M--Manifold pressure sensor NSN	774 61	MSD-V2 still needed for TMs	779 61
120M--Service kit NSN	781 16	IMPROVED TARGET ACQUISITION SYSTEM (ITAS)	
120M--Tie rod boot NSN	777 61	MITAS--Training, missile lock handle...	779 40
GUN, MACHINE		KITCHEN EQUIPMENT	
Barrels, don't mix and match	773 26	M59A Range--10-gal stock pot bracket fix	775 47
M2/M2A1--Bolt wear prevention	776 40	MTRCS--Oil drain line rub fix	774 53
M2/M2A1--Bushing gage not needed	774 39	MTRCS--Rear door parts	778 51
M2/M2A1--Sear spring check	776 39	Ventilation hood cleaning	778 52
M2A1--Cover latch, file/stone to fit part	771 39	LAUNDRY ADVANCED SYSTEM (LADS)	
M2A1--Second mounting rail installation	776 38	PDISE, not between LADS and generator	778 50
M240B--Bipod and parts listing	780 40	LOADER, BACKHOE (BHL)	
M240B--Stuck round removal procedure	779 38	Front drive axle steering cylinder NSN	771 60
M240B--Trigger pin spring NSN	775 45	Fuel/water separator filter NSN	779 61
M240L--Gas port erosion tool	771 40	HMEE-1--Backhoe lube fitting	778 18
M240-Series--Jamming issue bolt-related	780 39	HMEE-1--Front fender bracket tube cracks	771 17
M240-Series, M249--BFA for each barrel	775 41	HMEE-1--Headlamp removal	779 16
M240-Series, M249--BFA tips	773 24	LOADER, SCOOP-TYPE	
M249--Scraper NSN	772 34	924H--Precleaner repair parts	777 16
MK 19--Loading procedure in TM wrong	772 34	924H--Service kit NSN	781 16
MK 19--LSAT/GMD, rear sight, timing screw...	775 42	966H--Service kit NSN	781 16
HAZARDOUS MATERIALS & WASTE (HAZMAT)		LOADER, SKID-STEER, BOBCAT	
DLA Disposition Services HAZMAT disposal	778 58	M400W--Battery drain prevention	779 17
Shipping help from PSCC	775 61	LOGISTICS ASSISTANCE	
Shipping help from PSCC	778 56	AMSAA field studies	770 60
Stop Private Mix-a-Lot!	774 62	DLA document services	781 58
HELMETS, AVIATION		DLA support for SMS-coded items	770 26
IHADSS--Modification check	774 23	JLLIS training	778 60
HELMETS, GROUND		LARs, how to find	770 24
ECH--HMWA to attach night vision goggles	773 43	Readiness Problems? BLST Them Away!	780 27
HOWITZERS, GENERAL		Tobyhanna Evaluation Inspection Program	777 52
Cannon cleaning tools	776 06	LOGISTICS MANAGEMENT	
Check tubes after EOD stuck round removal	771 03	DLA fraud, waste and abuse reporting	777 47
Digital video borescope available	773 23	Equipment drawdown guidance	775 61
HOWITZER, TOWED, M119-SERIES		Furniture turn-in to DLA	777 56
A3--Fire control computer PQDRs	774 03	GCSS-Army--AOAP data cleansing	775 61
A3--Firing platform wear normal	775 08	GCSS-Army--Early services impact	777 59
A3--VMS bellows coupling kit NSN	777 61		

Subject	Issue/Pg	Subject	Issue/Pg
GCSS-Army--End User Manual +	780 61	Gen 1 & 2 FLIRs replaced by Gen 3	774 60
GCSS-Army--Training info	779 55	W103 ECU/PPU cable, check for tightness	774 42
GCSS-Army--Turn-in credit explained	771 56	MISSILE, HIMARS	
Lateral transfer tips	770 04	Door hinge, seal damage	777 39
Property turn-in to DLA Disposition Services	770 08	Driveshaft U-joint kit replaced	773 16
MAINTENANCE MANAGEMENT		Engine K16 relay NSN	774 61
Bench stock management	770 56	Exercise, cleaning, slaving, wheel torque...	780 36
CMDP Knowledge Center	770 43	Hydraulic relief valve update (718-40-41)	778 36
Expert ASL role and responsibilities	770 09	Pivot joint lube point MWO	775 38
FedMall	771 53	Rear leaf spring clamp fix	771 14
Low-use equipment maintenance	770 38	Starter bolts loosen, crack housing	772 10
Maintenance terrain walk how-to	770 40	MISSILE, JAVELIN	
Maintenance walk-thru checklist-motor pool	770 41	PMCS, services tracking, storage case	775 36
Maintenance walk-thru checklist-property	770 59	MISSILE, PATRIOT	
Maintenance walk-thru checklist-SSA	770 57	Component cleaning	778 37
Two-level maintenance explained	770 44	ECS PPG cable, A/C covers, ECS filter...	772 35
WIN-T items reconfigured in MMDF	775 60	Outrigger PMCS, leaks, cracks, lubing...	777 36
MAINTENANCE, GENERAL		Spare tire PMCS	775 39
Annual services time guidelines	779 57	MLRS	
PMCS terms explained	773 58	Exercise, W19/20 cables, hoist cables...	773 04
Two-level maintenance explained	770 44	HMPT-800 transmission inspection	779 07
Unauthorized mods against regulations	771 50	MORTARS	
MASK, PROTECTIVE		Digital video borescope available	773 23
M40-, M50-Series--Canister expiration dates	778 43	M252--Bipod washers decreased	771 38
M50--Faceform needed for shipping, storing	773 40	M326 MSK--Hawker batteries unauthorized	773 23
M50--Outlet valve cover removal	778 42	MOUNT, WEAPONS	
M50--Testing intervals explained	773 39	GRS a part of machine gun mounts	781 12
MEDICAL EQUIPMENT		M3 Tripod--Serial number not available	776 41
MIRCS--Air filter NSN	777 61	M153 CROWS II--4-3-2-1 rule, covers...	778 40
MIRCS--Generator mounting bracket pin	776 60	M153 CROWS II--Cover replacement NSN	781 41
MINE CLEARING EQUIPMENT		M153 CROWS II--PMCS for refresher training	780 42
M1231 Husky--A/C filter cleaning	777 18	M153 CROWS II--Software upgrade MWO	777 43
M1231 Husky--Cab air filter cleaning	774 18	MK 64--MK 93 Mod 2 replaces	773 25
M1231 Husky--Step, no-step zones	778 16	Machine gun mount PM	776 42
M1231 Husky--Hydraulic lines, A/C filter...	776 20	Machine gun mount tips	781 36
M1231 Husky--Ink spray hoses, secure w/ties	774 19	Mount not allowed on A4 HEMTT, A1 PLS	781 61
M1231 Husky--Storage info	776 21	Mount Problems? Not Anymore!	773 27
M1272 Buffalo--Battery disconnect switches	775 15	NIGHT VISION EQUIPMENT	
MINE DETECTOR		AN/PSQ-20--Battery connector damage	778 47
AN/PSS-14--Cord clip, cable, battery seal...	772 38	AN/PSQ-20, -20A--HMWA to mount on ECH	773 43
MINE DISPENSER, M139 VOLCANO		AN/PSQ-20B--Batteries, TM (766-50)	774 49
Repair parts have long lead time	771 19	Pouch protects goggles	772 49
MISSILE, AVENGER		POL	

Subject	Issue/Pg	Subject	Issue/Pg
Flammable storage cabinets	777 48	RIOT CONTROL	
POL products guide	772 15	LESD Taser--DPM stays for storage	774 39
SCPL update (768-11-14)	779 60	ROLLER, VIBRATORY	
PS MAGAZINE		CS563D--Fuel line NSN	771 60
As Times Change, So Does PS!	775 27	SAFETY	
Back issue ordering	777 47	Eye wash stands	776 56
Back issues	776 58	Flammable storage cabinets	777 48
Have You Downloaded the PS App Yet?	775 62	Hearing protection	776 24
Official but optional	772 57	Loud Noise Harms Your Hearing!	772 62
PS Magazine Goes Digital-Gen Perna	775 01	Something Out of Reach? Use a Ladder!	778 62
PS Mag Live	772 56	SATELLITE COMMUNICATION	
PS mobile app download URLs	771 62	AN/TSC-183A transition to sustainment, Pt 1	780 45
PUBLICATIONS		AN/TSC-183A transition to sustainment, Pt 2	781 46
AR 11-33 revised	771 60	WIN-T Inc 1 transition	773 46
AR 702-16 updated	773 43	SCRAPER, EARTHMOVER, 621G	
AR 750-59 published	771 61	Air dryer filter	777 61
AR 2016-21 published	771 60	Cab air filter moisture problem	774 20
AR, DA Pam update list	780 58	Service kit NSN	781 16
Army publications, how to subscribe	774 56	SHOP EQUIPMENT	
Checking Army forms correction (769-61)	774 59	SECM--Websites/email for help	778 13
DLA Disposition Services Turn-in Smart Book	770 13	SIGHTS & SCOPES	
Electronic warfare smartbook	771 47	Securing sights to mounting rail	774 40
IETMs no longer viewable online	774 54	SLAVE CABLE, NATO	
TMs part of BII for turn-in	770 52	Various length NSNs	771 13
RADARS		SMALL ARMS	
Sentinel--FMTV platform safety measures	780 38	Battery leaks, CLP brush, bolt catch, PMCS...	774 36
RADIO SET, GENERAL		BFA guide available by email	779 37
EPLRS--Packaging for shipment	779 60	Demil done by DLA	776 41
LS-671--Loudspeaker turn-in	779 60	Demil done by DLA	777 55
RT-1967, Manpack--Low power defect check	774 48	Gaging and paperwork important	781 40
RADIO SET, SINGGARS		Gaging publications	772 33
RT-1523G--HUB expiration date fix	774 47	GTA breakdown for various small arms	771 39
RATIONS		Secure sights to mounting rail	774 40
MRE expiration dates	774 50	Secure sights to mounting rail correction (774-40)	777 61
RIFLE, M16-SERIES		Water-resistant target NSNs	777 42
BUIS, fix instead of replace	772 33	SMART SUGGESTION PROGRAM	
Cleaning, selector vs takedown/pivot springs	776 36	Tips and guidelines	771 54
Enhanced performance magazine issued	771 36	SUGGESTION PROGRAM	
Hybrid and collapsible buttstocks not the same	771 37	AI2 replaced old Army suggestion program	776 55
Loose parts check after firing	779 36	SUPPLY, GENERAL	
RIFLE, SNIPER		COSIS inspections identify storage problems	772 58
M2010--Loose sling insert fix	779 39	COSIS inspection worksheet	773 61
Turn-in guidance	777 44	CSDP, PA knowledge centers	770 02

Subject	Issue/Pg	Subject	Issue/Pg
Property classification	770 14	D7R II--Service kit NSN	781 16
Religious supply catalog	771 49	D7R II--Winch cable NSN	771 60
Shelf-life management	770 12	TRAILERS	
SMR codes explained	775 55	Caged brakes info	773 12
Unserviceable item turn-in	770 42	M149A2--Frame SMR correction	776 60
TANK, M1-SERIES		M149A2--Tire and wheel assembly	779 14
Battery drain, replenisher check	777 06	M1048A1 brake shoes and wheel cylinders	776 13
Engine inlet screen not repairable	779 06	M1082, M1095--Wheel assembly (766-12-15)	771 61
Gun tube disposal caution	777 05	M1112--Tire and wheel assembly components	781 61
Ice cleats NSN, tips	771 09	Wheel assemblies for small trailers	771 15
Ice cleats revisited (771-09)	775 61	TRAILERS, SEMI	
M1A1, A2 SEPv2--Start up, shut down	777 04	Caged brakes info	773 12
Main hydraulic pump O-rings	771 08	M860A1--Pre-colored outrigger NSNs	781 60
NBC filter fire prevention	780 04	M872A3--Brake shoe kit NSN	771 61
Reactive armor manuals available	774 61	TRAINING	
Roadwheel chunking	780 03	Army serial number tracking (ARSNT)	771 58
Wire race ring lubing	776 03	COMET teams	770 23
WTA only for lubing	777 07	Digital master gunner course	771 59
WTA only for lubing	777 60	MILES mobile apps	774 58
TENTS		TRUCK, 1 1/4-TON, HMMWV	
DRASH, HDT, PSI--ID help available	771 51	Air cleaner dust boot	777 11
LAMS support available	776 23	Alternator replacement hardware NSNs	772 14
TEST EQUIPMENT		Load range D and E differences	772 11
DSESTS help	774 07	M998-Series--M7 pedestal for MG mounting	774 11
DSESTS help	776 61	M1097R1--Protective control box NSN	778 11
Gage cases with foam cutouts	771 44	M1151/A1, M1167--Cargo hatch hinge brackets	778 12
Gage case update (771-44)	778 39	M1152, M1165--Main body harness P-clamp	776 12
HT402--TM location damages selector switch	780 43	Pintle hook kit bracket not needed	779 11
Obsolete set turn-in	776 61	Serpentine belt NSNs	778 11
Obsolete set turn-in	777 03	Steering shaft needs lube	775 12
TMDE calibration requirements, app	770 58	Towing tips	780 14
TOOLS		Transmission filter NSN uncovered	774 12
Aviation tools under RIA warranty program	780 22	Weather cap check for damage	776 11
Electrical safety board requirements	777 40	Windshield washer hose loop clamps	780 17
HT402--TM location damages selector switch	780 43	TRUCK, 5-TON, GENERAL	
SATS--Lifting strap NSNs	781 44	Dump Trucks--Tailgate chain covers	780 11
SATS--Ramp safety straps NSN	775 45	M934/A1/A2--MEL drops to zero	781 61
SECM--Websites/email for help	778 13	TRUCK, FMTV	
TRACTOR, D7E/F/G/R		A1/A1P2--C7 engine fuel hose NSN	778 61
D6K--Service kit NSN	781 16	A1/A1P2--Engine K16 relay NSN	774 61
D7R II--Decelerator pedal saves transmission	775 17	A1/A1P2/A1R--Air inlet heater relay NSN	777 61
D7R II--Frame bolts, check for looseness	776 17	A1P2--EHPU breather cap NSN	779 13
D7R II--Parking brake, winch handle, cleaning	771 18	A1P2 LTAS--Cab door shock absorber	779 61
D7R II--Seat adjustment knob bolt NSN	774 60	A/C compressor leaks	778 14

Subject	Issue/Pg	Subject	Issue/Pg
A/C V-belt pulley spacer plate installation	776 14	Fuel cap gasket kit NSN	776 60
Driveshaft U-joint kit replaced	773 16	Fuel cap, inspect rather than replace	773 08
Hydraulic manifold decal NSN	780 13	Fuel pumps, match to correct engine	773 07
M1078A1--100-amp alternator pulley NSN	779 61	LRU TMs available	776 61
M1078A1P2--Rear cab mount cylinder NSN	779 61	M242--14-pin connector, GMD, rounds fired	777 08
M1083A1P2--Flange bolt inspection for axle	774 14	M242--Cover correction (766-9)	774 05
M1088A1P2--Brake plunger seal NSN	778 61	M242--Indicator rod, don't push	778 09
M1088-Series, M1157A1P2--Rear leaf spring	771 14	M242--Stand plans available	775 10
M1094--Drive shaft assembly NSN	778 60	Reactive armor manuals available	774 61
M1157A1P2--Dump bed legs, lube points	771 12	Test set turn-in, PMCS, battery charging	776 04
M1157A1P2--Tailgate release valve NSN	773 16	TM revisions available	776 05
Starter bolts loosen, crack housing	772 10	Turret jams from spent rounds	781 08
Tire and wheel assembly mixing	781 11		
TRUCK, HEMTT		VEHICLE, MRAP	
A4 Models--Hydraulic manifold solenoids	779 12	MaxxPro Dash--Battery box/fuel cap access	775 13
A4 Models--Weapons mount unauthorized	781 61	MaxxPro Dash--Steering gear output shaft boot	774 13
HTARS--Fuel and oil servicing nozzle	779 60	Rollover prevention	771 11
M978A4--FTSS repair kit NSN	771 61		
M1120A2/A4--E-CHU shear pins snapping	777 14	VEHICLE, RECOVERY, M88-SERIES	
Winch cable safety	773 14	A1--Final drive sprocket bolts	775 04
		A1--Ground hop components	778 03
		A2--Engine maintenance tips	775 05
		Winch cable safety	773 14
TRUCK, M915-SERIES			
M915A5--Air horn NSN	778 61	VEHICLE, STRYKER	
M915A5--Module NSNs	781 13	Air intake, keep water out	774 09
M915A5--Radiator NSNs	776 60	AOAP enrollment mandatory	772 06
M915A5--Rear wheel seal NSN	774 60	Battery boxes, secure against rollover	776 07
M915A5--Service interval upped to 12K miles	781 61	Battery voltage, coolant, PECCH hose...	781 03
		DVE surge threat	779 03
TRUCK, M1070 HET		Engine service kits	773 10
A1--Alternator NSN	779 61	Idle for warm-up, cool-down	779 04
		M1128--A/C refrigerant leaks	781 05
TRUCK, PALLETIZED LOADING (PLS)		M1135--Drain plugs, JBPDS items...	773 36
A1 Models--Hydraulic manifold solenoids	779 12	M1135--ACADA correction (773-36-37)	779 41
A1 Models--Weapons mount unauthorized	781 61	Ramp hydraulic fluid levels	774 08
M1074, M1075--Alternator replacement	780 18	Ramp PM tips	780 06
M1074, M1075--DDEC II engine upgrade	774 60	Recovery lug shackle hardware installation	779 06
M1074A1, M1075A1--Steering pressure sensor	778 60	RWS lens caps prevent damage	778 09
M1074A1, M1075A1--Prop shaft boot NSN	777 60	Tow bar for flat towing	779 05
M1075--Proximity switch NSN	781 60	Winch solenoid hook-up	773 09
M1075/A1--E-CHU shear pins snapping	777 14	Winch solenoid hook-up correction (773-09)	776 60
PLS team email	781 13	Winch solenoid hook-up GPA message	776 60
TRUCKS, GENERAL		WATERCRAFT	
Battery box coating compound	779 61	Discharge standards update	781 15
Caged brakes info	773 12	LCU-2000--Anchor corrosion	779 18
VEHICLE, FIGHTING, M2/M3 BRADLEY			
BUSK III battery info	779 60		