

PS Magazine Index No. 74, 2018

Subject	Issue/Pg	Subject	Issue/Pg
AIR CONDITIONERS		AIRCRAFT, HH-60M, BLACK HAWK	
ECU--Refrigerant changes from R22 to R438A	787 50	Crew restraint tether deployed	791 22
ECU--Refrigerant sourced through DLA	792 61	Generator control, propulsion shaft turn-in	784 23
ECU--Turn-in from Germany/OCONUS	793 61	Hydraulic filter replacements	786 38
AIRCRAFT ARMAMENT SUBSYSTEMS		IMMSS, BMI parts info needed	789 21
M230--Chain assembly PM	786 42	IVHMU label placement	789 22
M230--Dummy test round fabrication	782 23	Litter platform turn-in	791 26
M230--Unserviceable turn-in help	793 38	Main shaft extension assembly NSN	786 40
AIRCRAFT AVIONICS		Personal restraint tether safety	793 36
AN/APX-123/A--SAFT battery	787 24	Rescue hoist device inspection	790 22
AIRCRAFT FORMS		Rescue hoist needs oil	787 22
DA Form 2028, SF 368 differences	793 40	Rig connecting link turn-in	793 60
AIRCRAFT, GENERAL		Tail rotor blade turn-in	785 26
Cold weather PM: fuel, lubes, seals, batteries	792 18	AIRCRAFT SAFETY	
Commercial cleaners may cause damage	784 24	FOD can	782 62
Corrosion help email	792 25	AIRCRAFT, UAV	
DD Form 1348-6 for parts without NSNs	789 24	MQ1 Gray Eagle--Fasteners, aft cowl...	786 44
Hardware, check bench stock for quality	787 26	MQ1 Gray Eagle--FOD, GCS door...	787 21
Parts with rust can be repaired	784 22	Shadow--Elements protection	792 26
PEO Soldier website, social media	792 25	Shadow--GDT cable, CRP nut plates...	782 24
T700 engine manual available	790 23	Shadow--Help by email	784 25
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		Shadow--Helpdesk emails	790 25
AGPU--Hydraulic filter replacements	786 38	Shadow--Propeller damage	793 42
FARP helmet update (721-37-38)	784 26	AIRCRAFT, UH-60, BLACK HAWK	
GMR-500 routers needed for turn-in	788 52	Crew restraint tether deployed	791 22
Pitot static test set components	786 37	ERFS tanks turn-in	783 26
SATS--Leaf spring wear inspection	792 24	Generator control, propulsion shaft turn-in	784 23
UMARK covered by two TMs	789 26	Hydraulic filter replacements	786 38
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		IMMSS, BMI parts info needed	789 21
PSGC zipper fix	783 26	Indicator panels needed for turn-in	788 51
AIRCRAFT, AH-64, APACHE		IVHMU label placement	789 22
AAIH helmet TM available	783 21	Litter platform turn-in	791 26
ECS filter system upgraded	791 25	Personal restraint tether safety	793 36
Hydraulic filter replacements	786 38	Safety help email	784 25
IAFS combo pack turn-in	787 23	Searchlights needed for turn-in	788 51
Lead lag link tool not authorized	790 24	Rescue hoist needs oil	787 22
Off-aircraft battery charger update (732-25)	782 26	Rig connecting link turn-in	793 60
Radome paint erosion repair	788 53	Tail rotor blade turn-in	785 26
Rescue hoist device inspection	790 22	AIRCRAFT, UH-72A, LAKOTA	
Support actuator assembly turn-in	783 25	Crew restraint tether deployed	791 22
Transport handle assembly	787 61	Engine cowling heat blankets	782 22
Wing pylons needed	785 23	FAQ available on JTDI website	783 23
AIRCRAFT, CH-47D/F, CHINOOK		Ground handling wheels, tow bar	785 24
Crew restraint tether deployed	791 22	ANTENNA, OE-254	
Ground cover NSNs	793 35	Mast parts identification	792 51
Rotor blade adjustment stand	783 24	AVLB, M60/M48	

Subject	Issue/Pg	Subject	Issue/Pg
Bridge hinge inspection	793 09	M159 CBRN DR SKO--Fridge plug danger	782 45
Transmission filter housing bolt torque	792 09	MPHS hydration system	784 44
AWARDS		Turn-in support	784 43
2018 AAME entry instructions	791 58	CLOTHING	
Driver's badge for safe driving	783 61	A2CU flight suit NSNs	790 26
BACK COVER		Insect repellent system	788 56
Always Follow the Lube Order!	784 62	Nitrile glove NSNs	789 55
Best Soldiers Soak Up Maint Info Like Sponge	792 62	OCIE protective gear turn-in	786 60
Cross-training Creates Well-Rounded Soldiers	791 62	COLD WEATHER	
Do Commo PM!	789 62	Cold weather equipment TMs available	782 60
Don't Roll the Dice with PM!	788 62	Winter storm vehicle preparation	792 12
Don't Set Your Mission Up for Failure!	786 62	COMMERCIAL CONSTRUCTION EQUIP (CCE)	
Do Start-up by the Book	783 62	Bucket draining to prevent corrosion	784 18
Not Sure How Long Annual Services Take?	790 62	ET training, POCs	793 43
PMCS--The Gift That Keeps On Giving	793 62	Hydraulic cylinder rust problems	782 20
Refueling?	785 62	COMMUNICATIONS EQUIPMENT	
Wanted: Big Fist Murphy	787 62	CECOM equipment returns	788 60
You've Got Yourself a FOD Can	782 62	Heat protection tips	786 47
BATTERY, LEAD-ACID		TEIP adds more C4ISR equipment	789 50
Battery box coating compound	787 61	COMPUTERS & SOFTWARE	
Installation: felt washer, silicone, rubber cover	784 16	CHESS for IT equipment and software	789 57
Silicone compound prevents corrosion	784 15	Command post tablet TMs	782 61
BODY ARMOR		DLA office device management program	783 59
ESAPI test videos website	792 61	JENM software user manual available	788 61
Plate damage tests	787 52	MSD--Software installation order	782 58
CAN, FUEL		TMDE, MSD move to milSuite	792 56
Storage tips	784 49	COMSEC EQUIPMENT	
CARBINE, M4-SERIES		COMSEC help	785 49
Action spring length	783 36	KG-250--Tamper key, internal battery	790 50
Bore clearing, rod instructions	784 38	Legacy equipment turn-in	791 48
Cleaning kits and replacement components	790 36	CONTAINERIZED KITCHEN	
Front sight tool, buy or fabricate	792 38	Exhaust pipe coupling replaced	789 53
Magazine PM	783 38	CONTAINERS	
Polymer magazines available	784 40	LLRC humidity indicators	784 60
Usable on codes (UOC)	792 35	CONTINUITY	
CARRIER, AMMO, M992A2		Anatomy of a Proper PMCS	793 27
Air cleaner box cleaning	788 06	Dax Torthon in the 26th Century	790 27
Engine air duct hose clamp	793 03	Dell's Kitchen	788 27
CARRIER, PERSONNEL, M113 FOV		Iron Oxide Ogre, the Reaping, Corrosion...	784 27
Engine intake/exhaust grille cover	792 04	James Bondo in Moonbreaker, Part 1	791 27
Engine oil filter NSN	793 60	James Bondo in Moonbreaker, Part 2	792 27
Hull draining to prevent component rust	791 08	Night Knight	783 27
M577A3, M1068A3 CPC--Generator air hose	786 03	No PM for Evil Villains	789 27
Manifold rust prevention	789 08	PM Mission to Mars	787 27
Ramp pulley housing damage	783 09	PM Wars: Return of the Jebbi	785 27
CBRN EQUIPMENT		Re-Introducing Your New M50/51 Mask	786 27
CBRN filter replacement for vehicles	789 14		

Subject	Issue/Pg	Subject	Issue/Pg
CORROSION		ATLAS--Fuel filter NSN	782 60
Aviation corrosion help email	792 25	ATLAS II--8-ft carriage available	785 21
Corrosion preventive compound (CPC) use	784 12	Tine adjustment instructions	788 19
Dax Torthon in the 26th Century	790 27	FORMS, GENERAL	
Dessiccant, drum of 300	790 61	CREPS report website	792 25
Iron Oxide Ogre, the Reaping, Corrosion...	784 27	DA Form 348--Keep for records	783 55
Method 20 packing	787 56	DD Form 1348-6--Ordering parts with no NSN	789 24
Method 50 packing	787 58	DA Form 2028--TACOM submissions	793 53
Rust Busters tip of the month #1	782 14	FORWARD REPAIR SYSTEM, M7	
Rust Busters tip of the month #2	783 11	Door latch NSN	791 39
Rust Busters tip of the month #3	784 11	Loading tips	791 38
Rust Busters tip of the month #4	785 12	GENERATOR, SMOKE, M56	
Rust Busters tip of the month #5	786 14	Fuel filter/separator maintenance kits	786 35
Rust Busters tip of the month #6	787 12	GENERATOR, SMOKE, M58	
Rust Busters tip of the month #7	788 10	Fuel filter/separator maintenance kits	786 35
Rust Busters tip of the month #8	789 12	GENERATORS, LARGE	
Rust Busters tip of the month #9	790 11	15-kW--MEP-804B alternator NSN	790 49
Rust Busters tip of the month #10	791 10	15-kW AMMPS--Oil filter NSN	783 51
Rust Busters tip of the month #11	792 10	30-kW--MEP-805B injection pump NSN	793 61
Rust Busters tip of the month #12	793 10	Power generation certification training	791 46
CRANES		GENERATORS, SMALL	
AT-422-T--Air cleaner intake pipe NSN	787 61	Power generation certification training	791 46
LRT-110--Seat rail kit NSN	791 61	GRADERS	
DECON		120M--Articulation rods, keep clean	784 20
M12A1, M26--Cold protection	783 41	120M--Cab filter vent blocked	789 18
M26--Water pressure gauge calibration	791 37	120M--ECM box loosened by vibration	789 19
M334 decon kit TM available	787 61	120M--Exhaust pipe rust	784 19
DETECTOR, CHEMICAL		120M--Moldboard slide cylinder not a step	782 18
M4 JCAD--Battery tray/rain cap, don't force	782 41	GRENADE LAUNCHER, M203	
EDITORIAL		M320A1 replacing by attrition	782 37
Bulk Up That Brain!	790 01	GRENADE LAUNCHER, M320	
Dirty Talk	786 01	Buttstock locking lever, secure before firing	790 39
Don't Take Flying Visually Impaired Lightly	792 01	GROUNDING	
Easy Answers?	787 01	MK-2551A grounding kit use at NTC	789 48
Is the Word Still Golden?	782 01	GUN, MACHINE	
Make Safety a Readiness Imperative	788 01	M2A1--Barrel installation	791 45
Next-Gen Needs PM, Too	791 01	M2A1--Barrel locking spring NSN	792 39
Right Approach	789 01	M2A1--Bolt and barrel extension mixup	785 36
Sergeant's Time Training	785 01	M2A1--Breech lock selection tool instructions	792 39
Sew Up Your PM	783 01	M2A1--Trigger lever stop assembly fix	783 37
Spring Into Action	784 01	M240B--Heat shield damage guidelines	783 40
Who Drives the Train	793 01	M240B, M240L--Buffer checks	792 40
FIRST AID KITS		M240L, M249--Barrel requirements	786 25
Customized medical kits	788 57	M240-Series--Adjustable buttstock MWO	791 44
Poison ivy treatment	788 55	M240-Series--Collapsible buttstock install	788 36
FORKLIFTS		M240-Series--Front mounting bushing pin	788 41
6K VRRT--Engine upgrade modification kit	791 20	M240-Series--Usable on codes (UOCs)	792 35
6K, ATLAS--Axle lube during services	783 19		

Subject	Issue/Pg	Subject	Issue/Pg
M249--AAL items added to TM	790 38	KITCHEN EQUIPMENT	
M249--Barrel feed throat dimple OK	788 42	FSC-2--MWO approved for MBUs	789 54
M249--Buttstock component NSNs	782 36	FSC-2--NSN correction (789-54)	793 61
M249--Feed box support kit	793 19	MKT--MEL chart released	791 56
M249--Guide rod assembly installation	793 23	MTRCS--Hook arm pin, battery box cover...	791 52
MK 19--Model descriptions	782 38	LAUNDRY ADVANCED SYSTEM (LADS)	
MK 19--Rear sight inspection	785 39	Drain water to prep for cold weather	792 46
MK 19--Sear assembly (775-44)	785 38	LOADER, BACKHOE (BHL)	
HAZARDOUS MATERIALS & WASTE (HAZMAT)		Digging tips	791 16
HMIRS Nex Gen introduction	783 54	Ether spray for engine starts a no-go	792 17
PSCC transportation help	793 61	HMEE-1--Axle grease fitting lube	787 17
HEATER, SPACE		HMEE-1--Swing lock pin, insert before travel	785 19
Convective Space Heater--Battery tips	782 47	HMEE-1--Windshield washer hose T-fitting	788 20
HELMETS, AVIATION		Prime turbo at startup, after storage	785 20
AAIH--Intro to new helmet	788 50	Prime turbo at startup, after storage	791 18
AAIH--Liner supply, use HGU-56 liners	788 48	LOADER, SCOOP-TYPE	
AAIH--TM available	783 21	966H--Bucket lubing	783 17
AAIH--TM available	790 23	LOADER, SKID-STEER, BOBCAT	
Helmet bags for helmets only	783 22	M400T, M400W--Door assembly NSN	782 60
IHADSS--Helmet frame not repairable	786 41	LOGISTICS ASSISTANCE	
IHADSS--HOLT software upgrade	788 47	AMSAA helps with bench and shop stock	791 57
IHADSS--Visor housing display not available	791 21	ASL help from LOGSA PSCC	784 55
HELMETS, GROUND		CTC planning steps	785 55
CVC--Helmet shell NSNs	793 48	DLA customer interaction center	788 25
ECH--Helmets with sensors replaced	791 55	Warehouse operations help	788 26
Night vision equipment mounting videos	782 60	LOGISTICS MANAGEMENT	
HOWITZER, SP, M109A6 PALADIN		AACA clears cargo for air clearance	785 58
Air cleaner box cleaning	788 06	B-Kit accountability	790 58
Engine air duct hose clamp	793 03	GCSS-Army--AIT handheld transaction codes	793 58
Idler arm housing lube	793 04	GCSS-Army--Codes decoded	786 56
MCS hose not for personal A/C	786 04	GCSS-Army--Corrosion cause code	792 15
Repaired gun tube corrosion	784 06	GCSS-Army--Greenwich Mean Time chart	791 58
Travel lock friction linings	791 09	GCSS-Army--HR BOM discrepancy	791 60
HOWITZER, TOWED, M119-SERIES		GCSS-Army--RDD needed for 02 parts	784 57
A3--Exercise, cannon tube cracks, recoil rails...	785 06	GCSS-Army--Serial number profile request	782 55
BOP points for hearing protection	787 07	GCSS-Army--Supply smartbook download	791 60
Cradle crack check	790 08	GCSS-Army--TELS hardware required	792 56
Firing pin fix	782 03	GCSS-Army--Terms & abbreviations	789 60
HOWITZER, TOWED, M777A2		GCSS-Army--Training request email	791 61
Breech block witness marks	785 04	GCSS-Army--Website URL change	790 61
Cradle crack check	790 08	Manufacturer location	789 58
Spade latch spring, breech carrier...	784 04	PAVPB for property accountability training	782 59
IMPROVED TARGET ACQUISITION SYSTEM (ITAS)		MASK, PROTECTIVE	
Battery charger, TU lift, TU case, cleaning	793 16	C2A1 canisters leaking carbon	786 26
Launch tube crack prevention	788 44	M40, M42, JSGPM--Fitting issues	793 24
LRU tracking for accountability	789 36	M40-, M50-Series--Faceforms for storage	785 43
		M50--Outsert, nosecup retaining ring, storage...	790 44

Subject	Issue/Pg	Subject	Issue/Pg
M50, M51--Improvements, PM help	786 27	NIGHT VISION EQUIPMENT	
MEDICAL EQUIPMENT		AN/PSQ-39--Operator's manual released	790 49
Maintenance--significant medical equipment	785 50	AN/PVS-7, -14--ACH viewer mount	789 51
Poison ivy treatment	788 55	AN/PVS-7B/D, -14--LIF, packing, lens paper...	790 47
Tactical combat casualty care (TCCC) card	783 52	AN/PVS-14--LIF, parts, batteries	788 58
MINE CLEARING EQUIPMENT		AN/VAS-5--DVE sensors replaced	787 47
Buffalo--Camera dots, electrical disconnect...	790 17	AN/VVS-2--Turn-in needed	790 51
Buffalo--Cold weather fluid warmup...	792 16	Battery acid damage	793 18
Buffalo--Hoses, keep CARC away	785 17	Helmet mounting videos	782 60
Buffalo--Ladder operation to prevent damage	785 18	PACKAGING	
Buffalo--Walking beam bushings check	791 19	Corrosion assistance publications	792 58
Calibration, LOSS, head angle, RF, fatigue	787 18	Desiccant NSNs, use	785 52
M1231 Husky--Air cleaner, dust cap	786 18	Fast Pack types, uses	793 54
M1231 Husky--Detection panel stowing	782 18	Method 20 packing	787 56
M1231 Husky--Sealant, hydraulic leaks...	788 18	Method 50 packing	787 58
M1231 Husky--Stowage bin access door	782 19	Preservative types to prevent corrosion	784 58
M1231 Husky--Transmission filter cover	783 18	PERSONAL EQUIPMENT	
Minehound--Powerhound kit, weight strap...	790 41	Hydration systems	786 50
Strider--Control cable, LEDs, sensing unit...	785 44	OCIE protective equipment turn-in	786 60
MISSILE, HIMARS		Pop-up bed w/insect net	786 49
Connector cleaning, second-chance adapters	792 44	PISTOLS	
Frame rail inspection criteria	789 38	M9--Trigger pull test required	782 40
Hatch not a seat	789 40	POL	
Hoist cable tips	788 43	PQAS-E--Hookup for external power	789 52
M240B, store in cab during firing	791 41	POWER DISTRIBUTION	
Newsletter	787 43	DISE turn-in and PDISE replacement	783 50
Rear cab support latch cracks	790 45	PDISE, unpack to avoid corrosion	784 52
W513 adapter chain replacement	789 41	PS MAGAZINE	
MISSILE, JAVELIN		Article submission criteria	792 54
CLU batteries	792 45	Heard About PS Magazine's Mobile App?	785 61
MISSILE, PATRIOT		Posting PS info on bulletin boards	786 54
GPS cables, disconnect properly	789 37	PS Mag Live	784 53
Track lube, outrigger sight glass, LEM drain	785 46	PS Mag Live	793 51
MLRS		PS mobile app ad	785 60
300WP3 engine cable, keep feet away	786 05	Radionerds website for old issues	783 61
Connector cleaning, second-chance adapters	792 44	PUBLICATIONS	
Hoist cable tips	788 43	AR 750-1 revised	783 61
Newsletter	787 43	CALL handbook 18-12 available	793 52
MORTARS		CALL radio system handbook	784 51
M120A1--Breech cap, don't use hammer	790 40	Cold weather equipment TMs available	782 60
M120A1, M121--Bipod lubing, PMCS	789 44	Combat skills GTAs	793 48
M252A1--MWO causing cracks, rust	788 40	Command post tablet TMs	782 61
MOUNT, WEAPONS		EMS newsletter URL	790 61
M66--Ring mount kit change (773-27-35)	782 40	M334 decon kit TM available	787 61
M153 CROWS II--Cocking bracket	788 42	NCO Journal moves to new website	789 60
M153 CROWS II--Diagnostic kit	786 21	PAAWNS SATCOM TM released	791 47
		Property Accountability newsletter URL	789 60

Subject	Issue/Pg	Subject	Issue/Pg
STT TMs released	791 47	SIGHTS & SCOPES	
TC 6-02.20 released	790 49	Lenspen for cleaning sights and NVDs	789 45
TB 43-180 released	790 25	M150, ACOG--Turn-in info	790 40
TM shortages affect readiness	783 56	M151--Turn in for MWO upgrade	785 37
UHST TMs published	788 61	SLAVE CABLE, NATO	
RADIAC EQUIPMENT		Various length NSNs	789 15
AN/UDR-13--Beeping problem from software	782 42	SMALL ARMS	
AN/VDR-2--Probe/base serial number match	782 43	Amnesty box fabrication	793 20
Q&A	782 43	Bore snake/cleaning rod, lubing, front sight...	789 42
RADIO SET, GENERAL		Camouflage paint info	787 40
CALL radio system handbook	784 51	Caps, plugs and bags NSNs	783 42
Harris radio installation instructions	793 49	Cleaning, how often?	784 41
RADIO SET, SINCGARS		Cleaning tank tips	784 42
PLS radio installation kit	787 49	Degrease weapons before using SFL	792 36
Radio frequency cable (W2) connecting	792 52	Desert Do's and Don'ts	786 24
RT-1523E--Installation help	787 48	Inspect before and after transferring	792 38
RIFLE, M3		LARs, MWOs, gaging, clean and lube...	785 40
TMs now available	787 38	Lube guide	784 36
RIFLE, M16-SERIES		Lube instructions, uncocked for storage...	787 36
Action spring length	783 36	Operator's manual, maint forms, mods	791 42
Bore clearing, rod instructions	784 38	Property book info on serial numbers	793 22
Cleaning kits and replacement components	790 36	Rack security	782 39
Front sight tool, buy or fabricate	792 38	SFL paint pen NSN	787 38
Magazine PM	783 38	SFL paint pen NSN	793 21
Polymer magazines available	784 40	SMR code check for turn-in	787 39
Usable on codes (UOC)	792 35	STORAGE	
RIFLE, SNIPER		Warehouse pallet racks	786 49
Advanced ballistic weather meter	783 37	SUGGESTION PROGRAM	
SAFETY		Soldier Enhancement Program (SEP)	792 48
Exertional heat illness, signs and symptoms	788 22	SUPPLY, GENERAL	
Fire extinguisher recall	791 54	Data plates needed for proper inventory	792 50
Noise hazards defined	793 46	Hardware catalogs	784 47
Wiley X Valor lenses recalled	784 48	Shelf life help	788 24
SATELLITE COMMUNICATION		Special packaging instructions (SPI) info	790 60
AN/TSC-154A--ALPS maintenance website	782 51	SURVEILLANCE SYSTEMS	
AN/TSC-183A--PN correction (780-47)	783 60	AN/TAS-8 LRAS3--Purging procedure	782 53
PAAWNS TM released	791 47	TANK, M1-SERIES	
STT cover NSNs	793 50	Ammo compartment corrosion protection	784 03
STT TMs released	791 47	Battery drain prevention	783 03
TEIP adds more C4ISR equipment	789 50	Battery PM	787 08
Terminal reflector paint	789 47	DSESTS--Store CSFM before collapsing	793 26
UHST TM published	788 61	Engine oil clogged filter warning light	788 04
WIN-T--STT towing information	782 52	Final drive filler cap vent, plug torque	791 02
SHELTERS		Fire extinguisher service life extended	791 61
JECP SKI TM available	793 47	Hub cap installation	783 06
SHOP EQUIPMENT		Muzzle cap prevents rust, obstructions	788 03
M1022/A1 Dolly Set--Hydraulic fluid change	783 61	Tarp, full coverage	789 07

Subject	Issue/Pg	Subject	Issue/Pg
Turret basket screens, keep tight	783 04	A/C console louver damage	786 13
TEST EQUIPMENT		A/C console louver damage correction (786-13)	790 61
DSESTS--Store CSFM before collapsing	793 26	Bumper guide rod instructions	782 11
SWICE online training	793 59	Front bumper, lifting shackle parts info	792 13
TMDE, MSD move to milSuite	792 56	Headlight drain hole info	793 12
TIRES		Side marker light bulb replacement	784 14
Tire assembly shelf life code explained	789 11	Tow bar bracket, spring washer NSN fix	793 60
Tire shelf life, service life	788 14	Under seat storage	782 12
Tire shine products unauthorized	791 15	Windshield delamination Q&A	790 14
TOOLS		TRUCK, FMTV	
Hardware catalogs	784 47	100-amp alternator replaced	783 14
Hardware fastener catalogs	783 61	A1P2--Turn signal switch NSN	791 61
Jack stand FAQ	783 46	A1P2 LTAS--Cab lift cylinder NSN	792 61
SATS--Corrosion, generator weight...	792 41	A/C compressor belt seizing	787 11
Silicone spray, grease for rubber parts	787 41	CTIS air hose leak detection	792 14
Special tools go on hand receipt	785 47	Headlight drain holes not allowed	793 12
TK-101/G--Component listing	790 52	LMTV hydraulic tank NSN	792 15
TRACTOR, D6K		TRUCK, HEMTT	
Winch clevis, don't secure to tow pin	789 17	A2 Models--Boom control valve NSN	793 15
TRACTOR, D7E/F/G/R		A4 Models--Distribution manifold NSNs	792 61
D7R II--Fuse box corrosion	789 16	A4 Models--Weapon mount not authorized	785 15
D7R II--Messenger display codes important	793 45	Fuel tank repair kit change	792 61
D7R II--Parking brake engaged for start	793 45	Load test guidance	793 60
D7R II--Stabilizer mounting bolt replacement	793 44	MEL update	793 14
D7R II--Start up right to save turbocharger	782 17	TRUCK, M915-SERIES	
D7R II--Winch clevis, don't secure to tow pin	789 17	M915A5--Front speed sensor NSN	783 60
TRAILERS		M915A5--Oil change intervals	783 15
Linseed oil to preserve decks	782 60	M915A5--Radiator NSNs	787 61
M149A2--Brake hose assembly NSN	782 61	M915A5--Rear wheel seal NSN	787 61
M149A2--Landing leg NSN	793 60	M915A5--Taillight NSN	783 60
M149A2--Manhole gasket replacement	786 12	M915A5--VORAD sensor, bracket NSNs	782 60
M149-Series--Water only in tank	786 11	M915A5--VORAD side sensor NSN	783 60
M149A2, M1112--Diesel heater kit	790 61	M915A5--Windshield NSNs	783 60
M1101, M1102--Brake master cylinder cap	787 15	M917A2--Tire & wheel assembly components	782 15
Wheel assembly NSN correction (766)	790 61	TRUCK, M1070 HET	
TRAILERS, SEMI		A1--Axle breather PM	788 13
Linseed oil to preserve decks	782 60	A1--Belt tensioner NSN	787 61
M870A1--Hub wheel left out of conversion kit	787 14	TRUCK, PALLETIZED LOADING (PLS)	
M870A1--Wood decking kit	782 61	A1 Models--Distribution manifold NSNs	792 61
M1076/A1--MEL update	793 14	A1 Models--Engine control unit NSN	787 61
TRAINING		A1 Models--Weapon mount not authorized	785 15
Armorer training support package	785 59	CHU, E-CHU--MEL update	785 11
Army training devices catalog released	793 47	E-CHU hydraulic manifold NSN	783 60
TRANSPORTATION		E-CHU roller beam parts	783 60
Bradley OCONUS rail transport info	793 02	Flatrack ratchet strap replacement NSN	783 15
TRUCK, 1 1/4-TON, HMMVV		Maintenance team email address	793 15
Accelerator pedal linkage lubing	785 13	MEL update	793 14
		Radio installation kit NSN	787 49

Subject	Issue/Pg	Subject	Issue/Pg
TRUCKS, GENERAL			
B-Kit accountability	790 58	Coolant, fluids, hub oil	785 03
Cargo cover bulk tie-down cord	793 61	EA seat shear pins	790 04
CBRN filter replacement	789 14	EA troop seats, no storage underneath	793 07
Jack stand FAQ	783 46	Engine coolant checks	786 06
Rust Busters tip of the month, #1	782 14	Engine hatch gas springs	790 02
Rust Busters tip of the month #2	783 11	Engine oil copper levels	792 08
Rust Busters tip of the month #3	784 11	Engine rpms, keep below 2,900	789 05
Rust Busters tip of the month #4	785 12	Hub nut tightening sequence	789 04
Rust Busters tip of the month #5	786 14	M1127, M1131A1--GLU switch damage	788 08
Rust Busters tip of the month #6	787 12	M1128 MGS--Gun tube pitting	782 07
Rust Busters tip of the month #7	788 10	M1129, M1133, M1134--EA seatbelt buckle	792 05
Rust Busters tip of the month #8	789 12	M1129E1, M1252--Mortar tube inspection	790 06
Rust Busters tip of the month #9	790 11	M1134 ATGM--Basic Skills Trainer tips	791 40
Rust Busters tip of the month #10	791 10	M1134 ATGM--MITAS BITS	787 42
Rust Busters tip of the month #11	792 10	M1134 ATGM--TOW sight door damage	783 08
Rust Busters tip of the month #12	793 10	M1135 NBCRV--CBMS, SIM, PMCS...	791 35
Wheel lift for mounting tires	785 14	M1135 NBCRV--PM tips	787 44
Winter storm vehicle preparation	792 12	Rear service brake reservoir draining	792 07
		Towing procedures	792 06
		Voltage regulator cable caution	793 08
VEHICLE, FIGHTING, M2/M3 BRADLEY		Wheel hub fill plug O-ring	783 07
AFES hydrostatic test interval	793 05	Wheel hub fluid contamination	782 09
Ammo box covers vibrate loose	789 03	Wheel hub leaks	782 08
Idle wheel nuts loosening	791 05	Wheel hub seals, wire cutter, exhaust cover...	787 04
M242--91F only repairer allowed	787 06		
M242--Gun card mandatory	786 08	VEHICLES, COMBAT	
OCONUS rail transport info	793 02	LRUs, check for serviceability before turn-in	787 03
Periscope thumbscrew rust	790 09		
Transmission oil dipstick gasket	791 04	VEHICLES, GENERAL	
		CBRN filter replacement	789 14
VEHICLE, RECOVERY, M88-SERIES		Jack stand FAQ	783 46
A1--Boom pivot pin lubing	784 08	Rust Busters tip of the Month #1	782 14
A2--Engine oil check 2 hours after shutdown	791 07	Rust Busters tip of the month #2	783 11
A2--Ground hop kit components	782 61	Rust Busters tip of the month #3	784 11
A2--Heater exhaust tube check	792 03	Rust Busters tip of the month #4	785 12
A2--Tarp for complete vehicle coverage	791 06	Rust Busters tip of the month #5	786 14
A2--Tow bar inspection, replacement	792 02	Rust Busters tip of the month #6	787 12
Hydraulic wrench PM	782 04	Rust Busters tip of the month #7	788 10
Spare roadwheel rust prevention	785 08	Rust Busters tip of the month #8	789 12
Stow boom to stop hydraulic problems	782 05	Rust Busters tip of the month #9	790 11
Towing app to improve recovery operations	788 05	Rust Busters tip of the month #10	791 10
Towing app to improve recovery operations	793 61	Rust Busters tip of the month #11	792 10
Track end connector, center guide PM	793 06	Rust Busters tip of the month #12	793 10
Winch cable kinking	785 09		
		WATER SUPPLY	
VEHICLE, STRYKER		Hydration systems	786 50
AC inverter access door, keep closed	782 06		
Alternator troubleshooting	789 06	WELDING	
Brake chamber exhaust hose, two wrenches	786 07	Gas cylinder ordering, returns	783 44
Cargo net NSNs	790 07	WIRE AND EQUIPMENT	
		Cable & wire handbook released	790 49