


GET EAWIS SOFTWARE UPDATED



Encrypted airborne wireless intercommunication system (EAWIS) may need a software update.




Check EME Front and Back




Check IAIU Front

Inspect your aircraft now and record the software being used on the handheld enhanced mobile equipment (EME) and the integrated aircraft interface unit (IAIU) located on the main EAWIS hub in the cabin overhead. Submit that information to PM Air Warrior (PM-AW) to make sure the systems have the latest software.



Verify EME has latest software update label on back of EME



Verify IAIU has latest software update label on front of IAIU

Contact POCs for help.



Contact PM Air Warrior for arrangements on upgrade guidance. The POC is Michael Carpenter, contact him by email at: michael.w.carpenter4.civ@mail.mil

For Air Warrior information, check out their website at: <https://airwarrior.peoavn.army.mil>