

PS Magazine Index No. 75

Issue 794 (Jan '19) — 804 (Nov '19)

Subject	Issue/Pg	Subject	Issue/Pg
AIR CONDITIONERS		Hoist training offered	802 19
R438A refrigerant NSNs	800 61	Internal rescue hoist lanyard length	802 18
AIRCRAFT ARMAMENT SUBSYSTEMS		IVHMU battery cover screws	796 24
Aircraft Armament Repairer Tool Kit (AARTK)	801 20	IVHMU underwater beacon	796 23
M144--Ammo can MWO problem check	794 23	Parts list for turn-in	795 26
M230--Loading procedures	800 22	Parts list for turn-in	800 26
AIRCRAFT ENGINES		Parts list for turn-in	801 23
T700 engine plugs	799 21	Parts list for turn-in	801 25
T700-series cold section module check	800 24	Rescue basket skid shoes approved	804 26
AIRCRAFT, GENERAL		Rescue hoist vest approved	801 22
AMCOM corrosion team training offered	799 22	Searchlights with dissipation issues replaced	802 21
AN/APR-39A--New processor added	801 26	Tail rotor retention plate bolts	795 21
Aviation safety email help	802 60	AIRCRAFT, UAV	
Corrosion treatment help	797 24	Raven--MWO changes NSN	797 26
CPC protects aircraft electrical connectors	800 25	Shadow--TM, pitot tube/CRS antenna, space..	801 23
FOD responsibility	804 21	Shadow--UGCS, AVT shelter tow hitch use	803 24
PEO Soldier social media contact info	799 20	TB 43-0002-3 covers UAV MELs	794 26
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		AIRCRAFT, UH-60, BLACK HAWK	
AAFARS--Collapsible fuel drum	804 24	AN/PRC-117F SATCOM B-kit turn-in	803 27
ALUMMC headlight assembly NSN	797 23	EAWIS resistors improved	803 21
Aviation crash kit NSN and components	798 38	EAWIS software update	796 26
Composite repair kit tools	802 20	EBAPS may need part number change	802 22
Trailer repair parts	799 26	Engine a no-step zone	794 22
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		Engine oil level caution	795 25
ALSE shop setup help	799 25	External rescue hoist fairing mod	803 26
Aqualung breathing device inspection	794 24	External rescue hoist washer change	802 17
Flexible body armor NSNs	804 25	Gas turbine APU turn-in	796 25
AIRCRAFT, AH-64, APACHE		Hoist slide-loks modified	801 24
Engine a no-step zone	794 22	Hoist training offered	802 19
Engine oil level caution	795 25	Internal rescue hoist lanyard length	802 18
HADS probe cover	795 24	Internal rescue hoist TM available	803 25
MUMT support	799 23	IVHMU battery cover screws	796 24
MUMT transport tracking	799 24	IVHMU underwater beacon	796 23
NIU protection from moisture	796 22	Parts list for turn-in	795 26
AIRCRAFT, CH-47D/F, CHINOOK		Parts list for turn-in	800 26
EAWIS software update	796 26	Parts list for turn-in	801 23
ILCA jam test tool blueprints	794 20	Parts list for turn-in	801 25
Spyder crane info, TM	798 40	Rescue basket skid shoes approved	804 26
Two-wheel tow bar info, parts	795 22	Rescue hoist vest approved	801 22
AIRCRAFT, HH-60M, BLACK HAWK		Tail rotor retention plate bolts	795 21
AN/PRC-117F SATCOM B-kit turn-in	803 27	Turn-in credit reversal fix	798 35
EBAPS may need part number change	802 22	AIRCRAFT, UH-72A, LAKOTA	
ECS system, no service w/o certification	797 22	Erosion, corrosion prevention	803 22
Engine a no-step zone	794 22	Rescue hoist hooks	804 22
Engine oil level caution	795 25	AMMUNITION	
External rescue hoist washer change	802 17	Brass, pick up after firing at range	801 38
Hoist slide-loks modified	801 24	ARMORED COMBAT EARTHMOVER, M9	
		Apron, dozer and blade parts	804 61

Subject	Issue/Pg	Subject	Issue/Pg
Battery switch to 6TAGM Hawker	802 60	Coolant, engine start/shutdown, air cleaner...	802 08
Hatch hinge lubing	802 45	Exhaust manifold, cover rust and dry rot	799 06
Hydraulic fluid check	804 60	Fan gearbox oil level check	794 05
Hydraulic kit NSN	804 61	Hatch locking pin	798 09
AVLB, M104 WOLVERINE		M1064--Ramp pulley housing damage	798 10
Bridge workout a monthly task	797 09	Smoke grenade launcher tube covers	795 07
BACK COVER		CBRN EQUIPMENT	
Don't Have Time to Schedule Maintenance?	801 62	Graphic training aids for equipment help	794 43
Don't Let Tools Trip You Up!	797 62	ICBM 400, M49 gas filter expiration info	800 37
Don't Ship Us Like This!	802 62	JACKS website for CBRN alerts, info	796 43
Ins and Outs of Operator Maintenance	798 62	Shelf life vs service life explained	798 47
Let Tool Guide Be Your Guide	800 62	CLOTHING	
Make PM a Monumental Priority!	795 62	Army Certification Program	801 52
Make PMCS a Team Effort	804 62	CLOTHING, PROTECTIVE	
Nothing's Scariest than Bad PMCS!	803 62	JSLIST--Hood tightness fix	795 44
PMCS Trivia	796 62	COLD WEATHER	
Times Change and Your Batteries Should, Too	799 62	Cold injury prevention tips	804 58
What 'chu Lookin' at, Dawg? (PS mobile app)	794 62	COMMERCIAL CONSTRUCTION EQUIP (CCE)	
BATTERY, HAWKER		CAT parts, how to find	798 24
Dead battery charging trick	803 15	CAT service kit NSNs	797 17
BATTERY, LEAD-ACID		Key and key blank NSNs	800 16
Bituminous compound for battery boxes	804 60	MEL changes	794 17
Terminal cover NSNs	804 61	Service kit NSNs	798 12
BATTLE DAMAGE AND REPAIR (BDAR)		Tire wear guidance	801 19
Tire repair kit	799 08	Turn-in instructions and key notes	794 16
BODY ARMOR		COMMUNICATIONS EQUIPMENT	
IOTV Gen IV TM available	796 61	CECOM customer service contact info	799 61
CAMOUFLAGE		ESD causes, prevention	794 47
ULCANS--Only authorized camo netting	801 49	TEIP name change to C5ISR CLAT	799 60
CAN, FUEL		COMPUTERS & SOFTWARE	
Inspection, 5-year lifespan	799 52	Airspace work station TM available	796 53
NSNs, markings	802 52	MSD, issues with loading ETM/IETMs	802 27
CAN, WATER		COMSEC EQUIPMENT	
NSNs, markings	802 52	Crypto support portal	797 60
CARBINE, M4-SERIES		KG-175D--Clock drift, battery life	800 45
Front sight post detent lube	800 42	TSEC/KY-58 TM available	796 53
Inspection for dirty, unlubed weapons	800 40	CONTAINERIZED KITCHEN	
M12 rack fitting	803 42	A/C condenser guard	800 50
Ripcord barrel cleaning tool	801 42	Condensation, carbon monoxide, wiring...	801 50
Sling NSNs	804 37	New TMs released	796 61
CARRIER, COMMAND POST, M577-SERIES		Safety and PM tips	795 53
5-kW APU PMCS checks	794 06	CONTAINERS	
A3--APU fuel line NSN	800 61	Inspection a unit responsibility	799 52
CARRIER, COMMAND POST, M1068-SERIES		CONTINUITY	
5-kW APU PMCS checks	794 06	Crushing the ETM/IETM MSD Conundrum	802 27
A3--APU fuel line NSN	800 61	Dust Driver	798 27
AS-4701/VRC loop antenna stowage	797 35	Leaders Train PMCS!	800 27
CARRIER, PERSONNEL, M113 FOV		M240, M249: Secrets for Success	797 27
6V53 engine oil filter NSN	804 60	Max Torque: The Maltese Longjohns, Pt 1	795 27

Subject	Issue/Pg	Subject	Issue/Pg
Max Torque: The Maltese Longjohns, Pt 2	796 27	FORMS, GENERAL	
New Beach City Vice	799 27	DD Form 1348-6 email change (789-24)	795 61
PM Keeps You in the Fight! (Bradleys)	801 27	DD Form 1348-6 for parts without NSNs	797 56
CORROSION		FORWARD REPAIR SYSTEM, M7	
Desiccant bags absorb moisture	795 56	Crane PMCS, rotation gear, exhaust cap...	799 46
UTAP corrosion resources	801 13	Hydraulic hose checks	798 49
CRANES		GENERATORS, LARGE	
LRT-110--Oil sending unit NSN	802 60	150-kW--Service kit NSNs	798 12
LRT-110--Rear wheel cylinder NSN	796 61	ATP 3-34.45 released	796 55
DECON		MEL listing	800 46
M26--Engine, water pump oil NSNs	794 42	Power generation training pub	797 61
M26--Starter replacement w/instructions	800 39	PU-822A DRASH--Speed switch faulty	796 54
DETECTOR, CHEMICAL		Service kits, parts listing	800 48
M4/M4A1 JCAD--Seal components	800 38	GENERATORS, SMALL	
EDITORIAL		5-kW MEP-1030--Paralleling cable NSN	803 50
Ask for Help!	797 01	5-kW TQG--Exhaust muffler gasket NSN	802 49
Back to Basics Readiness	802 01	ATP 3-34.45 released	796 55
Change Is Good!	799 01	MEL listing	800 46
Everyone's Responsible for FOD Control	796 01	MEP-831A, -832A 3-kW--Engine NSN	800 61
Memorial Day	798 01	Power generation training pub	797 61
Modern Note in an Old Song	800 01	GLOBAL POSITIONING SYSTEM (GPS)	
Ownership of the Vehicle	795 01	DAGR--Return & replacement info	804 50
PS Magazine-The Evolution Continues, Pt 1	803 01	GRADERS	
PS Magazine-The Evolution Continues, Pt 2	804 01	120M--Articulation lock pin...	798 25
What Do They Really Know?	801 01	120M--Battery disconnect switch	799 19
Wrecked by Neglect	794 01	120M--Battery drain prevention	797 18
ELECTRICAL, GENERAL		120M--Cab safety	802 47
MK-3413/U maintenance kit TM	804 49	120M--Cab step caution, circle drive hose	799 17
Solder, lead required	797 50	120M--Cab upper door stop adjustment	803 18
ENVIRONMENTAL CONTROL UNITS (ECU)		120M--Hydraulic hose leaks	797 19
60K-BTU IECU--Vinyl cover NSN	799 50	120M--Joysticks not a handhold	798 26
ECU/FDECU turn-ins needed	803 48	120M--Shank storage	801 18
IECU--Use legacy ECUs until fielded	800 54	120M--Tandem drive oil check	799 16
R438A refrigerant NSNs	800 61	GRENADE LAUNCHER, M320	
EXCAVATOR, HYEX		A1--Sight support cracks	803 44
230LCRD--Engine types	794 19	GROUNDING	
Hydraulic hoses, walk back on reel	800 19	TC 6-02.6 grounding techniques released	794 61
Swing bearing ring gear cleaning, lubing	802 46	GUN, MACHINE	
FORKLIFTS		M2/M2A1--Accelerator wear, coating...	801 40
ATLAS--Hoist boom cylinder hydraulic hose	803 61	M2/M2A1--Loading instructions	803 40
ATLAS--Wheel assembly correction (766-15)	795 61	M2/M2A1--Mandatory parts replacement	801 39
ATLAS II--Floodlight NSN	803 61	M2/M2A1--No bolt slam when unloaded	798 46
ATLAS II--Fuel pump NSN	802 61	M2/M2A1--Receiver NMC checks	794 36
ATLAS II--Parking brake pad NSN	803 19	M2/M2A1--Spade grip NMC if loose	794 38
ATLAS II--STE/ICE-R bolt NSN	798 61	M2/M2A1--Training, differences	804 38
M4K--Horn NSN	801 16	M2A1--Armorer checks headspace (794-38)	800 43
M10A--Wiper motor kit	800 61	M2A1--Barrel cap needed with BFA	796 36
RT-022 LCRTF--Starter cranking	797 21	M2A1--Barrel installation check	794 35
RT-022 LCRTF--Tire air pressure	798 21	M2A1--Bolt erosion criteria	803 41

Subject	Issue/Pg	Subject	Issue/Pg
M2A1--Flash suppressor, no anti-seize	797 41	LASER RANGEFINDER	
M2A1--Headspace and timing still required	794 38	AN/PED-5--Protective eyepiece filter MWO	799 39
M2A1--Visual user guide download	800 43	LIGHTING SETS	
M240--Buffer assembly cracks	801 39	DISE, PDISE--MEL list	800 46
M240--M80A1, M62A1 ammo, no changes	796 37	LOADER, BACKHOE (BHL)	
M240, M249--Finish standards changed	800 44	Battery PM	797 20
M240, M249--Gas system, scraper, BFA...	797 27	Bucket, rest on wood board when not in use	801 16
M249--Barrel collar movement	802 39	HMEE-1--Bucket pivot pin lubing	795 16
M249--Extractor pin check, no kicking	801 34	HMEE-1--Bucket, lay flat to keep water out	795 17
M249--Feed box support kit update (793-19)	802 40	HMEE-1--Egress window knob corrosion	796 20
M249--Scraper NSN change	798 46	HMEE-1--Tire and wheel assembly NSN	799 60
M249--Scraper NSN change	804 60	Repair parts, maintenance support	803 61
M249--Slamming feed cover causes damage	796 35	Transmission oil NSNs	800 17
MK 19--Feed tray cover, sight bar, charging	804 40	LOADER, SCOOP-TYPE	
MK 19--Rear sight replaced	799 40	966H--Joystick NSN	800 61
MK 19--Round removal tool required	799 39	966H--Quick-coupler parts NSNs	803 16
HARDWARE		LOADER, SKID-STEER, BOBCAT	
Bench stock help	803 58	M400W--Battery drain prevention	798 26
Lock washers, torque wrench, lockwire...	795 40	M400W--Cab door sensor drains batteries	803 17
HAZARDOUS MATERIALS & WASTE (HAZMAT)		M400W--Locking lever, debris in latches	796 21
Absorbent compound NSN	799 60	M400W--Rear cab bolt replacement	796 21
DAU HAZMAT website	797 59	LOCKS	
Drip pan NSNs	804 61	Safe combination security	803 51
PSCC help for shipping, storage	803 58	Series 200 padlock control	803 59
Spill kit NSNs, components	796 48	LOGISTICS ASSISTANCE	
Warning labels, shipping placards explained	794 56	AESIP, adding UICs	798 54
HEATER, SPACE		COMET POC	804 41
Maintenance a year-round effort	803 52	Deployer's toolbox	799 54
HELMETS, AVIATION		DLA-DS locations	801 61
AAIH, HGU-56P--Zeta III liners available	800 20	DLA handbook	798 60
AN/AVS-7 HUD TM available	796 55	DLA RTD program	803 55
HOWITZER, SP, M109A6/A7 PALADIN		ETID registration for DLA turn-in	801 55
Cradle mount bearing lube points	803 04	Property turn-in with DD Form 1348-1A	798 56
Fallback prevention tips	801 02	Safety, maintenance message web locations	798 58
HOWITZER, TOWED, M119-SERIES		UIC transfer help	802 57
A2--Equilibrator spring damage	795 08	LOGISTICS MANAGEMENT	
A3--Firing pin sticking	803 05	AR-COP training	796 58
HOWITZER, TOWED, M777A2		DEMIL codes defined	804 56
Hydrostrut cylinder corrosion	794 03	GCSS-Army--Help desk website	797 59
Loading tray piston swivel eye loosening	794 04	GCSS-Army--Serial number profile	804 59
INSECT REPELLENT		GCSS-Army--SLOcs w/T-code printing	799 57
Deet-free repellent available	799 49	GCSS-Army--Storage codes	800 56
INTERCOM SETS		GCSS-Army--Transaction codes defined	804 55
AN/VIC-3--Power cable arcing	803 46	GCSS-Army--Unit of issue changes	799 56
KITCHEN EQUIPMENT		GCSS-Army--Warehouse activity monitor	802 58
Field sanitation team not required (794-53)	797 60	TMC/MCS added to MMDF	794 60
MBU--Dust protection tips	797 46	MASK, PROTECTIVE	
MTRCS--Top engine panel doors, rain cap	804 42	JSGPM--Carriers disappearing	802 42
MTRCS--Rollers, locking pins/clips missing	800 49	JSGPM--Faceform, outsert pouches	803 45

Subject	Issue/Pg	Subject	Issue/Pg
JSGPM--JSLIST hood too tight	795 44	MOUNT, WEAPONS	
M53A1--TM with parts list	804 43	FMTV LTAS ring mount components	799 44
Night vision device use and training	798 48	M153 CROWS II--Clearance issues	803 38
MATERIAL HANDLING EQUIPMENT		M153 CROWS II--Cover NSN changed	799 61
MEL updates	798 22	M153 CROWS II--Cover NSN changed	801 41
POC emails	797 60	NIGHT VISION EQUIPMENT	
MEDICAL EQUIPMENT		AN/PSQ-40--TM available	803 49
Repair parts in GCSS-Army	802 53	AN/PVS-14--Eyeguard vs eyeshield (788-59)	794 61
MINE CLEARING EQUIPMENT		Protective mask use and training	798 48
Buffalo--Emergency door, keep closed	797 19	PACKAGING	
Buffalo--Generator NSN	794 61	COSIS instructional videos	803 59
Buffalo--Water draining tips	796 16	LLRC inspection tips	802 55
M7 Spider--Battery tips	803 39	Packaged items, keep sealed until needed	797 55
M1231 Husky--Air dryer filter change interval	795 20	Strapping and sealing kit NSNs	797 44
M1231 Husky--Component maintenance help	804 20	PARACHUTES	
M1231 Husky--Fuel system contamination	796 19	T-11--Slider mesh panel criteria increased	800 52
M1231 Husky--Steering wheel clip	798 22	PAVING MACHINE	
M1270 MMPV--Talon robot parking	795 18	8816M BMPM--Air filter cleaning	801 17
MINE DETECTOR		8816M BMPM--Cold weather starts	804 16
AN/PSS-14--Turn-in request	794 43	8816M BMPM--Conveyor grease fittings	804 17
MISSILE, AVENGER		PISTOLS	
Caps/covers, tarp, NATO cable, CDT...	797 36	M9--Ammo, holstering, safety	797 40
ECU/PPU, use as primary power source	795 42	M9--Recoil spring flat spot criteria	801 38
MISSILE, HELLFIRE		M17/M18 MHS--Introduction	801 36
Launcher, loading and missile tips	802 35	POL	
MISSILE, HIMARS		Drip pan NSNs	804 61
AS-4701/VRC loop antenna stowage	797 35	Petroleum ops smart book	803 54
Hoist cable positioning	803 34	USAPC website	804 57
MISSILE, JAVELIN		POWER SUPPLY	
CLU protection in the field	796 38	X60M 60-KW--TM with enhanced videos	801 48
MISSILE, PATRIOT		PS MAGAZINE	
15-kW generator oil drain fitting	794 41	milSuite group added	800 53
Air filters, keep extra sets on hand	799 38	POC for article suggestions	804 57
AN/MPQ-65/A--CLET filter cracks	794 40	PS Mag Live	801 47
Connector caps, keep in place	797 39	Search engine instructions	796 44
Data recorder, ECH handle, PAC 2 MCU...	804 36	What'chu Lookin' at, Dawg? (PS mobile app)	794 62
Moisture, fiber optic cables, J4/J10/J11 cables...	803 35	PUBLICATIONS	
MISSILE, THAAD		AN/GYK-78B(V)3 TM released	803 49
PMCS, coolant leaks, antenna unit grounding...	799 35	AN/TPX-57(V)1 & 2 interrogator set TM	802 61
MLRS		AN/TSQ-232 TM correction	794 44
AS-4701/VRC loop antenna stowage	797 35	AN/TSX-4 TM revised	798 61
Cab lift, hoist pulley, hoist markings	796 40	AN/TYS-94H(V)2 TM	803 49
Hoist cable positioning	803 34	Army Sustainment goes quarterly	804 57
Shock absorber PM tips	795 06	ATP 4-25.12 provides sanitation guidance	794 53
Transmission housing cleaning	798 08	ATP 6-02.54 released	794 61
MORTARS		EIR digest	795 61
M120/A1--Firing pin alignment explanation	795 35	ICIDS-V TM available	802 49
M120/A1--Gun card updated for tracking	796 37	IHPS TM available	804 43
		Kit! Magazine	795 61

Subject	Issue/Pg	Subject	Issue/Pg
PM Bridging Newsletter download	802 61	SIGHTS & SCOPES	
TB 43-0002-3 covers UAV MELs	794 26	Lithium batteries, use only if TM allows	797 53
TB 43-0134 updated	795 61	M68--NMC if ARD is missing	797 42
TB 43-180 revised	795 61	M68--Windage/elevation caps, cleaning...	802 38
TB 55-46-1 updated	797 55	M150--Lens cover NSNs	794 39
TC 3-04.71 released	796 61	M150--Tritium leak check	799 41
TC 6-02.6 grounding techniques released	794 61	Sight/weapon mix explained	803 28
TM 10-6130-523-10 released	795 61	SMALL ARMS	
RADARS		Acetylene torch not allowed for stuck parts	802 42
AN/TPQ-50--TM available	804 49	CCMCK cleaning reminder	802 41
Sentinel--Voltage, cybersecurity, cleaning...	798 42	CCMCK dangers explained	795 36
RADIAC EQUIPMENT		Controlled parts, statement needed for damage	794 39
AN/PDR-77--Pancake probes defective	799 48	Gaging not required for new weapons	797 43
RADIO SET, GENERAL		Gaging requirement back to 2 years	796 36
AN/TRC-238 radio terminal set TMs released	796 61	Lube not allowed for chamber, bore, ammo	801 35
Connector mating, knob jamming...	804 54	Shipping Do's and Dont's	799 42
Turn-in procedures explained	800 58	SMALL EMPLACEMENT EXCAVATOR (SEE)	
Vehicle power surge damages radios	795 45	Ball joint lubing	800 19
RADIO SET, SINGGARS		SUPPLY, GENERAL	
Installation kits stay with vehicle	796 52	CAGE code POC identification	800 57
RF and synthesizer CCA turn-in	794 44	CAGE codes, identify through SAM	804 57
RIFLE, M16-SERIES		DD Form 1348-6 for parts without NSNs	797 56
Front sight post detent lube	800 42	DLA handbook	798 60
Inspection for dirty, unlubed weapons	800 40	GCSS-Army stock control functions	796 59
M12 rack fitting	803 42	Property, equipment turn-in to DLA-DS	799 55
Ripcord barrel cleaning tool	801 42	Usable On Code (UOC) explained	796 56
Sling NSNs	804 37	TANK, M1-SERIES	
ROBOTS, GROUND		Air precleaner PM	796 06
Talon--Proper parking on M1270 MMPV	795 18	Ammo compartment lubing	798 04
ROLLER, VIBRATORY		Ammo tube round stopper damage	800 04
CS-433C--Seat belt replacement criteria	799 18	Cleaning tips for inside and out	801 08
SAFETY		Crosswind sensor fault caused by insects	800 02
Cold weather injuries	795 59	EMFS water damage	800 03
Eyewear protection NSNs	794 54	Engine exhaust deflector for towing	803 06
Laser myths and facts	795 57	Fire prevention: belly plate, grill doors...	801 06
SATELLITE COMMUNICATION		Gun mount travel lock pin	797 04
AN/FYQ-110C DSCS TM released	797 61	Hydraulic reservoir level check	801 05
AN/TSC-154A SMART-T--Ground rod door	804 48	M1A2 SEP--CROWS WSCP switch guards	797 03
AN/TSC-185(V)1, (V)2--HPA cables	801 46	M1A2 SEP--WTR only lube authorized	801 05
AN/TSC-185A(V)2 fire extinguisher bracket	798 52	Mine Blade--Hydraulic jack replaced	799 60
ATP 6-02.54 released	794 61	Oil types for engines	798 02
SCRAPER, EARTHMOVER, 621G		Parking brake check	802 03
Battery disconnect switch	803 20	Pintle lubing	796 08
Push loading allowed	797 60	Replenisher level, recoil bleeding	795 02
SHELTERS		Shock absorber sight glass cleaning	794 09
Commo--Exterior PM tips	795 50	Skirt hinge points	797 05
Commo--Interior PM tips	795 46	Transmission turn-in	798 61
TAS--NSNs	797 52	Transmission turn-in	800 05
		V-pack cleaning, maintenance	795 04

Subject	Issue/Pg	Subject	Issue/Pg
TENTS		M1101, M1102--Landing leg wheels	804 15
Bed net protects against insects	798 53	M1102--Breakaway cable carabiner NSN	798 61
TEST EQUIPMENT		M1112--Walking beam arm clearance	797 10
AN/GRM-122--Component TMs	797 48	Service kit NSNs	798 12
AN/PRM-36--Lithium batteries not allowed	799 51	XCK2000E1--Tire and wheel assembly NSN	798 61
Fluke multimeters recalled	801 44	TRAILERS, SEMI	
UIC change for TMDE	803 38	Brake chamber dust cap NSNs	800 14
TIRES		Linseed oil for deck preservation	804 61
FedMall tire catalog	794 14	M3/M3A1 CROP--Data plate NSNs	794 11
Tire lube NSNs	804 61	M3/M3A1 CROP--Strap assembly NSN	803 61
Universal high-flow ground tire inflator kit	796 10	M3/M3A1 CROP--Web tie-down straps	794 10
Universal high-flow tire inflator kit accessories	799 60	M3A1 CROP--Wear plates not needed	800 13
TOOLS		M172A1--Hub bearing NSN fix	799 61
Biometric automated toolset TM revised	798 61	M172A1--Hub bearing NSN fix	800 11
Calibration, keep current	802 43	M870A1--Hub & drum kit missing parts	802 60
Component lists, how to find	795 38	M871--Series--Glad hand cover seals	799 12
Don't Let Tools Trip You Up!	797 62	M969--Series--Vapor integrity test	802 61
JGMTK replaces GMTK	802 60	M1000--APU battery solar panel	799 13
Pallet jack NSN	803 61	M1000--APU hydraulic reservoir valve	799 14
SATS--A/C door panel thumbscrew	801 45	Service kit NSNs	798 12
SATS--Component list available	795 41	TRAINING	
SATS--Parts list	804 35	UTAP training materials website	798 20
SECM--Rain tube and gutter NSN	803 37	TRUCK, 1 1/4-TON, HMMVV	
SEW--Repair parts listing	800 36	A/C refrigerant charge weight	801 14
SKOT help desk email	799 61	High seat kit NSNs	797 60
TMDE coordinator online training	804 47	Incandescent vs LED bulbs, mix or match?	795 14
Tool set component lists	800 35	Installation kit for AN/VRC-104(V)5	802 48
TRACTOR, D6K		M1097R1--Special purpose kits	799 61
Platform wiring harness NSN	802 61	M1151A1--Gunner's sling NSN	802 15
TRACTOR, D7E/F/G/R		M1151A1--Gunner's sling NSN	804 60
D7G--Gear shifting precaution	804 19	Slave starting steps	804 10
D7R II--Battery drain prevention	799 19	Tow bar bracket mod	798 18
D7R II--Blade float indicator check	799 60	Turret traversing handle replacement	801 12
D7R II--Hydraulic filter clearance	797 16	Unauthorized modifications	799 10
D7R II--Idling after startup	797 17	Up-armored--Ball joint NSN	803 60
D7R II--Track adjuster O-ring seal	794 18	TRUCK, FMTV	
TRACTOR, D8K		A1/A1P2--Electrical system part NSNs	801 10
Gear shifting precaution	804 19	A1/A1P2--Tire wear indicators	794 13
TRAILERS		A1P2--Door shock absorber NSN	798 17
Cargo net NSNs	804 14	A1P2--EHPU cap NSN	797 61
M149A2--Hose assembly NSN	802 61	A1P2--Lift cylinder NSN	796 61
M149A2--Master cylinder NSN	803 60	A1P2--Window latch NSN	795 15
M149A2--Master cylinder NSN	804 15	A/C belt NSNs	798 16
M1076--Air chamber dust cap NSNs	803 14	A/C refrigerant pressure by temperature	801 14
M1082, M1095--Tire & wheel assembly NSN	803 61	CTIS electronic control module, A0 vs A1	797 14
M1095--ABS light caps	797 61	Door handle parts NSNs	797 60
M1101--Shackle nut NSN	799 61	Gunner's platform NSN	803 13
M1101, M1102--Brake drum NSN	798 61	LTAS--Heater switch NSN	796 13
M1101, M1102--Cover kit NSN	798 61	LTAS--Tow bar decal NSNs	801 11
		LTAS--Transmission control valve module	803 60

Subject	Issue/Pg	Subject	Issue/Pg
M1078A1--Mud flap, splash guard NSNs	803 14	Shock absorber PM tips	795 06
M1087A1P2--Side platform parts list	797 12	Towing techniques explained	800 08
M1089A1P2--20-ton jack, amber light in BII	797 61	Track tension, cdr's hatch, ramp, idler wheels...	801 27
M1157A1P2--HVAC system parts	800 12	Transmission housing cleaning	798 08
Packing wheel bearings	802 14	VEHICLE, MRAP	
Power steering gasket NSN	797 61	Doors, hatches need glow-in-the-dark tape	802 16
Spare wheel assy for trucks	798 15	M-ATV--Cab drain plugs	796 14
Towing FMTV/LTAS vehicles	795 12	VEHICLE, RECOVERY, M88-SERIES	
Transmission parts reversed	803 10	A1--Road wheel arm bearing lube	801 04
Troop seats and safety straps	800 10	A2--AFES PM tips	804 06
TRUCK, HEMTT		A2--Engine fire prevention checks	802 06
Battery liner prevents corrosion	794 12	A2--Engine fire prevention flipbook	801 03
Fuel containment berms	797 15	A2--Engine fires: oil levels and batteries	803 02
Fuel tanker cleaning instructions	803 61	A2--Fuel injection lines faulty	800 06
M978--Main pump motor NSN	798 17	A2--Tarp NSN for full vehicle	794 03
M978-Series--Purging info	804 60	Hatch lever check	798 11
M983A4 LET--Fifth wheel mount screws	800 15	Transmission oil filter mounting bolt sequence	795 09
REBS retrieval cautions	796 18	VEHICLE, STRYKER	
Towing FMTV/LTAS vehicles	795 12	Armor panel damaged by winch cable	800 07
TRUCK, M878 YARD TRACTOR		Brake check before shutdown	797 06
A2--Backup alarm NSN	794 15	Bustle rack, cargo nets for storage	799 04
TRUCK, M915-SERIES		Cargo net NSNs	796 03
M915A5--Front hub rubber fill plug NSN	796 13	Driver's hatch stay device, detent assembly	804 03
M915-Series--Coolant filter kit	800 61	DVE cable routing	796 02
M917A2--Tire & wheel assy components	802 60	Fuel injector line inspection	797 07
TRUCK, M1070 HET		Fuel shutoff switch damage	798 05
A1--Engine fan clutch NSN	794 61	Height management system	804 04
TRUCK, PALLETIZED LOADING (PLS)		Hub seal replacement	803 07
Cold weather pubs, no ether for starts	795 10	ITH headset troubleshooting, repair parts	803 08
M1075-Series--Transfer case training	802 11	M1135 NBCRV--Detection PM tips	804 44
TRUCKS, GENERAL		Start-up and shutdown procedures	797 08
Brake chamber dust cap NSNs	800 14	Steering damper damage, leaks	797 02
Cargo net NSNs	804 14	VV-Hull--Control arm assembly adjustment	794 02
Diesel engine slobber	804 13	VEHICLES, COMBAT	
OGPK transparent armor glass installation	796 09	Service kit NSNs	798 12
Service kit NSNs	798 12	WATERCRAFT	
Universal high-flow ground tire inflater kit	796 10	DA Pam 750-8 update	795 20
Windshield washer fluid	804 61	Diving equipment, boats, motors POC	794 61
VEHICLE, FIGHTING, M2/M3 BRADLEY		M30 BEB--M15 bridge adapter pallet	804 18
DVDB turn-in	803 07	MKII--Artwork correction (794-19)	799 60
Engine access door hydraulic reservoir	798 06	MKII--Bilge drain plug location	794 19
M242--14-pin connector damage	802 04	MK-7 life raft replacements	800 18
M242--91F, recoil damper fluid, lockwire...	799 02	WELDING	
M242--Installation tips	794 07	Gas cylinder turn-in, delivery	802 50
M242--Track & bolt assemblies stay together	794 08	SEW--Repair parts listing	800 36
Oil level checks	804 08	WIRE ROPE	
Ramp and door seal check	796 04	Wire rope NSNs	794 15