

PS Magazine Index No. 71, 2015

Subject	Issue/Pg	Subject	Issue/Pg
AIR CONDITIONERS		Engine accessory gearbox seal kits	748 61
R-134 refrigerant NSNs	751 60	Rotor blade touchup with CARC	757 24
Reclaimed R-22 available	751 42	TS-3920C/ASM CTS calibration fix (742-60)	754 21
AIRCRAFT ARMAMENT SUBSYSTEMS		TS-3920C/ASM CTS needed for turn-in	757 24
134 Mini-gun--Barrel bolt changes	746 24	AIRCRAFT, UH-72A, LAKOTA	
M230 Gun--GMD vs TW-25B for lubing	755 45	Turbine outlet temperature spikes	756 22
M230 Gun--Loading tips	751 22	AMMUNITION	
AIRCRAFT, GENERAL		Dummy rounds easily identifiable	750 49
Acrylic window repair	753 23	Fire extinguishers required for transport	748 42
AMCOM Corrosion Program Office	750 35	M855A1 enhanced performance round	748 40
Aviation Dirty Dozen, Part 1	747 21	M855A1, M80A1 not for live fire shoot houses	748 61
Aviation Dirty Dozen, Part 2	748 21	MK 19 and M203 ammo don't mix	746 37
Don't Let FOD Take You Out!	757 27	Propellant management guide	748 61
FOD prevention program	752 15	Yellow Book available online	747 59
General aircraft TMs	750 22	ANTENNAS, GENERAL	
Hydraulic RSU replacement	753 24	AS-4701--Damage during transport	749 50
Transferring aircraft between units	752 16	AOAP	
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		Labels save time and improve tracking	754 52
CATS tools replace old sets	749 23	ARMORED COMBAT EARTHMOVER, M9	
Equipment movement caution	746 26	Roadwheel damage criteria	754 16
Fix equipment problems before turn-in	757 26	ARMORED SECURITY VEHICLE, M1117	
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		Data plate updated, location info	750 56
PSGC components	751 24	Maintenance questions help by email	751 61
AIRCRAFT, AH-64, APACHE		MWO updates in MMIS	751 61
Canopy window ejection prevention	757 23	Sustainment training from MTTs	755 16
DA Form 2028 to make maintenance changes	746 24	AWARDS	
M230 Gun--Loading tips	751 22	2015 CLEA winners	755 53
AIRCRAFT, CH-47D/F, CHINOOK		BACK COVER	
CARC paint touch-up kits	754 60	Aircraft No-step, No-hand Zones	750 62
Windows, close to protect from elements	749 26	Don't Guess! Use the MSDS!	746 62
AIRCRAFT, HH-60M, BLACK HAWK		FOD Is Your Responsibility!	757 62
Sound-proofing panel, keep in place while packing	751 25	Lighten Your Load with Lithium Batteries	754 62
AIRCRAFT, OH-58D, KIOWA		LOGSAP 746-1, Packaging-the Basics	752 62
Expandable bolt cleaning	752 14	Looking for Training Materials-UTAP	753 62
FOD can, hang on tail stinger for maintenance	751 26	M16/M4 Dirty Dozen	756 62
AIRCRAFT, UAV		Seeing Safety Can Save Your Sight!	747 62
MQ-1C--F-24 approved for use	753 24	Times Change, Batteries Should, Too (Lithium)	751 62
Shadow--GCS and TALS equipment lists	753 26	TM Wise Means PM Wise	749 62
AIRCRAFT, UH-60, BLACK HAWK		Turn Off Vehicle's Battery Disconnect Switch	755 62
DACU stock suspended	757 60	You Can't Take the Cdr Out of Command Maint	748 62

Subject	Issue/Pg	Subject	Issue/Pg
BATTERY, HAWKER		COMPUTERS & SOFTWARE	
Terminal stud kit	747 11	Computer cleaning kit	747 47
BATTERY, LEAD-ACID		CSS-VSAts to Reset for upgrade	757 61
Terminal washer, rubber cover, silicone	750 39	Heat damage, cleaning	753 44
BATTERY, LITHIUM		PQAS-E--Admin password, pass on	751 53
Lighten your load	754 62	COMSEC EQUIPMENT	
Lithium vs alkaline, differences	752 58	AN/PYQ-10--Fill cable, stylus	752 49
Power preservation tips	752 32	Ordering and accounting for COMSEC	754 59
BATTLE DAMAGE AND REPAIR (BDAR)		CONTAINERIZED KITCHEN	
BDAR kit replaces crew/maintainer kits	747 03	Packing to prevent damage	753 49
BINOCULARS		CONTAINERS	
M24--Eyepiece dust cover, objective lens cover	749 61	Blocking and bracing materials, how-to	752 35
CARBINE, M4-SERIES		DLA container calculator	751 60
Dirty Dozen	756 62	Inspection guidance in MIL-HDBK-138B	751 60
Extractor plugged with cotton swabs	750 48	Labels/placards, don't paint over them	752 42
Firing stoppage, immediate vs remedial action	755 44	MILVAN--Collapsible containers, strap/tie-downs	752 22
Individual, improved cleaning kits added	750 46	CONTINUITY	
M12 rack modification made easier	746 40	Attack of the Corrosion Zombies, Part 1	750 27
M12 rack modification, third method	753 40	Attack of the Corrosion Zombies, Part 2	751 27
CARRIER, PERSONNEL, M113 FOV		Clean Up with Cleaning Kit Savings	747 27
Engine, transmission oil level checks	750 08	Cold Weather Hermit	755 27
Final drive oil level check	749 07	Don't Let FOD Take You Out!	757 27
M113A3--IETM now available	746 08	Dukes of HAZMAT	756 27
Oil filter replacement NSN	753 60	Hike the PM Mountain	748 27
Ramp reservoir level check	747 04	Sub Sunk by a Toilet	749 27
Roadwheels: aluminum vs steel	748 09	CORROSION	
Steering control bearing lube	757 08	Attack of the Corrosion Zombies, Part 1	750 27
Track tension gages	747 05	Attack of the Corrosion Zombies, Part 2	751 27
CBRN EQUIPMENT		Types, prevention, inhibitor, pubs	750 40
M4 JCAD--M42 alarm still needed	756 46	DECON	
M4 JCAD--Sieve pack PM	747 41	M12A1--Fuel line installation, NSN changes	755 47
M4 JCAD--Sieve pack shelf life eliminated	748 42	M26--Lube NSN, water pump oil	755 48
M41 PATS--Humidifier adds air particles	749 42	M26--Weight, starter switch, throttle, fuses...	757 43
COMMERCIAL CONSTRUCTION EQUIP (CCE)		EDITORIAL	
AGM batteries for CCE vehicles	749 21	Help Us Help Soldiers	746 01
Diesel vs F-24 use	751 55	Indomitable Foe	750 01
Nuclear density moisture tester PM	757 14	Just Ask Already!	754 01
COMMUNICATIONS EQUIPMENT		Knowledge Is a Powerful Safety Tool	747 01
CAISI 2.0 shifts to sustainment	748 46	Mom, Apple Pie and PM	752 01
CECOM item return addresses	746 58	Pick Up PS Online	753 01
COMPACTOR, 815F		PM Propels Performance	756 01
Air cleaner indicator check	751 58	Protect Yourself Against Heat	751 01

Subject	Issue/Pg	Subject	Issue/Pg
Put Mechanics in the Spotlight	748 01	120M--Wiper motor NSN	757 61
Unauthorized Mods Are Just That	755 01	GRENADE LAUNCHER, M203	
What's in a Name? (PS, not PM)	757 01	Ammo not for use with MK 19	746 37
You're in the Readiness Driver's Seat	749 01	GUN, MACHINE	
EXCAVATOR, HYEX		M2--Trigger block kit component NSNs	757 42
Lubricity filter service interval changed	746 22	M2, M2A1--One model per unit	746 36
Upper support roller lubing	752 12	M2, M240, M249--Barrels, take extras	746 38
FIRE SUPPORT VEHICLES		M2A1--Barrels interchangeable	754 41
M1200--Battery disconnect before maintenance	748 03	M2A1--Flash suppressor for firing only	755 42
M1200--Maintenance questions email help	751 61	M240L--HMMWV mounting authorized	748 38
FORKLIFTS		M240L--HMMWV mounting authorized	748 61
6K VRRT--Steering cylinders too short	757 13	M240L--Long barrel OK for M240B	756 36
ATLAS, 6K VRRT--CLS manuals	756 20	M240L--MWO 9-1005-313-23-2, -4 end early	754 46
MHE-270--Starter flywheel ring gear teeth	752 11	M240L--Short barrel parts	755 43
MHE-270/271--Tire pressure set at 40 psi	752 10	M240-Series--Two barrels required	748 37
FORMS, GENERAL		M240-Series, M249--Carry MG properly	749 41
DA Form 2028, forward to APD	748 61	MK 19--Bolt/back plate assy spring, setscrews	757 40
DA Form 3999-4 phased out	753 34	MK 19--Helical spring NSN correction	753 39
FORWARD REPAIR SYSTEM, M7		MK 19--M203 ammo not allowed	746 37
Exercise crane, moisture, bay doors...	753 41	MK 19--Mandatory parts list eliminated	749 40
FUEL		MK 19--Training, secondary drive lever tool	755 40
F-24 OK for MQ-1C Gray Eagle UAV	753 24	HARDWARE	
GENERATORS, LARGE		Bolts, standard vs. metric	756 38
30-, 60-kW TQG--Keypad assemblies faulty	746 60	Parts bag NSNs	749 60
Faster requisitioning	753 46	Sealing compound NSNs	753 59
GENERATORS, SMALL		Snap rings and pliers NSNs	754 28
3-kW MEP-831A TQG--Alternator screw size	755 51	HAZARDOUS MATERIALS & WASTE (HAZMAT)	
3-kW TQG--Fuel line clamp	756 49	Dukes of HAZMAT	756 27
3-kW TQG--Muffler mounting hardware	752 60	Spill kit NSNs, components	747 48
5-kW TQG--Air cleaner assembly ordering	749 47	HOWITZER, SP, M109A6 PALADIN	
Faster requisitioning	753 46	Damper spring cracks	757 05
GRADERS		M284 gun tube corrosion check, cleaning	750 10
120M--Air filter cleaning	756 19	Tube temperature sensor cleaning, testing	757 04
120M--Articulation lock pin, wheel lean lock...	753 19	HOWITZER, TOWED, M119-SERIES	
120M--Battery disconnect switch	754 18	A2--Exercise, muzzle cleaning, sight mount...	749 08
120M--Cab entry/exit safety	753 21	A2--Gunner's quadrant corrosion	750 37
120M--Engine oil level checks	755 24	A2--M137A2 telescope, stow for travel	752 03
120M--Hydraulic hose wear	752 07	A2, A3--Firing pin retaining pin	751 08
120M--Joysticks not handholds	753 20	A2, A3--Telescope level vial retaining clips	757 07
120M--Starter, ether canister, fuel/water separator	755 23	A3--8W0 power cable design changed	757 06
120M--Tandem drive oil level check	754 18	A3--Firing pin retaining plunger stuck	756 05
120M--Warm up, cool down, hydraulic oil temp	755 18		

Subject	Issue/Pg	Subject	Issue/Pg
HOWITZER, TOWED, M777A2		GCSS-A turn-in credit requests	755 60
Breech, PFM body, tray cleaning	751 06	GCSS-A Wave 2 data cleanup	749 53
Breech ring sector threads inspection	755 09	GCSS-A website, notifications	746 61
Hoist ring assembly circlips	748 08	LMI DST introduction	753 30
IMPROVED TARGET ACQUISITION SYSTEM (ITAS)		TULSA safety, maintenance messages	749 56
Battery charging program critical	747 40	LUBRICATION	
INTERNET		Silicone grease NSN, uses	753 58
milWiki takes comments on Army doctrine	755 58	MAINTENANCE MANAGEMENT	
KITCHEN EQUIPMENT		Brigade maintenance meetings	748 58
Food service equipment PM	757 48	CMDP knowledge center website	748 51
Joint culinary & food services portal	756 51	Maintenance reports = maintenance dollars	755 56
MBU--Venting checks	753 51	MMIS user roles changed	757 54
LASER OBSERVATION SET		MSD-V2 loses Windows XP support	747 55
AN/PVS-6 MELIOS--Carrying case	746 43	MSD-V2 still needed for some IETMs	749 58
LASER RANGEFINDER		PQDR how-to, pitfalls, web submission	750 58
AN/PED-1/1A/1B--Handle with care	755 50	SMR codes explained	756 55
AN/PED-5--Battery cassette installation	752 54	MAINTENANCE, GENERAL	
AN/PED-5--IR switch check	754 48	Kit creation website	747 60
Model 1600--Commercial manual wrong	754 61	Maintenance focus for PMCS	748 54
LIGHTING SETS		Maintenance standards back to basics	748 52
DISE--MEL drops to zero	756 50	Motor stables reward system	748 55
PDISE--Crates can cause corrosion	757 51	Scrap break definition	747 57
LOADER, BACKHOE (BHL)		MASK, PROTECTIVE	
A/C v-belt NSN	757 60	M40-, M42-Series--Contacts/glasses prohibited	746 44
Alternator impeller fan NSN	754 61	M40-, M42-Series--Retaining clamp zip tie	754 49
Backhoe swing lock pin	757 12	M40-, M42-Series--Use, forms, drink tube...	756 44
Tire and wheel must be ordered separately	746 21	M40, M42, M50-Series--Testing exceptions	747 42
Turbocharger priming before startup	751 56	M40-, M42-Series, M50, M51--C2A1 canister	751 19
Warm up, cool down for 2 minutes	751 57	M42A2--Conversion to M40A1 not allowed	755 48
LOADER, SCOOP-TYPE		M50, M51--Operator cards needed	754 50
924H--Light switch NSN replacement	752 09	M-GATOR	
H100C--Air compressor types	757 16	Starter wire placement fire caution	748 17
LOADER, SKID-STEER, BOBCAT		MINE CLEARING EQUIPMENT	
Pallet assembly NSN	747 16	Husky--Detector heads, hydraulic line QDs	757 11
LOGISTICS ASSISTANCE		Husky--Flat-tow only	754 15
AESD-W email address	749 60	M1272 Buffalo--Fluid warmup, access cover...	756 17
LIW user support in theater	757 61	MINE DETECTOR	
LOGISTICS MANAGEMENT		VMR2 Minehound--Strap, head parallel...	755 20
CTA items available for free from SIAD	746 52	MISSILE, AVENGER	
FED LOG available for downloading	753 28	Caps/covers, tarp, track M3P rounds...	757 36
GCSS-A regs updated by ALARACTS	747 56	MISSILE, HIMARS	
GCSS-A training for record	756 53	Blast shield cleaning, water can cover ties	752 48

Subject	Issue/Pg	Subject	Issue/Pg
Brake line fittings, flat-tow, Cdr's hatch...	749 44	Sight storage, batteries, dust cap/neck cord...	756 40
Hydraulic fluid reservoir air drain	755 46	PACKAGING	
ICP cab web sling NSN	746 15	Desiccant NSNs	753 54
Window laminate NSNs	749 43	Heat-sealable bags, sealers	752 24
MISSILE, JAVELIN		LOGSAP 746-1, Packaging-the Basics	752 62
Exercise, storage case, batteries	756 42	PSSC email change	756 51
MISSILE, PATRIOT		Repair parts, keep inside packaging till needed	752 40
AMG strut security	751 14	Shipping material NSNs (Fast Packs)	752 27
Cables, QEAM, grounding, shroud strap...	751 12	Strapping and sealing kits	747 52
Trailer kingpin, data link terminal, radar...	747 36	PS MAGAZINE	
MLRS		65th anniversary toast request	757 60
1W5 cable, fuel filter priming, heater location	751 10	2014 index	746 27
IEDBs needed for turn-in	754 61	Binders for PS archiving	748 57
Link assembly door rod link, track roller checks	752 51	Pick Up PS Online	753 01
Oil filter cover assembly DPI removed	753 04	PS Mag Live	750 20
PTOs needed for turn-in	753 61	PS Mag Live	751 47
Rearview mirror NSN	754 61	Subscription info	750 55
MOLLE		PUBLICATIONS	
Repair instructions	753 48	Ammo Yellow Book available online	747 59
MORTARS		APD website	757 57
120mm--Cannon bore erosion gage set	754 47	AR 1-201 revised	751 61
Baseplate not a step during firing	752 55	AR 56-4 revised	749 60
M23 MBC--Replaced by M32 LHMV computer	746 39	AR 700-20 updated	754 35
M252A1--Now fielding	754 47	AR 700-139 updated	754 35
M326 MSK--Electrical drive assy quantity	757 42	Army Environmental Command contacts	749 60
M326 MSK--Water inside manual lift drive arm	757 41	CALL CDDP handbook	754 58
Round counts go on gun card	749 40	DA Form 12 in PDF format	757 58
Round inspections	753 38	IETMs now downloadable	746 48
MOUNT, WEAPONS		LOGSAP 746-1, Packaging-the Basics	752 62
M153 CROWS II--Elevation during travel	751 16	milWiki takes comments on Army doctrine	755 58
M153 CROWS II--Training, TM, locks...	754 42	OCP transition pocket guide	757 61
Machine gun mount accountability	752 56	Operator's manuals needed with equipment	746 03
NIGHT VISION EQUIPMENT		Propellant management guide	748 61
AN/AVS-6--Battery cord during packing	751 20	TEA MI 55-19 updated	755 59
AN/PAS-13--Thermal target DIY instructions	746 55	TB 1-1500-348-30 to be destroyed	754 22
AN/PVS-4/4A, AN/TVS-5/5A--Turn in	755 49	PUMPS	
AN/PVS-14--MILES battery, don't use	752 61	65 GPM Water--NSN, Class change	753 48
AN/PVS-14--Neck cord needed	746 41	RADARS	
ANVIS--TB 1-1500-348-30 to be destroyed	754 22	AN/TPQ-36--Wave guide, 801 test	752 50
Lithium batteries only	746 59	AN/TPQ-37--M1048A1 trailer tire belt	747 16
MTM-PI now available	753 61	AN/TPQ-37--Receiver cabinet, RF cables...	752 52
MTM-PI now available	756 36	Sentinel--Mini-grabber test leads for circuit cards	749 43

Subject	Issue/Pg	Subject	Issue/Pg
Sentinel--Slide hammer rust prevention	752 47	SMALL ARMS	
RADIAC EQUIPMENT		Arms room lock NSNs, website	748 38
AN/UDR-13--Software beeping problem	748 44	BFAs for all small arms	750 52
RADIATION SAFETY		Cleaning tank use	750 38
RSO training for radioactive equipment	756 43	Clean Up with Cleaning Kit Savings	747 27
RADIO SET, GENERAL		Desert maintenance tips	751 36
AN/PRQ-7--Repair part NSNs	754 20	Interactive Multimedia Instruction (IMI) course	751 18
JTT-SR--POCs for repair	749 49	Items needed for the field	757 39
RADIO SET, SINGGARS		Lube types and uses	753 56
MEL changes for components	749 48	M2 feed cover, gun card, mortar services...	749 36
RT-1523 turn-in to SSA	756 48	Maintenance tracking spreadsheet	751 15
RIFLE, M16-SERIES		Parts cleaning can	754 61
Dirty Dozen	756 62	P-D-680 replaced by MIL-PRF-680	749 39
Extractor plugged with cotton swabs	750 48	Shipping for deployment	753 36
Firing stoppage, immediate vs remedial action	755 44	Special tools all needed	754 46
Individual, improved cleaning kits added	750 46	STORAGE	
M12 rack modification made easier	746 40	Humidity indicators for LLRCs	752 19
M12 rack modification, third method	753 40	SUPPLY, GENERAL	
RIFLE, SNIPER		Local purchase can save money	754 27
Turn-in, exchange instructions	748 36	Shelf and service life explained	754 24
ROBOTS, GROUND		Unit-provided crests, remove before PCS	754 32
COLTS repair part website	747 15	TANK, M1-SERIES	
SAFETY		Ammo box desiccant to prevent corrosion	753 08
Cold Weather--Frostbite, clothing, heaters...	755 36	Ammo compartment PM	755 04
Don't Guess! Use the MSDS!	746 62	DSESTS turn-in needed	754 03
Explosives Safety Assistance Visits (ESAV)	751 17	DVE stowage box NSN	753 09
Fire extinguishers required for ammo transport	748 42	Exhaust duct seal, rotate to extend life	752 06
Footwear, tripping safety	746 46	Final drive oil level checks	756 03
Jewelry, remove before maintenance	752 45	Flareback prevention	750 03
Railway safety tips	747 58	Fuel tank cover gasket sealant NSN	753 09
Safety board components, NSN	750 50	Hydraulic line kit	753 05
Wet bulb-globe temperature unit parts	751 52	M1A1 SEP--IETM available	755 03
Wet bulb-globe temp unit correction (751-52)	757 47	Mine Blade, Roller--Readiness reporting	746 08
Winter safety tips	755 35	Phone handset NSN	757 60
SCRAPER, EARTHMOVER, 621G		Skirts, don't open two at same hinge point	757 03
EMS fault alarm NSN	757 60	Stub base extraction tools	750 07
SHOTGUN		Turret cracks	756 04
M26, M500 only shotguns authorized	748 41	V-pack damage checks	748 06
SIGHTS & SCOPES		TENTS	
AN/PSQ-23/23A STORM--Battery type	748 39	LME--50-watt fluorescent lamp NSN	751 61
Lens care	747 44	Modular general tent replaces MCPS	749 51

Subject	Issue/Pg	Subject	Issue/Pg
TEST EQUIPMENT		Hot weather PMCS, AoA considerations	751 38
DSESTS turn-in needed	754 03	M915/A1--Air dryer, repair with desiccant	753 60
TMDE app available on LIW	746 42	TRUCK, M1070 HET	
TIRES		Air cleaner assembly mounting stud kit	747 15
DLA tire catalog in EMALL	756 14	Sustainment training from MTTs	755 16
Service life extended for some assemblies	754 34	TRUCK, 1 1/4-TON, HMMWW	
Tire lube NSNs	749 61	4-door conversion kit	747 14
TOOLS		4L80E transmission troubleshooting	746 16
HEPPOE--Breaker drill warranty	752 08	A/C red service port cap NSN	751 61
Repair parts, TM, maintenance question POC	749 61	Battery disconnect kit	747 12
SATS tool listing, locator guide	747 45	Battery type revisited (749-11)	753 61
Urban Ops Set--Assault ladder, inspection kit	756 37	Cargo box nets	752 39
TRACTOR, D7E/F/G/R		Condenser fan intake grille cleaning	751 46
Fuel injector misfire	753 61	Exide batteries not authorized	749 11
Fuel injector misfire	755 19	Geared hub magnetic drain plug	756 13
Fuel injector pump air/fuel line crack	746 20	Hawker, Exide battery update (749-11, 753-61)	754 60
Idler wheel mud removal	755 26	M998-Series--Radiator hose protection	755 11
TRAILERS		Run-flat insert components	750 14
M149A2--Manhole cover seal installation	750 15	Shock absorber kit NSNs	753 11
M989A1 HEMAT--Tow bar lock	750 16	Silicone brake fluid	749 60
M1048A1--Belt damage deadline criteria	747 16	Special equipment, turn off after operation	749 12
M1101, M1102--Shock absorber kit NSN	754 60	Tire and wheel assy, don't mix NSNs	749 15
M1112--Plumbing part mixup	755 17	Transfer shifting	756 12
Safety chains for larger towing shackles	746 14	Up-armored--A/C flow control valve reset	751 47
TRAILERS, SEMI		Up-armored--Exhaust pipe crack check	747 18
M200A1--Landing leg NSN	749 61	Windshield wiper PM	757 18
M870A1--Tire covers to protect from heat	751 41	TRUCK, FMTV	
M871A3--Amber clearance light NSN	754 60	A1P2--Electromagnetic relay NSN	754 61
M967A1, M969A1/A2--Wheel assy change	753 15	Brake air tank draining	754 12
TRAINING		C7 engine waste gate solenoid valve NSN	751 60
CLRT/MAIT offer unit help	753 33	Cab ride height limit switch dust boot	754 11
Driver's training test examples	752 05	GRS selection by armor type	755 13
Looking for Training Materials-UTAP	753 62	Intercom no longer supported	755 12
Master driver trainer qualification course	756 11	Interconnecting box free issue	753 14
RSO training for radioactive equipment	756 43	Interconnecting box free issue correction (753-14)	757 61
Small arms IMI course	751 18	Jack adapter NSNs	754 14
UTAP equipment training	757 56	Lift-towing restrictions	756 61
TRANSPORTATION		M1087A1--Side doors open before expanding	748 11
Rail transport, secure vehicle doors	752 44	M1148A1P2 LHS--Wheel roller stop bar bend	748 12
SDDCTEA website, deployability pubs	756 54	M1157A1P2 LTAS--Seat restraint latch damage	753 12
TRUCK, M915-SERIES		Safety chains for larger towing shackles	746 14
Coolant filter kit	749 61	Securing steering wheel with chain, lock	746 11

Subject	Issue/Pg	Subject	Issue/Pg
Spare tire carrier chain adjuster	749 12	IETM available	756 09
Trailer light breaker check	749 20	M2A3--Unserviceable LRU needed for turn-in	755 07
Up-armored--A/C charge weight	751 44	M242--14-pin connector protection	756 06
TRUCK, HEMTT		Oil filter cover assembly DPI removed	753 04
A0/A1/A2--Air dryer, repair with desiccant	753 60	Subsystem schematics available	757 09
A2, A4 Models--Assembly NSN list	747 13	VEHICLE, MRAP	
A4 Models--Radiator cap NSN	757 60	M-ATV--DVE component match-up	747 19
A4 Models--Universal service kit problems	754 60	M-ATV--Hull drain plugs	750 19
Axle popping explained	746 13	MaxxPro--Headlight NSN	754 13
Fuel system priming explained	754 15	MaxxPro Dash--ESC operation instructions	757 60
M978-Series--HAV hoses, hose reel, fuel nozzle	749 18	MaxxPro Dash--OGPK hatch seal	749 61
M978-Series--Ladder use, PM	748 18	VEHICLE, RECOVERY, M88-SERIES	
M978-Series--Purging pointers	750 18	A1--Boom pivot pin lubing	749 04
M978-Series--Securing steering wheel	753 16	A1--Ground hop kit components	747 09
M985A4--Service kit add-ons	754 60	Hatch lever spring wear	752 04
Sustainment training from MTTs	755 16	Tow bar lifter	755 06
TM listing for all models	746 12	Track shoes, order only what's needed	746 04
TRUCK, PALLETIZED LOADING (PLS)		Winch cable kink prevention	749 06
Air cleaner assembly mounting stud kit	747 15	VEHICLE, STRYKER	
TRUCKS, GENERAL		VV Hull--Water shorts out ABS ECU	753 03
Alcohol evaporator stops brake lines freeze	757 19	M1129A1, M1252--Mortar tube, remove quarterly	755 07
Batteries drained by excessive cranking	751 59	Mirror, headlight cleaning	747 06
Battery box liner NSN	756 15	PECCH coolant supply hose inspection	749 03
Corrosion inhibitor	753 53	Steering system cracks	754 05
Dexron VI NSNs	757 20	Switch guard rubber seal	751 07
Diesel engine slobber	750 17	Transmission service interval extended	755 08
Drip pans, crushproof	749 60	VEHICLES, COMBAT	
Electrical connector NSNs (Packard-type)	754 36	Corrosion inhibitor	753 53
JCIMS update (CIP, TIP, Phoenix)	751 03	Drip pans, crushproof	749 60
Leaks and what to do about them	748 14	JCIMS update (CIP, TIP, Phoenix)	751 03
R-134 refrigerant NSNs	751 60	Operators manuals needed with vehicles	746 03
Reclaimed R-22 available	751 42	Towbars and adapter NSNs	754 06
Towbars and adapter NSNs	754 06	Track shoes, pad kits	748 04
Windshield washer fluid	751 52	VEHICLES, GENERAL	
VEHICLE, FIGHTING, M2/M3 BRADLEY		Slave receptacle cap freeze prevention	757 21
Aluminum transmission housing damage	748 07	WATER SUPPLY	
Ammo box latches	747 07	Canteens, cups, hydration systems	751 48
BUSK--Battery maintenance, charging tips	746 05	WELDING	
Engine hydraulic reservoir check	756 07	SEW--Parts available	751 60
		TMWSS, SEW--Spare tire MWO	754 48