

PS Magazine Index No. 72, 2016

Subject	Issue/Pg	Subject	Issue/Pg
AIRCRAFT, GENERAL		Combustion chamber liner, anti-icing valve turn-in	760 33
Aviation components move to sustainment	762 23	ESIS computer turn-in needed	769 60
Electrical bonding info, definitions	769 19	ESIS display turn-in needed	769 60
Hydraulic RSUs now available	768 20	Fuel cell liner tape NSN	759 57
Jacks required for aircraft lifts	767 20	Hoist hook component check	765 20
JTDI takes over for CAPS	760 33	ICU software different than Chinook	765 61
Rescue hoist check for corrosion	764 19	MEDEVAC news, discussion forums	767 61
Spot paint stripping materials	763 25	Propulsion shaft turn-in needed	760 32
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		Repair parts needed for turn-in	759 51
ALUMMC parts cart being fielded	763 23	Rotor blade clamp installation	765 24
AMTRACKS--Safety/maint msg compliance	762 22	Swashplate control turn-in	766 60
DAWS--Some DAWS unauthorized	759 48	AIRCRAFT, OH-58, KIOWA	
Jack maintenance, rebuild	760 27	Swashplate assembly nuts	766 26
Nitrogen cylinder color (744-14)	759 49	AIRCRAFT, OH-58D, KIOWA	
Tool kits and sets listing	765 16	Hardware removal with penetrating fluid	762 21
UMARK--Components NSN list	758 21	AIRCRAFT, UAV	
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		MQ-1 Gray Eagle--Brake rotor, safety wire...	766 24
AEBP--Repair needs disposition instructions	769 23	Raven--Keep UAVs apart, avoid jamming...	764 26
Air Warrior equipment list for Reset	768 24	Shadow--Exercise, tape on power cable	764 24
ALSE questions, answers	760 31	Shadow--Landing gear bucket, O-ring...	769 25
JSVPLR life raft turn-in help	764 23	Shadow--Training, ground support, tools...	766 22
MCU--Parts list update (740-25)	765 61	AIRCRAFT, UH-60, BLACK HAWK	
PRT snap hook ejector check	764 25	APU vent screens a no-step area	762 26
AIRCRAFT, AH-64, APACHE		Blade pole holder blueprints	761 24
Catwalk door wind damage	759 56	Cabin sound proofing material NSNs	759 61
Forward and aft ball bearing units	768 23	Castellated nut substitute NSN	765 60
Hardware, use what the TM says	759 50	Combustion chamber liner, anti-icing valve turn-in	760 33
Main rotor blade turn-in	764 21	Hardware, use what the TM says	759 50
Panel repair, NSNs	759 52	Hoist hook component check	765 20
PQDR submission guidelines	765 19	IBF-configured APUs needed for turn-in	768 26
Pressure tester replacement available	767 26	Modulating valve turn-in	766 60
Quadrant control assembly mounting bracket	762 25	Propulsion shaft turn-in needed	760 32
Stabilator cover for safety	761 23	Propulsion shaft turn-in needed	767 60
Tail rotor blade ordering	768 22	Repair parts needed for turn-in	759 51
TM 1-1520-264-23 (EM 0319) updated	765 19	Stabilator amplifier, single box replaces dual	764 22
Unserviceable parts list for turn-in	764 21	Stabilator cover for safety	761 23
Wiring and fuel line chafing	767 24	Swashplate control turn-in	766 60
AIRCRAFT, CH-47D/F, CHINOOK		AIRCRAFT, UH-72A, LAKOTA	
Covers, regular and alternate	759 53	RT-5000 radio, check PN	762 24
ICU software different than Black Hawk	765 61	AMMUNITION	
Rotor blade paint NSNs	761 26	Blown Apart by Wax!	758 62
AIRCRAFT, HH-60M, BLACK HAWK		CCMCK dangers	759 36
APU vent screens a no-step area	762 26	M855A1--Not for shoot house training	766 42
Blade pole holder blueprints	761 24		

Subject	Issue/Pg	Subject	Issue/Pg
ANTENNA, AS-3900		Clearing procedure TM/FM disagreement	762 36
Gasket still required	767 49	Clearing procedure explained	759 39
Supply issue POC	758 61	Firing pin not a cleaning tool	765 37
ANTENNA, OE-254		Grips and buttstocks authorized	759 45
Silicone compound storage	761 53	M12 rack mod needed to secure M4	769 40
ANTENNAS, GENERAL		Mounting rail secure, loose barrel	759 40
Vehicle tie-down safety	761 14	Sling choices	768 49
ARMORED COMBAT EARTHMOVER, M9		Sling, only one needed per weapon	762 41
Blade lock pin, retaining clip NSNs	758 16	Special tools found in TM 9-1005-319-23&P	769 43
Blade lock pin, retaining clip NSNs	759 21	SPORTS acronym for firing stoppage	763 40
Hydraulic parts kit NSN	759 21	Stuck round procedure step-by-step	767 38
ARMORED SECURITY VEHICLE, M1117		CARRIER, PERSONNEL, M113 FOV	
Windshield washer pump NSN	769 61	Driver's hatch latch safety pin	769 04
AWARDS		Exhaust manifold rust prevention	759 03
2016 LEA winners	769 52	Prop shaft bolt alignment marks	762 07
AAME history, submission guidelines	766 56	Ramp PM tips	767 04
BACK COVER		CBRN EQUIPMENT	
Best Place to Find PS?	764 62	CBRN-IRC email address updated	764 61
Big Clang Theory!	760 62	Dosimeter badge care	759 44
Blown Apart by Wax!	758 62	Equipment codes explained	763 46
Contact Lenses in the Field Are No Go!	762 62	M4 JCAD--Reset after sieve pack change	767 43
Don't Guess When Reading Oil Levels!	768 62	Signs not needed if radioactive material gone	767 44
Do You Know What Happened to that Tool?	767 62	CLOTHING	
Keying Is the Key!	761 62	Black socks allowed with fitness uniforms	761 61
Pub Got It Wrong? Help Make It Right!	759 62	CLOTHING, PROTECTIVE	
Smart Maintenance: Follow the TM	765 62	JSLIST--Fitting, sizes, order of assembly	762 44
Use Your TM!	766 62	COMMERCIAL CONSTRUCTION EQUIP (CCE)	
When It's Time to Do PM...	769 62	Grease fitting protective caps	768 17
Would You Stake Your Life Right Now...	763 62	Parts help from CAT	763 13
BATTERY, HAWKER		COMMUNICATIONS EQUIPMENT	
Trick for charging dead batteries	766 03	CAISI 2.0 parts and support	763 48
BATTERY, LEAD-ACID		COMPACTOR, 815F	
Distilled water NSN	761 11	Fan pulley lube fitting	763 11
BATTERY, LITHIUM		Steering system articulation danger	760 21
Lithium vs alkaline batteries	768 01	COMPUTERS & SOFTWARE	
BATTERY, NONRECHARGEABLE		EMS NG error codes	766 55
Expiration date, storage, damage...	768 36	EWO laptops, turn in for upgrades	760 52
BATTERY, RECHARGEABLE		MSD--Docking connectors breaking	765 52
BB-2590--Charger software updates	769 47	MSD--V2 vs V3	758 56
CARBINE, M4-SERIES		COMSEC EQUIPMENT	
Ambidextrous selector switch available	758 40	KGV-72--Direct exchange request POC	768 60
Ambidextrous selector switch MIM published	761 39	KIV-7M--Battery replacement instructions	764 48
Barrel gage after CCMCK firing (759-36-38)	766 39	CONTAINER HANDLER, ROUGH TERRAIN (RTCH)	
Cleaning, BUIS, cleaning rod, buttstock lock...	761 40	Hydraulic hose fitting NSN	765 60

Subject	Issue/Pg	Subject	Issue/Pg
CONTAINERIZED KITCHEN		FIRST AID KITS	
Oven blower motor NSN	765 60	Junctional tourniquet NSN	766 51
CONTAINERIZED SHOWER		FORKLIFTS	
WH-400--Safety and restricted lockout fix	761 45	5K LCRTF--Fork pin takes dry film lubricant	766 18
CONTAINERS		6K VRRT--Steering cylinder correction (757-13)	761 61
ISO--Twist locks required for security	764 58	ATLAS--Fuel pressure sender banjo bolt NSN	760 23
MEL guidance, POC	766 53	ATLAS II--Auto-level controller NSN	769 61
CONTINUITY		ATLAS II--TMs revised	769 61
65 Great Years!	763 27	FORMS, GENERAL	
Accidental Martian	764 27	DA Form 2028--Where to send	759 62
Duel at Dessau	766 27	GENERATORS, LARGE	
Not a Second Thought	767 27	5-60-kW AMMPS--Fuel sensor replacement	767 48
Old Nat's Cannon (A Burst of PM)	759 27	15-kW--Diode replacement	768 38
PM Force Awakens	768 27	15-kW--Voltage regulator TM corrections	769 60
PM Royale	761 27	30-kW--Fuel filter seal kit NSN	759 60
Supply Diaries	762 27	35-kW GET--Circuit breakers, oil check...	768 40
Untold Tale of Teddy and the Rough Riders	769 27	GENERATORS, SMALL	
World of Jurassic PM	765 27	5-60-kW AMMPS--Fuel sensor replacement	767 48
DECON		10-kW AMMPS--Overspeed shutdown fault	762 48
M26--Data plate fading	764 42	MEP-803A 10-kW--Door handle NSN	762 51
M26--Wand damage prevention	766 44	GLOBAL POSITIONING SYSTEM (GPS)	
DETECTOR, CHEMICAL		COMSEC keying vital	761 49
M4 JCAD--Reset after sieve pack change	767 43	DAGR--CECOM now supports	758 18
EDITORIAL		DAGR--Software update instructions	766 47
65 Great Years!	763 01	GRADERS	
Bad URL's Like a Bad Smell	765 01	120M--Blade cutting edge minimum	768 18
Don't Overlook BII, COEI	762 01	120M--Cab air filter cleaning	766 19
Don't Spin Our Wheels!	759 01	120M--Circle drive breather valve clogging	763 10
Do Your Best! Don't Give TMs a Rest	769 01	120M--Circle drive lube	762 17
Got Maintenance Procedure Problems?	767 01	120M--Drawbar assembly wear strip shims	760 25
Just Any Battery Won't Do!	768 01	120M--EMS fault alarm repositioned	760 24
Long, Hot Summer	764 01	120M--Inching pedal not a foot rest	766 20
PM's Not a Back Burner Issue	766 01	120M--Input lockout switch NSN	766 61
PS Has Your Back!	761 01	120M--Moldboard lower wear strip cracking	759 24
Read 'Em and Heed 'Em	758 01	120M--Rear composite light NSN	768 61
ELECTRICAL, GENERAL		120M--Scarifier shank stowage location	759 22
Grounding and bonding pamphlet	765 61	120M--Service interval correction	759 23
Lead-free solder not allowed in Army equipment	760 48	120M--Tire tread not directional	761 19
EXCAVATOR, HYEX		120M--Transmission oil level check	764 15
Swing bearing ring gear lubing	759 26	GRENADE LAUNCHER, M320	
FED LOG		Day/night sight no longer COEI	765 60
Disc disposal address	767 61	Finger position on grip	760 42
FIRE EXTINGUISHERS		GUN, MACHINE	
Bottle turn-in safety	769 58	M2--Locking plate for securing weapons	762 43
		M2--Stuck bolt tool	768 50

Subject	Issue/Pg	Subject	Issue/Pg
M2, M2A1, MK 19--M3, keep til M205 arrives	768 52	Primer extraction/removal tools	759 07
M2A1--Barrel assembly bracket parts	769 42	Recuperator gasket damage	765 04
M2A1--Barrel installation	763 38	Segment board cleaning	760 07
M2A1--Barrel installation steps	765 36	HOWITZER, TOWED, M119-SERIES	
M2A1--Breech lock spring pin NSN	764 39	A3--Breech straight pin, fire control battery	767 08
M2A1--Buffer body lock staking	767 40	A3--Cable check, sled, tarp, GPS cable...	758 04
M2A1--Headspacing/timing still needed	759 41	A3--Connector caps, M2 storage, batteries...	761 08
M2A1--M3 recoil adapter OK, but headspace	767 41	Optical fire control elevation vials	758 03
M2A1--Mandatory replacement parts no more	767 41	HOWITZER, TOWED, M777A2	
M153 CROWS II--Tool kit, order the old one	758 43	EPIAFS, don't hot swap the PIK	759 09
M197--MWO needed	768 52	Optical fire control elevation vials	758 03
M205 Tripod--Replaces M3 tripod	760 43	Primer extraction/removal tools	759 07
M240--Gas regulator, tool depends on barrel	765 38	IMPROVED TARGET ACQUISITION SYSTEM (ITAS)	
M240, M249--Barrel ID tagging	763 39	Lifting, TAS interface cable, second chance adapter	758 37
M240, M249--Gas system pocket cleaning tool	759 38	PMCS, charging, lenses, cracks, TU coupling clamp...	768 44
M240, M249--Gas system pocket cleaning tool	760 40	LASER RANGEFINDER	
M240B/L, M249--Camouflage painting	760 39	AN/PED-5--I/O interface connector cable	758 43
M240L--Short barrel regulator correction (755-43)	769 61	Demil list of lasers and sensors	764 40
M240L--Short barrel regulator NSN	766 37	LOADER, BACKHOE (BHL)	
M249--Front/rear sling kit fix	767 36	Digging tips, backfilling, bucket swinging	759 18
M249--Gas piston roll pin check	758 42	Front bucket cylinder hose NSNs	764 61
M249--Short barrel washer NSN	769 43	Fuel pump solenoid to prime turbocharger	764 16
MK 19--Bolt, backplate NSNs corrected	762 41	Seat adjustment knobs	759 20
MK 19--Clearing procedures	766 38	Slope operation, cautions	759 17
MK 19--Semiannual maintenance change	761 42	Transmission lubricant types, NSNs	763 12
HARDWARE		Turn signal mount reinforcement	760 22
Shipping bag NSNs	766 60	Wheel nuts, mark for easy movement check	764 17
HAZARDOUS MATERIALS & WASTE (HAZMAT)		LOADER, SCOOP-TYPE	
Absorbent compound for spills	759 60	924G, 966H--Light switch NSN (752-9)	766 61
Fuel containment berm NSNs	764 11	924H--Air precleaner parts available	759 25
Solvent cleaning	761 59	924H--Camera cable NSN	764 61
HEATER, SPACE		924H--Rear composite light NSN	768 61
FOSH--Types, operation, carbon monoxide...	758 46	LOADER, SKID-STEER, BOBCAT	
HELMETS, AVIATION		M400T--Auger component NSNs	760 23
IHADSS--Parts turn-in for repair	765 18	M400W--Cab door switch NSN	760 23
HELMETS, GROUND		M400W--Solid tire NSNs	767 60
Mount hardware for AN/PVS-7, -14	767 52	LOGISTICS MANAGEMENT	
HIGH MOBILITY MATERIAL HANDLER (HMMH)		FSC2 added to MMDF	765 56
Tire replacement	766 17	GCSS-Army--Lockout solutions	761 58
HOWITZER, SP, M109A6 PALADIN		GCSS-Army--Supply request rejections	758 59
Master power, shut off to save batteries	764 09	GCSS-Army--Training info	768 54
Breech takes light lubing	765 06	Key security part of property accountability	760 59
Cannon tube cleaning, inspection	758 07	NTC DODAAC needed for Guard/Reserve	768 57
EPIAFS, don't hot swap the PIK	759 09	PBUSE user role/permission verification	760 56
Gun muzzle cover	765 03		

Subject	Issue/Pg	Subject	Issue/Pg
MAINTENANCE MANAGEMENT		M326 MSK--Gear box disengage lever	767 42
DOD EMALL--Check IE settings	759 61	M326 MSK--Keep covered with tarp	760 41
MSD--Help desk contact	761 61	MOUNT, WEAPONS	
MSD--V2 vs V3	758 56	M2, M2A1, MK 19--M3, keep til M205 arrives	768 52
PBUSE--Correcting MSD entries	758 54	M66--Canvas cover NSN	765 38
PQDR website	760 58	M66--TM for maintenance and repair	760 43
MAINTENANCE, GENERAL		M153 CROWS II--Protective caps needed	762 03
LAR, how to contact	759 14	M153 CROWS II--Tool kit, order the old one	758 43
LARs are here to help	761 20	M205 Tripod--Replaces M3 tripod	760 43
Maintenance Haulin'	760 01	MK 93--Replaces the MK 64	759 42
MASK, PROTECTIVE		NIGHT VISION EQUIPMENT	
C2A1 canisters, bad lots	766 43	AN/PSQ-20, -20A--Turn in for repair	766 50
M40-, M42-Series--Outsert use, installation	765 39	AN/PVS-7, -14--Helmet mount hardware	767 52
M40-, M42-Series--Storage, outserts, carrier...	763 44	AN/PVS-14--Services, storage case, battery...	762 50
M50, M51--PATS adapter, velcro, filter...	765 40	AN/PVS-14--Tube retainer ring spanner wrench	768 39
M50, M51--Nosecup retaining ring missing	760 45	Army pubs only from official sources	767 54
M50, M51--TM not needed for every mask	760 46	TS-4348/UV--NSN and TM instructions	767 47
M50, M51, M53--Amplifier, remove before wash	759 43	PACKAGING	
MINE CLEARING EQUIPMENT		WPM insect protection	764 53
Husky--Battery isolator switch	769 14	PAVING MACHINE	
Husky--Front and rear frame, order by SN	767 16	8816M BMPM--Air filter cleaning	763 09
Husky--Ink reservoir freeze caution	769 13	8816M BMPM--Conveyor grease fittings	762 19
MISSILE, HIMARS		8816M BMPM--Start up procedures	762 18
Dirt deflector improved	758 39	PISTOLS	
MISSILE, JAVELIN		M9--Cracks, magazine, trigger bar, rail...	760 36
CLU cleaning, caps, case	763 42	M9--MWO to fix slide	758 41
CLU purging	768 43	M11--Breechblock pin installation	762 42
Monthly maintenance and training needed	758 36	POL	
Shipping instructions	766 37	Single Common Powertrain Lubricant (SCPL)	768 11
MISSILE, PATRIOT		POWER SUPPLY	
AN/MPQ-65--Semiannual adjustment list	764 41	UPS battery backup PM	769 49
Outtrigger lubing	766 36	PS MAGAZINE	
MISSILES, GENERAL		Back issue guidance	766 54
FIREIT reporting system	768 48	Improve maintenance with PS	759 58
MLRS		PS Mag Live	759 59
Cab elevation tips	767 06	PS Mag Live	768 59
GPS antenna ordering information	761 39	Search engine instructions	762 55
Launcher exercise, prop shaft bolt safety wire...	769 36	Soldier kudos for 65th anniversary	763 60
Second generator relay box welds	764 08	Soldier service program, article submission	763 54
Speedometer NSN	765 60	Videos for PS mobile app	766 60
Track tension how-to	763 15	PUBLICATIONS	
Unserviceable equipment turn-in list	760 12	ADP/ADRs changing over to ePubs format	760 57
MORTARS		Aircraft painting, marking TM replaced	767 60
MFCs--Turn in all components	760 41	APD website makeover	765 57
		AR 25-12 revised	763 57

Subject	Issue/Pg	Subject	Issue/Pg
AR 700-80 revised	765 57	Cleaning, BUIS, cleaning rod, buttstock lock...	761 40
AR 700-141 updated	765 59	Clearing procedure TM/FM disagreement	762 36
AR 700-145 updated	767 59	Clearing procedure explained	759 39
ATP 4-43 updated	763 59	M12 rack mod needed to secure M16A4	769 40
ATP 6-02.75 published	765 59	Mounting rail secure, loose barrel	759 40
DA Pam 25-30 available	769 61	Sling choices	768 49
DA Pam 385-24 revised	763 59	Sling, only one needed per weapon	762 41
DA Pam 385-63 for range safety	768 60	Special tools found in TM 9-1005-319-23&P	769 43
DA Pam 708-2 revised	765 59	SPORTS acronym for firing stoppage	763 40
DA Pam 708-3 revised	763 57	Stuck round procedure step-by-step	767 38
DA Pam 735-5 revised	767 59		
DLA customer assistance handbook	766 61	RIOT CONTROL	
DLA eDocs system moves	766 56	Non-lethal capability set PM tips	761 46
EIR Digest returns	765 55		
EMS Insider newsletter	766 59	ROLLER, VIBRATORY	
EMS NG customer support	769 57	CS-563D--8-ply tires on 12-ply assembly	761 21
EOPDB tailored pubs list	764 60	CS-563D--Hydraulic system hose assembly	769 60
Publication status checker	768 60		
Safety newsletters, reports subscriptions	767 61	SAFETY	
SB 700-20 found in LIW	767 58	Contact Lenses in the Field Are No Go!	762 62
SOP exchange library	762 61	Hand sanitizer NSN	766 61
TC 21-305-20 revised	767 57	Newsletters, reports subscriptions	767 61
		Safety board less costly (750-50-51)	759 46
		Safety paint NSN	766 61
		Solvent cleaning	761 59
		Vehicle mounting safety	760 60
PUMPS			
125-GPM Water--Filter warning indicator	765 61	SATELLITE COMMO TERMINAL	
Fuel and water pump NSNs	764 56	AN/TSC-154A--KGV-310B battery life	762 49
RADARS		SENSORS	
Sentinel--Voltage danger, dummy load, brake...	761 36	Demil list of lasers and sensors	764 40
RADIAC EQUIPMENT		SIGHTS & SCOPES	
AN/PDR-75A--Dosimeter changes from -75	767 45	M68 CCO--Battery cap O-ring lubing	761 43
AN/VDR-2--Batteries, storage, beta shield...	769 44	M145--Turn in excess for demil	759 42
		M151--Spotting scope upgraded	769 39
RADIO SET, GENERAL		M320/A1 grenade launcher sight not COEI	765 60
AN/ARC-220--LCD panel cover NSN	759 61		
TACSAT, Handheld radio NSNs, TMs	765 48	SLAVE CABLE, NATO	
		Extension adapter NSN	760 10
RADIO SET, SINCGARS			
AN/GRM-122--RT-1796/1694D test cable	760 49	SMALL ARMS	
Installation kits stay with vehicle	765 46	CCMCK dangers	759 36
Installation kits, turn in unserviceables	765 61	DA Form 2404, PMCS for each weapon	762 40
MT-6352/A not repairable	767 60	Humidifier for arms room	764 36
RT-1523E/F--Knobs, P1 connector, pins...	762 52	M16 BUIS, M2 extractor switch, M26 safety...	763 36
RT-1523F--Mount NSN	765 60	Range supplies	762 38
		Security rules, regulations	766 40
REELING EQUIPMENT		SFL pen for touchup	760 42
RL-309--Intro, tips, repair parts	761 51	Unauthorized mods illegal and dangerous	764 38
RIFLE, M16-SERIES		SMALL EMPLACEMENT EXCAVATOR (SEE)	
Ambidextrous selector switch available	758 40	Tire replacement	766 17
Ambidextrous selector switch MIM published	761 39		
Barrel gage after CCMCK firing (759-36-38)	766 39		

Subject	Issue/Pg	Subject	Issue/Pg
SUPPLY, GENERAL		TRAILERS, SEMI	
CECOM supply requisition cancellations	759 60	M870A1--Spare tire positioning	769 13
DLA Disposition Services	763 56	M967A1, M969A1/A2--Wheel assy (753-15)	758 61
DOD EMALL--Check IE settings	759 61	M969A3--Engine alternator belt NSN	759 61
PBUSE user role/permission verification	760 56	M1000--Bogie locknuts snag drain valve	762 12
RFID tag NSNs	758 58	Transport load height restrictions	765 11
Shelf-life workshop from PSCC	765 58		
TANK, M1-SERIES		TRAINING	
Air induction system, don't block with gear	764 04	91B wheeled vehicle mechanic training	760 55
Air induction system PM	768 03	AAAC certification renewal	766 58
Engine oil classes	762 04	CASCOM sustainment unit one stop (SUOS)	759 61
FBCB2 CPU latch security	763 19	Central Army Registry (CAR) website	763 58
Fuel cells, don't overflow	764 05	Customer Assistance Team (CAT)	762 61
Heat deflector needed for towing	762 06	DAC mobile apps	761 56
M1A1 SA--FBCB2 CPU latch tie-down	769 03	Digital Job Book for tracking training	768 55
M1A2 SEP--CROWS control damage	762 03	Driver's training records transfer	769 55
M1A2 SEP--Slave start procedures	766 04	Driver's training toolbox	762 58
Main hydraulic pump mounting stud damage	759 06	Driver's training website, training circulars	767 56
Muzzle plug keeps water out	763 21	GCSS-Army training	768 54
Recoil fluid residue sponge	764 03	Petroleum & Water Knowledge Portal (PWKP)	761 55
Service brake linkage cotter pin damage	760 08	Serial number tracking	762 60
Sprockets, reverse when wear marks reached	763 20	Warfighter training support packages (WTSP)	758 53
TDV inlet strainer screen check	767 03		
Track tension adjustments	758 08	TRANSPORTATION	
		M105 HIPPO--Ship empty	761 12
		RFID tag NSNs	758 58
		Secondary cargo load planning	758 11
TEST EQUIPMENT		TRUCK, 1 1/4-TON, HMMWW	
AN/GRM-122--Component list	767 50	Ballistic glass delamination guidance	762 11
AN/GRM-122--Parts needed for turn-in	764 50	Fuel injector pump fouling from bad fuel	763 04
AN/PRM-36--Battery replacement	764 47	Fuel pumps upgraded	760 15
TMDE--Calibration schedule, pickup, help	758 44	Fuel tank drain plug leaks	769 12
TS-3920C--Calibration help correction (752-60)	761 61	Geared hub plug correction (756-13)	761 61
TIRES		Glow plug wait light	759 15
Tire and wheel assembly NSN list	766 12	Glow plug warning label NSN	766 61
TOOLS		M1151-, M1165-Series--Oil cooler leak	767 10
Brass fittings kit NSN	763 43	Serpentine belt squeak	762 10
Numbered security seal NSNs	760 46	TACOM equipment specialist email address	759 60
SATS--Blue light bulb NSN	769 45	TCM water damage from snow melt	769 16
SATS--Ramp non-skid strips, landing legs...	764 43	Tow pintle lube points	763 03
TRACTOR, D6K		Up-armored--Power steering check	761 12
Blade mounting hole cracks	761 18	Up-armored--Tow bar and bracket NSNs	766 11
TRACTOR, D7E/F/G/R		Up-armored--Windshield, door glass NSNs	760 18
Engine compartment light can drain battery	767 17	Up-armored--Windshield washer nozzle, bracket	759 60
Hydraulic reservoir, don't open when hot	768 16		
TRAILERS		TRUCK, FMTV	
M1082, M1095--Tire and wheel assembly	759 61	A1P1--A/C vent louvers	763 06
		A1P2--EHPU breather cap	762 15
		Air springs, keep inflated	762 14

Subject	Issue/Pg	Subject	Issue/Pg
C7 engine fuel/water separator bracket	769 61	Ramp and ramp door seal check	759 04
Headlight dimming cause	768 14	Track tension how-to	763 15
Headlight, turn signal grounding fix	763 07	Unserviceable equipment turn-in list	760 12
M1083, M1093--Troop seat retractor hooks	767 12	VEHICLE, MRAP	
M1089A1P2--Crane hydraulic swivel joint	768 61	M1235A5--BEATS gunner seat NSN	767 61
M1157A1P2--Seat belt caught in door frame	767 13	MaxxPro--Door seal NSN	763 06
Transfer case NSN	765 61	RG31--TES-295 transmission fluid NSNs	759 60
Voltage regulator cause of generator problems	769 11	RG31 FOV--Self-recovery winch eliminated	767 14
WTEC II to III transmission upgrade kit	759 12	VEHICLE, RECOVERY, M88-SERIES	
TRUCK, HEMTT		A2--Generator power cable rub	761 06
Dash pin pulling tool	759 12	Roadwheel nuts, check for looseness	764 06
LHS--E-CHU front slider bed pad fix	764 12	Spade lockpin cleaning, lubing	769 05
M978--Emergency fuel shutoff cable freeze	769 15	VEHICLE, STRYKER	
M984A4--ECM NSN added	765 60	AFES fire bottles change to steel	767 07
Transfer case oil switch to 15W40	764 13	Air intake, keep cover to keep out water	763 18
TRUCK, M915-SERIES		CTIS settings to prevent tire damage	766 06
M915A3--Air system valve NSN	766 60	Double V-hull--Oil drain pan leaks	761 03
M915A3--Door seal NSN	766 60	Emergency fuel shutoff panel damage	761 04
M915A3--Main prop shaft retaining strap, bolts	759 11	Engine shutdown procedure	769 09
M915A5--VORAD sensor, bracket NSNs	764 61	Fuel pump leaks	761 05
TRUCK, M1070 HET		GRS harness, disconnect before dismounting	764 07
A1--Prop shaft TM mixup	760 17	Hull, drain to prevent component damage	765 08
GPFU air duct hose assembly parts	763 05	Hull drain plugs, use antiseize compound	758 09
TRUCK, PALLETIZED LOADING (PLS)		M1132, XM1257--Trailer brake check	766 08
E-CHU--Front slider bed pad fix	764 12	M1135 NBCRV--3 point contact, hub oil...	765 42
M6 dump body tarp NSN	766 60	M1135 NBCRV--CBMS II PM tips	762 46
M1074--Manifold solenoid NSN	764 13	Parking brake instructions	762 08
M1074/A1, M1075/A1--Fuel/water separator	762 13	Shifting to prevent transfer case damage	766 07
Transfer case oil switch to 15W40	764 13	VEHICLES, COMBAT	
TRUCKS, GENERAL		BII and COEI, keep handy for NTC rotation	769 08
Antenna tie-down safety	761 14	Surplus vehicles for hard targets	764 61
Blue force tracker transceiver water damage	760 16	VEHICLES, GENERAL	
Fuel containment berm NSNs	764 11	Chock block NSNs	762 15
Secondary cargo load planning	758 11	WATERCRAFT	
Transport load height restrictions	765 11	I&CLT--BII gauge NSN	767 18
VEHICLE, FIGHTING, M2/M3 BRADLEY		I&CLT--BII nozzle NSN	767 18
Battery drain fix	767 05	I&CLT--Directional control linear valve NSN	767 18
Commander's hatch cover latch lube	769 06	I&CLT--Gun mount and cover added to AAL	767 18
Fuel lever, leave out at shutdown	765 07	WATER PURIFICATION	
Fuel shutoff valves	769 07	Purification tablets	764 61
M51 mask quick-disconnect	760 11	TWPS--High pressure air tank expiration date	760 51
M242 cover NSN	766 09	WATER SUPPLY	
Radiator cap seal check	765 07	M105 HIPPO--IETM revised	767 10
		M105 HIPPO--Ship empty	761 12