



TB 43-PS-833

**THE
PREVENTIVE
MAINTENANCE
MONTHLY
INDEX**

**15
JUNE
2023**

Of Online Articles

<https://www.psmagazine.army.mil>



HERE'S AN INDEX OF THE
PS MAGAZINE ARTICLES
THAT APPEARED ON OUR
WEBSITE FROM
MAY 1, 2023
THROUGH
MAY 31, 2023.



The Preventive Maintenance Monthly Index of Online Articles

Issue 833

General & Special Topics	2
Aviation	5
CBRN	8
Combat Vehicles	10
Construction	12
Commo/Electronics	14
H2F	16
Logistics/Maintenance Management	18
Medical Logistics	20
Mines	22
Missiles	24
Small Arms	26
Soldier Support	28
Tactical Vehicles	30
Tools	33

TB 43-PS-833, **The Preventive Maintenance Monthly Index of Online Articles** is an official publication of the Department of the Army, providing a reference tool for all Soldiers assigned to combat and combat support units to access PS Magazine articles published to its official .mil website. All referenced articles have been reviewed and approved by the agency responsible for the equipment, publication or policy discussed in any referenced article. Application of the information in those articles is encouraged but optional with the user. The use of product or company names does not constitute endorsement of those products, services or companies by the U.S. Army. The use of non-DoD hyperlinks, along with that content, does not constitute endorsement by the DoD or DA. Neither DoD nor DA exercises any editorial control over, and cannot vouch for, content on non-DoD websites.

PS: The Preventive Maintenance Monthly Index of Online Articles (ISSN 0475-2953)
is published monthly by the Department of the Army, Redstone Arsenal, AL 35898.

You are invited to send PS your ideas for improving maintenance procedures, questions on maintenance and supply problems and questions or comments on material published in PS.

Just write to:

MSG Half-Mast
PS, the Preventive Maintenance Monthly
USAMC ARMY SUSTAINMENT COMMAND
BLDG 3218 Snooper Rd.
Redstone Arsenal, AL 35898

Or email:

usarmy.redstone.asc.mbx.psmag@army.mil

Internet address:

<https://www.psmagazine.army.mil>

By Order of the Secretary of the Army:

JAMES C. MCCONVILLE
General, United States Army
Chief of Staff

Official:

MARK F. AVERILL
Administrative Assistant
to the Secretary of the Army

2314651

DISTRIBUTION:
Distributed in electronic media only (EMO).


General and Special Topics



Date	Article Title	Link	Excerpt
4-May-23	Leader Interview: Mr. Duxbury, AMC C5ISR L-STR	https://www.psmagazine.army.mil/News/Article/3384328/leader-interview-mr-duxbury-amc-c5isr-l-str/	MSG Half-Mast recently traveled to Ft Drum to visit with Mr. James Duxbury, the AMC C5ISR Lead-System Tech Rep (L-STR) for the 10th Mountain Division/CECOM Integrated Logistics Support Center (ILSE) Forward Element – East Region, Army Field Support Battalion-Drum, 406th AFSB. They discussed the role of the L-STR in helping to improve C5ISR readiness. Keep reading to learn more about this vital role...
4-May-23	I Sustain This: April 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3385194/i-sustain-this-april-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For Apr 2023, we had one civilian sustainer nominated for this program. Read on to learn about the nominee and his contributions to Army readiness...
5-May-23	I Own This Campaign: Nominate a Deserving Warfighter	https://www.psmagazine.army.mil/News/Article/2188371/i-own-this-campaign-nominate-a-deserving-warfighter/	Taking ownership and pride in assigned vehicles and equipment is vital to ensuring personal, unit and fleet readiness. Without this personal investment and active involvement, Warfighters fail to ensure preventive and scheduled maintenance gets done when it should and by the book. This failure, in turn, results in non-mission capable (NMC) vehicles...
5-May-23	Logistics Management: CY 2022 Petroleum Excellence Winners	https://www.psmagazine.army.mil/News/Article/3386271/logistics-management-cy-2022-petroleum-excellence-winners/	The annual Petroleum Excellence awards recognize superior performance in petroleum management and fuel handling. The CY22 Petroleum Excellence awards are announced. To find out where to get the list of winners, read on...

8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
10-May-23	M1022-Series Dolly Set Mobilizer: Tire and Wheel Assembly NSN	https://www.psmagazine.army.mil/News/Article/3390711/m1022-series-dolly-set-mobilizer-tire-and-wheel-assembly-nsn/	Maintainers, the current TM for the M1022-series dolly set mobilizer doesn't include the NSN for the tire and wheel assembly. Get it here...
15-May-23	M30 BEB: Transmission Oil NSNs	https://www.psmagazine.army.mil/News/Article/3393464/m30-beb-transmission-oil-nsns/	The lube order for the BEB lists a 55-gal drum and its NSN but provides no other sizes. Smaller quantities are available. For the NSNs, keep reading...
15-May-23	SINGGARS: Circuit Card Assembly PN Marking Problem	https://www.psmagazine.army.mil/News/Article/3393564/singgars-circuit-card-assembly-pn-marking-problem/	Did you run into a problem when trying to turn in the SINGGARS Circuit Card Assembly – Flexible Rear Panel – RT (NSN 5998-01-539-5371)? Find out why here....
23-May-23	Half-Mast Sends: Just Ask Already	https://www.psmagazine.army.mil/News/Article/3404531/half-mast-sends-just-ask-already/	This article initially appeared in PS 753, p. 1 (Sep 15). Got a burning question but reluctant to speak up? Here's something to think about...

Aviation



Date	Article Title	Link	Excerpt
3-May-23	Black Hawk: EBAPS Part Number Update	https://www.psmagazine.army.mil/News/Article/3382879/black-hawk-ebaps-part-number-update/	All UH-60s flying under AWR 1752 that have the enhanced ballistic armament protection system (EBAPS) kit installed need to contact UH-60 Program Office for a part number change. Read on to find out more...
5-May-23	Shadow: Don't Throw Away Cables!	https://www.psmagazine.army.mil/News/Article/2703441/shadow-dont-throw-away-cables/	Mechanics, the Army Shadow team needs your help. They're running short on some of the cables found in the Shadow system, so they're asking you to check the list below before you throw any cables away. Read on to find out more...
8-May-23	H-60 Series: Look Before You Hook!	https://www.psmagazine.army.mil/News/Article/3387648/h-60-series-look-before-you-hook/	This article initially appeared in PS 710 (Jan 12), p. 21. Pitot tubes can be dangerous, so watch out for them when putting on nose the cover for your H-60 helicopters. Read on to find out more...
8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
10-May-23	AH-64: New ECS Servicing Cart PN Now Available	https://www.psmagazine.army.mil/News/Article/3389857/ah-64-new-ecs-servicing-cart-pn-now-available/	Environmental control system (ECS) servicing cart, PN 7-562104012-605 and PN 7-562104012-603, have been replaced with PN 7-562104012-607. Until units get the newer cart, they must maintain existing carts. Read on to find out more...
17-May-23	AH-64: Removing Nose Gearbox Blocker Plates	https://www.psmagazine.army.mil/News/Article/3397692/ah-64-removing-nose-gearbox-blocker-plates/	This article initially appeared in PS 699 (Feb 11). Removing the Apache nose gearbox plates requires some elbow grease but avoid using a pocket tool or screwdriver to remove them. Read on to learn more...

17-May-23	All Aircraft: Repair Acrylic Windows	https://www.psmagazine.army.mil/News/Article/3398694/all-aircraft-repair-acrylic-windows/	This article initially appeared in PS 753 (Aug 15), p. 23. Instead of tossing out acrylic windows with scratches, blemishes or minor damage follow the good words in TM 1-1500-204-23-10 to repair them. Read on to find out more...
23-May-23	HH/UH-60M, AH-64E, CH-47F: Aircraft Hand-held Fire Extinguishers	https://www.psmagazine.army.mil/News/Article/3404734/hhuh-60mah-64e-ch-47f-aircraft-hand-held-fire-extinguishers/	This article initially appeared in PS 735 (Feb 14), p. 22. Black Hawks, Apache's and Chinooks require a certain number of portable hand-held fire extinguishers. Read on to find out more...
24-May-23	Shadow: Use Digital Instead of Dial Torque Wrench	https://www.psmagazine.army.mil/News/Article/3405427/shadow-use-digital-instead-of-dial-torque-wrench/	MEOs S1705A and S1798 allow Shadow users to use a digital torque wrench to test caliper brake pressure because the dial torque wrench is no longer provisioned. Read on to find out more...
24-May-23	Aviation Maintenance: MOS 15H Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3406130/aviation-maintenance-mos-15h-invited-to-take-job-analysis-survey/	All aircraft pneudraulics repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
24-May-23	CH-47F Chinook: Replacement for Bad Engine Cowling Sealing Strip	https://www.psmagazine.army.mil/News/Article/3406193/ch-47f-chinook-replacement-for-bad-engine-cowling-sealing-strip/	The fairing sealing strip on the lower cowling does not stay in place because of chafing. The remedy is to use anti-chafe rubber bumpers instead. Read on to find out how to install them...

CBRN




Date	Article Title	Link	Excerpt
2-May-23	CBRN: M8 Paper Improvements	https://www.psmagazine.army.mil/News/Article/3380958/cbrn-m8-paper-improvements/	Current M8 paper not only detects blister and nerve (G and VX) agents but can also detect liquid A-series agents as indicated by a color change from dark green to yellow green after 10 or more minutes. Keep reading to learn more...

Combat Vehicles



Date	Article Title	Link	Excerpt
16-May-23	Ground Vehicles: BDAR Kit NSN	https://www.psmagazine.army.mil/News/Article/3396937/ground-vehicles-bdar-kit-nsn/	Get the latest and greatest Class IX Battle Damage and Assessment Repair (BDAR) crew kit with NSN 2590-01-659-5620. It's suitable for all combat and tactical vehicles. Read on for more info...

Construction




Date	Article Title	Link	Excerpt
10-May-23	M1022-Series Dolly Set Mobilizer: Tire and Wheel Assembly NSN	https://www.psmagazine.army.mil/News/Article/3390711/m1022-series-dolly-set-mobilizer-tire-and-wheel-assembly-nsn/	Maintainers, the current TM for the M1022-series dolly set mobilizer doesn't include the NSN for the tire and wheel assembly. Get it here...
15-May-23	M30 BEB: Transmission Oil NSNs	https://www.psmagazine.army.mil/News/Article/3393464/m30-beb-transmission-oil-nsns/	The lube order for the BEB lists a 55-gal drum and its NSN but provides no other sizes. Smaller quantities are available. For the NSNs, keep reading...
23-May-23	924H/G Wheel Loader: Double-check Front Bucket Hydraulic Hose Couplings	https://www.psmagazine.army.mil/News/Article/3404209/924hg-wheel-loader-double-check-front-bucket-hydraulic-hose-couplings/	Inspect the bucket's hydraulic hose couplings for oil leaks. Make sure the couplings "click" tight in place. Keep reading for more...

Commo/Electronics




Date	Article Title	Link	Excerpt
2-May-23	Radio Systems: GEN II MANPACK HUB Maintenance and Replacement	https://www.psmagazine.army.mil/News/Article/3381566/radio-systems-gen-ii-manpack-hub-maintenance-and-replacement/	It's important to know the correct steps for R/T HUB replacement. Mistakes can mean elevation to higher maintenance levels. To learn more, keep reading....
15-May-23	SINCGARS: Circuit Card Assembly PN Marking Problem	https://www.psmagazine.army.mil/News/Article/3393564/sincgars-circuit-card-assembly-pn-marking-problem/	Did you run into a problem when trying to turn in the SINCGARS Circuit Card Assembly – Flexible Rear Panel – RT (NSN 5998-01-539-5371)? Find out why here...

H2F



There are no new articles this month.

Logistics Management



Date	Article Title	Link	Excerpt
5-May-23	Logistics Management: CY 2022 Petroleum Excellence Winners	https://www.psmagazine.army.mil/News/Article/3386271/logistics-management-cy-2022-petroleum-excellence-winners/	<p>The annual Petroleum Excellence awards recognize superior performance in petroleum management and fuel handling. The CY22 Petroleum Excellence awards are announced. To find out where to get the list of winners, read on...</p>
8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	<p>All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...</p>
24-May-23	Publications: ETM Updates and IADS Conversion	https://www.psmagazine.army.mil/News/Article/3405787/publications-etm-updates-and-iads-conversion/	<p>Looking for ETM or IETM updates, such as when they convert to IADS? Keep reading to find out where to track them...</p>

Medical Logistics




There are no new articles this month.

Mines




Date	Article Title	Link	Excerpt
4-May-23	M1270 MMPV Type II: New Annual Service Kit NSN	https://www.psmagazine.army.mil/News/Article/3384656/m1270-mmpv-type-ii-new-annual-service-kit-nsn/	Maintainers, there's a new annual service kit for the M1270 MMPV Type II that's not in the current TM. Get the NSN here...
18-May-23	M1272 Buffalo: Annual Service Kit NSN	https://www.psmagazine.army.mil/News/Article/3399400/m1272-buffalo-annual-service-kit-nsn/	The M1272 has an annual service kit but it's not listed in the TM. Read on to learn the NSN...

Missiles



Date	Article Title	Link	Excerpt
25-May-23	Avenger: Argon Bottles Inspect and Replace Criteria	https://www.psmagazine.army.mil/News/Article/3407041/avenger-argon-bottles-inspect-and-replace-criteria/	Pay attention to two dates annotated on each Avenger argon bottle. There's a 5-year proof pressure tested and manufacture build date. Why? Keep reading for all the details...

Small Arms



Date	Article Title	Link	Excerpt
8-May-23	M16-Series Rifle, M4/M4A1 Carbine: See the New AAL Items	https://www.psmagazine.army.mil/News/Article/3387505/m16-series-rifle-m4m4a1-carbine-see-the-new-aal-items/	TACOM has added new items to the M16-Series Rifle, M4/M4A1 Carbine additional authorization list (AAL). Keep reading to see the new items...
10-May-23	M4 and M16 Series Rifles: Only You Can Avoid a Cook Off	https://www.psmagazine.army.mil/News/Article/3389878/m4-and-m16-series-rifles-only-you-can-avoid-a-cook-off/	Know your weapons' sustained rate of fire. Don't exceed the sustained rate of fire except under extreme circumstances to avoid a possible cook off or catastrophic failure. Read on to get the full story...

Soldier Support



Date	Article Title	Link	Excerpt
5-May-23	Logistics Management: CY 2022 Petroleum Excellence Winners	https://www.psmagazine.army.mil/News/Article/3386271/logistics-management-cy-2022-petroleum-excellence-winners/	The annual Petroleum Excellence awards recognize superior performance in petroleum management and fuel handling. The CY22 Petroleum Excellence awards are announced. To find out where to get the list of winners, read on...
8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
15-May-23	Laundry Advanced Systems: No Open Door Policy	https://www.psmagazine.army.mil/News/Article/3394193/laundry-advanced-systems-no-open-door-policy/	Keep the doors to all enclosures shut tight. An open door is an invitation for fine dirt and sand to settle on electrical and electronic components and contacts. Keep reading to learn the problems this will cause...
16-May-23	Soldier Support: New Limitations on Shipping Lithium Batteries	https://www.psmagazine.army.mil/News/Article/3397036/soldier-support-new-limitations-on-shipping-lithium-batteries/	Time to make a PCS? Plan ahead and note the new limitations on shipping lithium batteries. Find out more here...
24-May-23	Tactical Expandable Shelters: Keep Cautions in Mind	https://www.psmagazine.army.mil/News/Article/3405747/tactical-expandable-shelters-keep-cautions-in-mind/	There are some important warnings to keep in mind when opening or closing tactical expanded shelters. Here's what to know...


Tactical Vehicles



Date	Article Title	Link	Excerpt
2-May-23	M149-Series Water Trailers: NSNs for Safety Chain and Accessories	https://www.psmagazine.army.mil/News/Article/3381427/m149-series-water-trailers-nsns-for-safety-chain-and-accessories/	Get safety chain in bulk with NSN 4030-01-501-6946. We've got all the NSNs for replacing the safety chain and assembly. Get them here..
3-May-23	HMMWV: Need Hardtops?	https://www.psmagazine.army.mil/News/Article/3383349/hmmwv-need-hardtops/	Do you need hardtop covers for your HMMWV? The Army has only authorized certain variations of hardtops for HMMWVs and you won't find them in any of the HMMWV TMs because the Army doesn't support them. But if you want them, you can still get them. Keep reading to see a complete list.....
9-May-23	Ground Vehicles: View New CARC Spot Painting Videos	https://www.psmagazine.army.mil/News/Article/3389190/ground-vehicles-view-new-carc-spot-painting-videos/	TACOM CPC has released new CARC spot painting videos. There's a video for using aerosol paints and a video for using pint and quart kits. Get more info...
10-May-23	M1022-Series Dolly Set Mobilizer: Tire and Wheel Assembly NSN	https://www.psmagazine.army.mil/News/Article/3390711/m1022-series-dolly-set-mobilizer-tire-and-wheel-assembly-nsn/	Maintainers, the current TM for the M1022-series dolly set mobilizer doesn't include the NSN for the tire and wheel assembly. Get it here...
15-May-23	M872-Series Semitrailers: Corrosion Inspections	https://www.psmagazine.army.mil/News/Article/3395309/m872-series-semitrailers-corrosion-inspections/	TACOM MIM 23-015 advises there's a reinspection for corrosion on M872-series semitrailers. This includes the M872A4 model that wasn't inspected for corrosion in 2016. Get more info...

16-May-23	Ground Vehicles: BDAR Kit NSN	https://www.psmagazine.army.mil/News/Article/3396937/ground-vehicles-bdar-kit-nsn/	<p>Get the latest and greatest Class IX Battle Damage and Assessment Repair (BDAR) crew kit with NSN 2590-01-659-5620. It's suitable for all combat and tactical vehicles. Read on for more info...</p>
16-May-23	Fuel Tanker Trailers: New NSNs for Fire Extinguishers and Brackets	https://www.psmagazine.army.mil/News/Article/3397163/fuel-tanker-trailers-new-nsns-for-fire-extinguishers-and-brackets/	<p>TACOM has some NSN changes to the fire extinguishers and brackets for fuel tanker trailers that aren't in the current TMs. Get them here...</p>
24-May-23	PLS: M6 Dump Body Tarp	https://www.psmagazine.army.mil/News/Article/3405635/pls-m6-dump-body-tarp/	<p>This article initially appeared in PS 766 (Sep 16), p.60. NSN 2540-01-449-5775, which is shown as Item 19 in Fig 1 of TM 9-3930-259-13&P (Jun 07), is for the M917 dump truck. It's too wide and short for the M6 dump body modular. Get the right NSN here...</p>

Tools



Date	Article Title	Link	Excerpt
3-May-23	Tools: DeWALT Miter Saw Recall	https://www.psmagazine.army.mil/News/Article/3382024/tools-dewalt-miter-saw-recall/	Follow the detailed instructions on how to replace your DeWALT® miter saw's plastic rear guard assembly. Before and after operation, make it a point to always inspect your saw for any damage. Keep reading the full story...

Make **PMCS**...

WOULD YOU STAKE
YOUR LIFE, *RIGHT NOW*,
ON THE CONDITION OF
YOUR EQUIPMENT?



...a **Team Effort** in
your **Motor Pool!**