



2023 Index Of Online Articles



HERE'S AN INDEX OF THE
PS MAGAZINE ARTICLES
THAT APPEARED ON OUR
WEBSITE FROM
JANUARY 1, 2023
THROUGH
DECEMBER 31, 2023.



The Preventive Maintenance Monthly Index of Online Articles

2023 Roll-up

General & Special Topics	2
Aviation	16
CBRN	28
Combat Vehicles	31
Construction	39
Commo/Electronics	46
H2F	54
Logistics/Maintenance Management	56
Medical Logistics	63
Mines	65
Missiles	68
Small Arms	71
Soldier Support	76
Tactical Vehicles	84
Tools	92
Watercraft	94

TB 43-PS 2023 Roll-up, *The Preventive Maintenance Monthly Index of Online Articles* is an official publication of the Department of the Army, providing a reference tool for all Soldiers assigned to combat and combat support units to access PS Magazine articles published to its official .mil website. All referenced articles have been reviewed and approved by the agency responsible for the equipment, publication or policy discussed in any referenced article. Application of the information in those articles is encouraged but optional with the user. The use of product or company names does not constitute endorsement of those products, services or companies by the U.S. Army. The use of non-DoD hyperlinks, along with that content, does not constitute endorsement by the DoD or DA. Neither DoD nor DA exercises any editorial control over, and cannot vouch for, content on non-DoD websites.

PS: The Preventive Maintenance Monthly Index of Online Articles (ISSN 0475-2953)
is published monthly by the Department of the Army, Redstone Arsenal, AL 35898.

You are invited to send PS your ideas for improving maintenance procedures, questions on maintenance and supply problems and questions or comments on material published in PS.

Just write to:

MSG Half-Mast
PS, the Preventive Maintenance Monthly
USAMC ARMY SUSTAINMENT COMMAND

3218 Snooper Rd.
Redstone Arsenal, AL 35898

Or email:

usarmy.redstone.asc.mbx.psmag@army.mil

Internet address:

<https://www.psmagazine.army.mil>

By Order of the Secretary of the Army:

RANDY A. GEORGE
General, United States Army
Chief of Staff

Official:

MARK F. AVERILL
Administrative Assistant
to the Secretary of the Army

DISTRIBUTION:
Distributed in electronic media only(EMO).

General and Special Topics



Date	Article Title	Link	Excerpt
6-Jan-23	I Own This: December 2022 Nominees	https://www.psmagazine.army.mil/News/Article/3260633/i-own-this-december-2022-nominees/	PS Magazine's I Own This campaign is designed to recognize Warfighters of all services who exemplify the highest standards of care for their assigned vehicles and equipment and contribute in meaningful ways to their unit's overall maintenance and supply posture. In short, they live and breathe readiness. For December 2022, eight (8) Warfighters were nominated for this program. Read on to learn who they are...
6-Jan-23	Leader Interview: COL Medaglia, UAS PM	https://www.psmagazine.army.mil/News/Article/3260818/leader-interview-col-medaglia-uas-pm/	MSG Half-Mast recently drove across Redstone Arsenal to speak with COL Danielle Medaglia, Unmanned Aircraft Systems (UAS) Project Manager to discuss the current state of UAS, future development efforts and some maintenance best practices. Read on to learn more about UAS...
12-Jan-23	Tactical Vehicles Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265719/tactical-vehicles-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for tactical vehicles and equipment. Get them here.....
13-Jan-23	Aviation Year-in- Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265474/aviation-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for aircraft and aviation equipment. Get them here...
13-Jan-23	Small Arms Year-in- Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265268/small-arms-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for small arms. Get them here...

13-Jan-23	Commo/Electronics & Soldier Support Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265481/commoelectronics-soldier-support-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for commo/electronics and Soldier support. Get them here...
13-Jan-23	Construction Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3266053/construction-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for construction equipment and vehicles. Get them here...
13-Jan-23	Combat Vehicles Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3266058/combat-vehicles-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for combat vehicles and equipment. Get them here...
13-Jan-23	PS Magazine Year-In-Review: Top 10 Website Downloads	https://www.psmagazine.army.mil/News/Article/3267702/ps-magazine-year-in-review-top-10-website-downloads/	The PS Magazine website features helpful documents, posters and charts that were downloaded over 80,000 times. You might be interested to learn what the most downloaded items were. Read on to find out...
18-Jan-23	Flat Half-Mast: Seeking Rendezvous with History and More	https://www.psmagazine.army.mil/News/Article/3271204/flat-half-mast-seeking-rendezvous-with-history-and-more/	You probably know about Flat Stanley. Now meet Flat Half-Mast. He's raring for some new adventures and seeks travel partners to take him to new places. Read on to learn how...
23-Jan-23	Leader Interview: CW5 Beck, ASC Stockage Determination	https://www.psmagazine.army.mil/News/Article/3274595/leader-interview-cw5-beck-asc-stockage-determination/	MSG Half-Mast didn't have to travel far to meet with CW5 John P. Beck, the Deputy of the Stockage Determination Branch, a subordinate activity of Army Sustainment Command, located on Redstone Arsenal, Alabama...

24-Jan-23	Soldier Support: Info about Soldier Referral Program	https://www.psmagazine.army.mil/News/Article/3275057/soldier-support-info-about-soldier-referral-program/	Ready to support Army recruiting efforts? Now's the time with the new Soldier Referral Program. The rewards are awesome. To learn more, read on...
24-Jan-23	SINCGARS: M917 Dump Truck Not on List	https://www.psmagazine.army.mil/News/Article/3276247/sincgars-m917-dump-truck-not-on-list/	A reader asks if a SINCGARS installation kit is available for the M917 dump truck. The simple answer is, No. But there's more, so keep reading...
26-Jan-23	Half-Mast Sends: Keep on Trucking	https://www.psmagazine.army.mil/News/Article/3277954/half-mast-sends-keep-on-trucking/	The war in Ukraine is offering a lot of lessons. The question is: Are we learning them? An informative CNN article offers some insights on the importance of maintenance and logistics basics that are worth heeding. And we offer links to articles in our archive that reinforce important lessons learned. So read on...
1-Feb-23	MEP-831A Generator: Finding an XB-coded Part	https://www.psmagazine.army.mil/News/Article/3285040/mep-831a-generator-finding-an-xb-coded-part/	The 3-kW MEP 831A generator has a metal plate that's coded XB. What does it mean when a part is coded XB? Keep reading to learn Half-Mast's answer...
1-Feb-23	MEP-1050/1051 Generators: Finding Elusive Oil Filter	https://www.psmagazine.army.mil/News/Article/3285190/mep-10501051-generators-finding-elusive-oil-filter/	A Soldier is looking for an NSN for the MEP-1050 generator oil filter. Get the scoop here...
2-Feb-23	M1-Series Tank: Turret Maintenance Stand Fabrication Plans	https://www.psmagazine.army.mil/News/Article/3286693/m1-series-tank-turret-maintenance-stand-fabrication-plans/	The M1-series tank turret maintenance stand cannot be ordered; instead, it is fabricated by units. Read on for info on where to find the plans...

2-Feb-23	FMTV: Updated Flex Plate Bolt Torque	https://www.psmagazine.army.mil/News/Article/3286243/fmtv-updated-flex-plate-bolt-torque/	TACOM has revised the flex plate bolts torque for FMTVs. Get the info you need here...
3-Feb-23	I Own This: January 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3287546/i-own-this-january-2023-nominees/	PS Magazine's I Own This campaign is designed to recognize Warfighters of all services who exemplify the highest standards of care for their assigned vehicles and equipment and contribute in meaningful ways to their unit's overall maintenance and supply posture. In short, they live and breathe readiness. For January 2023, one (1) Warfighter was nominated for this program. Read on to learn who they are...
7-Feb-23	SINCGARS: FMTV Radio Installation Kits Differ	https://www.psmagazine.army.mil/News/Article/3291540/sincgars-fmtv-radio-installation-kits-differ/	The up-armored FMTV LTAS variant's SINCGARS radio installation kit and that of the non-armored FMTV are different. Read on to learn more...
9-Feb-23	Corrosion: TACOM Introduces Basic Corrosion Course for Operators	https://www.psmagazine.army.mil/News/Article/3293573/corrosion-tacom-introduces-basic-corrosion-course-for-operators/	There's a new corrosion course available for all Army personnel, including civilians and contractors who operate and maintain Army ground equipment. Read on...
14-Feb-23	Leader Interview: SFC Asher, TRADOC CADD	https://www.psmagazine.army.mil/News/Article/3296642/leader-interview-sfc-asher-tradoc-cadd/	MSG Half-Mast recently stopped by the scenic post of Ft Leavenworth, KS to meet and greet SFC Matthew J. Asher, the face of the newly updated FM 3-0, Operations (Oct 22). Read on to learn more about how FM 3-0 and readiness intersect...

14-Feb-23	PS Magazine: A One-Stop Shop for 70 Years of PS	https://www.psmagazine.army.mil/News/Article/3297478/ps-magazine-a-one-stop-shop-for-70-years-of-ps/	This article initially appeared in PS 783, p.61. Want a peek at PS history? We have the website for you! Get a glimpse of the PS gang from years gone by....
14-Feb-23	M240B Machine Gun: Properly Clean the Gas System to Avoid Malfunction	https://www.psmagazine.army.mil/News/Article/3297430/m240b-machine-gun-properly-clean-the-gas-system-to-avoid-malfunction/	If the M240 machine gun isn't cleaned properly, to include using the proper special tools, then the weapon can malfunction. Keep reading to see how to properly clean the gas port system...
23-Feb-23	Communications: JBC-P Fuse Proves Elusive	https://www.psmagazine.army.mil/News/Article/3306698/communications-jbc-p-fuse-proves-elusive/	A reader is looking for the NSN for the 8-amp, 250V glass fuse for the Joint Battle Command-Platform. Half-Mast helps them out. Read on for that NSN....
2-Mar-23	I Sustain This: February 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3316749/i-sustain-this-february-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For Feb 2023, we had one civilian sustainer nominated for this program. Read on to learn about the nominee and their contributions to Army readiness...
March 6, 2023	Half-Mast Sends: Lose the 'Rabbit Habit'	https://www.psmagazine.army.mil/News/Article/3320071/half-mast-sends-lose-the-rabbit-habit/	This article initially appeared in PS 736, p.1 (Mar 14). Tempted to take a PMCS shortcut? Read an important reminder here...

15-Mar-23	PS Magazine: Breakdown of Reader Inquiries in 2022	https://www.psmagazine.army.mil/News/Article/3328856/ps-magazine-breakdown-of-reader-inquiries-in-2022/	PS Magazine actively encourages readers to submit questions on matters that have them stumped or ideas for improving readiness across the force. In 2022, Soldiers and civilians from around the world did just that. Keep reading to see the breakdown...
21-Mar-23	Safety: USACRC Launches New Courses	https://www.psmagazine.army.mil/News/Article/3335638/safety-usacrc-launches-new-courses/	There are three new safety courses available beginning on 1 Apr 23. Read on to get all the info...
23-Mar-23	Publications: How to Find New and Revised TMs	https://www.psmagazine.army.mil/News/Article/3339167/publication-how-to-find-new-and-revised-tms/	A Soldier is looking for a list of brand-new TMs, as well as revisions to existing TMs. Connie refers them to the Army Publishing Directorate website. Read on to learn more...
30-Mar-23	Half-Mast Sends: Heed PMCS Cautions and Warnings	https://www.psmagazine.army.mil/News/Article/3345325/half-mast-sends-heed-pmcs-cautions-and-warnings/	An article in Risk Management Magazine, written by MAJ Eric Tolska, gives a real-life example of why paying attention to PMCS warnings and cautions is so important. Read on to learn more about the article...
3-Apr-23	Leader Interview: CW3 RiveraOrtiz, 10th Support Group	https://www.psmagazine.army.mil/News/Article/3348176/leader-interview-cw3-riveraortiz-10th-support-group/	MSG Half-Mast recently travelled to Torii Station, Okinawa, Japan, to meet with CW3 Jaime L. RiveraOrtiz, the senior maintenance technician for the 10th Support Group (SG). The two discussed the challenges of sustaining equipment in the unique operating environment found on the island, with special emphasis on corrosion. Keep reading to discover how the 10th SG masters those challenges...

4-Apr-23	I Sustain This: March 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3351409/i-sustain-this-march-2023-nominees/	<p>PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For Mar 2023, we had two civilian sustainers nominated for this program. Read on to learn about the nominees and their contributions to Army readiness...</p>
14-Apr-23	Half-Mast Sends: Reminder on Safeguarding Classified Information	https://www.psmagazine.army.mil/News/Article/3362893/half-mast-sends-reminder-on-safeguarding-classified-information/	<p>Personnel with access to classified information are trusted stewards of that information. The responsibility to safeguard classified information is a lifetime requirement for everyone granted a security clearance. Continue reading for this reminder...</p>
28-Apr-23	Half-Mast Sends: Readiness Starts with You	https://www.psmagazine.army.mil/News/Article/3376829/half-mast-sends-readiness-starts-with-you/	<p>This article initially appeared in PS 780 (Nov 17), p. 1. The person best suited to determine your equipment's readiness is you. Remember that the next time you pull PMCS. Fix what you can and report what you can't. Keep reading to learn more of Half-Mast's wisdom on this topic...</p>
4-May-23	Leader Interview: Mr. Duxbury, AMC C5ISR L-STR	https://www.psmagazine.army.mil/News/Article/3384328/leader-interview-mr-duxbury-amc-c5isr-l-str/	<p>MSG Half-Mast recently traveled to Ft Drum to visit with Mr. James Duxbury, the AMC C5ISR Lead-System Tech Rep (L-STR) for the 10th Mountain Division/CECOM Integrated Logistics Support Center (ILSE) Forward Element – East Region, Army Field Support Battalion-Drum, 406th AFSB. They discussed the role of the L-STR in helping to improve C5ISR readiness. Keep reading to learn more about this vital role...</p>

4-May-23	I Sustain This: April 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3385194/i-sustain-this-april-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For April 2023, we had one civilian sustainer nominated for this program. Read on to learn about the nominee and his contributions to Army readiness...
5-May-23	I Own This Campaign: Nominate a Deserving Warfighter	https://www.psmagazine.army.mil/News/Article/2188371/i-own-this-campaign-nominate-a-deserving-warfighter/	Taking ownership and pride in assigned vehicles and equipment is vital to ensuring personal, unit and fleet readiness. Without this personal investment and active involvement, Warfighters fail to ensure preventive and scheduled maintenance gets done when it should and by the book. This failure, in turn, results in non-mission capable (NMC) vehicles...
5-May-23	Logistics Management: CY 2022 Petroleum Excellence Winners	https://www.psmagazine.army.mil/News/Article/3386271/logistics-management-cy-2022-petroleum-excellence-winners/	The annual Petroleum Excellence awards recognize superior performance in petroleum management and fuel handling. The CY22 Petroleum Excellence awards are announced. To find out where to get the list of winners, read on...
8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
10-May-23	M1022-Series Dolly Set Mobilizer: Tire and Wheel Assembly NSN	https://www.psmagazine.army.mil/News/Article/3390711/m1022-series-dolly-set-mobilizer-tire-and-wheel-assembly-nsn/	Maintainers, the current TM for the M1022-series dolly set mobilizer doesn't include the NSN for the tire and wheel assembly. Get it here...

15-May-23	M30 BEB: Transmission Oil NSNs	https://www.psmagazine.army.mil/News/Article/3393464/m30-beb-transmission-oil-nsns/	The lube order for the BEB lists a 55-gal drum and its NSN but provides no other sizes. Smaller quantities are available. For the NSNs, keep reading...
15-May-23	SINCGARS: Circuit Card Assembly PN Marking Problem	https://www.psmagazine.army.mil/News/Article/3393564/sincgars-circuit-card-assembly-pn-marking-problem/	Did you run into a problem when trying to turn in the SINCGARS Circuit Card Assembly – Flexible Rear Panel – RT (NSN 5998-01-539-5371)? Find out why here....
23-May-23	Half-Mast Sends: Just Ask Already	https://www.psmagazine.army.mil/News/Article/3404531/half-mast-sends-just-ask-already/	This article initially appeared in PS 753, p. 1 (Sep 15). Got a burning question but reluctant to speak up? Here's something to think about...
1-Jun-23	Food Service: Connelly Awards Announced	https://www.psmagazine.army.mil/News/Article/3412980/food-service-connelly-awards-announced/	The annual awards for the FY23 55th annual Philip A. Connelly are announced. To find out who won, read on.....
5-Jun-23	I Sustain This: May 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3416611/i-sustain-this-may-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For May 2023, we had two civilian sustainers nominated for this program. Read on to learn about the nominees and their contributions to Army readiness...


6-Jun-23	I Own This: May 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3417730/i-own-this-may-2023-nominees/	PS Magazine's I Own This campaign is designed to recognize Warfighters of all services who exemplify the highest standards of care for their assigned vehicles and equipment and contribute in meaningful ways to their unit's overall maintenance and supply posture. In short, they live and breathe readiness. For May 2023, one Warfighter was nominated for this program. Read on to learn who they are...
7-Jun-23	Safety: Lethal Means Safety Can Reduce Suicides	https://www.psmagazine.army.mil/News/Article/3418831/safety-lethal-means-safety-can-reduce-suicides/	"Lethal Means Safety" is an approach to preventing self-harm by securing firearms, prescription drugs and other items that might be used in suicide attempts. Learn more here...
8-Jun-23	Half-Mast Sends: The Long, Hot Summer	https://www.psmagazine.army.mil/News/Article/3421935/half-mast-sends-the-long-hot-summer/	This article initially appeared in PS 764, p. 1 (Jul 16). Heat brings challenges to Soldiers and equipment alike. Read this important reminder about prepping for that scorching summertime...
6-Jul-23	I Sustain This: June 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3449470/i-sustain-this-june-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For June 2023, we had one civilian sustainer nominated for this program. Read on to learn about the nominee and their contributions to Army readiness...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...

10-Jul-23	Heat Safety: Army's Annual Guidance Worth the Read	https://www.psmagazine.army.mil/News/Article/3452510/heat-safety-armys-annual-guidance-worth-the-read/	Stay alert for the signs of heat-related illnesses with the Army's annual guidance. Learn more here...
11-Jul-23	SINCGARS: Searching for PMCS Tables	https://www.psmagazine.army.mil/News/Article/3454892/sincgars-searching-for-pmcs-tables/	A Soldier is asking about where to locate the PMCS tables for SINCGARS. Half-Mast has the answer. It's available in a TM covering over 20 models. To find out more, read on...
17-Jul-23	Apache: Correctly Reinstall Generator Wires	https://www.psmagazine.army.mil/News/Article/3460087/apache-correctly-reinstall-generator-wires/	This article initially appeared in PS 594 (02), p. 39. When removing generator wires, make sure you use heat-shrinkable bands to help you reinstall the wires correctly after maintenance. Read on to find out more...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
3-Aug-23	I Sustain This: July 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3481985/i-sustain-this-july-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For July 2023, we had one civilian sustainer nominated for this program: Jonina Young, FORSCOM G-2 Readiness Specialist. Read on to learn about the nominee and their contributions to Army readiness...

4-Aug-23	Interview: 2ABCT, 3ID Log/Maint Leaders Discuss NTC Rotation	https://www.psmagazine.army.mil/News/Article/3476354/interview-2abct-3id-logmaint-leaders-discuss-ntc-rotation/	MSG Half-Mast recently traveled to Ft Stewart to visit with MAJ Ryan Bocklage, 3rd ID Deputy G4, and CW4 Calvin Sanders, 2nd ABCT Maintenance Technician, about the Spartan Brigade's recent rotation to the National Training Center (Feb 23). They discussed the challenges, lessons learned and successes encountered during the rotation...
14-Aug-23	MRZR Polaris: Not Army Supported, So No RPSTL	https://www.psmagazine.army.mil/News/Article/3492315/mrzs-polaris-not-army-supported-so-no-rpstl/	The MRZR Polaris utility vehicle is a unit-purchased item. That means there's no RPSTL because the Army doesn't maintain them, and spare parts and equipment must be a local purchase. Keep reading to learn more...
18-Aug-23	Suicide Prevention: New AR Provides Comprehensive Guidance	https://www.psmagazine.army.mil/News/Article/3497514/suicide-prevention-new-ar-provides-comprehensive-guidance/	The Army has provided additional guidance and resources for suicide prevention in a new publication, AR 600-92. Learn more here...
21-Aug-23	Leader Interview: Mr. John Mayatte, Director ASC PSCC	https://www.psmagazine.army.mil/News/Article/3498997/leader-interview-mr-john-mayatte-director-asc-pscc/	A few weeks back, MSG Half-Mast travelled to Tobyhanna Army Depot to speak with Mr. John Mayatte, Director of the Army Sustainment Command's (ASCs) Packaging, Storage and Containerization Center (PSCC) to gain a better understanding of the organization's mission and impact on Army readiness. Keep reading to learn more about this unique organization...

6-Oct-23	Leader Interview: CW3 Jones & SFC Conaway, 10th SG	https://www.psmagazine.army.mil/News/Article/3550739/leader-interview-cw3-jones-sfc-conaway-10th-sg/	<p>MSG Half-Mast recently travelled back to Okinawa, Japan, where he met with CW3 Paul B. Jones, the Accountable Officer, 10th Support Group (SG) ammunition depot, and SFC Alexander Conaway, the ammo depot NCOIC. The three of them discussed the challenges inherent with maintaining and sustaining ammunition in East Asia. Keep reading to learn more about the 10th SG's unique mission on Okinawa...</p>
9-Oct-23	I Own This: September 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3551832/i-own-this-september-2023-nominees/	<p>PS Magazine's I Own This campaign is designed to recognize Warfighters of all services who exemplify the highest standards of care for their assigned vehicles and equipment and contribute in meaningful ways to their unit's overall maintenance and supply posture. In short, they live and breathe readiness. For September 2023, 11 Warfighters were nominated for this program. Read on to learn who they are...</p>
4-Dec-23	I Own This: November 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3605108/i-own-this-november-2023-nominees/	<p>PS Magazine's I Own This campaign is designed to recognize Warfighters of all services who exemplify the highest standards of care for their assigned vehicles and equipment and contribute in meaningful ways to their unit's overall maintenance and supply posture. In short, they live and breathe readiness. For November 2023, two Warfighters were nominated for this program. Read on to learn who they are...</p>

Aviation



Date	Article Title	Link	Excerpt
3-Jan-23	UH-60: Corrosion Compound Now Authorized for Stabilator	https://www.psmagazine.army.mil/News/Article/3257439/uh-60-corrosion-compound-now-authorized-for-stabilator/	Several TM work packages are being corrected to allow limited application of Cor-Ban 27L corrosion preventive compound on the stabilator.
3-Jan-23	Black Hawk: New Inspection Criteria for HSS Expandable Pins	https://www.psmagazine.army.mil/News/Article/3257476/black-hawk-new-inspection-criteria-for-hss-expandable-pins/	Inspection criteria for the HSS expandable pins has changed and the relevant work packages must be updated.
10-Jan-23	AH-64/H-60: Sign Up for T700 Engine Classes for 2023	https://www.psmagazine.army.mil/News/Article/3263625/ah-64h-60-sign-up-for-t700-engine-classes-for-2023/	General Electric has announced its 2023 training schedule for classes on the T700-series engine.
13-Jan-23	Aviation Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265474/aviation-year-in-review-new-and-updated-nsns-captured-in-2022/	Here's a list of new or updated NSNs that PS captured in 2022 for aviation, as well as NSN turn-ins that are needed for repair.
19-Jan-23	AH-64/H-60: T700-GE-701D Engine Gets Newer PTM	https://www.psmagazine.army.mil/News/Article/3269541/ah-64h-60-t700-ge-701d-engine-gets-newer-ptm/	The T700 engine gets a new Power Turbine Module (PTM) starting in January 2023.
20-Jan-23	AH-64/H-60: Managing Compressor Issues and Engine Noise	https://www.psmagazine.army.mil/News/Article/3270670/ah-64h-60-managing-compressor-issues-and-engine-noise/	The Utility Helicopter Project Office offers guidance on ways to manage compressor issues and engine noise.
20-Jan-23	UH-60V: Mission Equipment Needed for New Aircraft Fielding	https://www.psmagazine.army.mil/News/Article/3270805/uh-60v-mission-equipment-needed-for-new-aircraft-fielding/	The fielding of UH-60V MEDEVAC aircraft in FY24 depends on units turning in MEDEVAC mission equipment now.

26-Jan-23	MEDEVAC: Hoist Cowling Modification Reduces Maintenance Burden	https://www.psmagazine.army.mil/News/Article/3279059/medevac-hoist-cowling-modification-reduces-maintenance-burden/	MEO B3379 allows for cowling modification on the external rescue hoist to make event counter viewing easier.
27-Jan-23	AGSE: Magnetic Particle Inspection Kit Added to NDI Shelter	https://www.psmagazine.army.mil/News/Article/3279639/agse-magnetic-particle-inspection-kit-added-to-ndi-shelter/	Maintenance information message AGSE-23-MIM-01 adds a new tool, the magnetic particle inspection kit, to the NDI shelter.
1-Feb-23	Apache: Inspect for Missing Grommet in E-Model Extended Forward Avionics Bay	https://www.psmagazine.army.mil/News/Article/3285244/apache-inspect-for-missing-grommet-in-e-model-extended-forward-avionics-bay/	AMAM H-64-23-AMAM-05 requires inspection of the right-hand extended forward avionics bay (EFAB) skate angle for a missing grommet on select aircraft.
7-Feb-23	AGSE: TMs for Aviation Ground Support Equipment	https://www.psmagazine.army.mil/News/Article/3291001/agse-tms-for-aviation-ground-support-equipment/	Here's a list of aviation ground support equipment (AGSE) TMs and how to access them.
23-Feb-23	AGSE: Now on milSuite Update	https://www.psmagazine.army.mil/News/Article/3078387/agse-now-on-milsuite-update/	AGSE has a milSuite site for all relevant AGSE information and help (use it rather than JDTI).
24-Feb-23	Black Hawk: Update MAC-Airframe Work Packages in IADS	https://www.psmagazine.army.mil/News/Article/3308228/black-hawk-update-mac-airframe-work-packages-in-iads/	The work package titled Maintenance Allocation Chart – Airframe in three TMs needs updating in IADS.
24-Feb-23	Lakota: Use Correct Hardware to Install Cowling Gas Springs	https://www.psmagazine.army.mil/News/Article/3308259/lakota-use-correct-hardware-to-install-cowling-gas-springs/	Inspect Lakota cowling gas springs for incorrect hardware and replace them with correct hardware.
24-Feb-23	Aircraft General: Birds—Small Creatures, Big Impact	https://www.psmagazine.army.mil/News/Article/3308313/aircraft-general-birdssmall-creatures-big-impact/	Don't let birds affect your aircraft's maintenance and operational readiness.
27-Feb-23	AGSE: SATS Radiator Flat Washer NSN Correction	https://www.psmagazine.army.mil/News/Article/3309783/agse-sats-radiator-flat-washer-nsn-correction/	The correct NSN for the standard aircraft towing system (SATS) radiator flat washer is NSN 5310-01-598-8683.

28-Feb-23	MEDEVAC: Strictly Follow Aviation SOP When Using D-Lok Hoist Hook	https://www.psmagazine.army.mil/News/Article/3312908/medevac-strictly-follow-aviation-sop-when-using-d-lok-hoist-hook/	MEDEVAC units must follow the aviation rescue hoist SOP as stated in H-60-17-SOF-03, despite new guidance issued by the Lifesaving Systems Corporation.
2-Mar-23	Chinook: Prevent Transmission Corrosion	https://www.psmagazine.army.mil/News/Article/3315426/chinook-prevent-transmission-corrosion/	Prevent Chinook transmission corrosion during shipping by using the procedures in the IETM, TM 1-1520-271-23&P (15 Feb 23).
2-Mar-23	General Aviation: Lock-out/Tag-out and Confined Space Resources	https://www.psmagazine.army.mil/News/Article/3315697/general-aviation-lock-out-tag-out-and-confined-space-resources/	The USACRC website details available lock-out/tag-out and confined space resources, to include training.
9-Mar-23	AGSE: SATS Tire Chains NSN	https://www.psmagazine.army.mil/News/Article/3322985/agse-sats-tire-chains-nsn/	Order tire chains for the standard aircraft towing system (SATS) with NSN 2540-00-528-7360.
15-Mar-23	Apache D/E: Gun Barrel Cleaning Done Right	https://www.psmagazine.army.mil/News/Article/3329133/apache-de-gun-barrel-cleaning-done-right/	The best way to clean the Apache's M230 gun is to remove the barrel first before cleaning.
16-Mar-23	Apache: Keep Rocket Launcher Firing Contacts Clean	https://www.psmagazine.army.mil/News/Article/3329978/apache-keep-rocket-launcher-firing-contacts-clean/	If the Apache M231 rocket launcher doesn't register when rockets are loaded, then check the contacts first before troubleshooting further.
16-Mar-23	AGSE: ALUMMC Battery NSN	https://www.psmagazine.army.mil/News/Article/3331079/agse-alummc-battery-nsn/	Order the battery for the aviation light utility mobile maintenance cart (ALUMMC) with NSN 6140-01-523-6288.
20-Mar-23	Chinook: Protect Cockpit from Elements	https://www.psmagazine.army.mil/News/Article/3333639/chinook-protect-cockpit-from-elements/	Keep cockpit windows closed to prevent rain from causing damage to electrical panels.
5-Apr-23	Apache: Get Rid of Standing Water	https://www.psmagazine.army.mil/News/Article/3352313/apache-get-rid-of-standing-water/	Before washing your Apache, cover components and openings to prevent water intrusion and, after washing, always check for standing water and dry it up.

11-Apr-23	Chinook: Engine Work Packages Being Updated	https://www.psmagazine.army.mil/News/Article/3358197/chinook-engine-work-packages-being-updated/	New troubleshooting steps to inspect and clean electrical connectors/cannon plugs are coming for multiple T55 engine work packages (WP).
13-Apr-23	RQ-7B Shadow: Launcher Needs Maintenance Too	https://www.psmagazine.army.mil/News/Article/3360605/rq-7b-shadow-launcher-needs-maintenance-too/	The launcher must be checked regularly for proper nitrogen pressurization before launching the Shadow.
19-Apr-23	Apache: Aviation Maintenance Training Program Prevents Errors and Mishaps	https://www.psmagazine.army.mil/News/Article/3367667/apache-aviation-maintenance-training-program-prevents-errors-and-mishaps/	The Aviation Maintenance Training Program (AMTP) trains Soldiers on properly maintaining their aircraft, weapon systems and ground support equipment and preventing human errors that result in mishaps. Keep reading to learn more about the AMTP...
21-Apr-23	Black Hawk: Turn In Data Transfer Modules	https://www.psmagazine.army.mil/News/Article/3368158/black-hawk-turn-in-data-transfer-modules/	If you have any data transfer modules, NSN 7025-01-542-8454, PN D6291000001, left over from the L-model Black Hawks, turn them in.
21-Apr-23	Black Hawk: Group Email for UH Safety Office	https://www.psmagazine.army.mil/News/Article/3370118/black-hawk-group-email-for-uh-safety-office/	Field units can contact the Utility Helicopter Safety Office by email to resolve safety issues.
27-Apr-23	Chinook: SCAMP II Exceeds Floor Load Limits	https://www.psmagazine.army.mil/News/Article/3375617/chinook-scamp-ii-exceeds-floor-load-limits/	All Chinook personnel must stop loading the SCAMP II into their aircraft because it exceeds load limits for the floor.
28-Apr-23	All Aircraft: Be Safe With Electrical Systems!	https://www.psmagazine.army.mil/News/Article/3377678/all-aircraft-be-safe-with-electrical-systems/	If applicable, make sure to lock out circuit breakers before working on electrical systems.

3-May-23	Black Hawk: EBAPS Part Number Update	https://www.psmagazine.army.mil/News/Article/3382879/black-hawk-ebaps-part-number-update/	All UH-60s flying under AWR 1752 that have the enhanced ballistic armament protection system (EBAPS) kit installed need to contact UH-60 Program Office for a part number change. Read on to find out more...
5-May-23	Shadow: Don't Throw Away Cables!	https://www.psmagazine.army.mil/News/Article/2703441/shadow-dont-throw-away-cables/	Mechanics, the Army Shadow team needs your help. They're running short on some of the cables found in the Shadow system, so they're asking you to check the list below before you throw any cables away. Read on to find out more...
8-May-23	H-60 Series: Look Before You Hook!	https://www.psmagazine.army.mil/News/Article/3387648/h-60-series-look-before-you-hook/	This article initially appeared in PS 710 (Jan 12), p. 21. Pitot tubes can be dangerous, so watch out for them when putting on nose the cover for your H-60 helicopters. Read on to find out more...
8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
10-May-23	AH-64: New ECS Servicing Cart PN Now Available	https://www.psmagazine.army.mil/News/Article/3389857/ah-64-new-ecs-servicing-cart-pn-now-available/	Environmental control system (ECS) servicing cart, PN 7-562104012-605 and PN 7-562104012-603, have been replaced with PN 7-562104012-607. Until units get the newer cart, they must maintain existing carts. Read on to find out more...
17-May-23	AH-64: Removing Nose Gearbox Blocker Plates	https://www.psmagazine.army.mil/News/Article/3397692/ah-64-removing-nose-gearbox-blocker-plates/	This article initially appeared in PS 699 (Feb 11). Removing the Apache nose gearbox plates requires some elbow grease but avoid using a pocket tool or screwdriver to remove them. Read on to learn more...

17-May-23	All Aircraft: Repair Acrylic Windows	https://www.psmagazine.army.mil/News/Article/3398694/all-aircraft-repair-acrylic-windows/	This article initially appeared in PS 753 (Aug 15), p. 23. Instead of tossing out acrylic windows with scratches, blemishes or minor damage follow the good words in TM 1-1500-204-23-10 to repair them. Read on to find out more...
23-May-23	HH/UH-60M, AH-64E, CH-47F: Aircraft Hand-held Fire Extinguishers	https://www.psmagazine.army.mil/News/Article/3404734/hhuh-60mah-64e-ch-47f-aircraft-hand-held-fire-extinguishers/	This article initially appeared in PS 735 (Feb 14), p. 22. Black Hawks, Apache's and Chinooks require a certain number of portable hand-held fire extinguishers. Read on to find out more...
24-May-23	Shadow: Use Digital Instead of Dial Torque Wrench	https://www.psmagazine.army.mil/News/Article/3405427/shadow-use-digital-instead-of-dial-torque-wrench/	MEOs S1705A and S1798 allow Shadow users to use a digital torque wrench to test caliper brake pressure because the dial torque wrench is no longer provisioned. Read on to find out more...
24-May-23	Aviation Maintenance: MOS 15H Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3406130/aviation-maintenance-mos-15h-invited-to-take-job-analysis-survey/	All aircraft pneudraulics repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
24-May-23	CH-47F Chinook: Replacement for Bad Engine Cowling Sealing Strip	https://www.psmagazine.army.mil/News/Article/3406193/ch-47f-chinook-replacement-for-bad-engine-cowling-sealing-strip/	The fairing sealing strip on the lower cowling does not stay in place because of chafing. The remedy is to use anti-chafe rubber bumpers instead. Read on to find out how to install them...
2-Jun-23	AH-64E Apache: Inspect for Missing or Loose Set Screws	https://www.psmagazine.army.mil/News/Article/3415411/ah-64e-apache-inspect-for-missing-or-loose-set-screws/	Inspect W111 and W112 wire harness 90-degree connectors to see if they're loose or missing; if either, repair or replace.

6-Jun-23	Air Warrior: Two Types of Snaps for Your PSGC	https://www.psmagazine.army.mil/News/Article/3418109/air-warrior-two-types-of-snaps-for-your-psgc/	Here's how to order replacement snaps for the new primary survival gear carrier (PSGC), NSN 8415-01-620-3360.
14-Jun-23	UH-60: More Parts for Turn In	https://www.psmagazine.army.mil/News/Article/3426783/uh-60-more-parts-for-turn-in/	Turn in these unserviceable parts ASAP to support repair programs.
14-Jun-23	UH-60: Turn in APU Generators with Covers	https://www.psmagazine.army.mil/News/Article/3426818/uh-60-turn-in-apu-generators-with-covers/	When turning in the APU generator for repair, include its cover, NSN 6115-01-155-4580, to prevent work stoppage.
21-Jun-23	UH-72: Lakota Aircraft Transitions to Sustainment	https://www.psmagazine.army.mil/News/Article/3431374/uh-72-lakota-aircraft-transitions-to-sustainment/	The UH-72 Lakota helicopter has transitioned to AMCOM sustainment and is no longer under PEO Aviation responsibility.
28-Jun-23	Aviation Publications: Fuel Cell Corrosion Inspection WP	https://www.psmagazine.army.mil/News/Article/3442110/aviation-publications-fuel-cell-corrosion-inspection-wp/	Step Six (6) to the fuel cell corrosion inspection work package has changed and needs to be uploaded to IADS.
28-Jun-23	Chinook: Cockpit Center Console Work Platform	https://www.psmagazine.army.mil/News/Article/3442163/chinook-cockpit-center-console-work-platform/	Use this unit-constructed work platform to protect Chinook center console components from damage.
6-Jul-23	Publications: Update Pubs Account Address	https://www.psmagazine.army.mil/News/Article/3449003/publication-s-update-pubs-account-address/	Change your pubs account address to reflect the new Army base installation name changes to receive publications.
6-Jul-23	UH-60: Install Wire Jumper Kits ASAP	https://www.psmagazine.army.mil/News/Article/3448794/uh-60-install-wire-jumper-kits-asap/	All Black Hawk aircraft units need to install the wire jumper kits by Feb 2024 per AMAM 22-09.

6-Jul-23	Apache: Color of Grease Not Cause for Gearbox Replacement	https://www.psmagazine.army.mil/News/Article/3448719/apache-color-of-grease-not-cause-for-gearbox-replacement/	Grease discoloration in the Apache tail rotor gearbox and intermediate gearbox is not sufficient cause for replacing them.
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	This "corrosion basics" slide presentation offers a template for corrosion training.
11-Jul-23	Apache: Servocylinders Critically Needed	https://www.psmagazine.army.mil/News/Article/3454228/apache-servocylinders-critically-needed/	Turn in unserviceable Apache servocylinders, NSN 1650-01-494-0084, ASAP to support repair program.
13-Jul-23	MEDEVAC: Discharge Cable Helps with Static Electricity	https://www.psmagazine.army.mil/News/Article/3456297/medevac-discharge-cable-helps-with-static-electricity/	Using a static discharge cable during MEDEVAC hoist operations can lessen the negative effects of static electricity.
13-Jul-23	Aviation Maintenance: MOS 15B Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3457514/aviation-maintenance-mos-15b-invited-to-take-job-analysis-survey/	All MOS 15Bs should take the job analysis survey at the link below.
17-Jul-23	Black Hawk: Use Proper Pliers	https://www.psmagazine.army.mil/News/Article/3460648/black-hawk-use-proper-pliers/	Use cannon plug pliers to remove the load-demand and the power-available rotary input housing.
17-Jul-23	Apache: Correctly Reinstall Generator Wires	https://www.psmagazine.army.mil/News/Article/3460087/apache-correctly-reinstall-generator-wires/	Make sure Apache generator wire leads are marked properly so they can be reinstalled correctly after maintenance to prevent frying generators.

21-Jul-23	H-60 Series: Keep Struts Lubed	https://www.psmagazine.army.mil/News/Article/3466629/h-60-series-keep-struts-lubed/	Landing gear struts and the stabilator actuator rod should be lubed every 40 hours to prevent landing gear problems.
25-Jul-23	Apache: Generator is Heavier Than You Think	https://www.psmagazine.army.mil/News/Article/3470342/apache-generator-is-heavier-than-you-think/	.The Apache generator is heavy so always use tool kit, NSN 5180-01-508-5887 when installing or removing the generator.
28-Jul-23	All Aircraft: Pay Attention to TM Warnings, Cautions and Notes	https://www.psmagazine.army.mil/News/Article/3474566/all-aircraft-pay-attention-to-tm-warnings-cautions-and-notes/	Warnings, cautions and notes in every TM keep you safe while performing maintenance so read them and heed them
1-Aug-23	Apache: Check Fuel Manifold Cover Latch Rivets	https://www.psmagazine.army.mil/News/Article/3478563/apache-check-fuel-manifold-cover-latch-rivets/	Aviation maintenance action message, H-64-23-AMAM-1, requires a one-time inspection to make sure the fuel manifold panel latch rivets are installed properly or need replacing. Keep reading to learn more...
3-Aug-23	Aviation Maintenance: MOS 15N Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3481463/aviation-maintenance-mos-15n-invited-to-take-job-analysis-survey/	All aircraft avionics mechanics, MOS 15N, are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
9-Aug-23	Apache: Inspect M299 HML Rail Launchers for Proper Microswitch Harness Routing	https://www.psmagazine.army.mil/News/Article/3488703/apache-inspect-m299-hml-rail-launchers-for-proper-microswitch-harness-routing/	Aviation maintenance action message, H-64-23-AMAM-11, requires a one-time inspection to make sure the M299 launcher rail microswitch harness is routed correctly to prevent pinching. Keep reading to learn more...

11-Aug-23	Black Hawk: Get Alternative Nut for Pedal Adjuster Assemblies	https://www.psmagazine.army.mil/News/Article/3491142/black-hawk-get-alternative-nut-for-pedal-adjuster-assemblies/	The UH-60A/L/M can use alternative nut SS5092-4 on the pedestal assemblies until the preferred nut, MS21244-4, is again available in the supply system. Keep reading to learn more...
29-Aug-23	Black Hawk: Bifilar Weight Nut Guidance	https://www.psmagazine.army.mil/News/Article/3508418/black-hawk-bifilar-weight-nut-guidance/	There are two types of bifilar weight nuts. Due to a shortage of one type, mechanics are authorized to use the SS5086C10 nuts instead of the SS5086C10S nuts specified in TM 1-1520-280-23&P (Apr 23). Keep reading to learn more, including the need to update the affected work package...
17-Oct-23	General Aircraft: Use Aircraft Maintenance Manuals for Composite Repairs	https://www.psmagazine.army.mil/News/Article/3555577/general-aircraft-use-aircraft-maintenance-manuals-for-composite-repairs/	Use the appropriate aircraft manuals for composite repairs on helicopters.
20-Oct-23	UH-60: Cabin Tub Inspection Video Now Available on JTDI	https://www.psmagazine.army.mil/News/Article/3562590/uh-60-cabin-tub-inspection-video-now-available-on-jtdi/	Check out the H-60 48-month inspection video on the JTDI website.
24-Oct-23	MEDEVAC: HH-60M Aircraft and Mission Equipment Status Reporting	https://www.psmagazine.army.mil/News/Article/3566203/medevac-hh-60m-aircraft-and-mission-equipment-status-reporting/	For status reporting of HH-60M MEDEVAC aircraft and mission equipment, follow the addendum to GEN-19-AMAM-01 (Nov 18).
8-Dec-23	All Aircraft: Cold Weather Knowledge Will Keep Aircraft Flying	https://www.psmagazine.army.mil/News/Article/3610093/all-aircraft-cold-weather-knowledge-will-keep-aircraft-flying/	Winter can be particularly harsh on aircraft. Knowing a few facts about how cold weather affects your helicopters will help your unit ensure they're protected. Flightfax 5 can help. Keep reading to learn more...


8-Dec-23	AGSE: ALUMMC Clutch Removal Tool NSN	https://www.psmagazine.army.mil/News/Article/3610873/agse-alummc-clutch-removal-tool-nsn/	<p>If you're looking for the ALUMMC clutch removal tool in TM 1-1740-213-13&P (Feb 16), it's not there. Keep reading to learn what the NSN is and how to submit a recommended change to the TM when it's missing information or has errors...</p>
10-Dec-23	AGSE: AGPU Hydraulic Hose Adapter Assemblies - New NSNs	https://www.psmagazine.army.mil/News/Article/3611531/agse-agpu-hydraulic-hose-adapter-assemblies-new-nsns/	<p>New NSNs have been assigned for AGPU hydraulic hose assemblies in TM 1-1730-229-24P (Jan 16) that have several benefits beyond the hoses by themselves. Read on to learn about these benefits, get the new NSNs and start ordering them to establish demand...</p>
21-Dec-23	UH-60/AH-64: 2024 T700-GE-701D Training Course Dates	https://www.psmagazine.army.mil/News/Article/3623465/uh-60ah-64-2024-t700-ge-701d-training-course-dates/	<p>The 2024 schedule for the T700 Army Engine Line Maintenance Course, provided by General Electric, has been published. Keep reading to learn more about available dates and how to register...</p>

CBRN



Date	Article Title	Link	Excerpt
1-Feb-23	M12A1 Decon: Belt NSNs Switched in TM	https://www.psmagazine.army.mil/News/Article/3285044/m12a1-decon-belt-nsns-switched-in-tm/	The M12A1 decon TM has the generator belt and centrifugal pump belt NSNs switched. Keep reading to get the correct NSN info...
14-Feb-23	M8E1 CBPS: Boot Screen Troubleshooting Update	https://www.psmagazine.army.mil/News/Article/3298180/m8e1-cbps-boot-screen-troubleshooting-update/	The CBPS -23&P-1 TM needs an update for troubleshooting the boot screen. The revised TM will add a new work package. Until then keep reading to get the troubleshooting steps...
9-Mar-23	M26 Decon: Diesel Engine Throttle Cable NSN	https://www.psmagazine.army.mil/News/Article/3323058/m26-decon-diesel-engine-throttle-cable-nsn/	If you need to order a throttle cable, you'll need to order the push-pull control assembly with NSN 2590-01-623-6988. Read on for the whole story...
16-Mar-23	CBRN: Get the New NRC Form 3	https://www.psmagazine.army.mil/News/Article/3330567/cbrn-get-the-new-nrc-form-3/	If there's any radioactive equipment stored in your unit's CBRN room, posting an NRC Form 3 for everyone to see is required. Make sure to use the most current NRC Form 3 (Nov 22). Read on for more information...
2-May-23	CBRN: M8 Paper Improvements	https://www.psmagazine.army.mil/News/Article/3380958/cbrn-m8-paper-improvements/	Current M8 paper not only detects blister and nerve (G and VX) agents but can also detect liquid A-series agents as indicated by a color change from dark green to yellow green after 10 or more minutes. Keep reading to learn more...
10-Jul-23	M12A1 Decon: New Mixing Instructions for JGPD-HME	https://www.psmagazine.army.mil/News/Article/3452686/m12a1-decon-new-mixing-instructions-for-jgpd-hme/	The M12A1 decontaminating apparatus has new mixing instructions for JGPD-HME M333 decontamination kit. You can get the complete instructions on the JACKS website. Keep reading for more...
10-Jul-23	M26 Decon: New Throttle Lever Modification	https://www.psmagazine.army.mil/News/Article/3452795/m26-decon-new-throttle-lever-modification/	If you have a new M26 throttle lever, NSN 3040-12-371-3949, it will need to be modified before use. The throttle lever assembly orientation is incorrect so the lever assembly must be disassembled to make the necessary modifications. Keep reading for the instructions...
24-Oct-23	M26 Decon: Water Pressure Gauge Needs Calibration	https://www.psmagazine.army.mil/News/Article/3567373/m26-decon-water-pressure-gauge-needs-calibration/	This article initially appeared in PS 791 (Oct 18), p.37. Warfighters, the M26 is considered NMC if the gauge hasn't been calibrated or the TMDE calibration sticker is missing. Get more info here...

Combat Vehicles



Date	Article Title	Link	Excerpt
11-Jan-23	M1-Series Tank: Coast Your Way to Proper Track Tension	https://www.psmagazine.army.mil/News/Article/3265232/m1-series-tank-coast-your-way-to-proper-track-tension/	Proper track tension adjustment helps to avoid worn end connectors and cupped sprocket teeth. Read on for more information...
13-Jan-23	Combat Vehicles Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3266058/combat-vehicles-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for combat vehicles and equipment. Get them here...
13-Jan-23	M1-Series Tank: Splash Guard Do's and Don'ts	https://www.psmagazine.army.mil/News/Article/3267847/m1-series-tank-splash-guard-dos-and-donts/	Operating your M1-series tank without the rear mud guard (skirt #7) in place can lead to engine damage or even complete engine failure. And opening skirts improperly can lead to injury. Keep reading for more info...
23-Jan-23	M113-Series FOV: Heater Box Engines Phased Out	https://www.psmagazine.army.mil/News/Article/3274023/m113-series-fov-heater-box-engines-phased-out/	Heater box engines have been phased out. Replace unserviceable heater box engines with glow plug engines. Read on for more info...
26-Jan-23	Half-Mast Sends: Keep on Trucking	https://www.psmagazine.army.mil/News/Article/3277954/half-mast-sends-keep-on-trucking/	The war in Ukraine is offering a lot of lessons. The question is: Are we learning them? An informative CNN article offers some insights on the importance of maintenance and logistics basics that are worth heeding. And we offer links to articles in our archive that reinforce important lessons learned. So read on...
2-Feb-23	M1-Series Tank: Turret Maintenance Stand Fabrication Plans	https://www.psmagazine.army.mil/News/Article/3286693/m1-series-tank-turret-maintenance-stand-fabrication-plans/	The M1-series tank turret maintenance stand cannot be ordered; instead, it is fabricated by units. Read on for info on where to find the plans...

23-Feb-23	Stryker: Check Vehicle Fluids the Right Way	https://www.psmagazine.army.mil/News/Article/3305884/stryker-check-vehicle-fluids-the-right-way/	Check ALL Stryker fluids regularly both before and after missions to keep the vehicle combat ready. The TMs say to check fluids after each mission. But checking them before a mission is never a bad idea. Keep reading for more info...
23-Feb-23	M1-Series Tank: Start and Shut Down by the Book	https://www.psmagazine.army.mil/News/Article/3306754/m1-series-tank-start-and-shut-down-by-the-book/	The startup and shutdown procedures for the M1-series tank are complicated. Following the instructions in the TMs and having a good understanding of how your tank operates will prevent engine damage. Read on for more info...
24-Feb-23	M1A2 SEPv2: Slave Starting the Right Way Avoids Damage	https://www.psmagazine.army.mil/News/Article/3308769/m1a2-sepv2-slave-starting-the-right-way-avoids-damage/	Slave start your M1A2 SEPv2 tank correctly to avoid costly damage. Failure to read the procedures could result in equipment damage or cause injury or death to personnel. Read on for more information...
6-Mar-23	M1070A1 HET: Steering Gear NSN	https://www.psmagazine.army.mil/News/Article/3319965/m1070a1-het-steering-gear-nsn/	The HET has a new steering gear. When disconnecting the old steering gear, make sure to keep the associated tube in place. The new gear comes without the tube. Read on for the full story...
9-Mar-23	Ground Vehicles: Remove Battery Corrosion	https://www.psmagazine.army.mil/News/Article/3324517/ground-vehicles-remove-battery-corrosion/	When cleaning and removing corrosion from your vehicle's lead-acid batteries, follow the guidance in WP 0027 of TM 9-6140-200-13 (May 11) and your vehicle's operator and field maintenance TMs. Get more info...
15-Mar-23	Ground Vehicles: Contact LARs for Maintenance Assistance	https://www.psmagazine.army.mil/News/Article/3329899/ground-vehicles-contact-lars-for-maintenance-assistance/	If you need maintenance or logistics help for ground vehicles or equipment, just reach out to a logistics assistance representative or LAR. Get more info here...

15-Mar-23	M1-Series Tanks: Keep Safety in Mind During Mine Clearing Operations	https://www.psmagazine.army.mil/News/Article/3329565/m1-series-tanks-keep-safety-in-mind-during-mine-clearing-operations/	The M1-series tank's mine clearing blade is a powerful battlefield tool. However, not following proper safety precautions during mine clearing operations can result in Soldiers being injured and equipment being damaged. Keep reading for more info...
15-Mar-23	M113-Series FOV: Regular Maintenance Reduces Fire Risk	https://www.psmagazine.army.mil/News/Article/3329597/m113-series-fov-regular-maintenance-reduces-fire-risk/	M113-series vehicles are experiencing far too many engine compartment fires. Many of these fires can be prevented with regular maintenance. Read on for more info...
16-Mar-23	M88A1 Recovery Vehicle: Convert to Hatz APU	https://www.psmagazine.army.mil/News/Article/3329626/m88a1-recovery-vehicle-convert-to-hatz-apu/	The M88A1 recovery vehicle's ONAN auxiliary power unit (APU) is obsolete. Order a kit to convert your vehicle to the Hatz APU configuration. The kit includes everything needed, including new fuel pumps...
28-Mar-23	Lead-Acid Batteries: WP Update for TM 9-6140-200-13	https://www.psmagazine.army.mil/News/Article/3342995/lead-acid-batteries-wp-update-for-tm-9-6140-200-13/	AR 750-1 was recently updated which caused a need for an update in work package (WP) 0020 of TM 9-6140-200-13, Operator and Field Maintenance for Automotive Lead-Acid Storage Batteries (May 11). Get the correct info here...
28-Mar-23	M88A2 Recovery Vehicles: Be Mindful of TM Typos	https://www.psmagazine.army.mil/News/Article/3343327/m88a2-recovery-vehicles-be-mindful-of-tm-typos/	Typographical errors in TM 9-2350-292-10 (May 22) for the M88A2 recovery vehicle could cause confusion for users. The errors will be corrected in the next TM update. Read on for more info and how to access TACOM Maintenance Action Message 23-014...
13-Apr-23	M119A3 Towed Howitzer: Use Correct Brake Fluid	https://www.psmagazine.army.mil/News/Article/3360880/m119a3-towed-howitzer-use-correct-brake-fluid/	The only authorized brake fluid for the M119A3 howitzer is MIL-PRF-46176. Other types of brake fluid can cause the brakes to lock up and catch fire. Read on for more info...

13-Apr-23	Stryker FOV: Do Not Reattach On Board Oil Exchanger (OBOE)	https://www.psmagazine.army.mil/News/Article/3360896/stryker-fov-do-not-reattach-on-board-oil-exchanger-oboe/	Stryker FOV: Do Not Reattach On Board Oil Exchanger (OBOE)
14-Apr-23	Ground Vehicles: Want to Order in Bulk?	https://www.psmagazine.army.mil/News/Article/3362656/ground-vehicles-want-to-order-in-bulk/	There are items you can order in bulk for your vehicles and equipment. Ordering in bulk can save units money and ensure high-usage items are available when needed. Here's how to find what you can order in bulk...
16-May-23	Ground Vehicles: BDAR Kit NSN	https://www.psmagazine.army.mil/News/Article/3396937/ground-vehicles-bdar-kit-nsn/	Get the latest and greatest Class IX Battle Damage and Assessment Repair (BDAR) crew kit with NSN 2590-01-659-5620. It's suitable for all combat and tactical vehicles. Read on for more info...
5-Jun-23	M1A2 SEPv2 Tank: Updated CITV-SGSA/TIS-TRU Reprogramming Procedures	https://www.psmagazine.army.mil/News/Article/3416860/m1a2-sepv2-tank-updated-citv-sgsatis-tru-reprogramming-procedures/	There are new reprogramming procedures for the M1A2 SEPv2 tank's commander's independent thermal viewer-second generation sight assembly (CITV-SGSA) and thermal imaging system-thermal receiver unit (TIS-TRU) line replaceable unit (LRU). The updated procedures are necessary to overcome reprogramming errors being encountered by users. Read on for more information.....
5-Jun-23	M1-Series Tanks: TIGER Program Offers Engine Support	https://www.psmagazine.army.mil/News/Article/3416885/m1-series-tanks-tiger-program-offers-engine-support/	Field service engineers (FSE) are available to provide a wide range of support for the M1-series tank as part of the Totally Integrated Engine Revitalization (TIGER) Program. The program's goal is to help keep engines running and increase combat readiness. Keep reading for more info.....


13-Jun-23	M113-Series Vehicles: Label Container Correctly When Turning in Heater Box Engines	https://www.psmagazine.army.mil/News/Article/3426160/m113-series-vehicles-label-container-correctly-when-turning-in-heater-box-engines/	Units should turn in unserviceable and obsolete M113-series FOV heater box engines to the supply system. But mislabeling the shipping containers can cost repair depots time and money. Read on for more info.....
21-Jun-23	Bradley FOV: 24V Turret Battery Replacement	https://www.psmagazine.army.mil/News/Article/3430984/bradley-fov-24v-turret-battery-replacement/	Replace Bradley 24V turret batteries with AGM 12V batteries. Two 12V batteries are needed to replace one 24V battery. Keep reading for more info.....
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
11-Jul-23	Bradley FOV: Properly Dispose of Fuel After Checking for Contamination	https://www.psmagazine.army.mil/News/Article/3454484/bradley-fov-properly-dispose-of-fuel-after-checking-for-contamination/	Don't put fuel drained from the Bradley fuel filter used to test for contamination back into the fuel tank, even if not contaminated. Read on for more info...
18-Jul-23	M1-Series Tank: Turn In Unserviceable LRUs ASAP	https://www.psmagazine.army.mil/News/Article/3461656/m1-series-tank-turn-in-unserviceable-lrus-asap/	Units can get turn-in credit and improve combat readiness by turning in line replaceable units (LRUs) for the M1-series tank. Not turning in unserviceable LRUs can cause supply issues. Read on for more info...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...

19-Jul-23	Bradley FOV: Check Towing Pintle Regularly for Damage	https://www.psmagazine.army.mil/News/Article/3463300/bradley-fov-check-towing-pintle-regularly-for-damage/	Checking the towing pintle for signs of damage is a regular part of maintenance. Read on for more info...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
3-Aug-23	Bradley FOV: Minimum PMCS Checks After Every Mission	https://www.psmagazine.army.mil/News/Article/3482100/bradley-fov-minimum-pmcs-checks-after-every-mission/	Conducting AFTER PMCS on the Bradley is critical to maintaining operational readiness. Read on for more info...
11-Aug-23	M777A2 Towed Howitzers: Inspect Cannon Tube for Cracks Immediately	https://www.psmagazine.army.mil/News/Article/3491088/m777a2-towed-howitzers-inspect-cannon-tube-for-cracks-immediately/	A crack in the M777A2 howitzer's muzzle brake keyway can lead to cannon tube failure. That will damage the howitzer and could seriously injure personnel. Read on for more info...
23-Oct-23	Batteries: Solar Maintainers Required for Long-Term Equipment Storage	https://www.psmagazine.army.mil/News/Article/3565076/batteries-solar-maintainers-required-for-long-term-equipment-storage/	AR 750-1 and DA PAM 750-1 were updated to clarify that approved solar maintainers are required for equipment in LUP, NCOMP and outdoor storage. Read on to learn more...
25-Oct-23	Bradley FOV: Check Bilge Pumps Monthly	https://www.psmagazine.army.mil/News/Article/3567955/bradley-fov-check-bilge-pumps-monthly/	Regular maintenance on your Bradley's bilge pumps is quick and easy. And it's critical to keeping them working properly. Read on for more info...

31-Oct-23	M113-Series FOV: Chock it Up to Being Ready	https://www.psmagazine.army.mil/News/Article/3572769/m113-series-fov-chock-it-up-to-being-ready/	This article initially appeared in PS 678 (May 09), p. 4 Use chock blocks when disconnecting the final drives on an M113-series vehicle. If you don't, the vehicle could roll and possibly injure someone. Read on for more info...
8-Nov-23	M88A2 Recovery Vehicle: What You Need to Know About the Service Kit	https://www.psmagazine.army.mil/News/Article/3582624/m88a2-recovery-vehicle-what-you-need-to-know-about-the-service-kit/	There's a new M88A2 recovery vehicle service kit with redesigned transmission filter housing components that isn't available in the supply system yet. Use the current service kit, along with the transmission filter housing kit, until the new service kit is available. Read on for more info...
16-Nov-23	Stryker FOV: Stop Circuit Breaker Tripping	https://www.psmagazine.army.mil/News/Article/3589331/stryker-fov-stop-circuit-breaker-tripping/	Turning on the MFoCS2 processor power switch before powering on the auxiliary power bus will keep circuit breaker 81 on the FFCB2 from tripping. Read on for more info...
17-Nov-23	M777A2 Howitzer: New Operator TM Released	https://www.psmagazine.army.mil/News/Article/3591324/m777a2-howitzer-new-operator-tm-released/	The M777A2 howitzer has a new operator-level TM available for download. Read on for more info...
19-Dec-23	M113-Series FOV: Drain Away Hull Rust Problems	https://www.psmagazine.army.mil/News/Article/3620586/m113-series-fov-drain-away-hull-rust-problems/	This article initially appeared in PS 738 (May 14), p. 4. Water in the hull of your M113-series vehicle can cause problems with rust. But three little plugs make it very easy to avoid rust and the problems it causes. Read on for more info...
20-Dec-23	M1-Series Tanks: Just Say Nay to GAA!	https://www.psmagazine.army.mil/News/Article/3621639/m1-series-tanks-just-say-nay-to-gaa/	This article initially appeared in PS 777 (Aug 17), p. 7. Never use GAA grease on your M1-series tank. WTR is the only authorized grease. Read on for more info...

20-Dec-23	M777A2 Towed Howitzers: Connect Service Air Lines Before Towing	https://www.psmagazine.army.mil/News/Article/3617723/m777a2-towed-howitzers-connect-service-air-lines-before-towing/	<p>The M777A2 howitzer and its prime mover are a heavy load. That's why it's critical to connect service air lines when the howitzer is being towed to prevent damage to equipment. Read on for more info...</p>
26-Dec-23	M113-Series FOV: Cold Weather Tips	https://www.psmagazine.army.mil/News/Article/3624463/m113-series-fov-cold-weather-tips/	<p>There are steps you can take to make sure your M113-series vehicles are mission ready no matter how cold it gets. Read on for more info...</p>

Construction



Date	Article Title	Link	Excerpt
13-Jan-23	Construction Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3266053/construction-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for construction equipment and vehicles. Get them here...
31-Jan-23	966H Scoop Loader: Complete Joystick NSN	https://www.psmagazine.army.mil/News/Article/3283363/966h-scoop-loader-complete-joystick-nsn/	This post script initially appeared in PS 800 (Jul 19), p. 61. There's an error in Item 1 in Fig 151 of TM 5-3805-291-23P (Jan 10). It brings only the top handle control rather than the complete joystick. Here's the scoop on the correct NSN...
3-Feb-23	ATLAS II Forklift: Wider Carriage Available	https://www.psmagazine.army.mil/News/Article/3287024/atlas-ii-forklift-wider-carriage-available/	Operators must use caution when using a wide carriage on the ATLAS II forklift. Keep reading to learn more about these precautions and how to order the wider carriage...
10-Feb-23	MK II Bridge Boat: Bilge Pump Relay NSN	https://www.psmagazine.army.mil/News/Article/3294006/mk-ii-bridge-boat-bilge-pump-relay-nsn/	Dear Half-Mast, our unit supports a large number of MK II bridge boats and we need to replace a bad bilge pump relay in a few of them. Can you help? Click MORE>> to learn his answer...
14-Feb-23	BEB: BII Capstan Handle	https://www.psmagazine.army.mil/News/Article/3297950/beb-bii-capstan-handle/	BEB capstan handle NSN is missing from the TM. Keep reading to find the NSN...
15-Feb-23	REBS: Wire Rope Needs TLC	https://www.psmagazine.army.mil/News/Article/3299058/rebs-wire-rope-needs-tlc/	Failure to properly clean, lube or maintain the REB's wire rope can result in poor performance, or possibly failure. Read on for some tips to keep it mission-ready...
23-Feb-23	D6K Dozer: Door Seal NSN	https://www.psmagazine.army.mil/News/Article/3306950/d6k-dozer-door-seal-nsn/	Need an NSN for the D6K door seal? One is now available. Read on for more info...
27-Feb-23	M400W Skid Loader: Solid Tire NSNs	https://www.psmagazine.army.mil/News/Article/3310785/m400w-skid-loader-solid-tire-nsns/	Use these NSNs for the skid loader's left and right solid tires. Keep reading for more information...

27-Feb-23	120M Road Grader: Drain Out the Water	https://www.psmagazine.army.mil/News/Article/3307516/120m-road-grader-drain-out-the-water/	Drain water out of the fuel system to keep the 120M road grader's engine running smoothly. Keep reading to learn more...
27-Feb-23	Atlas I and II Forklifts: Transmission Removal Reminder	https://www.psmagazine.army.mil/News/Article/3311100/atlas-i-and-ii-forklifts-transmission-removal-reminder/	When removing the transmission for repair or replacement, be sure to retain the ATLAS forklift's spacer sleeve and shoulder shaft. Keep reading for more info about why...
9-Mar-23	HMEE-1: SINCGARS Mount?	https://www.psmagazine.army.mil/News/Article/3323098/hmee-1-sincgars-mount/	If you're thinking of putting a SINCGARS radio mount kit in your HMEE, installing it isn't approved. Read on to learn more...
9-Mar-23	Ground Vehicles: Remove Battery Corrosion	https://www.psmagazine.army.mil/News/Article/3324517/ground-vehicles-remove-battery-corrosion/	When cleaning and removing corrosion from your vehicle's lead-acid batteries, follow the guidance in WP 0027 of TM 9-6140-200-13 (May 11) and your vehicle's operator and field maintenance TMs. Get more info...
15-Mar-23	Ground Vehicles: Contact LARs for Maintenance Assistance	https://www.psmagazine.army.mil/News/Article/3329899/ground-vehicles-contact-lars-for-maintenance-assistance/	If you need maintenance or logistics help for ground vehicles or equipment, just reach out to a logistics assistance representative or LAR. Get more info here...
28-Mar-23	Lead-Acid Batteries: WP Update for TM 9- 6140-200-13	https://www.psmagazine.army.mil/News/Article/3342995/lead-acid-batteries-wp-update-for-tm-9-6140-200-13/	AR 750-1 was recently updated which caused a need for an update in work package (WP) 0020 of TM 9-6140-200-13, Operator and Field Maintenance for Automotive Lead-Acid Storage Batteries (May 11). Get the correct info here...
29-Mar-23	HMEE-1: Egress Window WARNING Reminder	https://www.psmagazine.army.mil/News/Article/3344758/hmee-1-egress-window-warning-reminder/	While operating the HMEE-I, a Soldier rolled over while crossing a river and barely escaped because the egress knobs were stuck. Heeding a WARNING in the TM would likely have caught this problem before it became serious. Keep reading to understand why it's important to heed all CAUTIONS and WARNINGS...

14-Apr-23	Ground Vehicles: Want to Order in Bulk?	https://www.psmagazine.army.mil/News/Article/3362656/ground-vehicles-want-to-order-in-bulk/	There are items you can order in bulk for your vehicles and equipment. Ordering in bulk can save units money and ensure high-usage items are available when needed. Here's how to find what you can order in bulk...
28-Apr-23	M1231 MK III VMMD Husky: Annual Service Kit NSN	https://www.psmagazine.army.mil/News/Article/3378373/m1231-mk-iii-vmmd-husky-annual-service-kit-nsn/	Mechanics, you won't find the NSN for the annual service kit in TM 9-2355-316-23P (Jun 18). The NSN will be added to the next revision of the TM. Get the NSN here...
10-May-23	M1022-Series Dolly Set Mobilizer: Tire and Wheel Assembly NSN	https://www.psmagazine.army.mil/News/Article/3390711/m1022-series-dolly-set-mobilizer-tire-and-wheel-assembly-nsn/	Maintainers, the current TM for the M1022-series dolly set mobilizer doesn't include the NSN for the tire and wheel assembly. Get it here...
15-May-23	M30 BEB: Transmission Oil NSNs	https://www.psmagazine.army.mil/News/Article/3393464/m30-beb-transmission-oil-nsns/	The lube order for the BEB lists a 55-gal drum and its NSN but provides no other sizes. Smaller quantities are available. For the NSNs, keep reading...
23-May-23	924H/G Wheel Loader: Double-check Front Bucket Hydraulic Hose Couplings	https://www.psmagazine.army.mil/News/Article/3404209/924hg-wheel-loader-double-check-front-bucket-hydraulic-hose-couplings/	Inspect the bucket's hydraulic hose couplings for oil leaks. Make sure the couplings "click" tight in place. Keep reading for more...
1-Jun-23	120M Road Grader: Wrap Hydraulic Hoses	https://www.psmagazine.army.mil/News/Article/3412807/120m-road-grader-wrap-hydraulic-hoses/	Use spiral wrap, NSN 9330-00-889-7776, to protect the hydraulic hoses on the road grader's front hydraulic drive. Keep reading to find out more...
7-Jun-23	BEB: Handle Engine Access Door With Care	https://www.psmagazine.army.mil/News/Article/3420289/beb-handle-engine-access-door-with-care/	Hold onto the engine access door handle when you close it. Don't let the access door slam shut. Keep reading to learn more.....

15-Jun-23	BEB: Turn Master Disconnect Switches Off After Operations	https://www.psmagazine.army.mil/News/Article/3429246/beb-turn-master-disconnect-switches-off-after-operations/	Use the master disconnect switches to cut off all flow from the batteries. If not, the batteries can drain and then your BEB won't start. More info here...
6-Jul-23	BEB: BII Hand Pump	https://www.psmagazine.army.mil/News/Article/3449832/beb-bii-hand-pump/	Excess water in the bridge boat's hull can cause problems, but there's a remedy among the basic issue items. Read on to find out what it is...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
24-Jul-23	M917A3 Heavy Dump Truck: Helpful Reminders during Dumping Ops	https://www.psmagazine.army.mil/News/Article/3468685/m917a3-heavy-dump-truck-helpful-reminders-during-dumping-ops/	Maintenance leaders, operating the M917A3 30-ton heavy dump truck is challenging. Here's a few key reminders when dropping dirt or gravel with your heavy dump truck. Get them here...

1-Aug-23	M1231 HUSKY Red Pack: Updated Corrosion Mitigation Procedures	https://www.psmagazine.army.mil/News/Article/3478775/m1231-husky-red-pack-updated-corrosion-mitigation-procedures/	ACOM developed corrosion mitigation procedures for the M1231 HUSKY Red Pack (spare parts trailer). The procedures are available in TACOM MAM 23-025. Read on...
3-Aug-23	ATLAS Forklifts: Upper Half Door NSN	https://www.psmagazine.army.mil/News/Article/3481575/atlas-forklifts-upper-half-door-nsn/	Use NSN 2510-01-573-1520 to get the upper half door for the ATLAS forklift. Read on for more info...
17-Oct-23	M30 Bridge Erection Boat: Upgrade Bungee Cords and Save Money	https://www.psmagazine.army.mil/News/Article/3554405/m30-bridge-erection-boat-upgrade-bungee-cords-and-save-money/	The standard bungee cords used to store the M30 bridge erection boat's navigation light wear out from the elements and are expensive to replace. Order better, cheaper bungee cords using NSN 5342-01-109-3221. Read on for more info...
17-Oct-23	CCE: Drain the Fuel/Water Separator	https://www.psmagazine.army.mil/News/Article/3559713/cce-drain-the-fuelwater-separator/	Operators, it's crucial that you follow the BEFORE OPERATIONS PMCS like it says in the -10 TM. Draining out the water keeps it from freezing in the fuel/water separator. Here's what else you need to know...
17-Oct-23	D7R II CAT Dozer: A/C Line Quick-Release Coupling NSN	https://www.psmagazine.army.mil/News/Article/3559954/d7r-ii-cat-dozer-ac-line-quick-release-coupling-nsn/	Warfighters, order a quick-release coupling for the D7R II CAT dozer's A/C refrigerant line with NSN 5940-01-437-6772. Get more info here...
23-Oct-23	Batteries: Solar Maintainers Required for Long-Term Equipment Storage	https://www.psmagazine.army.mil/News/Article/3565076/batteries-solar-maintainers-required-for-long-term-equipment-storage/	AR 750-1 and DA PAM 750-1 were updated to clarify that approved solar maintainers are required for equipment in LUP, NCOMP and outdoor storage. Read on to learn more...

27-Oct-23	924H/G Wheel Loader: Arm Lube's a Must	https://www.psmagazine.army.mil/News/Article/3570980/924hg-wheel-loader-arm-lubes-a-must/	<p>Warfighters, lube the lift arm of your 924H/G wheel loader like the TM's PMCS instructions tell you. That way your loader will continue working properly. Read more here...</p>
1-Dec-23	Backhoe Loader: Get the Low Down on Alternator Parts	https://www.psmagazine.army.mil/News/Article/3602725/backhoe-loader-get-the-low-down-on-alternator-parts/	<p>If you order the backhoe loader's alternator shown as Item 1 (with down parts 2-7) in Fig 39 of TM 5-2420-231-24 (Jun 13), you won't get the pulley or impeller fan. Keep reading to get the NSNs for the backhoe loader's pulley kit and impeller fan...</p>
21-Dec-23	120M Road Grader: Avoid Battery Drain	https://www.psmagazine.army.mil/News/Article/3623052/120m-road-grader-avoid-battery-drain/	<p>The 120M road grader's battery can drain when the vehicle sits unused, particularly for long periods. There's a simple fix, so keep reading to find out what it is and how to potentially save yourself grief and your unit money...</p>

Commo/Electronics



Date	Article Title	Link	Excerpt
5-Jan-23	KG-175D: Battle Blackout! Mind TACLANE Checks	https://www.psmagazine.army.mil/News/Article/3260220/kg-175d-battle-blackout-mind-taclane-checks/	This article initially appeared in PS 800, p.45 (Jul 19). It's important to know about the KG-175D inline encryptor's clock drift and battery life. Find out why...
10-Jan-23	Publications: AN/MRC-150A TM Released	https://www.psmagazine.army.mil/News/Articles-anmrc-150a-tm-released/	A newly released commo TM covers the AN/MRC-150A communication system. Read on to learn more...
10-Jan-23	Soldier Support: LAR Toolbox Revisited	https://www.psmagazine.army.mil/News/Article/3263258/soldier-support-lar-toolbox-revisited/	The LAR Toolbox offers resources covering power generation and environmental systems. To find out how to access the materials, read on...
13-Jan-23	Commo/Electronics & Soldier Support Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Articles-commo-electronics-soldier-support-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for commo/electronics and Soldier support. Get them here...
20-Jan-23	Lithium Batteries: Don't Get Burned By Wrong Type	https://www.psmagazine.army.mil/News/Article/3271744/lithium-batteries-dont-get-burned-by-wrong-type/	This article initially appeared in PS 797 (Apr 19), pp.53-54. Pay close attention to the battery type used in sights and night vision equipment. Using the wrong kind can lead to disaster...
24-Jan-23	AN/PRQ-7 CSEL: Order Non-rechargeable Batteries	https://www.psmagazine.army.mil/News/Article/3275666/anprq-7-csel-order-non-rechargeable-batteries/	Until stock of the rechargeable CSEL batteries increases, substitute non-rechargeable batteries. Read on to learn more....
24-Jan-23	SINCGARS: M917 Dump Truck Not on List	https://www.psmagazine.army.mil/News/Article/3276247/sinrgars-m917-dump-truck-not-on-list/	A reader asks if a SINCGARS installation kit is available for the M917 dump truck. The simple answer is, No. But there's more, so keep reading...

26-Jan-23	SATCOM: KGV-310B TRANSEC Module Destruct Switch Alert	https://www.psmagazine.army.mil/News/Article/3278905/satcom-kgv-310b-transec-module-destruct-switch-alert/	Units need to be careful when zeroizing the SMART-T TRANSEC module or they may mistakenly destroy the module. To learn more, read on...
30-Jan-23	Batteries: The ABCs of Battery Care	https://www.psmagazine.army.mil/News/Article/3281650/batteries-the-abcs-of-battery-care/	This article initially appeared in PS 768 (Nov 16), pp. 36-37. There are several rules worth remembering when it comes to battery care that'll ensure they work when needed, as well as not cause damage to equipment. Read on to learn more...
1-Feb-23	MEP-831A Generator: Finding an XB-coded Part	https://www.psmagazine.army.mil/News/Article/3285040/mep-831a-generator-finding-an-xb-coded-part/	The 3-kW MEP 831A generator has a metal plate that's coded XB. What does it mean when a part is coded XB? Keep reading to learn Half-Mast's answer...
1-Feb-23	MEP-1050/1051 Generators: Finding Elusive Oil Filter	https://www.psmagazine.army.mil/News/Article/3285190/mep-10501051-generators-finding-elusive-oil-filter/	A Soldier is looking for an NSN for the MEP-1050 generator oil filter. Get the scoop here...
2-Feb-23	MEP-805A TQG: Replacement for Obsolete Engine Parts	https://www.psmagazine.army.mil/News/Article/3286591/mep-805a-tqg-replacement-for-obsolete-engine-parts/	Units currently using the MEP-805A that need secondary parts or line replaceable units (LRUs) for repair must replace the next higher assembly, which is the entire system. In short, MEP-805As with consistent repair issues need to be replaced by MEP-805Bs. Keep reading to learn more...
7-Feb-23	SINGGARS: FMTV Radio Installation Kits Differ	https://www.psmagazine.army.mil/News/Article/3291540/singgars-fmtv-radio-installation-kits-differ/	The up-armored FMTV LTAS variant's SINGGARS radio installation kit and that of the non-armored FMTV are different. Read on to learn more...

10-Feb-23	Satellite Communication Terminal: Operator and Maintenance TMs Released	https://www.psmagazine.army.mil/News/Article/3295134/satellite-communication-terminal-operator-and-maintenance-tms-released/	Three (3) TMs have been released for the satellite communication terminal AN/TSC-208. Read on to learn more...
10-Feb-23	Tactical Intelligence Ground Station: Updated TM Available	https://www.psmagazine.army.mil/News/Article/3295147/tactical-intelligence-ground-station-updated-tm-available/	A newly updated TM covers the AN/TSQ-179F(V)2 tactical intelligence ground station. Continue to learn more...
23-Feb-23	Communications: JBC-P Fuse Proves Elusive	https://www.psmagazine.army.mil/News/Article/3306698/communications-jbc-p-fuse-proves-elusive/	A reader is looking for the NSN for the 8-amp, 250V glass fuse for the Joint Battle Command-Platform. Half-Mast helps them out. Read on for that NSN...
24-Feb-23	NVD: Handle Screen with Care	https://www.psmagazine.army.mil/News/Article/3308221/nvd-handle-screen-with-care/	NVDs give you a great view in low light. But they also contain toxic materials that can injure you. Learn more here...
9-Mar-23	TCN-L: Three New TMs Released	https://www.psmagazine.army.mil/News/Article/3323043/tcn-l-three-new-tms-released/	Three (3) TMs have been released for the Tactical Communications Node-Lite (TCN-L), NSN 5895-01-657-3979. Continue reading to learn more and get a video link about TCN-L...
9-Mar-23	HMEE-1: SINCGARS Mount?	https://www.psmagazine.army.mil/News/Article/3323098/hmee-1-sincgars-mount/	If you're thinking of putting a SINCGARS radio mount kit in your HMEE, installing it isn't approved. Read on to learn more.....
16-Mar-23	NOSC-L: Two New TMs Available	https://www.psmagazine.army.mil/News/Article/3329755/nosc-l-two-new-tms-available/	Two (2) new TMs cover the AN/TSC-234(V1) network management system network operations and security center-lite (NOSC-L). Read on to learn more about them and where to download...

28-Mar-23	CSS ISA VSAT: Antenna Retrofit Scheduled for FY23	https://www.psmagazine.army.mil/News/Article/3342745/css-isa-vsantenna-retrofit-scheduled-for-fy23/	The 4QFY23 retrofit for the CSS ISA VSAT/AN/TSC-245 (v)2 includes numerous upgrades and will change the system's nomenclature. To learn more, read on.....
11-Apr-23	PQAS-E: Hard Drive Software Update	https://www.psmagazine.army.mil/News/Article/3357342/pqas-e-hard-drive-software-update/	The PQAS-E laptop's hard drive software needed to be updated on a short timeline and the deadline to comply has technically passed, so make sure you're compliant.
21-Apr-23	MEP-831A/832A TQGs: Return Correct Engines Only	https://www.psmagazine.army.mil/News/Article/3368171/mep-831a832a-tqgs-return-correct-engines-only/	The 3-kW tactical quiet generators (TQGs) MEP-831A/MEP-823A are powered by two versions of Yanmar L70 diesel engines. Each is disposed of differently. CECOM needs units to double-check which version they have before disposition is undertaken. Read on to learn the details...
2-May-23	Radio Systems: GEN II MANPACK HUB Maintenance and Replacement	https://www.psmagazine.army.mil/News/Article/3381566/radio-systems-gen-ii-manpack-hub-maintenance-and-replacement/	It's important to know the correct steps for R/T HUB replacement. Mistakes can mean elevation to higher maintenance levels. To learn more, keep reading....
15-May-23	SINCGARS: Circuit Card Assembly PN Marking Problem	https://www.psmagazine.army.mil/News/Article/3393564/sincgars-circuit-card-assembly-pn-marking-problem/	Did you run into a problem when trying to turn in the SINCGARS Circuit Card Assembly – Flexible Rear Panel – RT (NSN 5998-01-539-5371)? Find out why here...
13-Jun-23	NVDs: How to Get Replacement Data Plates	https://www.psmagazine.army.mil/News/Article/3426359/nvds-how-to-get-replacement-data-plates/	Is your night vision device missing its data plate, or is the data plate unreadable? You can get free data plate replacements. Here's how...

22-Jun-23	PQAS-E: Hard Drive Software Update	https://www.psmagazine.army.mil/News/Article/3357342/pqas-e-hard-drive-software-update/	The PQAS-E laptop's hard drive software needs to be updated on a short timeline and the deadline to comply is July 22, 2023. Make sure you're compliant. It's also transitioning to a new update method using USB technology. To learn more, read on....
26-Jun-23	MEP-831A 3kW TQG: NSN Confusion Leads to Faulty Orders	https://www.psmagazine.army.mil/News/Article/2607411/mep-831a-3kw-tqg-nsn-confusion-leads-to-faulty-orders/	The MEP-831A 3kW tactical quiet generator (TQG) set, NSN 6115-01-285-3012, is covered in TM 9-6115-639-13&P (Aug 17). Before this publication, there was an error with the callouts for the 60Hz and 400Hz frequency converters in the RPSTL. This resulted in invalid requisitions. Learn more here...
26-Jun-23	HMMWV Shelter: Searching for Generator NSN	https://www.psmagazine.army.mil/News/Article/3439386/hmmwv-shelter-searching-for-generator-nsn/	A Soldier is looking for the NSN for a generator in a HMMWV shelter. Half-Mast explains that one doesn't exist and how and where to repair them. Read on...
6-Jul-23	VOSS: Recycle Old or Used Desiccators	https://www.psmagazine.army.mil/News/Article/3448716/voss-recycle-old-or-used-desiccators/	Find out how to inspect or replace the desiccator in the VOSS gimbal, NSN 5855-01-626-6338. WP 0030 in TM 5-5895-1984-10 (Oct 16) shows you how....
6-Jul-23	OGS: TM Updated	https://www.psmagazine.army.mil/News/Article/3449562/ogs-tm-updated/	An updated TM has been published for the operational intelligence ground station (OGS). Learn more here...
11-Jul-23	SINCGARS: Searching for PMCS Tables	https://www.psmagazine.army.mil/News/Article/3454892/sincgars-searching-for-pmcs-tables/	A Soldier is asking about where to locate the PMCS tables for SINCGARS. Half-Mast has the answer. It's available in a TM covering over 20 models. To find out more, read on...
26-Jul-23	NVGs: Order the Correct Army Helmet Mount	https://www.psmagazine.army.mil/News/Article/3471961/nvgs-order-the-correct-army-helmet-mount/	When it comes to Army NVG helmet mounts for the NVGs AN/PVS-7 and NVG AN/PVS-14, only one NSN is approved. Learn more here...

1-Aug-23	DAGR: Long-term Storage and Disposition	https://www.psmagazine.army.mil/News/Article/3478890/dagr-long-term-storage-and-disposition/	There are specific instructions for DAGR storage, turn-in, repair and disposal. To learn what they are, read on...
2-Aug-23	DAGR/GB-GRAM: Keying is Key to Successful Operations	https://www.psmagazine.army.mil/News/Article/3479746/dagrgb-gram-keying-is-key-to-successful-operations/	Keying your DAGR or GB-GRAM is a critical step toward achieving mission success. To learn more about the why and how, keep reading...
18-Aug-23	GB-GRAM: RSAM Software 2.0 Released	https://www.psmagazine.army.mil/News/Article/3497382/gb-gram-rsam-software-20-released/	A GB-GRAM software is now available. Keep reading to find out what the improvements include...
18-Aug-23	PQAS-E: Newer SST25 Generator Needs OEM Support	https://www.psmagazine.army.mil/News/Article/3498257/pqas-e-newer-sst25-generator-needs-oem-support/	The PQAS-E SST25 generators have one of two electronic and wiring systems, but only one is currently covered in the system's TMs. The OEM is available to provide wiring diagrams and troubleshooting support. To find out more, read on...
25-Aug-23	IFS: New TM Gives Maintenance Guidance	https://www.psmagazine.army.mil/News/Article/3505727/ifs-new-tm-gives-maintenance-guidance/	A new TM covers the intelligence fusion server (IFS) AN/TYQ-94J(V)2, NSN 7010-01-674-1704, and AN/TYQ-94K(V)2, NSN 7010-01-685-6919. Read on to learn more about the TM and where to download it...
29-Aug-23	JBC-P: Use Authorized Hard Drive	https://www.psmagazine.army.mil/News/Article/3508302/jbc-p-use-authorized-hard-drive/	Commercial off-the-shelf hard drives can't be used with JBC-P. Read on to find out why and to learn how to get the right ones...
4-Oct-23	AN/PSQ-40 ENVG III: When to Involve RSC for Repairs	https://www.psmagazine.army.mil/News/Article/3547536/anpsq-40-envg-iii-when-to-involve-rsc-for-repairs/	Is your AN-PSQ-40 ENVG III in need of major repair? Look to the RSC at Fort Liberty for help. Find out more.....


18-Oct-23	M75 Smoke Generator: New TM Available	https://www.psmagazine.army.mil/News/Article/3560155/m75-smoke-generator-new-tm-available/	The new TM 3-1040-297-13&P (Oct 23) can be found on the ETM website. Learn more here....
30-Nov-23	ENFIRE: New TM Released	https://www.psmagazine.army.mil/News/Article/3601107/enfire-new-tm-released/	A new TM covers the ENFIRE 9.0 (AN/TYQ-X(V)X), NSN 6675-01-617-9193. Read on to learn more about the TM and where to download it...
26-Dec-23	AN/PVS-7 & AN/PVS-14 NVD: ACH Lever Bracket Supply Sub	https://www.psmagazine.army.mil/News/Article/3623992/anpvs-7-anpvs-14-nvd-ach-lever-bracket-supply-sub/	A shortage in AN/PVS-7 & AN/PVS-14 NVD ACH lever brackets, NSN 5340-01-509-1467, can be mitigated by ordering the next higher assembly, NSN 5855-01-610-8704, but there are some important things to know before you place your order. Keep reading to find out more details...

H2F



Date	Article Title	Link	Excerpt
1/19/2023	H2F: ATP Guide Gives Guidance	https://www.psmagazine.army.mil/News/Article/3271717/h2f-atp-guide-gives-guidance/	ATP 7-22.02 covers physical fitness for the Soldier, enhancing personal and Army readiness. Learn more here...
21-Apr-23	H2F: GTA Posters Highlight Five Readiness Areas	https://www.psmagazine.army.mil/News/Article/3370299/h2f-gta-posters-highlight-five-readiness-areas/	A new GTA is available through the Central Army Registry consisting of five (5) posters covering the H2F Soldier Readiness System. To find out how to get them, keep reading...

Logistics Management



Date	Article Title	Link	Excerpt
11-Jan-23	ASC Materiel Readiness Training Div Offers Virtual Option	https://www.psmagazine.army.mil/News/Article/2534184/asc-materiel-readiness-training-div-offers-virtual-option/	The Army Sustainment Command's (ASC) Materiel Readiness Training Division (MRTD) offers valuable automated logistics sustainment training on logistics tools, applications and programs. MRTD creates and delivers tailored unit-specific instruction based on the customer's needs. Keep reading to learn what training is available and how to schedule it. (Article updated 1/11/2023)...
11-Jan-23	Packaging: New COSIS Approach	https://www.psmagazine.army.mil/News/Article/3264791/packaging-new-cosis-approach/	The new COSIS priority groups will help you prioritize which stored items need to be inspected. Click on the link to learn more about these CPGs...
26-Jan-23	Half-Mast Sends: Keep on Trucking	https://www.psmagazine.army.mil/News/Article/3277954/half-mast-sends-keep-on-trucking/	The war in Ukraine is offering a lot of lessons. The question is: Are we learning them? An informative CNN article offers some insights on the importance of maintenance and logistics basics that are worth heeding. And we offer links to articles in our archive that reinforce important lessons learned. So read on...
3-Feb-23	Packaging: Managing COSIS MOP 50 Items	https://www.psmagazine.army.mil/News/Article/3286977/packaging-managing-cosis-mop-50-items/	Need know more about COSIS Priority Group (CPG) 1 - MOP 50 items, what they are and tips on their proper care? Read on!...
9-Feb-23	Corrosion: TACOM Introduces Basic Corrosion Course for Operators	https://www.psmagazine.army.mil/News/Article/3293573/corrosion-tacom-introduces-basic-corrosion-course-for-operators/	There's a new corrosion course available for all Army personnel, including civilians and contractors who operate and maintain Army ground equipment. Read on...

14-Feb-23	PS Magazine: A One-Stop Shop for 70 Years of PS	https://www.psmagazine.army.mil/News/Article/3297478/ps-magazine-a-one-stop-shop-for-70-years-of-ps/	This article initially appeared in PS 783, p.61. Want a peek at PS history? We have the website for you! Get a glimpse of the PS gang from years gone by....
17-Feb-23	Soldier Support: PM's not a Back Burner Issue	https://www.psmagazine.army.mil/News/Article/3301719/soldier-support-pms-not-a-back-burner-issue/	This article initially appeared in PS 766, p. 1 (Sep 16). Tackling PM now keeps equipment prepped, which increases readiness! Learn how here...
27-Feb-23	Packaging: Managing COSIS ESDS Items	https://www.psmagazine.army.mil/News/Article/3311178/packaging-managing-cosis-esds-items/	COSIS ESDS items require special care and handling. There are a number of important requirements to keep in mind to avoid damage to these high-value items. Read on to learn the details!...
28-Feb-23	Small Arms: Replacing Lower Receiver?	https://www.psmagazine.army.mil/News/Article/3311982/small-arms-replacing-lower-receiver/	When the lower receiver is changed out, the job isn't done until the paperwork is complete. Keep reading to see what must be done...
6-Mar-23	Half-Mast Sends: Lose the 'Rabbit Habit'	https://www.psmagazine.army.mil/News/Article/3320071/half-mast-sends-lose-the-rabbit-habit/	This article initially appeared in PS 736, p.1 (Mar 14). Tempted to take a PMCS shortcut? Read an important reminder here...
13-Mar-23	Log Management: DLA Battery Network Program	https://www.psmagazine.army.mil/News/Article/3327025/log-management-dla-battery-network-program/	The Defense Logistics Agency (DLA) has a Battery Network (BATTNET) Program designed to increase the shelf life and safety of batteries as well as reduce premature disposals. Keep reading to learn more about this program...
21-Mar-23	Log Management: DLA Technical Assistance	https://www.psmagazine.army.mil/News/Article/3336354/log-management-dla-technical-assistance/	Need help with DLA system access or technical issues? DLA has several ways to assist you. Keep reading to learn what they are!...

28-Mar-23	GCSS-Army: Introducing My Workplace UI5	https://www.psmagazine.army.mil/News/Article/3342868/gcss-army-introducing-my-workplace-ui5/	The new AIT UI5 interface offers improvements to make materiel management easier. Read on to find out how...
30-Mar-23	Half-Mast Sends: Heed PMCS Cautions and Warnings	https://www.psmagazine.army.mil/News/Article/3345325/half-mast-sends-heed-pmcs-cautions-and-warnings/	An article in Risk Management Magazine, written by MAJ Eric Tolska, gives a real-life example of why paying attention to PMCS warnings and cautions is so important. Read on to learn more about the article...
13-Apr-23	Maintenance Mgmt: Army Software Factory PMCS App Update	https://www.psmagazine.army.mil/News/Article/3362161/maintenance-mgmt-army-software-factory-pmcs-app-update/	The Army Software Factory (SWF) has added a new feature to the PMCS app. It allows users to add Unit Identification Codes (UICs) to their equipment lists. Keep reading to find out more...
14-Apr-23	Ground Vehicles: Want to Order in Bulk?	https://www.psmagazine.army.mil/News/Article/3362656/ground-vehicles-want-to-order-in-bulk/	There are items you can order in bulk for your vehicles and equipment. Ordering in bulk can save units money and ensure high-usage items are available when needed. Here's how to find what you can order in bulk...
28-Apr-23	Half-Mast Sends: Readiness Starts with You	https://www.psmagazine.army.mil/News/Article/3376829/half-mast-sends-readiness-starts-with-you/	This article initially appeared in PS 780 (Nov 17), p. 1. The person best suited to determine your equipment's readiness is you. Remember that the next time you pull PMCS. Fix what you can and report what you can't. Keep reading to learn more of Half-Mast's wisdom on this topic...
5-May-23	Logistics Management: CY 2022 Petroleum Excellence Winners	https://www.psmagazine.army.mil/News/Article/3386271/logistics-management-cy-2022-petroleum-excellence-winners/	The annual Petroleum Excellence awards recognize superior performance in petroleum management and fuel handling. The CY22 Petroleum Excellence awards are announced. To find out where to get the list of winners, read on...

8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
24-May-23	Publications: ETM Updates and IADS Conversion	https://www.psmagazine.army.mil/News/Article/3405787/publication-s-etm-updates-and-iads-conversion/	Looking for ETM or IETM updates, such as when they convert to IADS? Keep reading to find out where to track them...
8-Jun-23	Maintenance Mgmt: DA Form 5990-E Now Required	https://www.psmagazine.army.mil/News/Article/3421916/maintenance-mgmt-da-form-5990-e-now-required/	Did you hear about the new DA Form 5990-E requirement? Service packets must now include this form. Keep reading to find out more...
8-Jun-23	Half-Mast Sends: The Long, Hot Summer	https://www.psmagazine.army.mil/News/Article/3421935/half-mast-sends-the-long-hot-summer/	This article initially appeared in PS 764, p. 1 (Jul 16). Heat brings challenges to Soldiers and equipment alike. Read this important reminder about prepping for that scorching summertime.....
13-Jun-23	NVDs: How to Get Replacement Data Plates	https://www.psmagazine.army.mil/News/Article/3426359/nvds-how-to-get-replacement-data-plates/	Is your night vision device missing its data plate, or is the data plate unreadable? You can get free data plate replacements. Here's how...
26-Jun-23	Packaging: Turn-In AFES Bottles Correctly	https://www.psmagazine.army.mil/News/Article/3438842/packaging-turn-in-afes-bottles-correctly/	Need to turn in AFES bottles but not sure how? Keep reading to find out what you need to do...
29-Jun-23	Packaging: Managing CPG 4 Items	https://www.psmagazine.army.mil/News/Article/3443010/packaging-managing-cpg-4-items/	CPG 4 covers Shelf-Life (SL) Type 2 expendable items. Units can benefit from effectively managing extendable items. To learn about the proper COSIS for SL Type 2, read on!...

7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
10-Aug-23	Packaging: Properly Managing CPG 5 Items	https://www.psmagazine.army.mil/News/Article/3489987/packaging-properly-managing-cpg-5-items/	CPG 5 covers the proper Care of Supplies in Storage (COSIS) of items containing hazardous materials (HAZMAT). Keep reading to learn more!...
14-Aug-23	MRZR Polaris: Not Army Supported, So No RPSTL	https://www.psmagazine.army.mil/News/Article/3492315/mrzs-polaris-not-army-supported-so-no-rpstl/	The MRZR Polaris utility vehicle is a unit-purchased item. That means there's no RPSTL because the Army doesn't maintain them, and spare parts and equipment must be a local purchase. Keep reading to learn more...
19-Oct-23	Log/Maint Management: 2023 Army Logistics Excellence Award Winners	https://www.psmagazine.army.mil/News/Article/3561667/logmaint-management-2023-army-logistics-excellence-award-winners/	Read on to find out which units won the Fiscal Year 2023 Army Chief of Staff Logistics Excellence Awards...
23-Oct-23	Maintenance Mgmt: i2Log Extended	https://www.psmagazine.army.mil/News/Article/3565260/maintenance-mgmt-i2log-extended/	Not sure how to look up item managers once the i2Log sunset date arrives? Keep reading for an important i2Log update...

27-Oct-23	Log/Maint Management: Advanced Manufacturing at CECOM	https://www.psmagazine.army.mil/News/Article/3570925/logmaint-advanced-manufacturing-at-cecom/	There's a new development called advanced manufacturing that can help improve readiness rates by increasing parts availability. CECOM is quickly adopting this technology. Learn more here...
21-Nov-23	Maintenance Mgmt: Chock Blocks - Any Inspection Criteria?	https://www.psmagazine.army.mil/News/Article/3595310/maintenance-mgmt-chock-blocks-any-inspection-criteria/	Chock blocks looking a little damaged? How can you tell if they are too far gone, and what can you do about it if they are? Keep reading to find out...
14-Dec-23	Packaging: 2024 DoD Shelf-Life Course Dates	https://www.psmagazine.army.mil/News/Article/3617473/packaging-2024-dod-shelf-life-course-dates/	The DoD Shelf-Life (SL) course, a two-day resident program of instruction, has dates available in 2024. Keep reading to find out what they are and how to register...
29-Dec-23	Maintenance Mgmt: Glass Cutting Kit Component List	https://www.psmagazine.army.mil/News/Article/3627617/maintenance-mgmt-glass-cutting-kit-component-list/	A Soldier tells MSG Half-Mast he's having difficulty getting the component listing for the vehicle glass repair glass cutting shop set. Keep reading to find out Half-Mast's reply...

Medical Logistics



Date	Article Title	Link	Excerpt
23-Jun-23	MedLog: Medical Maintenance Video Launches	https://www.psmagazine.army.mil/News/Article/3435386/medlog-medical-maintenance-video-launches/	AMLC has added another training video to its MEDLOG Ready! series. Find out how to view it here...

Mines



Date	Article Title	Link	Excerpt
15-Mar-23	Ground Vehicles: Contact LARs for Maintenance Assistance	https://www.psmagazine.army.mil/News/Article/3329899/ground-vehicles-contact-lars-for-maintenance-assistance/	If you need maintenance or logistics help for ground vehicles or equipment, just reach out to a logistics assistance representative or LAR. Get more info here...
4-May-23	M1270 MMPV Type II: New Annual Service Kit NSN	https://www.psmagazine.army.mil/News/Article/3384656/m1270-mmpv-type-ii-new-annual-service-kit-nsn/	Maintainers, there's a new annual service kit for the M1270 MMPV Type II that's not in the current TM. Get the NSN here...
18-May-23	M1272 Buffalo: Annual Service Kit NSN	https://www.psmagazine.army.mil/News/Article/3399400/m1272-buffalo-annual-service-kit-nsn/	The M1272 has an annual service kit but it's not listed in the TM. Read on to learn the NSN...
5-Jul-23	AN/PSS 14C Mine Detector: Get a Grip on the Grip	https://www.psmagazine.army.mil/News/Article/3447397/anpss-14c-mine-detector-get-a-grip-on-the-grip/	The AN/PSS 14C mine detector handle is made of plastic, so handle it with care. Use the forearm strap when operating the mine detector, to reduce the chance of damage. Read on for more tips to keep the detector detecting...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
1-Aug-23	M160 Light Flail: TM Lists Incorrect O-ring NSN	https://www.psmagazine.army.mil/News/Article/3478517/m160-light-flail-tm-lists-incorrect-o-ring-nsn/	The O-ring listed as NSN 5331-53-000-0869 in Item 7 of Fig 77 of TM 9-2360-392-23-3 (Jun 19) is incorrect. Keep reading to get the right NSN...
1-Aug-23	M160 Light Flail: New NSN for Primary Element Filter	https://www.psmagazine.army.mil/News/Article/3478632/m160-light-flail-new-nsn-for-primary-element-filter/	Don't use NSN 4330-01-602-2321 to order the primary element filter (air filter) shown as Item 14 in Fig 21 of TM 9-2360-392-23-3 (Jun 19). Read on to get the right NSN to use...


1-Aug-23

M1231 HUSKY Red
Pack: Updated
Corrosion Mitigation
Procedures

<https://www.psmagazine.army.mil/News/Article/3478775/m1231-husky-red-pack-updated-corrosion-mitigation-procedures/>

TACOM developed corrosion mitigation procedures for the M1231 HUSKY Red Pack (spare parts trailer). The procedures are available in TACOM MAM 23-025. Read on...

Missiles



Date	Article Title	Link	Excerpt
6-Feb-23	Patriot: Stow the Antenna Shroud by the Book	https://www.psmagazine.army.mil/News/Article/3289222/patriot-stow-the-antenna-shroud-by-the-book/	Patriot crew members must always follow the TM when stowing the antenna shroud to prevent damage to the SLC access covers. Keep reading for the full story...
27-Apr-23	Avenger: PM Is Best Served Often!	https://www.psmagazine.army.mil/News/Article/3375069/avenger-pm-is-best-served-often/	This article initially appeared in PS 718 (Sep 12), pp. 44-45. Preventive maintenance often is the best revenge against the forces that can stop the Avenger in its tracks. Make sure to pay attention to the M3P machine gun. Watch where you step and check the W103 cable to insure it's tight. Keep reading for more information...
25-May-23	Avenger: Argon Bottles Inspect and Replace Criteria	https://www.psmagazine.army.mil/News/Article/3407041/avenger-argon-bottles-inspect-and-replace-criteria/	Pay attention to two dates annotated on each Avenger argon bottle. There's a 5-year proof pressure tested and manufacture build date. Why? Keep reading for all the details...
28-Jun-23	Avenger: New Potting Compound With New NSNs	https://www.psmagazine.army.mil/News/Article/3441790/avenger-new-potting-compound-with-new-nsns/	There's new potting compound for Avenger repair that comes with NSN 8040-01-416-5200, PN 3M DP460, for a 1.25 oz tube. A quart size is also available. Keep reading for more...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
10-Jul-23	Avenger: Remote Control Unit with VIC-5	https://www.psmagazine.army.mil/News/Article/3452594/avenger-remote-control-unit-with-vic-5/	Avenger has new remote control units (RCUs) available for the VIC-5 with a permanent dual operator system bracket. There are two models, each with its own NSN and part number. Read on for more...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...

19-Jul-23	Avenger: New Canopy Covers Now Available	https://www.psmagazine.army.mil/News/Article/3462616/avenger-new-canopy-covers-now-available/	There are newly designed canopy covers for the Avenger. They come in tan or green. Keep reading to get the NSNs...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
24-Jul-23	Avenger: New Bar Type Cable Clamp	https://www.psmagazine.army.mil/News/Article/3462544/avenger-new-bar-type-cable-clamp/	The Avenger has a new style cable clamp. You can get it with NSN 5342-01-116-7949, PN BACC10DS5. Keep reading for more...
7-Aug-23	Avenger: New Ultra-High Purity Argon Gas NSN	https://www.psmagazine.army.mil/News/Article/3485726/avenger-new-ultra-high-purity-argon-gas-nsn/	The Avenger argon gas supply cylinder is being replaced with a new ultra-high purity argon gas cylinder NSN 6830-01-649-5578. Keep reading for more...
29-Aug-23	Avenger: Potting Compound Dispensing Gun	https://www.psmagazine.army.mil/News/Article/3508635/avenger-potting-compound-dispensing-gun/	When applying 3MTM DP460 (Scotch-Weld), use the potting compound dispensing gun, NSN 5120-01-552-0154. Keep reading for more information...

Small Arms



Date	Article Title	Link	Excerpt
1-Jan-23	60mm Mortar: Emplacing the Baseplate on Frozen Ground	https://www.psmagazine.army.mil/News/Article/3256040/60mm-mortar-emplacing-the-baseplate-on-frozen-ground/	<p>When firing the 60mm mortar during freezing conditions, the baseplate can crack. Keep reading to learn how to protect the mortar baseplate when operating your 60mm mortar in very cold weather...</p>
5-Jan-23	M17/M18 MHS: Help Stop Extractor Pin Damage	https://www.psmagazine.army.mil/News/Article/3258814/m17m18-mhs-help-stop-extractor-pin-damage/	<p>It's important to only perform tasks designated for your level of maintenance. Removing and reinstalling the M17/M18 MHS extractor tension pin is to be performed by a 91F. Keep reading for instructions...</p>
11-Jan-23	81mm Mortars: Frozen Ground Emplacement	https://www.psmagazine.army.mil/News/Article/3264738/81mm-mortars-frozen-ground-emplacement/	<p>Protecting the 81mm mortar baseplate from cracking when firing in freezing weather is critical. There are specific methods that crews can employ to protect the baseplate. Read on to learn what they are...</p>
13-Jan-23	Small Arms Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265268/small-arms-year-in-review-new-and-updated-nsns-captured-in-2022/	<p>Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for small arms. Get them here...</p>
26-Jan-23	Half-Mast Sends: Keep on Trucking	https://www.psmagazine.army.mil/News/Article/3277954/half-mast-sends-keep-on-trucking/	<p>The war in Ukraine is offering a lot of lessons. The question is: Are we learning them? An informative CNN article offers some insights on the importance of maintenance and logistics basics that are worth heeding. And we offer links to articles in our archive that reinforce important lessons learned. So read on...</p>

30-Jan-23	Small Arms and Ammunition: Keep Good Accountability	https://www.psmagazine.army.mil/News/Article/3282402/small-arms-and-ammunition-keep-good-accountability	Lost or stolen military weapons and ammo could end up in the wrong hands and used indiscriminately. Do your part to stop this from happening by maintaining proper accountability of weapons and munitions entrusted to your safeguarding. Always follow prescribed security measures and procedures and report any discrepancies IMMEDIATELY in accordance with command guidance. Keep reading for some key point...
14-Feb-23	M240B Machine Gun: Properly Clean the Gas System to Avoid Malfunction	https://www.psmagazine.army.mil/News/Article/3297430/m240b-machine-gun-properly-clean-the-gas-system-to-avoid-malfunction/	If the M240 machine gun isn't cleaned properly, to include using the proper special tools, then the weapon can malfunction. Keep reading to see how to properly clean the gas port system...
28-Feb-23	Small Arms: Replacing Lower Receiver?	https://www.psmagazine.army.mil/News/Article/3311982/small-arms-replacing-lower-receiver/	When the lower receiver is changed out, the job isn't done until the paperwork is complete. Keep reading to see what must be done...
6-Mar-23	M2A1 Machine Gun: Enhance Training with Visual User Guide	https://www.psmagazine.army.mil/News/Article/3307911/m2a1-machine-gun-enhance-training-with-visual-user-guide/	The visual user guide (VUG) is a great resource to train soldiers on the M2A1 machine gun. It was issued when the weapon was fielded but if you need a copy, we have the link. There's also a headspace and timing VUG for the M2. Keep reading to to download copies...
22-Mar-23	Small Arms: Firing Range NSNs	https://www.psmagazine.army.mil/News/Article/3337066/small-arms-firing-range-nsns/	This article initially appeared in PS 762 (May 16). With spring comes trips to the firing range. Here's a list of NSNs you may need to run your range successfully. Keep reading to get the list...
6-Apr-23	M16-Series Rifle, M4/M4A1 Carbine: 30-Round Magazine NSN Clarification	https://www.psmagazine.army.mil/News/Article/3353034/m16-series-rifle-m4m4a1-carbine-30-round-magazine-nsn-clarification/	The M16-series rifle and M4/M4A1 carbine -10 TM lists two different 30-round magazines in the COEI table. Only one of them has a good NSN. Keep reading to see which magazine to order...

8-May-23	M16-Series Rifle, M4/M4A1 Carbine: See the New AAL Items	https://www.psmagazine.army.mil/News/Article/3387505/m16-series-rifle-m4m4a1-carbine-see-the-new-aal-items/	TACOM has added new items to the M16-Series Rifle, M4/M4A1 Carbine additional authorization list (AAL). Keep reading to see the new items...
10-May-23	M4 and M16 Series Rifles: Only You Can Avoid a Cook Off	https://www.psmagazine.army.mil/News/Article/3389878/m4-and-m16-series-rifles-only-you-can-avoid-a-cook-off/	Know your weapons' sustained rate of fire. Don't exceed the sustained rate of fire except under extreme circumstances to avoid a possible cook off or catastrophic failure. Read on to get the full story...
6-Jun-23	M3/M3A1 Rifles: Only Count Effective Full Charge Rounds	https://www.psmagazine.army.mil/News/Article/3418371/m3m3a1-rifles-only-count-effective-full-charge-rounds/	Not all M3/M3A1 rifle rounds are alike. It's required to log all effective full charge rounds on the TULSA website. Keep reading to learn more.....
9-Jun-23	M240 Machine Gun: Dry Firing Can Crack the Receiver	https://www.psmagazine.army.mil/News/Article/3422593/m240-machine-gun-dry-firing-can-crack-the-receiver/	When handling the M240, it's important to never dry fire the weapon. When the locking bar strikes the guide rails, the force can cause it to crack. This will take your M240 out of the fight. Keep reading to find out more.....
13-Jun-23	MK19 Grenade Machine Gun: Upgraded Rear Sight Assembly	https://www.psmagazine.army.mil/News/Article/3424272/mk19-grenade-machine-gun-upgraded-rear-sight-assembly/	The MK19 grenade machine gun has an updated rear sight assembly. Contact the MWO coordinator if your unit needs to have the MWO installed. Read on to learn more.....
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
10-Aug-23	M240 Machine Gun: Need a BFA Discriminator?	https://www.psmagazine.army.mil/News/Article/3034382/m240-machine-gun-need-a-bfa-discriminator/	The discriminator will be added to the M240 machine gun additional authorization list (AAL) according to TACOM. Here's how to get one...

4-Oct-23	Hand Grenades: Follow Good Practices	https://www.psmagazine.army.mil/News/Article/3545295/hand-grenades-follow-good-practices/	When handling bursting and burning hand grenades, there are some safety precautions you need to heed. Injuries are preventable if you follow the correct handling procedures. Keep reading to find out what to do...
10-Oct-23	M326 Mortar Kit: Only Lead-Acid Battery Can Be Used	https://www.psmagazine.army.mil/News/Article/3552023/m326-mortar-kit-only-lead-acid-battery-can-be-used/	Our article "No Hawkers for M326 Mortar Kit!" found in PS 773 (Apr 17) is no longer valid. The M326 mortar stowage kit can now use any brand of lead-acid battery. Read on for the details...
17-Oct-23	M320 Grenade Launcher: TM Clarification on Mounting Adaptor Screws	https://www.psmagazine.army.mil/News/Article/3554801/m320-grenade-launcher-tm-clarification-on-mounting-adaptor-screws/	There's a discrepancy between the TM 9-1010-232-10 and -23&P. The M320 grenade launcher forward and rear mounting adaptor screws aren't listed in the -10 TM. Keep reading to get the NSNs...
17-Oct-23	MK19 Grenade Machine Gun: Army Continues to Perform Semiannual DTI	https://www.psmagazine.army.mil/News/Article/3559518/mk19-grenade-machine-gun-army-continues-to-perform-semiannual-dti/	The Army will continue to perform the MK19 grenade machine gun semi-annual bolt and backplate detailed technical inspection (DTI). Read on for the full story...

Soldier Support



Date	Article Title	Link	Excerpt
11-Jan-23	ASC Materiel Readiness Training Div Offers Virtual Option	https://www.psmagazine.army.mil/News/Article/2534184/asc-materiel-readiness-training-div-offers-virtual-option/	The Army Sustainment Command's (ASC) Materiel Readiness Training Division (MRTD) offers valuable automated logistics sustainment training on logistics tools, applications and programs. MRTD creates and delivers tailored unit-specific instruction based on the customer's needs. Keep reading to learn what training is available and how to schedule it. (Article updated 1/11/2023)...
13-Jan-23	Commo/Electronics & Soldier Support Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265481/commoelectronics-soldier-support-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for commo/electronics and Soldier support. Get them here...
1/19/2023	H2F: ATP Guide Gives Guidance	https://www.psmagazine.army.mil/News/Article/3271717/h2f-atp-guide-gives-guidance/	ATP 7-22.02 covers physical fitness for the Soldier, enhancing personal and Army readiness. Learn more here...
24-Jan-23	Soldier Support: Info about Soldier Referral Program	https://www.psmagazine.army.mil/News/Article/3275057/soldier-support-info-about-soldier-referral-program/	Ready to support Army recruiting efforts? Now's the time with the new Soldier Referral Program. The rewards are awesome. To learn more, read on...
14-Feb-23	PS Magazine: A One-Stop Shop for 70 Years of PS	https://www.psmagazine.army.mil/News/Article/3297478/ps-magazine-a-one-stop-shop-for-70-years-of-ps/	This article initially appeared in PS 783, p.61. Want a peek at PS history? We have the website for you! Get a glimpse of the PS gang from years gone by....
17-Feb-23	Soldier Support: PM's not a Back Burner Issue	https://www.psmagazine.army.mil/News/Article/3301719/soldier-support-pms-not-a-back-burner-issue/	This article initially appeared in PS 766, p. 1 (Sep 16). Tackling PM now keeps equipment prepped, which increases readiness! Learn how here...

28-Feb-23	Laundry Advanced System: Beware of Static Electricity	https://www.psmagazine.army.mil/News/Article/3313406/laundry-advanced-system-beware-of-static-electricity/	This article initially appeared in PS 735, p. 52 (Feb 14). You may not know it, but electrostatic discharge when troubleshooting the LADS can bring it to a tumbling halt. Learn more here...
6-Mar-23	Half-Mast Sends: Lose the 'Rabbit Habit'	https://www.psmagazine.army.mil/News/Article/3320071/half-mast-sends-lose-the-rabbit-habit/	This article initially appeared in PS 736, p.1 (Mar 14). Tempted to take a PMCS shortcut? Read an important reminder here...
20-Mar-23	Modern Burner Unit: Left in the Dust	https://www.psmagazine.army.mil/News/Article/3333558/modern-burner-unit-left-in-the-dust/	This article initially appeared in PS 736, pp. 48-49 (Apr 14). Dust can shut down your modern burner unit (MBU). Follow these tips to keep it burning bright...
21-Mar-23	Safety: USACRC Launches New Courses	https://www.psmagazine.army.mil/News/Article/3335638/safety-usacrc-launches-new-courses/	There are three new safety courses available beginning on 1 Apr 23. Read on to get all the info...
23-Mar-23	Publications: How to Find New and Revised TMs	https://www.psmagazine.army.mil/News/Article/3339167/publication-how-to-find-new-and-revised-tms/	A Soldier is looking for a list of brand-new TMs, as well as revisions to existing TMs. Connie refers them to the Army Publishing Directorate website. Read on to learn more.....
30-Mar-23	Half-Mast Sends: Heed PMCS Cautions and Warnings	https://www.psmagazine.army.mil/News/Article/3345325/half-mast-sends-heed-pmcs-cautions-and-warnings/	An article in Risk Management Magazine, written by MAJ Eric Tolska, gives a real-life example of why paying attention to PMCS warnings and cautions is so important. Read on to learn more about the article.....
14-Apr-23	Half-Mast Sends: Reminder on Safeguarding Classified Information	https://www.psmagazine.army.mil/News/Article/3362893/half-mast-sends-reminder-on-safeguarding-classified-information/	Personnel with access to classified information are trusted stewards of that information. The responsibility to safeguard classified information is a lifetime requirement for everyone granted a security clearance. Continue reading for this reminder...

21-Apr-23	H2F: GTA Posters Highlight Five Readiness Areas	https://www.psmagazine.army.mil/News/Article/3370299/h2f-gta-posters-highlight-five-readiness-areas/	A new GTA is available through the Central Army Registry consisting of five (5) posters covering the H2F Soldier Readiness System. To find out how to get them, keep reading...
5-May-23	Logistics Management: CY 2022 Petroleum Excellence Winners	https://www.psmagazine.army.mil/News/Article/3386271/logistics-management-cy-2022-petroleum-excellence-winners/	The annual Petroleum Excellence awards recognize superior performance in petroleum management and fuel handling. The CY22 Petroleum Excellence awards are announced. To find out where to get the list of winners, read on...
8-May-23	Aviation Maintenance: MOS 15D Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3387861/aviation-maintenance-mos-15d-invited-to-take-job-analysis-survey/	All aircraft powertrain repairers are asked to participate in a job analysis survey to update critical tasks and training for their MOS. Read on to find out more...
15-May-23	Laundry Advanced Systems: No Open Door Policy	https://www.psmagazine.army.mil/News/Article/3394193/laundry-advanced-systems-no-open-door-policy/	Keep the doors to all enclosures shut tight. An open door is an invitation for fine dirt and sand to settle on electrical and electronic components and contacts. Keep reading to learn the problems this will cause...
16-May-23	Soldier Support: New Limitations on Shipping Lithium Batteries	https://www.psmagazine.army.mil/News/Article/3397036/soldier-support-new-limitations-on-shipping-lithium-batteries/	Time to make a PCS? Plan ahead and note the new limitations on shipping lithium batteries. Find out more here...
24-May-23	Tactical Expandable Shelters: Keep Cautions in Mind	https://www.psmagazine.army.mil/News/Article/3405747/tactical-expandable-shelters-keep-cautions-in-mind/	There are some important warnings to keep in mind when opening or closing tactical expanded shelters. Here's what to know...
1-Jun-23	Food Service: Connelly Awards Announced	https://www.psmagazine.army.mil/News/Article/3412980/food-service-connelly-awards-announced/	The annual awards for the FY23 55th annual Philip A. Connelly are announced. To find out who won, read on...

7-Jun-23	Safety: Lethal Means Safety Can Reduce Suicides	https://www.psmagazine.army.mil/News/Article/3418831/safety-lethal-means-safety-can-reduce-suicides/	“Lethal Means Safety” is an approach to preventing self-harm by securing firearms, prescription drugs and other items that might be used in suicide attempts. Learn more here...
23-Jun-23	Publications: Fuel System TB Updated	https://www.psmagazine.army.mil/News/Article/3435357/publication-s-fuel-system-tb-updated/	TB 10-5430-253-13 (Jun 23) has been updated. Find out more here...
10-Jul-23	Heat Safety: Army’s Annual Guidance Worth the Read	https://www.psmagazine.army.mil/News/Article/3452510/heat-safety-armys-annual-guidance-worth-the-read/	Stay alert for the signs of heat-related illnesses with the Army’s annual guidance. Learn more here....
9-Aug-23	Containerized Kitchen: Label New CO Monitor with Expiration Date	https://www.psmagazine.army.mil/News/Article/3488273/containerized-kitchen-label-new-co-monitor-with-expiration-date/	There’s a new CO monitor model that has a five-year replacement cycle. It also needs to be labeled with an expiration date. Learn why here...
9-Aug-23	Containerized Kitchen: New Cable Replacement Guidelines	https://www.psmagazine.army.mil/News/Article/3488324/containerized-kitchen-new-cable-replacement-guidelines/	The TM currently states that CK cables should be replaced if there’s more than one flat spot. This guidance is changing with a new cable NSN. To find out why, keep reading...
18-Aug-23	Suicide Prevention: New AR Provides Comprehensive Guidance	https://www.psmagazine.army.mil/News/Article/3497514/suicide-prevention-new-ar-provides-comprehensive-guidance/	The Army has provided additional guidance and resources for suicide prevention in a new publication, AR 600-92. Learn more here.....
25-Aug-23	IFS: New TM Gives Maintenance Guidance	https://www.psmagazine.army.mil/News/Article/3505727/ifs-new-tm-gives-maintenance-guidance/	A new TM covers the intelligence fusion server (IFS) AN/TYQ-94J(V)2, NSN 7010-01-674-1704, and AN/TYQ-94K(V)2, NSN 7010-01-685-6919. Read on to learn more about the TM and where to download it...

18-Oct-23	M75 Smoke Generator: New TM Available	https://www.psmagazine.army.mil/News/Article/3560155/m75-smoke-generator-new-tm-available/	The new TM 3-1040-297-13&P (Oct 23) can be found on the ETM website. Learn more here...
23-Oct-23	Batteries: Solar Maintainers Required for Long-Term Equipment Storage	https://www.psmagazine.army.mil/News/Article/3565076/batteries-solar-maintainers-required-for-long-term-equipment-storage/	AR 750-1 and DA PAM 750-1 were updated to clarify that approved solar maintainers are required for equipment in LUP, NCOMP and outdoor storage. Read on to learn more...
3-Nov-23	Safety: Cold Weather Brings Warnings	https://www.psmagazine.army.mil/News/Article/3578445/safety-cold-weather-brings-warnings/	It's wise to prepare, plan and train for cold weather. The Army's released an ALARACT that can help. Read on to learn more...
7-Nov-23	Clothing: Ordering Mechanics Coveralls	https://www.psmagazine.army.mil/News/Article/3581278/clothing-ordering-mechanics-coveralls/	How do you keep a uniform clean in the motor pool? Coveralls are the answer. Read on for the NSNs to order...
8-Nov-23	Health Safety: Cold Weather Causes Problems, Too	https://www.psmagazine.army.mil/News/Article/3582534/health-safety-cold-weather-causes-problems-too/	This article initially appeared in PS 795 (Feb 19), p. 59-60. We often hear about the dangers of hot weather injuries, but cold weather can be dangerous too.
9-Nov-23	ULCANS Increment I: Updated Camouflage Nets Available	https://www.psmagazine.army.mil/News/Article/3584197/ulcans-increment-i-updated-camouflage-nets-available/	ULCANS Increment I is the newest version of camouflage netting systems. Learn more, including how to order it, here....
14-Nov-23	Fuels: Petroleum Smart Book Updated	https://www.psmagazine.army.mil/News/Article/3195855/fuels-petroleum-smart-book-updated/	Petroleum planners can now download the FY24 edition of the Petroleum Planning and Operations Smart Book. To find out how, read on...

30-Nov-23

ENFIRE: New TM
Released

<https://www.psmagazine.army.mil/News/Article/3601107/enfire-new-tm-released/> A new TM covers the ENFIRE 9.0 (AN/TYQ-X(V)X), NSN 6675-01-617-9193. Read on to learn more about the TM and where to download it...

Tactical Vehicles



Date	Article Title	Link	Excerpt
10-Jan-23	HEMTT A4-PLS A1-HET A1: Engine Cranks but Won't Start	https://www.psmagazine.army.mil/News/Article/3263295/hemtt-a4-pls-a1-het-a1-engine-cranks-but-wont-start/	There's a possible issue with the C15 and C18 engine on certain vehicles cranking but not starting due to a damaged engine cluster gear. Here's what you need to know.....
12-Jan-23	Tactical Vehicles Year-in-Review: New and Updated NSNs Captured in 2022	https://www.psmagazine.army.mil/News/Article/3265719/tactical-vehicles-year-in-review-new-and-updated-nsns-captured-in-2022/	Updated or new NSNs are a challenge to keep up with. Here's a list that PS captured in 2022 for tactical vehicles and equipment. Get them here.....
17-Jan-23	M870A3 Semitrailer: Retrofit Kit for M983A2/A4 HEMTTs	https://www.psmagazine.army.mil/News/Article/3269637/m870a3-semitrailer-retrofit-kit-for-m983a2a4-hemtt/	This article initially appeared in PS 720 (Nov 12), p. 61. If no power is supplied to M870A3 semitrailer ABS ECU or service lights when hooked to an M983A2 or M983A4 LET tractor truck you may need to install an electrical system retrofit kit. Read on
26-Jan-23	M915A3 Tractor Truck: Get the Correct ECM Assembly	https://www.psmagazine.army.mil/News/Article/3278470/m915a3-tractor-truck-get-the-correct-ecm-assembly/	Need an electronic control module (ECM) assembly (modulator assembly) for your M915A3 truck? Here's how you get the right assembly...
26-Jan-23	Half-Mast Sends: Keep on Trucking	https://www.psmagazine.army.mil/News/Article/3277954/half-mast-sends-keep-on-trucking/	The war in Ukraine is offering a lot of lessons. The question is: Are we learning them? An informative CNN article offers some insights on the importance of maintenance and logistics basics that are worth heeding. And we offer links to articles in our archive that reinforce important lessons learned. So read on...
1-Feb-23	M149A2 Water Trailer: Wheel Assembly NSN Updates	https://www.psmagazine.army.mil/News/Article/3285156/m149a2-water-trailer-wheel-assembly-nsn-updates/	There are a couple wheel assembly NSN updates to WP 0095 that aren't in the current TM. Get them here...

2-Feb-23	FMTV: Updated Flex Plate Bolt Torque	https://www.psmagazine.army.mil/News/Article/3286243/fmtv-updated-flex-plate-bolt-torque/	TACOM has revised the flex plate bolts torque for FMTVs. Get the info you need here...
7-Feb-23	M1083A1P2 FMTV: New Cap Protects Hydraulic Fluid!	https://www.psmagazine.army.mil/News/Article/3291430/m1083a1p2-fmtv-new-cap-protects-hydraulic-fluid/	This article initially appeared in PS 779 (Oct 17) p. 13. To keep your EPHU from getting water contamination you'll need a protective (breather) cap for your A1P2 FMTV. Read about it here...
7-Feb-23	SINCGARS: FMTV Radio Installation Kits Differ	https://www.psmagazine.army.mil/News/Article/3291540/sincgars-fmtv-radio-installation-kits-differ/	The up-armored FMTV LTAS variant's SINCGARS radio installation kit and that of the non-armored FMTV are different. Read on to learn more.....
9-Feb-23	FMTV: A Little Tweak Seals the Leak	https://www.psmagazine.army.mil/News/Article/3293940/fmtv-a-little-tweak-seals-the-leak/	A rusty water stain on the ceiling of your FMTV's cab usually means water is seeping past the roof's cab bolts, so check for stains inside the cab. Read on for more info on how to correct this problem.....
13-Feb-23	M1270 MMPV: Transmission Fluid NSNs	https://www.psmagazine.army.mil/News/Article/3296768/m1270-mmpv-transmission-fluid-nsns/	Use only TES-295 transmission fluid in the M1270 MMPV. And don't mix with other fluids if you want to avoid performance problems. Read on to get NSN info and more...
14-Feb-23	M1082, M1095 FMTV Trailers: Authorized Air Brake Chamber	https://www.psmagazine.army.mil/News/Article/3297681/m1082-m1095-fmtv-trailers-authorized-air-brake-chamber/	There's only one authorized air brake chamber for M1082 and M1095 FMTV trailers. Read on to learn the details...
28-Feb-23	FMTV: Tan-Colored Side Window Covers	https://www.psmagazine.army.mil/News/Article/3312506/fmtv-tan-colored-side-window-covers/	You can order OD green side window covers but if you want tan, you'll need to contact AAR Mobility Systems. Keep reading to learn more...

28-Feb-23	M915A5 Tractor Truck: Vent Louver Assembly NSN	https://www.psmagazine.army.mil/News/Article/3311932/m915a5-tractor-truck-vent-louver-assembly-nsn/	The M915A5 vent louver assembly comes with NSN 2540-01-576-7334. Make note of this until the TM is updated. Read on for full details.....
6-Mar-23	M-ATV MRAP: Think Twice Before Scrapping Shocks	https://www.psmagazine.army.mil/News/Article/3319450/m-atv-mrap-think-twice-before-scrapping-shocks/	Damaged or leaky shock absorbers on your M-ATV MRAP make the vehicle NMC. However, not all condensation is a leak, so carefully evaluate the situation before replacing any shock absorber. Keep reading for all the details...
6-Mar-23	M149-Series Water Trailers: Water Tank Cleaning Tips	https://www.psmagazine.army.mil/News/Article/3320140/m149-series-water-trailers-water-tank-cleaning-tips/	This article initially appeared in PS 726, p. 6-7 (May 13). Cleaning the water trailer's tank improves the taste of the water and keeps the tank safe to use. The TM says to clean the tank annually or when the medics tell you the tank is contaminated. Get more tips...
9-Mar-23	Ground Vehicles: Remove Battery Corrosion	https://www.psmagazine.army.mil/News/Article/3324517/ground-vehicles-remove-battery-corrosion/	When cleaning and removing corrosion from your vehicle's lead-acid batteries, follow the guidance in WP 0027 of TM 9-6140-200-13 (May 11) and your vehicle's operator and field maintenance TMs. Get more info...
15-Mar-23	Ground Vehicles: Contact LARs for Maintenance Assistance	https://www.psmagazine.army.mil/News/Article/3329899/ground-vehicles-contact-lars-for-maintenance-assistance/	If you need maintenance or logistics help for ground vehicles or equipment, just reach out to a logistics assistance representative or LAR. Get more info here...
28-Mar-23	Lead-Acid Batteries: WP Update for TM 9-6140-200-13	https://www.psmagazine.army.mil/News/Article/3342995/lead-acid-batteries-wp-update-for-tm-9-6140-200-13/	AR 750-1 was recently updated which caused a need for an update in work package (WP) 0020 of TM 9-6140-200-13, Operator and Field Maintenance for Automotive Lead-Acid Storage Batteries (May 11). Get the correct info here...

29-Mar-23	MRAP: Troubleshooting 10-Amp Fuse Could Solve Problems	https://www.psmagazine.army.mil/News/Article/3345062/mrap-troubleshooting-10-amp-fuse-could-solve-problems/	In the current troubleshooting steps in the MRAP TMs, a step is missing to check a 10-AMP fuse. If you don't check the fuse on the C51 connector, it can lead to costly and time-consuming troubleshooting efforts. Read all about it...
13-Apr-23	M1000 HET Semi-trailer: OK to Mix Different Tire Treads	https://www.psmagazine.army.mil/News/Article/3360869/m1000-het-semi-trailer-ok-to-mix-different-tire-treads/	Tires with different tread patterns can be used together on the M1000 HET semi-trailer as long as they're the same size. But never mix bias and radial tires on the same trailer. Read on for more information.....
14-Apr-23	Ground Vehicles: Want to Order in Bulk?	https://www.psmagazine.army.mil/News/Article/3362656/ground-vehicles-want-to-order-in-bulk/	There are items you can order in bulk for your vehicles and equipment. Ordering in bulk can save units money and ensure high-usage items are available when needed. Here's how to find what you can order in bulk...
19-Apr-23	M989A1 HEMAT Trailer: Combat Water Intrusion	https://www.psmagazine.army.mil/News/Article/3367735/m989a1-hemat-trailer-combat-water-intrusion/	TACOM MAM 23-017 identifies water intrusion in M989A1 HEMAT trailers. You'll need to check for intrusion and take corrective action to mitigate it, both now and in the future. Get more info here...
2-May-23	M149-Series Water Trailers: NSNs for Safety Chain and Accessories	https://www.psmagazine.army.mil/News/Article/3381427/m149-series-water-trailers-nsns-for-safety-chain-and-accessories/	Get safety chain in bulk with NSN 4030-01-501-6946. We've got all the NSNs for replacing the safety chain and assembly. Get them here..
3-May-23	HMMWV: Need Hardtops?	https://www.psmagazine.army.mil/News/Article/3383349/hmmwv-need-hardtops/	Do you need hardtop covers for your HMMWV? The Army has only authorized certain variations of hardtops for HMMWVs and you won't find them in any of the HMMWV TMs because the Army doesn't support them. But if you want them, you can still get them. Keep reading to see a complete list.....


9-May-23	Ground Vehicles: View New CARC Spot Painting Videos	https://www.psmagazine.army.mil/News/Article/3389190/ground-vehicles-view-new-carc-spot-painting-videos/	TACOM CPC has released new CARC spot painting videos. There's a video for using aerosol paints and a video for using pint and quart kits. Get more info...
10-May-23	M1022-Series Dolly Set Mobilizer: Tire and Wheel Assembly NSN	https://www.psmagazine.army.mil/News/Article/3390711/m1022-series-dolly-set-mobilizer-tire-and-wheel-assembly-nsn/	Maintainers, the current TM for the M1022-series dolly set mobilizer doesn't include the NSN for the tire and wheel assembly. Get it here...
15-May-23	M872-Series Semitrailers: Corrosion Inspections	https://www.psmagazine.army.mil/News/Article/3395309/m872-series-semtrailers-corrosion-inspections/	TACOM MIM 23-015 advises there's a reinspection for corrosion on M872-series semitrailers. This includes the M872A4 model that wasn't inspected for corrosion in 2016. Get more info...
16-May-23	Ground Vehicles: BDAR Kit NSN	https://www.psmagazine.army.mil/News/Article/3396937/ground-vehicles-bdar-kit-nsn/	Get the latest and greatest Class IX Battle Damage and Assessment Repair (BDAR) crew kit with NSN 2590-01-659-5620. It's suitable for all combat and tactical vehicles. Read on for more info...
16-May-23	Fuel Tanker Trailers: New NSNs for Fire Extinguishers and Brackets	https://www.psmagazine.army.mil/News/Article/3397163/fuel-tanker-trailers-new-nsns-for-fire-extinguishers-and-brackets/	TACOM has some NSN changes to the fire extinguishers and brackets for fuel tanker trailers that aren't in the current TMs. Get them here...
24-May-23	PLS: M6 Dump Body Tarp	https://www.psmagazine.army.mil/News/Article/3405635/pls-m6-dump-body-tarp/	This article initially appeared in PS 766 (Sep 16), p.60. NSN 2540-01-449-5775, which is shown as Item 19 in Fig 1 of TM 9-3930-259-13&P (Jun 07), is for the M917 dump truck. It's too wide and short for the M6 dump body modular. Get the right NSN here...

6-Jun-23	M915A5 Tractor Truck: Stop Light Assembly NSN	https://www.psmagazine.army.mil/News/Article/3417854/m915a5-tractor-truck-stop-light-assembly-nsn/	The stop light assembly is listed as NSN 2320-01-550-1399 in Item 1 of Fig 103 of TM 9-2320-426-13&P in IETM EM 0308 (Aug 14), and that's wrong. Get the correct NSN here...
8-Jun-23	Fuel Tanker Trailers: Approved Winter Tire for Europe and Alaska	https://www.psmagazine.army.mil/News/Article/3421408/fuel-tanker-trailers-approved-winter-tire-for-europe-and-alaska/	If you're in Europe or Alaska, you can get a winter tire for your fuel tanker trailer with NSN 2610-01-602-7361. Read on for more info...
26-Jun-23	HMMWV Shelter: Searching for Generator NSN	https://www.psmagazine.army.mil/News/Article/3439386/hmmwv-shelter-searching-for-generator-nsn/	A Soldier is looking for the NSN for a generator in a HMMWV shelter. Half-Mast explains that one doesn't exist and how and where to repair them. Read on.....
29-Jun-23	M1101, M1102 Trailers: Trailer Cover Kit	https://www.psmagazine.army.mil/News/Article/3443813/m1101-m1102-trailers-trailer-cover-kit/	This article initially appeared in PS 798 (Jun 19), p.61. Warfighters, get a replacement canvas cover in camo or tan for your M1101 or M1102 trailers. Get the NSNs here...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...

19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
28-Jul-23	Wheeled Vehicles: One Stop Shop for Tire & Wheel Assemblies	https://www.psmagazine.army.mil/News/Article/2481765/wheeled-vehicles-one-stop-shop-for-tire-wheel-assemblies/	This article was updated 7/28/2023. Soldiers, before you go tire shopping, there's something you need to keep in mind. Ordering a replacement tire is not authorized when a tire and wheel assembly NSN exists. Read on for more information...
14-Aug-23	MRZR Polaris: Not Army Supported, So No RPSTL	https://www.psmagazine.army.mil/News/Article/3492315/mrzs-polaris-not-army-supported-so-no-rpstl/	The MRZR Polaris utility vehicle is a unit-purchased item. That means there's no RPSTL because the Army doesn't maintain them, and spare parts and equipment must be a local purchase. Keep reading to learn more...
14-Aug-23	MATV: Check the Shock Bushings	https://www.psmagazine.army.mil/News/Article/3492574/matv-check-the-shock-bushings/	TACOM has noticed that shock bushings, also known as resilient mounts, aren't being serviced during PMCS on MATVs. Here's what operators and mechanics need to know...
15-Aug-23	JLTV AO/A1: DSDU Supply Turn-in Procedures	https://www.psmagazine.army.mil/News/Article/3493211/jltv-aoa1-dsd-supply-turn-in-procedures/	If you have JLTVs, you'll want to read supply advisory message (SAM) 23-001 for detailed turn-in guidance for the driver smart display unit (DSDU). See more...
23-Oct-23	Batteries: Solar Maintainers Required for Long-Term Equipment Storage	https://www.psmagazine.army.mil/News/Article/3565076/batteries-solar-maintainers-required-for-long-term-equipment-storage/	AR 750-1 and DA PAM 750-1 were updated to clarify that approved solar maintainers are required for equipment in LUP, NCOMP and outdoor storage. Read on to learn more...

22-Nov-23	M1075 PLS: M4 Bituminous Distributor Fuel Filter Assembly NSN	https://www.psmagazine.army.mil/News/Article/3596382/m1075-pls-m4-bituminous-distributor-fuel-filter-assembly-nsn/	The fuel filter assembly, including the fuel housing, gasket and filter, for the M1075 PLS' M4 bituminous distributor comes with NSN 4330-00-219-4709. Read on for more info...
30-Nov-23	HMMWV: Does Missing Spare Tire Deadline Vehicle?	https://www.psmagazine.army.mil/News/Article/3602060/hmmwv-does-missing-spare-tire-deadline-vehicle/	A Soldier asks if a HMMWV missing a spare tire makes that HMMWV not mission capable (NMC). Read on for Half-Mast's response...
7-Dec-23	M900-series Fuel Tankers: Use the Proper Rim	https://www.psmagazine.army.mil/News/Article/3610187/m900-series-fuel-tankers-use-the-proper-rim/	If you need a rim for your fuel tankers, be sure to order the correct one. There are two (2) rims shown in TM 9-2330-339-23P (Dec 15). Get the info you need here...

Tools



Date	Article Title	Link	Excerpt
3-May-23	Tools: DeWALT Miter Saw Recall	https://www.psmagazine.army.mil/News/Article/3382024/tools-dewalt-miter-saw-recall/	<p>Follow the detailed instructions on how to replace your DeWALT® miter saw's plastic rear guard assembly. Before and after operation, make it a point to always inspect your saw for any damage. Keep reading the full story...</p>
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	<p>Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...</p>
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	<p>PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...</p>
16-Aug-23	SECM: Toolbox NSN Help	https://www.psmagazine.army.mil/News/Article/3494753/secm-toolbox-nsn-help/	<p>There's a reason you might be having trouble finding the NSNs and PNs for the SECM roadside and pass side boxes. Read on to find out why...</p>

Watercraft



Date	Article Title	Link	Excerpt
1/19/2023	H2F: ATP Guide Gives Guidance	https://www.psmagazine.army.mil/News/Article/3271717/h2f-atp-guide-gives-guidance/	ATP 7-22.02 covers physical fitness for the Soldier, enhancing personal and Army readiness. Learn more here...
21-Apr-23	H2F: GTA Posters Highlight Five Readiness Areas	https://www.psmagazine.army.mil/News/Article/3370299/h2f-gta-posters-highlight-five-readiness-areas/	A new GTA is available through the Central Army Registry consisting of five (5) posters covering the H2F Soldier Readiness System. To find out how to get them, keep reading...
23-Oct-23	Batteries: Solar Maintainers Required for Long-Term Equipment Storage	https://www.psmagazine.army.mil/News/Article/3565076/batteries-solar-maintainers-required-for-long-term-equipment-storage/	AR 750-1 and DA PAM 750-1 were updated to clarify that approved solar maintainers are required for equipment in LUP, NCOMP and outdoor storage. Read on to learn more...

This Page Intentionally Left Blank

Make **PMCS**...

WOULD YOU STAKE
YOUR LIFE, *RIGHT NOW*,
ON THE CONDITION OF
YOUR EQUIPMENT?



...a **Team Effort** in
your **Motor Pool!**